Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19012698/KHB3Q2

Date: 23/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 1800096299 Policy No: Claimant SKJ11K Insured Vehicle No: S9105CD Vehicle No:

Date of Loss: 07/07/2019 Nature of Claim: ΤP Claim No: 7938849935SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SKJ11K Reg No:

Make & Model: ROLLS-ROYCE GHOST, 6.6 (A) Engine No: 90134780

Chassis No: Reg. Date: 30/11/2011 (Man. Year: 2010) SCA664S0XAUH14803

Colour: Metallic Silver Odometer: 10843 km

Engine Capacity: Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

6592 cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 255/50 R19 Rear Tyre Size: 255/50 R19 Rear Left Side: Front Left Side: Goodyear 4 mm Goodyear 4 mm Front Right Side: Goodyear 4 mm Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,641.50	18,594.81	2,046.69	9.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	1,750.00	1,220.00	41.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,611.50	20,344.81	3,266.69	13.84
Approved Total (Overridden) (S\$)		16,250.00		
(S\$)	23,611.50	16,250.00	7,361.50	31.18
+ GST 7.00/7.00% (S\$)	1,652.81	1,137.50	515.31	31.18
Nett Amount (S\$)	25,264.31	17,387.50	7,876.81	31.18
+ Loss of Use (5.0 x S\$18	30.00/day) (S\$)	900.00		
	(S\$)	18,287.50		
Liable Amount (50.00%) (S\$) + Doc/Search Fee (S\$) Nett Liability (S\$) Global Sum Settlement (S\$)		9,143.75		
		2.00		
		9,145.75		
		9,145.00		

INSPECTION

Date of Assignment: 17/07/2019

Date Inspected: 17/07/2019 Inspected At: Adjuster Report Page 2 of 4

Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR ALLOY RIM RH	Dented	5,959.50 FL	*5,959.50 FL	
2	1		*REAR DOOR RH	Bent	13,598.20 FL	*13,598.20 FL	
3	1		*REAR DOOR RUBBER RH	Serviceable	586.20 FL	*- FL	
4	14		*REAR DOOR INNER TRIM CLIP RH	Not Necessary	179.20 FL	*- FL	
5	1		*REAR DOOR SEAL RUBBER RH	Serviceable	546.90 FL	*-FL	
6	1		*REAR QUARTER PANEL RH (NPA)	Repair	0.00 FL	*- FL	
7	1		*REAR TYRE RH	Serviceable	800.00 FS	*-FS	
8	1		*REAR TYRE TUBE VALVE RH	Necessary	15.00 FS	*15.00 FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
				Sub Total (S\$)	21,685.00	19,572.70	
			- List Item Discount on L Items 5.00/5.00% (S\$)		1,043.50	977.89	
				Total Parts (S\$)	20,641.50	18,594.81	
Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,REAJUST ACCIDENT AREAS & ETC	New	800.00	500.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR QUARTER PANEL RH ,REAR DOOR RH & ETC	New	1,200.00	800.00
3	TO REMOVE & REINSTALL REAR DOOR INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS }	New	400.00	200.00
4	TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC .BACK TO ORIGINAL OPERATIONS }	I New	200.00	0.00
5	TO WHEEL ALIGNMENT & BALANCING	New	120.00	50.00
6	TO DIGITAL & WIRING DIAGNOSIS & TO CLEAR FAULTY CODE	New	250.00	200.00
	Gross Labou	2,970.00	1,750.00	
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >