

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date: 17.07.2019

Acknowledged by Repairer No: SKJ11K

Signature: Model: ROLLS ROYCE GHOST 6.6

Date: Chassis: SCA664SOXAUH 4803 - 2010

Reg.Year: 2011

Kh

**OPTIMA WERKZ**  
SINGAPORE

OPTIMA WERKZ PTE LTD

Co. Reg. No. 201212455W

www.ow.sg

f /OptimaWerkz

© /OptimaWerkz

Third Party Insurer: AIG

Third Party Veh No: S9105CD

Date of Accident: 07.07.2019

Not Withain

Edas

61 Rm 8162501

Money After Paint

### ESTIMATE

| NO.         | DESCRIPTION                  | QTY | UNIT S\$ | AMOUNT S\$    |
|-------------|------------------------------|-----|----------|---------------|
| 1           | REAR ALLOY RIM RH            | 1   |          | Rs \$5,959.50 |
| 2           | REAR DOOR RH                 | 1   | Rs       | \$13,598.20   |
| 3           | REAR DOOR RUBBER RH          | 1   |          | Rs \$586.20   |
| 4           | REAR DOOR INNER TRIM CLIP RH | 14  | \$12.80  | Rs \$179.20   |
| 5           | REAR DOOR SEAL RUBBER RH     | 1   |          | Rs \$546.90   |
| 6           | REAR QUARTER PANEL RH        |     |          | REPAIR        |
| SUB TOTAL   |                              |     |          | \$20,870.00   |
| LESS 5%     |                              |     |          | -\$1,043.50   |
| PARTS TOTAL |                              |     |          | \$19,826.50   |

| NO.       | SPECIAL NETT            | QTY | UNIT S\$ | AMOUNT S\$  |
|-----------|-------------------------|-----|----------|-------------|
| 1         | REAR TYRE RH            | 1   |          | Rs \$800.00 |
| 2         | REAR TYRE TUBE VALVE RH | 1   |          | Rs \$15.00  |
| S/N TOTAL |                         |     |          | \$815.00    |

### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST ACCIDENT AREAS & ETC

\$800.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR QUARTER PANEL RH, REAR DOOR RH & ETC

\$1,200.00

TO REMOVE & REINSTALL REAR DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS

\$400.00

TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC. BACK TO ORIGINAL OPERATIONS

\$200.00

TO WHEEL ALIGNMENT & BALANCING

\$120.00

TO DIGITAL & WIRING DIAGNOSIS & TO CLEAR FAULTY CODE

\$250.00

LABOUR TOTAL \$2,970.00

ONG

TOTAL

\$23,596.50

Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415  
Tel: (+65) 6452 6868 Fax: (+65) 6452 9223

**OW**