

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5414R**AAD1907-165***Not Authorised**Rebony After Paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

18 JUL 2019

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 5414R

JTDKB3FU303079175

TOYOTA

PRIUS

17.7.19

III

17/1/2019

		PART		LIST	
1	1	REAR BUMPER	\$	11	458.60 X
2	1	REAR BUMPER RE-INFORCEMENT	\$	11	318.80 X
3	1	REAR BUMPER TOWING COVER	\$	11	14.70 X
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	Red 11	552.60
5	1	ANTENNA, ELECTRICAL KEY	\$	11	61.40
6	1	REAR BUMPER SIDE RETAINER LH	\$	11	112.70
7	1	REAR BUMPER SIDE RETAINER RH	\$	11	112.70
8	1	REAR TAILGATE	\$	11	1,547.27
9	1	REAR TAILGATE OUTER GARNISH	\$	11	905.10
10	1	COVER, REAR COMBINATION LAMP, RH	\$	11	54.70
11	1	COVER, REAR COMBINATION LAMP, RH	\$	11	54.70
12	1	GARNISH, BACK DOOR SIDE, LH	\$	11	93.60
13	1	GARNISH, BACK DOOR SIDE, RH	\$	11	93.60
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	11	55.40
15	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	11	55.40
16	1	BOARD ASSY, BACK DOOR TRIM	\$	11	254.40
17	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	11	51.20
18	1	REAR TAILGATE WEATHERSTRIP	\$	11	365.20
19	1	PANEL SUB-ASSY, BODY LOWER BACK (REAR END PANEL)	\$	11	641.50
20	1	TAILLAMP LOWER RH	\$	11	548.40
21	1	TAILLAMP UPPER RH	\$	11	557.90
22	1	REAR BUMPER SIDE RH	\$	11	232.00
23	1	REAR BUMPER SIDE LH	\$	11	232.00
24	1	TAILLAMP LOWER LH	\$	11	548.40
25	1	TAILLAMP UPPER LH	\$	11	557.90
26	1	REAR FENDER RH	\$	11	817.50
27	1	REAR FENDER LH	\$	11	817.50
28	1	LINER, REAR WHEEL HOUSE, LH	\$	11	138.10
29	1	LINER, REAR WHEEL HOUSE, RH	\$	11	138.10

Trans-cab Auto Services Pte Ltd

AAD1907-165

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5414R

30	1	BOARD, BACK DOOR TRIM
31	1	PANEL ASSY, DECK TRIM SIDE, RH
32	1	PANEL ASSY, DECK TRIM SIDE, LH
33	1	COVER, FLOOR UNDER, NO.1
34	1	COVER, FLOOR UNDER, NO.2
35	1	COVER, REAR FLOOR
36	1	PANEL SUB-ASSY, QUARTER, LH
37	1	PANEL, QUARTER WHEEL HOUSE, OUTER LH
38	1	PANEL SUB-ASSY, QUARTER, RH
39	1	PANEL, QUARTER WHEEL HOUSE, OUTER RH

\$	SH	220.70	}	X
\$	SH	351.10		
\$	SH	351.10		
\$	SH	172.60		
\$	SH	238.70		
\$	SH	226.80		
\$	SH	836.70		
\$	SH	290.50		
\$	SH	836.70		
\$	SH	290.50		
TOTAL	\$	14,206.77		
25%	\$	3,551.69		
	\$	10,655.08		

Special Nett

1	1SET	PARKING AID
2	1SET	REAR BUMPER CLIP
3	2	REAR WINDSCREEN SEALANT
4	1	WINDSCREEN MOULDING
5	1	REAR WINDSCREEN INNER SPONGE SEAL
6	1	REAR TAILGATE TOYOTA LOGO
7	1	REAR TAILGATE WORDING 'PRIUS'
8	1	REAR TAILGATE WORDING 'HYBRID'
9	1	REAR TAILGATE STICKER 'TRANS-CAB'
10	1	REAR TAILGATE STICKER '6555-3333'
11	1	REAR BUMPER PROTECTOR
12	1	REAR WHEEL RIM
13	1	REAR WHEEL RIM COVER
14	1	SPARE WHEEL RIM
15	1	SPARE WHEEL RIM COVER
16	1SET	FENDER WHEELARCH REAR LH CLIP
17	1SET	FENDER WHEELARCH REAR RH CLIP

\$	SH	700.00	}	X
\$	SH	22.00		
\$	SH	80.00		
\$	SH	100.00		
\$	SH	100.00		
\$	SH	47.00		
\$	SH	52.90		
\$	SH	53.50		
\$	SH	80.00		
\$	SH	80.00		
\$	SH	100.00		
\$	SH	1,570.55		
\$	SH	175.80		
\$	SH	1,570.55		
\$	SH	175.80		
\$	SH	35.00		
\$	SH	35.00		
TOTAL	\$	4,978.10		

TOTAL PARTS \$ 15,633.18**LABOUR**

Trans-cab Auto Services Pte Ltd**AAD1907-165**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5414R

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1501 4,500.00
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	~ 170.00 X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	~ 170.00 X
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 2201
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00 X
To Rust-Proofing Of The Affected Areas.	\$	~ 170.00 X
To reinstall rear bumper parking sensor.	\$	~ 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To Check Electrical Lighting Concerned.	\$	~ 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	~ 380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1907-165**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5414R

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

	\$	<i>nn</i> 380.00 <i>X</i>
TOTAL	\$	12,100.00

Over All Total	\$	27,733.18
-----------------------	----	------------------

(PART-BY-PART) Repair Days

15 Days
1 1/2 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: