

INS. CASE OWNER:

CC6 /EQ11901 2702, Ugb352

LKK:
IDAC:

Surveyor: MARMS DOI: ASSIGNMENT 18/7/19 Date / Time: 18/7/19
Registered in Merit: _____

Pre-assign / CCU / FTE



Insured Vehicle No.: GBH 2900 Claim No.: DMIAK001981
Name of Insured: Raffles Window Services Pte Policy No.: DMCPHX19-001673
Insured Tel No.: _____ HP: _____ Make / Model: KIA
Excess Sec II :SS _____ D.O.A.: 18/7/19 Place of Accident: SLE BU WOOLANDS
Is driver the owner? (YES / NO) Nature of Accident: _____
If NO. Driver Name / Age: LEW 101 KEE OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Driver Tel No.: _____ (VL: YES / NO) Insured Liability: % Final ? Yes / No

SJM 15010



INSRS: _____
WSP: Fastech
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

| Date/Time | STAGE | DATE / PIC |
|-----------|-----------------------------------|-------------------------------------|
| | Non-Reporting ltr (1st): | |
| | Non-Reporting ltr (2nd): | |
| | Non-Reporting ltr (Final): | |
| | Notification ltr (if non-pickup): | |
| | Call OI: | |
| | After call ltr to OI: | |
| | Documentation Check List: | Handler Typist |
| | Notification ltr (if non-pickup) | <input checked="" type="checkbox"/> |
| | After call ltr to OI: | <input checked="" type="checkbox"/> |
| | Authorisation To Act: | <input checked="" type="checkbox"/> |
| | Release Voucher: | <input checked="" type="checkbox"/> |
| | Final Repair Bill: | <input checked="" type="checkbox"/> |
| | Car Rental Invoice: | <input checked="" type="checkbox"/> |
| | Towing Invoice: | <input checked="" type="checkbox"/> |
| | LTA / GIA : | <input checked="" type="checkbox"/> |
| | Medical Bill: | <input checked="" type="checkbox"/> |
| | PIR: | <input checked="" type="checkbox"/> |
| | Mandate/Reject Instruction: | <input checked="" type="checkbox"/> |
| | LOD | <input checked="" type="checkbox"/> |
| | Payment Breakdown Form: | <input checked="" type="checkbox"/> |
| | Post-Repair Photos: | <input checked="" type="checkbox"/> |
| | Others: | <input checked="" type="checkbox"/> |

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: MARMS
Repair Cost: 45 SS 10,000.00, 9 days Reduction: 13,47.80 % 57 Email Call

FINAL SETTLEMENT Date/Time: 18/7/19 Confirm with: JASON Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 29
Repair Cost: (w/931) SS 10,700.00
Loss of Rental (LOR): SS 600.00 (5 days) x\$120
Loss of Use (LOU): SS - (5 x days)
Loss of Income (LOI): SS - (5 x days)
LOR only LOU only LOR + LOU LOR + LO [Tick only one]
GIA/LTA Search SS 2.00
Medical: SS -
Disbursement: SS - (e.g. Tow/Independent)
Legal Cost SS -
Total: SS 11,302.00 Global Sum SS: 11,300.00
1) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: \$400/-

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: SS 11,300.00 Name 1: Fastech Auto Pte Ltd
Payee 2: (Strike if N.A.) SS _____ Name 2: _____
Payee 3: (Strike if N.A.) SS _____ Name 3: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SJM1501D*

at Workshop m/s: *PL*

of _____

Insured: *GHSI 25104*

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: *SJM1501D* Yr Regn: *7/08*

Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CAI*

Make: *Honda Accord* c.c. *1998*

Colour: *Black* A/C: *Insured / Std / NI / NA*

Sp. Reading: *203273* T/Radio: *Insured / Std / NI / NA*

Eng/No: _____

C/No: *CL7 3304635*

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt or

Brake: *In order* / Jammed / Leaked / Burnt or

Modi: *Nil* / S/Rim / STD A/Rim or

Tyre Size: F: *2.5/55-217*

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: *\$50k*

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *9* days Res.: Yes or No

Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *2498D*

Date: _____ Person Contacted: _____
next 22852

Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front *6* mm Rear *6* mm

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. *17/7/19* D.O.I. *18/7/19*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
col 27-7-2018 LTA 33278

30/7/19 confirmed L/S \$10,000 with Alu. (Red. \$13,417.80/57.1)

5 repair days + 1 PRS + 1 Sat + 2 Sun = 9 days

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair:

1) Date/Time, File Return to?

Resurvey No. of Trip: _____

Survey Fee: _____

2) _____

Transportation: _____

Add Fee: : Site Insp (\$ _____)) S + RS. SI

: Interview (\$ _____)) Photos

: Tech. Invs (\$ _____)) Others

: Weekend (\$ _____))

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$ _____)

FASTECH AUTO PTE LTD
 BLK1 KAKI BUKIT AVE 6
 #01-46,48,50 AUTOBAY
 SINGAPORE 417883

Not Allowed
 18/7/19
 1/5 ~~10.000~~
 9dy.

VEHICLE NO: SJH 1501D

| QTY | PARTICULAR | | | |
|-------|--|----------------|-----------|-----------------|
| 1 PCS | BOOTLID | 892.20 | Body | \$1,350.00 |
| 1 PCS | BOOTLID 'ACCORD' EMBLEM | 38.30 | nu | \$49.50 |
| 1 PCS | BOOTLID 'H' LOGO | 38.50 | nu | \$48.00 |
| 2 PCS | BOOTLID REFLECTORS @\$450.00 | | cre | \$900.00 |
| 2 PCS | BOOTLID HINGES @\$155.00 | | bed/tw | \$310.00 |
| 2 PCS | BOOTLID DAMPERS @\$215.00 | | 11 | \$430.00 X |
| 1 PCS | BOOTLID WEATHERSTRIP | | twi | \$322.00 |
| 1 PCS | BOOTLID INNER LOCK | | twi | \$299.00 |
| 1 PCS | BOOTLID INNER TRIM | 322.20 | re/torn | \$418.30 |
| 1 SET | BOOTLID INNER TRIM CLIPS | | nu | \$50.00 |
| 1 PCS | REAR BUMPER | 781.10 | D.S | \$1,480.00 |
| 2 PCS | REAR BUMPER SIDE RETAINERS @\$45.00 | | sd | \$90.00 |
| 1 SET | REAR BUMPER CLIPS | | nu | \$50.00 |
| 2 PCS | REAR BUMPER REFLECTORS @\$85.00 | 45.00 | o/s cm | \$170.00 |
| 1 PCS | REAR BUMPER INNER TOP RETAINER | | beat | \$199.00 |
| 1 PCS | REAR END PANEL | 645.30 | body | \$725.00 |
| 1 PCS | REAR END PANEL TOP GARNISH | 288.50 | twi | \$366.00 |
| 2 PCS | REAR TAILLAMPS @\$850.00 | 525 x 2 = 1050 | cre | \$1,700.00 |
| 2 PCS | TAILLAMP HOUSING PANELS @\$295.00 | | NS | \$590.00 X |
| 2 PCS | REAR FENDERS @\$1125.00 | | n | \$2,300.00 X |
| 2 PCS | REAR FENDER INNER TRIMS @\$465.00 | | re/torn | \$930.00 |
| 1 PCS | REAR EXHAUST | 1220.00 | m/3d | \$1,250.00 |
| 2 PCS | REAR EXHAUST MOUNTINGS @\$60.00 | | 11 | \$120.00 X |
| 1 PCS | REAR FLOOR PANEL | 1480.60 | crayd/Buc | \$1,660.00 |
| 1 PCS | REAR FLOOR PANEL TOP BOARD | 645.20 | meqd | \$820.00 |
| 1 PCS | REAR BUMPER LOWER TRAY | 366.50 | twi | \$408.00 |
| 1 PCS | REAR WINDSCREEN MOULDING | | 11 | \$122.00 X |
| 1 PCS | REAR SPARE TYRE PANEL TOOLS SPONGE | 295 | Torn | \$314.00 |
| | | | | \$17,467.80 |
| | S.NETT | | | |
| 1 PCS | REAR BUMPR REVERSE SENSOR | | shhd | \$280.00 200 |
| 1 PCS | REAR END PANEL SEALANT | | nu | \$50.00 |
| 1 PCS | REAR FLOOR PANEL INSULATOR | | nu | \$220.00 100 |
| 1 PCS | REAR WINDSCREEN SEALANT | | 11 | \$50.00 X |
| 1 PCS | REAR LICENCE PLATE W/HOLDER | | CM | \$50.00 40 |
| | LABOUR CHARGES: | | | |
| | TO CHECK WIRING | | | \$80.00 30 |
| | TO DISMANTLE & REPLACING REVERSE SENSOR | | | \$80.00 50 |
| | TO DISMANTLE & REPLACING REAR EXHAUST | | | \$120.00 80 |
| | TO DISMANTLE & REFIX PETROL TANK | | | \$100.00 X |
| | TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY | | 11 | \$120.00 80 |
| | TO DISMANTLE & REFIX BOOTLID MECHANISM | | | \$100.00 60 |
| | TO SPRAY RUST PROOFING | | | \$120.00 100 |
| | TO MOUNT VEHICLE ON CAR O-LINER | | 11 | \$380.00 X |
| | LABOUR FOR PANEL BEATING & REPLACING PARTS | | | \$2,200.00/1400 |

11458.4
 202
 9166.72

| | | | | | |
|--|---------------------------|--|-------|-------------|------|
| | TO PUTTY & SPRAY PAINTING | | | \$2,000.00 | 1200 |
| | | | TOTAL | \$23,417.80 | |

1257672

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------------|--------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 498D |
| Vehicle Details | |
| Vehicle No.: | SJH1501D |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 19 Jul 2019 |
| Vehicle Make: | HONDA |
| Vehicle Model: | ACCORD 2.0 A |
| Primary Colour: | Black |
| Manufacturing Year: | 2008 |
| Engine No.: | K20A6055330 |
| Chassis No.: | CL73304635 |
| Maximum Power Output: | 114.0 kW (152 bhp) |
| Open Market Value: | \$19,230.00 |
| Original Registration Date: | 28 Jul 2008 |
| First Registration Date: | 28 Jul 2008 |
| Transfer Count: | 2 |
| Actual ARF Paid: | \$19,230.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Forfeited |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 27 Jul 2028 |
| COE Category: | B - Car (1601cc & above) |
| COE Period(Years): | 10 |
| PQP Paid: | \$36,888.00 |
| COE Rebate Amount: | \$33,278.00 |
| Total Rebate Amount: | \$33,278.00 |

The information contained herein is correct as at 19 Jul 2019

OK



Home » Used Cars » Top Drive Automobiles LLP » Honda Accord 2.0A (COE till 07/2028)

Honda Accord 2.0A (COE till 07/2028)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

| | | | |
|------------------------|-------------------------------|------------------------|--|
| Price | \$52,800 | | |
| Depreciation ⓘ | \$5,890 /yr | Reg Date | 02-Jul-2008 (8yrs 11mths 12days COE left) |
| Mileage | 140,000 km (12.7k /yr) | Manufactured ⓘ | 2008 |
| Road Tax ⓘ | \$1,331 /yr | Transmission | Auto |
| Dereg Value ⓘ | \$33,048 as of today (change) | OMV ⓘ | \$20,421 |
| COE ⓘ | \$36,888 | ARF ⓘ | \$20,421 |
| Engine Cap | 1,998 cc | Power | 114.0 kW (152 bhp) |
| Curb Weight ⓘ | 1,370 kg | No. of Owners ⓘ | 3 |
| Type of Vehicle | Luxury Sedan | | |



[Shortlist](#)
[Com](#)
[Report Error](#)
[M](#)

Features

Reliable 2.0 Litre Automatic I-VTEC At 155bhp, Climate Control, Electrical Retractable Side Mirrors, ABS. View specs of the Honda Accord

Accessories

Well Maintained Leather Seats, Reverse Sensors, Retractable Side Mirrors, Factory Fitted Audio System, Solar Films.

Description

Newly Replaced Aircon Extremely Important For The Hot Weather In This Sunny Island! Well Maintained By Fussy Owner, Wear And Tear Replaced, Honda Well Known For Reliability, Drive To End Of COE Without Any Worry, Consignment Unit, Viewing Via Appointment Only, Loan And Trade In Available, Contact Us Now!

Category

COE Car, Premium Ad Car

Status

Availabl-

[Compare](#)

Seller Information

| | |
|--------------------------|-------------|
| Company | Top |
| | » de |
| | » 4 v |
| Address | 190 I |
| Location | Fort |
| Contact Person(s) | Loh Chev |

Shu Pei (LKKAuto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Wednesday, 14 August 2019 9:55 AM
To: Shu Pei (LKKAuto)
Cc: Admin A; Cecilia Chong (LKK Auto)
Subject: RE: Direct Settlement - Accident Involving GBH2910U (OI : EQI - DM19HO01981/JT) AND SJH1501D (TP : LKK REF - CC6/EQI19012702/Ugb3) on 17.07.2019
Attachments: SAS2637382.PDF; TP GIA REPORT.PDF

Dear Shu Pei,

As attached.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAuto) [mailto:shupe@lkkauto.com]
Sent: Friday, July 19, 2019 3:45 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Subject: Direct Settlement - Accident Involving GBH2910U (OI : EQI - TBA) AND SJH1501D (TP : LKK REF - CC6/EQI19012702/Ugb3) on 17.07.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SJH 1501D at M/s Fastech Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:
- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Cecilia and she can be contacted at DID: 6749 4274.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Monday, 16 December 2019 3:19 PM
To: 'Janice Goh'
Subject: RE: YOUR REF: DMCPHQ19-001673 (OUR REF: CC6/EQI19012702/Ugb3s2) ***
ACCIDENT INVOLVING GBH 2910U & SJH 1501D ON 17/07/2019 ***
Attachments: ADJUSTMENT REPORT.pdf; INSPECTION REPORT.pdf; LKK RESURVEY PHOTO 2.pdf; LKK RESURVEY PHOTO.pdf; LKK SURVEY PHOTO.pdf; LOD AND OTHER DOCUMENTS.pdf; PARF COE REBATE.pdf

EQ ref : **DMCPHQ19-001673**
LKK ref : CC6/EQI19012702/Ugb3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING GBH 2910UEQ-OI) AND SJH 1501D(TP) ON 17/07/2019

We refer to the above matter.

This is a head-to-rear collision.
A letter was sent out to the Insured to notify Third Party claim and NCD issues. No further feedback till to date.

We seek your approval to offer Third Party repairer "**FASTECH AUTO PTE LTD**" at **11,602.00(all-in)**.

The summary is as follows: -

| | Claimed Amount | Revised Amount |
|--------------------------------------|----------------|-------------------------------|
| 1. Cost of Repair (w/GST) | \$ 23,417.80 | \$ 10,700.00 |
| 2. Loss of Rental (5days x \$180.00) | \$ 900.00 | \$ 900.00 (18days x \$180.00) |
| 3. LTA/ GIA Search Fee | \$ 2.00 | \$ 2.00 |
| Total | \$ 24,319.80 | \$ 11,602.00 |

**5days recommendation for repair + 2 Sunday + 1 Saturday + 1PRS = 9days

| | |
|--------------|----------------------------|
| Market Value | : \$50,000.00 (est) |
| LTA Rebate | : \$33,278.00 (est) |
| Nett Value | : \$16,722.00 (est) |

Enclosed here with all the relevant documents for your perusal.

Kindly let us have your approval/instruction.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,
Cecilia Chong | Case Handler

Cecilia Chong (LKK Auto)

From: Jason <Jason@fastechauto.com.sg>
Sent: Wednesday, 18 December 2019 11:52 AM
To: Cecilia Chong (LKK Auto)
Cc: Ong Shiyong
Subject: RE: YOUR REF:GBH2910U(EQ) MY REF:SJH1501D DOA:17/07/2019.

Without Prejudice

Dear Cecilia,

We are pleased to accept your offer at global sum of \$11,300.00 for my client's vehicle property claim.

Thank you.

Best Regards

Jason Tang
Fastech Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Cecilia Chong (LKK Auto) [mailto:CeciliaChong@lkkauto.com]
Sent: Wednesday, December 18, 2019 10:19 AM
To: Jason <Jason@fastechauto.com.sg>
Subject: RE: YOUR REF:GBH2910U(EQ) MY REF:SJH1501D DOA:17/07/2019.

WITHOUT PREJUDICE

Dear Jason,

We are pleased to offer G/S \$11,300.00 (all-in).

Kindly confirm acceptance.

Thanks



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQI19012702/Ugb3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 31-12-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|-----------------|----------------|------------|
| Insured Veh. | GBH 2910U | Veh. Inspected | SJH 1501D |
| Policy No. | DMCPHQ19-001673 | Coverage (\$) | 0.00 |
| Claim No. | DM19HO01981/JT | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 18/07/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|------------------|--------------|------------|
| Make & Model | HONDA ACCORD (A) | c.c | 1998 |
| Engine No. | HIDDEN | Year of Reg. | 2008 |
| Chassis No. | CL73304635 | Colour | BLACK |
| Odometer | 203273 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 215/55 R17 | MICHELIN | 6 mm |
| L/H Front Tyre | 215/55 R17 | MICHELIN | 6 mm |
| R/H Rear Tyre | 215/55 R17 | MICHELIN | 6 mm |
| L/H Rear Tyre | 215/55 R17 | MICHELIN | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 17/07/2019 | Inspection Date | 18/07/2019 |
| Survey held at | FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **9 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 1501D

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--------------------------------------|----------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | BOOTLID | BADLY DENTED | 1,350.00 | 892.20 |
| 1 | BOOTLID 'ACCORD' EMBLEM | NECESSARY | 49.50 | 38.30 |
| 1 | BOOTLID 'H' LOGO | NECESSARY | 48.00 | 38.50 |
| 2 | BOOTLID REFLECTORS @ \$450.00 | CRACKED | 900.00 | 900.00 |
| 2 | BOOTLID HINGES @ \$155.00 | BENT / TWISTED | 310.00 | 310.00 |
| 2 | BOOTLID DAMPERS @ \$215.00 | NOT NECESSARY | 430.00 | - |
| 1 | BOOTLID WEATHERSTRIP | TWISTED | 322.00 | 322.00 |
| 1 | BOOTLID INNER LOCK | TWISTED | 299.00 | 299.00 |
| 1 | BOOTLID INNER TRIM | DEFORMED / TORN | 418.30 | 322.20 |
| 1 | SET BOOTLID INNER TRIM CLIPS | NECESSARY | 50.00 | 50.00 |
| 1 | REAR BUMPER | DISTORTED | 1,480.00 | 981.10 |
| 2 | REAR BUMPER SIDE RETAINERS @ \$45.00 | BENT | 90.00 | 90.00 |
| 1 | SET REAR BUMPER CLIPS | NECESSARY | 50.00 | 50.00 |
| 2 | REAR BUMPER REFLECTORS @ \$85.00 | O/S CRACKED | 170.00 | 45.00 |
| 1 | REAR BUMPER INNER TOP RETAINER | BENT | 199.00 | 199.00 |
| 1 | REAR END PANEL | BADLY DENTED | 725.00 | 645.30 |
| 1 | REAR END PANEL TOP GARNISH | TWISTED | 366.00 | 288.50 |
| 2 | REAR TAILLAMPS @ \$850.00 | CRACKED | 1,700.00 | 1,050.00 |
| 2 | TAILLAMP HOUSING PANELS @ \$295.00 | NO SUCH PARTS | 590.00 | - |
| 2 | REAR FENDERS @ \$1125.00 | TO REPAIR SEE LABOUR | 2,300.00 | - |
| 2 | REAR FENDER INNER TRIMS @ \$465.00 | DEFORMED / TORN | 930.00 | 930.00 |
| 1 | REAR EXHAUST | DENTED / BENT | 1,250.00 | 1,220.00 |
| 2 | REAR EXHAUST MOUNTINGS @ \$60.00 | NOT NECESSARY | 120.00 | - |
| 1 | REAR FLOOR PANEL | CRUMPLED / BUCKLED | 1,660.00 | 1,480.60 |
| 1 | REAR FLOOR PANEL TOP BOARD | WARPED | 820.00 | 645.20 |
| 1 | REAR BUMPER LOWER TRAY | TWISTED | 408.00 | 366.50 |
| 1 | REAR WINDSCREEN MOULDING | NOT NECESSARY | 122.00 | - |
| 1 | REAR SPARE TYRE PANEL TOOLS SPONGE | TORN | 311.00 | 295.00 |

Report Ref No. CC6/EQ119012702/Ugb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|---------------|---------------------------|-------------------|
| | LESS 20% DISCOUNT | | - | -2,291.68 |
| | | | 17,467.80 | 9,166.72 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | REAR BUMPER REVERSE SENSOR (SN) | SHORTED | 280.00 | 200.00 |
| 1 | REAR END PANEL SEALANT (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | REAR FLOOR PANEL INSULATOR (SN) | NECESSARY | 220.00 | 100.00 |
| 1 | REAR WINDSCREEN SEALANT (SN) | NOT NECESSARY | 50.00 | - |
| 1 | REAR LICENCE PLATE W/HOLDER (SN) | CRACKED | 50.00 | 40.00 |
| | | | 650.00 | 390.00 |
| | <u>LABOUR</u> | | | |
| | TO CHECK WIRING. | | 80.00 | 30.00 |
| | TO DISMANTLE & REPLACING REVERSE SENSOR. | | 80.00 | 50.00 |
| | TO DISMANTLE & REPLACING REAR EXHAUST. | | 120.00 | 80.00 |
| | TO DISMANTLE & REFIX PETROL TANK. | NOT NECESSARY | 100.00 | - |
| | TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY. | | 120.00 | 80.00 |
| | TO DISMANTLE & REFIX BOOTLID MECHANISM. | | 100.00 | 60.00 |
| | TO SPRAY RUST PROOFING. | | 120.00 | 100.00 |
| | TO MOUNT VEHICLE ON CAR O-LINER. | NOT NECESSARY | 380.00 | - |
| | LABOUR FOR PANEL BEATING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDERS. | | 2,200.00 | 1,400.00 |
| | TO PUTTY & SPRAY PAINTING. | | 2,000.00 | 1,200.00 |
| | | | 5,300.00 | 3,000.00 |
| | GRAND TOTAL | | 23,417.80 | 12,556.72 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 10,000.00 |

Report Ref No. CC6/EQ119012702/Ugb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.