ORMANIA Wef . REF.	501
ASS. REC. BY: March	241
	ASSIGNMENT
8	(7 W 1671) D VE BOOK 7/08
From: Date:	Veh No: Veh No. 17 A Very I Tay I Prime Mover
Estimated Cost:	Type M.ear / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or V4
(41/1000	Make: Handa Accord c.c 1998
///	Colour Black A/C: Insured / Std / NI / NA
at Workshop m/s	Sp.Reading 203273 T/Radio: Insured / Std / NI / NA
of the second	,
Insured: GST 25104	Eng/No:
Policy No.	C/No: CL7 330 4635
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Incoder / Jammed / Leaked / Burnt or
Suiti insured.	Brake: Inorder Jammed / Leaked / Burnt or
(Client's Record)	Modi: Nil / S/Rim/ STD A/Rim or
Make of Veh:	Tyre Size: F: 215/55-217
	ryre Size. R:
(Policy Condition)	CO CUTCH LAND LOUISIL
Remark: The veh had commenced its	
repair at the time of inspection.	TOYO/YOKO or
Bal, or Market Value:	Front Rear 6
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6, / mm L/Bal. 6 mm
O Poor Voe or No	D.O.A. 17/7/18 D.O.I. 18/7/18
Est. Repairs.	Survey held at
Lum Sum. 4)	
CA / REV / REP. / 24 HRS 2 498	
m Outstale	The U/C / Chassis frame / Body Structure affected due to collision.
ADET DISC	The O/C / Chassis halite / Body chastars disease
Date / Time Action / Instruction GOL 17-7-2028 7-14	The second secon
3/ 1/18 confind 4/5 # 10.	1200 Mla Ala.
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
	Resurvey No. of Trip: Survey Fee:
1) : Final Report	Resurvey No. of Trip.
Date/Time, File Return to?	
2)	Add 1 doi:
	: Interview (\$) Photos
Report Format :	:Tech. Invs (\$) Others
,* Lump Sum / I.B.I: (\$:Weekend (\$)
,	TOTAL

			Not Allowed
FASTECH A	AUTO PTE LTD		N/21-
	BUKIT AVE 6		2/2/2
	0 AUTOBAY		18/7/19
SINGAPOR			1/ 1/0 2-2-3/
SINGAPOR	E 417003		2/5 # 10,000
VEHICLE NO	:SJH 1501D		9dy.
QTY	PARTICULAR		11
1 PCS	BOOTLID 852.20		Bollin \$1,350.00 _
1 PCS	BOOTLID 'ACCORD' EMBLEM 28-30		\$49.50
1 PCS	BOOTLID 'H' LOGO 38-50		\$48.00
2 PCS	BOOTLID REFECTORS @\$450.00		Cre \$900.00 —
2 PCS	BOOTLID HINGES @\$155.00		Bel (Tur \$310.00
2 PCS	BOOTLIS DAMPERS @\$215.00		17 \$430.00 X
1 PCS	BOOTLID WEATHERSTRIP		TNI \$322.00 -
1 PCS	BOOTLID INNER LOCK		Tw (\$299.00 -
1 PCS	BOOTLID INNER TRIM 321-20		De/70-1 \$418.30
1 SET	BOOTLID INNER TRIM CLIPS		ner \$50.00
1 PCS	REAR BUMPER 981-10		7-1 \$1,480.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$45.00		\$90.00
1 SET	REAR BUMPER CLIPS		\$50.00
2 PCS	REAR BUMPER REFLECTORS @\$85.00 45.00		Elecon \$170.00 120
1 PCS	REAR BUMPER INNER TOP RETAINER		Sea + \$199.00
1 PCS	REAR END PANEL 645.30		5 d 1 1 \$725.00
1 PCS	REAR END PANEL TOP GARNISH 2 ff. 50		Tul \$366.00
2 PCS	REAR TAILLAMPS @\$850.00 5-25 × 2 3	2/126)	cre \$1,700.00
2 PCS	TAILLAMP HOUSING PANELS @\$295.00		NS \$590.00 ∞
2 PCS	REAR FENDERS @\$1125.00		\$2,300.00 X
2 PCS	REAR FENDER INNER TRIMS @\$465.00		DelToin \$930.00
1 PCS	REAR EXHAUST /220.00		37/34 \$1,250,00
PCS	REAR EXHAUST MOUNTINGS @\$60.00		17 \$120.00 X
PCS	REAR FLOOR PANEL /480.60		cruyed/Bux \$1,660.00
PCS	REAR FLOOR PANEL TOP BOARD 645. 20	1	meg & \$820.00
PCS	REAR BUMPER LOWER TRAY 366.50	/ ~	du \$408.00
PCS	REAR WINDSCREEN MOULDING	1 297	11 \$122.00 X
PCS	REAR SPARE TYRE PANEL TOOLS SPONGE 285	100	70m \$314.00
			\$17,467.80
	S.NETT		
PCS	REAR BUMEPR REVERSE SENSOR		5hld \$280.00 20,
PCS	REAR END PANEL SEALANT		2er \$50.00 C
PCS	REAR FLOOR PANEL INSULATOR		Les \$220.00 /Ou
PCS	REAR WINDSCREEN SEALANT		77 \$50.00 X
PCS	REAR LICENECE PLATE W/HOLDER		CM \$50.00 40
	LABOUR CHARGES:		40
TO CHECK WIRING	TO CHECK WIRING		\$80.00 3
	TO DISMANTLE & REPLACING REVERSE SENSOR		\$80.00 \$2
	TO DISMANTLE & REPLACING REAR EXHAUST		
	TO DISMANTLE & REFIX PETROL TANK		\$120.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTER		N \$100.00 ×
		.1	\$120.00 PO
	TO DISMANTLE & REFIX BOOTLID MECHANISM		\$100.00 6.2
	TO SPRAY RUST PROOFING		\$120.00/00
	TO MOUNT VEHICLE ON CAR O-LINER		1 1 \$380.00 ₩
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$2,200.00/40

TO PUTTY & SPRAY PAINTING	\$2,000.00		1200
	TOTAL	\$23,417.80	,

1257672

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: