

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5569H**AAD1907-141**

Not Authored
CSmy B

Vehicle No.:

Chassis No.:

Vehicle Make:

17 JUL 2019

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5569H

VF1ABL15AUC279261

RENAULT

LATITUDE

12.7.19

AXA

15/9/2014

PART		LIST	
1	DOOR PANEL REAR LH	\$	<i>Rn</i> 2,844.66 ✓
1	DOOR HANDLE OUTER REAR LH	\$	<i>cl of / Rn</i> 126.49 ✓
1	DOOR HANDLE CAP REAR LH	\$	<i>Rn</i> 35.52 X
1	DOOR HANDLE SEAL REAR LH	\$	<i>Rn</i> 7.89 X
1	DOOR HANDLE COVER REAR LH	\$	<i>Rn</i> 13.22 X
1	DOOR HANDLE MODULE REAR LH	\$	<i>Rn</i> 133.60 X
1	DOOR PANEL FRT LH	\$	<i>Rn</i> 2,844.66 ✓
1	DOOR HANDLE OUTER FRT LH	\$	<i>cl of / Rn</i> 477.76 ✓
1	DOOR HANDLE COVER FRT LH	\$	<i>Rn</i> 13.22 X
1	DOOR HANDLE MODULE FRT LH	\$	<i>Rn</i> 133.60 X
1	ROCKER PANEL INNER GARNISH LH	\$	<i>Rn</i> 466.51 X
1	ROCKER PANEL INNER LH	\$	<i>Rn</i> 1,024.79 X
1	ROCKER PANEL OUTER LH	\$	<i>Rn</i> 1,184.99 X
1	ROCKER PANEL CENTER LH	\$	<i>Rn</i> 990.25 X
1	DOOR MIRROR ASSY LH	\$	<i>Part / Rn</i> 1,483.40 ✓
1	DOOR HARNESS WIRE LH	\$	<i>Rn</i> 2,670.00
1	FENDER PANEL REAR LH	\$	<i>Rn</i> 3,299.13
1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Rn</i> 671.45
1	WHEELARCH REAR LH	\$	<i>Rn</i> 543.47
1	FENDER PANEL FRT LH	\$	<i>Rn</i> 783.83
1	WHEELARCH FRT LH	\$	<i>Rn</i> 278.84
1	FENDER BRACKET LOWER LH	\$	<i>Rn</i> 15.79
1	FENDER INSULATOR LH	\$	<i>Rn</i> 130.84
1	AIR CLEANER BOX	\$	<i>Rn</i> 464.20
1	AIR CLEANER HOSE	\$	<i>Rn</i> 175.85
1	AIR CLEANER LOWER	\$	<i>Rn</i> 271.26
1	BUMPER COVER FRT	\$	<i>Rn</i> 1,259.42
1	BUMPER RETAINER FRT LH	\$	<i>Rn</i> 151.41
1	BUMPER SUPPORT FRT	\$	<i>Rn</i> 123.88

Trans-cab Auto Services Pte Ltd**AAD1907-141**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5569H

1	BUMPER FOG LAMP GRILLE LH	\$	207.21
1	HEADLAMP LH	\$	1,184.43
1	BUMPER COVER REAR	\$	1,108.46
1	BUMPER LOWER REAR	\$	768.84
1	BUMPER BRACKET CTR REAR	\$	113.47
1	BUMPER BRACKET SIDE LH REAR	\$	135.97
1	BUMPER RETAINER LH REAR	\$	44.99
1	BUMPER REFLECTOR LH	\$	43.61
1	BUMPER BEAM REAR	\$	777.52
1	BUMPER BEAM BRACKET LH REAR	\$	225.95
1	TAILLAMP LH	\$	552.55
1	TAILLAMP PANEL LH	\$	986.70
1	FUEL FLAP	\$	343.57

Perch

TOTAL	\$	29,113.23
10%	\$	2,911.32
	\$	26,201.91

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	<i>na</i> 100.00 <i>65/na</i>
1	FRONT DOOR STICKER 'Trans-Cab'	\$	<i>na</i> 80.00 <i>65/na</i>
1	FRONT DOOR STICKER 'Classic'	\$	<i>na</i> 80.00 <i>15/na</i>
1	REAR LEFT TYRE	\$	<i>na</i> 300.00
1	REAR LEFT TYRE RIM	\$	<i>na</i> 380.00
1	FRONT LEFT TYRE	\$	<i>na</i> 300.00
1SET	WHEELARCH CLIP FRT LH	\$	<i>na</i> 30.50
1	FENDER INNER TRIM CLIP LH	\$	<i>na</i> 28.00
1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>na</i> 35.00
1	FRONT LEFT TYRE RIM	\$	<i>na</i> 380.00
2	REAR WINDSCREEN SEALANT	\$	<i>na</i> 80.00
1	WINDSCREEN MOULDING	\$	<i>na</i> 100.00
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00
1	TAILLAMP CLIP LH	\$	<i>na</i> 5.00
1SET	REAR BUMPER CLIP	\$	<i>na</i> 66.00
1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00
1SET	BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00
1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00
1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00

X

Trans-cab Auto Services Pte Ltd**AAD1907-141**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5569H

1SET	PARKING AID	\$	<i>Pn</i> 700.00 X
1	BUMPER CLIP FRT	\$	<i>nn</i> 66.00 X
1	BUMPER BRACKET CLIP FRT LH	\$	<i>nn</i> 12.00 X
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>nn</i> 10.50 X
TOTAL		\$	3,004.00

TOTAL PARTS	\$	29,205.91
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00 <i>14.600</i>
Putty and spray painting of the affected portion.	\$	6,000.00 <i>11001</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 <i>801</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To rust-proofing of the affected areas.	\$	170.00 <i>601</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 <i>601</i>

Trans-cab Auto Services Pte Ltd**AAD1907-141**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5569H

To transfer of Front door fittings, attachment and perform water seepage test.	\$	380.00	6cl.
To Check Electrical Lighting Concerned.	\$	170.00	2cl
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
To transfer of Front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Front bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
TOTAL	\$	16,490.00	
Over All Total	\$	45,695.91	

LUMP SUM (REPAIR DAY)**20-DAYS***4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: