

He



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
Sin Ming Autocare Complex
Singapore 575721
Tel : (65) 6455 0600
Fax : (65) 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

LONPAC INSURANCE BHD
100 BEACH ROAD #19-00 SHAW TOWER
SINGAPORE 189702

Estimate : E19/2502

Attention : Motor Claim Department

Contact : 6250 7388 Fax No. : 6296 3767

Date : 17/07/2019
Vehicle Num. : SGY3347R
Make/Model : TOYOTA VIOS-2007
Chassis/Eng# : MR053HY9305025729
Accident Date : 15/07/2019
Claim No. : TP CLAIM
Reference : BFG/VMS
Policy No. : 5102940148

*Not within
61km @ 2800-4000
Resurvey After Paint 4 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1PC	REAR DOOR - LH	784.30	X
2.	1PC	REAR FENDER - LH	934.81	X
3.	1PC	REAR BUMPER	571.80	X
4.	1PC	REAR BUMPER SIDE RETAINER - LH	57.40	X
5.	8PCS	REAR BUMPER CLIPS	48.00	X
6.	1PC	REAR SHOCK ABSORBER - LH	285.20	X
7.	1PC	REAR AXLE ASSY	1,984.90	X
8.	1PC	REAR WHEEL BEARING - LH	493.20	X
9.	1PC	REAR WINDSCREEN MOULDING	118.80	X
10.	1PC	REAR FENDER INNER TRIM LH	149.40	X

List TotalS\$:
25.00% Discount S\$:

5,427.81
1,356.95
4,070.86

SPECIAL NETT ITEMS	
1	1PC REAR RIM LH
2	1TUBE REAR WINDSCREEN SEALANT

Special Nett Total S\$

650.00
65.00
715.00

LABOUR :
COMPUTER WHEEL ALIGNMENT
REMOVE & REINSTALL REAR SUSPENSION
SPRAY PAINT DAMAGED AREA AFFECTED
REMOVE & REINSTALL REAR WINDSCREEN GLASS
RUST PROOFING TREATMENT
TO CUT OFF REAR FENDER, KNOCK AND STRAIGHTEN REAR

120.00
280.00
1,400.00
180.00
100.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part's books are subject to confirmation
- "Third party survey" if on a "Without Prejudice" basis
- Agree to resurvey if allowed
- Should any surveying must be insurance and approved by the insurance company

Signature: _____ Date: _____
Print Name: _____
Position: _____



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
 Sin Ming Autocare Complex
 Singapore 575721
 Tel : (65) 6455 0600
 Fax : (65) 6455 6192
 Website: www.autocare.com.sg
 GST Reg. No: 20-0210033-N

LONPAC INSURANCE BHD
 100 BEACH ROAD #19-00 SHAW TOWER
 SINGAPORE 189702

Attention : Motor Claim Department
 Contact : 6250 7388 Fax No : 6296 3767

Estimate : E19/2502

Date : 17/07/2019
 Vehicle Num. : SGY3347R
 Make/Model : TOYOTA VIOS-2007
 Chassis/Eng# : MR053HY9305025729
 Accident Date : 15/07/2019
 Claim No. : TP CLAIM
 Reference : BFG/VMS
 Policy No. : 5102940148

S/N	Quantity	Particular	Unit Price	Amount S\$
		CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS		1,200.00 ^{\$501}
		Labour Total S\$:		3,280.00

E. & O.E.

Total S\$: 8,065.86

=====

for Sin Ming Autocare BFG Pte Ltd

Work Order: R032816
 VIN: SGY3347R
 Year: 09
 Date: 23.7.19 12:16



SGY3347R

Toyota Vios NCP93

Front : Left

Actual	Before	Specified Range
-0°37'	-0°37'	-0°53' 0°37'
4°54'	4°54'	3°59' 5°29'
-0°02'	-0°03'	-0°02' 0°11'
12°00'	12°00'	
11°23'	11°23'	

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°49'	-0°50'	-0°53' 0°37'
4°18'	4°18'	3°59' 5°29'
-0°22'	-0°22'	-0°02' 0°11'
11°16'	11°17'	
10°27'	10°27'	

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°12'	0°13'	-0°30' 0°30'
0°36'	0°36'	-0°30' 0°30'
0°44'	0°43'	
-0°24'	-0°25'	-0°04' 0°22'

Rear : Left

Actual	Before	Specified Range
-2°23'	-2°23'	-1°41' -0°11'
-0°12'	-0°11'	-0°02' 0°19'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-0°44'	-0°44'	-1°41' -0°11'
0°18'	0°18'	-0°02' 0°19'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-1°40'	-1°39'	-0°30' 0°30'
0°06'	0°07'	-0°03' 0°37'
-0°15'	-0°14'	