

INSURANCE

INS. CASE OWNER:

CC 4/LPC1901 2715, KEB39

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SGY 32472



INSRS:

WSP:

Tel:

Liability:

RMKS:

STN ming



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KAL

Repair Cost:

SS 2,800

(4 days) Reduction:

6.5 %

Email

Call

FINAL SETTLEMENT

Date/Time: 25-10-19

Confirm with: ANGELA

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

29

If NO or B 28, Ass. Lia:

Repair Cost:

SS 2,800

DO MOVING OUT OF PARKING LOT.

Loss of Rental (LOR):

SS 600.00

(10 days) > 4100

Loss of Use (LOU):

SS -

(\$ x days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GLA/LTA Search:

SS 2-3

Medical:

SS -

1) Claim status: ~~Normal~~/Reject/Private Settle

Disbursement:

SS -

(e.g. Tow/ Independent)

2) Report Format:

TP

Legal Cost:

SS -

3) Survey fee:

* 400

Total:

SS 3,598.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 25-10-19

Confirm with: ANGELA

Email

Call

Payee 1:

SS 3,598.00

Name 1:

SH MINING AUTOCARE BEG. PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Kenneth

From: _____ Date: _____

Veh No: SGY 334JR Yr Regn: 09, 07

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Ford Mustang CC 149Z

Colour M. Blue A/C: Insured / Std / NI / NA

Sp. Reading 179144 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: NR05314Y93.05025729

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / ~~STO~~ A/Rlm or

Tyre Size: F: 195/55R15

	N/S	O/S

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YPKO or

Front

R/Bal. 7 mm - R/Bal. 7 mm

L8al. 7 mm L8al. 7 mm

D.O.A. 15/7/19 D.O.I. 23/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]☐: Prel. Report

☐: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

Lump Sum / I.B.I: (S

☐ Interview (S

☐ Tech Invs (\$

	Weekend (\$)
1	10
2	15
3	20
4	25
5	30
6	35
7	40
8	45
9	50
10	55
11	60
12	65
13	70
14	75
15	80
16	85
17	90
18	95
19	100
20	105
21	110
22	115
23	120
24	125
25	130
26	135
27	140
28	145
29	150
30	155
31	160
32	165
33	170
34	175
35	180
36	185
37	190
38	195
39	200
40	205
41	210
42	215
43	220
44	225
45	230
46	235
47	240
48	245
49	250
50	255
51	260
52	265
53	270
54	275
55	280
56	285
57	290
58	295
59	300
60	305
61	310
62	315
63	320
64	325
65	330
66	335
67	340
68	345
69	350
70	355
71	360
72	365
73	370
74	375
75	380
76	385
77	390
78	395
79	400
80	405
81	410
82	415
83	420
84	425
85	430
86	435
87	440
88	445
89	450
90	455
91	460
92	465
93	470
94	475
95	480
96	485
97	490
98	495
99	500
100	505
101	510
102	515
103	520
104	525
105	530
106	535
107	540
108	545
109	550
110	555
111	560
112	565
113	570
114	575
115	580
116	585
117	590
118	595
119	600
120	605
121	610
122	615
123	620
124	625
125	630
126	635
127	640
128	645
129	650
130	655
131	660
132	665
133	670
134	675
135	680
136	685
137	690
138	695
139	700
140	705
141	710
142	715
143	720
144	725
145	730
146	735
147	740
148	745
149	750
150	755
151	760
152	765
153	770
154	775
155	780
156	785
157	790
158	795
159	800
160	805
161	810
162	815
163	820
164	825
165	830
166	835
167	840
168	

Survey Fee

Transportation

5-85 51

Где-то

Others

404



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19012715/Keb3

Date: 24.07.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SGY3347R

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23.07.2019 at the premises of M/s Sin Ming Autocare BFG Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	8,065.86
Revised Estimate Amount	: S\$	1,390.00
"Check" Items Amount	: S\$	2,352.48
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser



Sin Ming Autocare BFG Pte Ltd

114, Sin Ming Drive #02-71
Sin Ming Autocare Complex
Singapore 571771
Tel : (65) 6455 6400
Fax : (65) 6455 6197
Website: www.sinming.com.sg
Lic Reg. No: 200210011-N

LONPAC INSURANCE BHD
109 BEACH ROAD #19-00 SHAW TOWER
SINGAPORE 189702

Estimate : E18/2502

Attention: Motor Claim Department

Contact: 6256 7388 Fax No: 6296 3767

Date: 17/07/2019
Vehicle Num: SGY3347R
Make/Model: TOYOTA VIOS-2007
Chassis/Eng#: MR053HY9305025729
Accident Date: 15/07/2019
Claim No: TP CLAIM
Reference: BFG/VMS
Policy No: 5102940148

Not Authorised
11 Pm @ 2800-Vol
Resurvey After Pains 4 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		LIST ITEMS	
1	1PC	REAR DOOR - LH	
2	1PC	REAR FENDER - LH	
3	1PC	REAR BUMPER	
4	1PC	REAR BUMPER SIDE RETAINER - LH	
5	8PCS	REAR BUMPER CLIPS	
6	1PC	REAR SHOCK ABSORBER - LH	
7	1PC	REAR AXLE ASSY	
8	1PC	REAR WHEEL BEARING - LH	
9	1PC	REAR WINDSCREEN MOULDING	
10	1PC	REAR FENDER INNER TRIM LH	

1	784.30	X
2	934.81	X
3	571.80	X
4	57.40	X
5	48.00	X
6	285.20	X
7	1,984.90	X
8	493.20	X
9	118.80	X
10	149.40	X

List Total S\$:
25.00% Discount S\$

5,427.81
1,356.95
4,070.86

		SPECIAL NETT ITEMS	
1	1PC	REAR RIM LH	
2	11LBS	REAR WINDSCREEN SEALANT	

1	650.00	X
2	65.00	X
	715.00	

Special Net Total S\$

LABOUR
COMPUTER WHEEL ALIGNMENT
REMOVE & REINSTALL REAR SUSPENSION
SPRAY PAINT DAMAGED AREA AFFECTED
REMOVE & REINSTALL REAR WINDSCREEN GLASS
RUST PROOFING TREATMENT
TO CUT OFF REAR FENDER KNOCK AND STRAIGHTEN REAR

	120.00	601
	280.00	200
	1,400.00	6001
	180.00	X
	100.00	X

CONTINUE...





Sin Ming Autocare BFG Pte Ltd

114, Sin Ming Drive #112-113
Sin Ming Autocare Complex
Singapore 575721
Tel: +65 6433 0600
Fax: +65 6433 6142
Website: www.sinmingautocare.com.sg
GST Reg. No: 2045210011-N

LONPAC INSURANCE BHD
100 BEACH ROAD #19-00 SHAW TOWER
SINGAPORE 189702

Attention: Motor Claims Department

Contact: T250 7388 Fax No: 6296 3767

Estimate: E19/2502

Date: 17/07/2019
Vehicle Num: SGY3347R
Make/Model: TOYOTA VIOS-2007
Chassis/Eng#: MR053HY9305025729
Accident Date: 15/07/2019
Claim No: TP CLAIM
Reference: BFG/UMS
Policy No: 5102940148

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS

1 200.00

Labour Total S\$

3 280.00

450

E & O E

Total S\$

8 065.86

for Sin Ming Autocare BFG Pte Ltd

Work Order: R032816
 VIN: SGY3347R
 Year: 09
 Date: 23.7.19 12:16



SGY3347R

Toyota Vios NCP93

Front : Left

Actual	Before	Specified Range
		-0°53' 0°37'
		3°59' 5°29'
-0°02'	-0°03'	-0°02' 0°11'
12°00'	12°00'	
11°23'	11°23'	

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
		-0°53' 0°37'
		3°59' 5°29'
-0°22'	-0°22'	-0°02' 0°11'
11°16'	11°17'	
10°27'	10°27'	

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
		-0°30' 0°30'
0°36'	0°36'	-0°30' 0°30'
0°44'	0°43'	
-0°24'	-0°25'	-0°04' 0°22'

Rear : Left

Actual	Before	Specified Range
-2°23'	-2°23'	-1°41' -0°11'
-0°12'	-0°11'	-0°02' 0°19'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
		-1°41' -0°11'
		-0°02' 0°19'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-1°40'	-1°39'	-0°30' 0°30'
		-0°03' 0°37'
-0°15'	-0°14'	



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
Sin Ming Autocare Complex
Singapore 575721
Tel : (65) 6435 0600
Fax : (65) 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

LONPAC INSURANCE BHD
100 BEACH ROAD #19-00 SHAW TOWER
SINGAPORE 189702

Estimate : E19/2502

Attention : Motor Claim Department

Contact : 6250 7388 Fax No. : 6296 3767

Date : 17/07/2019
Vehicle Num. : SGY3347R
Make/Model : TOYOTA VIOS-2007
Chassis/Eng# : MR053HY9305025729
Accident Date : 15/07/2019
Claim No. : TP CLAIM
Reference : BFG/VMS
Policy No. : 5102940148

Not Withheld
61 Pm @ 1
Recovery After Paint 4 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1PC	REAR DOOR - LH		784.30 X
2.	1PC	REAR FENDER - LH		934.81 X
3.	1PC	REAR BUMPER		571.80 X
4.	1PC	REAR BUMPER SIDE RETAINER - LH		57.40 X
5.	8PCS	REAR BUMPER CLIPS	6.00	48.00 X
6.	1PC	REAR SHOCK ABSORBER - LH		285.20 X
7.	1PC	REAR AXLE ASSY		1,984.90 X
8.	1PC	REAR WHEEL BEARING - LH		493.20 X
9.	1PC	REAR WINDSCREEN MOULDING		118.80 X
10.	1PC	REAR FENDER INNER TRIM LH		149.40 X

List Total S\$:

25.00% Discount S\$:

5,427.81

1,356.95

4,070.86

SPECIAL NETT ITEMS :		
1.	1PC	REAR RIM LH
2.	1TUBE	REAR WINDSCREEN SEALANT

Special Nett Total S\$:

715.00

LABOUR :

COMPUTER WHEEL ALIGNMENT
REMOVE & REINSTALL REAR SUSPENSION
SPRAY PAINT DAMAGED AREA AFFECTED
REMOVE & REINSTALL REAR WINDSCREEN GLASS
RUST PROOFING TREATMENT
TO CUT OFF REAR FENDER, KNOCK AND STRAIGHTEN REAR

120.00

280.00

1,400.00

180.00 X

100.00 X

CONTINUE / ...

LKK Auto Consultants hereby notify the Repairer of the following:-

- To survey before start spray painting
- To display damaged part(s) using survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
 Sin Ming Autocare Complex
 Singapore 575721
 Tel : (65) 6453 0600
 Fax : (65) 6453 6192
 Website: www.autocare.com.sg
 GST Reg. No: 20-0210033-N

LONPAC INSURANCE BHD
 100 BEACH ROAD #19-00 SHAW TOWER
 SINGAPORE 189702

Attention : Motor Claim Department
 Contact : 6250 7388 Fax No. : 6296 3767

Estimate : E19/2502

Date : 17/07/2019
 Vehicle Num. : SGY3347R
 Make/Model : TOYOTA VIOS-2007
 Chassis/Eng# : MR053HY9305025729
 Accident Date : 15/07/2019
 Claim No. : TP CLAIM
 Reference : BFG/VMS
 Policy No. : 5102940148

S/N	Quantity	Particular	Unit Price	Amount S\$
		CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS		1,200.00
		Labour Total S\$:		3,280.00

4501

E. & O.E.

Total S\$: 8,065.86

=====

for Sin Ming Autocare BFG Pte Ltd

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 17 July 2019 2:59 PM
To: Motor Claims; assignments@lkkauto.com; Admin-D (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: THIRD PARTY CLAIM SGY3347R & SKD7783B ACCIDENT ON 15.07.2019 Our Ref: 19/19/19/VP05/022092 [External General]
Attachments: SAS.PDF

Lonpac External - General

Without Prejudice
Save as to Costs

Dear Sir/Mdm


FYI, our Insured has not reported the accident to us.

Please liaise with LKK Auto Consultants Pte Ltd for survey and assessment of liability.

Dear Nivitha

FYA

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Motor Claims [mailto:motorclaims@autocare.com.sg]
Sent: Wednesday, 17 July, 2019 2:15 PM
To: MT_Claim_SG
Subject: THIRD PARTY CLAIM SGY3347R & SKD7783B ACCIDENT ON 15.07.2019

To: Lonpac Motor Claims Dept. (Arrangement of Surveyor Unit)

RE: NOTICE TO THIRD PARTY INSURERS TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKINGS DAY PURSUANT TO
PARAGRAPH PHOTOCOL FOR NIN-INJURY MOTOR ACCIDENT CLAIMS (NIMA)
ACCIDENT INVOLVING SGY3347R & SKD7783B ALONG KALLANG LEISURE PARK CARPARK ON 15.07.2019

We are repairer for LA'BROOY LYNETTE KIARA the owner of vehicle no SGY3347R.

Please be informed that the said vehicle can inspected at the following venue:

Not Out

Sin Ming Autocare BFG Pte Ltd
176 Sin Ming Drive #02-05 Singapore 575721
Tel: 6455 0600 Fax: 64556192 Email: motorclaims@autocare.com.sg

Contact Person: **Angela Tan**

Please also provide us a list of 10 surveyors as your nominated SJE (Single Joint Expert)

PLEASE ARRANGE OFFICER-IN-CHARGE TO LET US KNOW ASAP IF WE COULD DO DIRECT SETTLEMENT FOR THIS CASE.

Thank you

With Regards,
Angela Tan
Claims & Admin Executive



Sin Ming Autocare BFG Pte Ltd
176 SIN MING DRIVE, #02-05 SINGAPORE 575721
Email: motorclaims@autocare.com.sg
Tel : 6455 0600 | Fax : 6455 6192

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19012715/Keb3q2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 18-12-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKD 7783B	Veh. Inspected	SGY 3347R
Policy No.	Z19VP05022246	Coverage (\$)	0.00
Claim No.	19/19/19/VP05/022092	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	17/07/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	MR053HY9305025729	Colour	METALLIC BLUE
Odometer	179144	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	YOKOHAMA	7 mm
L/H Front Tyre	195/55 R15	YOKOHAMA	7 mm
R/H Rear Tyre	195/55 R15	YOKOHAMA	7 mm
L/H Rear Tyre	195/55 R15	YOKOHAMA	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/07/2019	Inspection Date	23/07/2019
Survey held at	SIN MING AUTOCARE BFG PTE LTD 176, SIN MING DRIVE #02-05 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 3347R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR DOOR -LH	TO REPAIR SEE LABOUR	784.30	-
1	REAR FENDER -LH	TO REPAIR SEE LABOUR	934.81	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	571.80	-
1	REAR BUMPER SIDE RETAINER -LH	SERVICEABLE	57.40	-
8	REAR BUMPER CLIPS @\$6.00	NOT NECESSARY	48.00	-
1	REAR SHOCK ABSORBER -LH	BENT	285.20	285.20
1	REAR AXLE ASSY	BENT	1,984.90	1,839.90
1	REAR WHEEL BEARING -LH	NECESSARY	493.20	493.20
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	118.80	-
1	REAR FENDER INNER TRIM LH	SERVICEABLE	149.40	-
	LESS 25% DISCOUNT		-1,356.95	-654.58
			4,070.86	1,963.72
SPECIAL NETT ITEMS				
1	REAR RIM LH (SN)	DENTED	650.00	280.00
1	TUBE REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	65.00	-
			715.00	280.00
LABOUR				
	COMPUTER WHEEL ALIGNMENT.		120.00	60.00
	REMOVE & REINSTALL REAR SUSPENSION.		280.00	200.00
	SPRAY PAINT DAMAGED AREA AFFECTED.		1,400.00	600.00
	REMOVE & REINSTALL REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	RUST PROOFING TREATMENT.	NOT NECESSARY	100.00	-
	TO CUT OFF REAR FENDER ,KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF REAR DOOR - LH,REAR FENDER -LH AND REAR BUMPER.		1,200.00	450.00
			3,280.00	1,310.00
GRAND TOTAL			8,065.86	3,553.72

Report Ref No. CC4/LPC19012715/Keb3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00
---	--	--	----------

Report Ref No. CC4/LPC19012715/Keb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.