

KP



ESTIMATE TO REPAIR

VEHICLE NO. : SKZ 8208 Z
MAKE : HONDA
MODEL : CRV 2.4 5AT 2WD S/R
YEAR : 2015
CHASSIS NO : MRHRM3850GP000073

SURVEYOR NAME :
DATE OF SURVEY : 24th July 2019
TIME OF SURVEY :

DATE : 18-Jul-19
DATE OF ACCIDENT : 17-Jul-19
THIRD PARTY REF : FBH 5874 X / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			Bu	\$ 609.50
2 pcs	Rear Bumper Retainer		\$ 19.80		\$ 39.60
1 pc	Rear Bumper Lower Garnish			Roller	\$ 149.10
2 pcs	Rear Bumper Side Garnish		\$ 66.40		\$ 132.80
10 pcs	Rear Bumper Clips		\$ 3.50		\$ 35.00
1 pc	Rear Bumper Lower Cover			Sn	\$ 81.50
1 pc	Tailgate Outer Garnish				\$ 283.10
1 pc	Tailgate CRV Emblem				\$ 20.90
	Less 20%				\$ 1,351.50
					\$ 270.30
					\$ 1,081.20
1 set	Rear Bumper Sensor	S.Nett			\$ 400.00
	To putty and spray painting				\$ 500.00
	Labour Charges				\$ 400.00
	Not mentioned			Paints	\$1097.60
	11 Day 87			-20%	\$219.52
	Measuring After Paint				\$879.08
	3 days			Labour	\$700.00
					\$1578.08
				-20%	\$315.62
					\$1262.46
TG/RA-	Total				\$ 2,381.20
				4/8	\$1250.00

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website: www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

03 days

6/8/8/19

