

ESTIMATE TO REPAIR

VEHICLE NO. : SKZ 8208 Z
 MAKE : HONDA
 MODEL : CRV 2.4 5AT 2WD S/R
 YEAR : 2015
 CHASSIS NO : MRHRM3850GP000073

SURVEYOR NAME	:	
DATE OF SURVEY	:	
TIME OF SURVEY	:	

DATE : 18-Jul-19
 DATE OF ACCIDENT : 17-Jul-19
 THIRD PARTY REF : FBH 5874 X / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 609.50
2 pcs	Rear Bumper Retainer		\$ 19.80		\$ 39.60
1 pc	Rear Bumper Lower Garnish				\$ 149.10
2 pcs	Rear Bumper Side Garnish		\$ 66.40		\$ 132.80
10 pcs	Rear Bumper Clips		\$ 3.50		\$ 35.00
1 pc	Rear Bumper Lower Cover				\$ 81.50
1 pc	Tailgate Outer Garnish				\$ 283.10
1 pc	Tailgate CRV Emblem				\$ 20.90
					\$ 1,351.50
	Less 20%				\$ 270.30
					\$ 1,081.20
1 set	Rear Bumper Sensor	S.Nett			\$ 400.00
	To putty and spray painting				\$ 500.00
	Labour Charges				\$ 400.00
TG/RA-	Total				\$ 2,381.20

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd