

INS. CASE OWNER: CHAN KUAN HONG CC 6/16/190 12724, Khas 9 LKK: IDAC:

Surveyor: Kenneth DOI: 12/21/19 Date / Time: 12/21/19 Registered in Merimen: 12/21/19

Pre-assign / CCU / FTE



Insured Vehicle No.: SMC 6109L Claim No.: 621080870996
 Name of Insured: Eng Yuan Xin (Weng Yuan Xin) Policy No.:
 Insured Tel No.: HP: Make / Model:
 Excess Sec II : \$5 D.O.A: 16/07/2019 Place of Accident:
 Is driver the owner? (YES / NO) Nature of Accident:
 If NO, Driver Name / Age: OI GIA REPORT (YES / NO) ; TP GIA REPORT (YES / NO)
 Driver Tel No.: (V/L: YES / NO) Insured Liability: % Final ? Yes / No

SMC 6109L → SLG 6462E → SLG 5391J →



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP: optima
Tel:
Liability:
RMKS: TP



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time		STAGE	DATE / PIC
	SLG 6462E - X ; SMC 6109L - X	Non-Reporting ltr (1st):	
	MINIATURED	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
30/07/19	- THIS REPAIRWORK. OI INVOLVED IN A 4 VEH. C.C. W. WAS THE LAST CAR IN PARK- INGED TP. SEND LETTER TO OI.	Call OI:	
		After call ltr to OI:	30/07/19 - OK
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	
09/08/19	- TP LOD IN BY EMAIL	After call ltr to OI:	
	- TYPE REPORT FOR WARRANT APPROVAL	Authorisation To Act:	
	- REPORT FORM	Release Voucher:	
30/08/19	- SEND WARRANT APPROVAL TO AIG	Final Repair Bill:	
08/11/19	- AIG APPROVED WARRANT.	Car Rental Invoice:	
	- SEND 1st OFFER TO TP	Towing Invoice:	
14/12/19	- TP ACCEPTED OFFER.	LTA / GIA:	
	- ALL DOCS IN ORDER.	Medical Bill:	
	- TO CLOSE.	PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: \$11,024.02 SS 9,503.76 (9 days) Reduction: 31 % Email Call

FINAL SETTLEMENT Date/Time: 14/12/19 Confirm with: SHAMON Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28 If NO or B 28, Ass. Lia: 100%
 Repair Cost: (w/ GST) \$5 10,169.02 (A VEH. C.C. ; OI LAST)
 Loss of Rental (LOR) (w/ GST) \$5 856.00 (8 days) X & 100
 Loss of Use (LOU): \$5 - (5 x days)
 Loss of Income (LOI): \$5 - (5 x days)
 LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]
 GIA/LTA Search \$5 2.00
 Medical: \$5 -
 Disbursement: \$5 - (e.g. Tow/ Independent)
 Legal Cost \$5 -
 Total: \$5 11,024.02 Global Sum SS: -
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format:
 3) Survey fee: \$ 320.00

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$5 11,024.02 Name 1: OPTIMA WERKE PTE LTD
 Payee 2: (Strike if N.A.) \$5 - Name 2: -
 Payee 3: (Strike if N.A.) \$5 - Name 3: -

ASS. REC. BY:

REF:

AIG/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09

days

Res.: Yes or No

Lum Sum:

1-B1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1

File pass to

PIP \$ 9,503.76

Cred: \$ 4,286.88 (31%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Veh No:

SLG 6962E Yr Regn: 10, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c

1496

Colour:

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

102570

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU3

1210781

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

R:

225/508R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

2

mm

R/Bal.

2

mm

L/Bal.

2

mm

L/Bal.

2

mm

D.O.A

16/7/19

D.O.I

17/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& 1/4

The U/C / Chassis frame / Body Structure affected due to collision.

KH

OPTIMA WERKZ

SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

f /OptimaWerkz

o /OptimaWerkz

Date: 16.07.2019
Vehicle No: SLG6962E
Model: HONDA VEZEL 1.5
Chassis: RU31210781 - 2016
Reg. Year: 2016

Not Wholesaler
Remove Blipair

Third Party Insurer: AIG
Third Party Veh No: SMC6109L
Date of Accident: 16.07.2019

89503-76

9 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Ry</i> \$953.30
2	REAR TAILGATE "VEZEL" EMBLEM	1		<i>Re</i> \$45.80
3	REAR TAILGATE "RS" EMBLEM	1		<i>Re</i> \$54.60
4	REAR TAILGATE "HYBRID" EMBLEM	1		<i>Re</i> \$76.80
5	REAR TAILGATE INNER LOCK	1		<i>Re</i> \$216.20
6	REAR TAILGATE RUBBER	1		<i>Re</i> \$198.00
7	REAR WINDSCREEN RUBBER	1		<i>Re</i> \$35.00
8	REAR END PANEL <i>4</i>	1		<i>R</i> <i>Re</i> \$530.90
9	REAR END PANEL UPPER TRIM COVERING	1		<i>CM</i> \$208.80
10	REAR END PANEL UPPER TRIM COVERING CLIP	6	\$6.50	<i>Re</i> \$39.00
11	REAR FLOOR PANEL UPPER BOARD	1		<i>Reform</i> \$590.80
12	REAR FLOOR PANEL BOOT TRAY	1		<i>Re</i> \$1,140.75
13	REAR FLOOR PANEL UNDER COVER	1		<i>Re</i> \$284.85
14	REAR FLOOR PANEL UNDER COVER CLIP	4	\$11.50	<i>Re</i> \$46.00
15	REAR EXHAUST PIPE	1		<i>R</i> \$709.50
16	REAR EXHAUST PIPE TAIL	1		<i>Re</i> \$73.85
17	REAR BUMPER <i>801.00</i>	1		<i>Ry</i> \$935.60
18	FRONT BONNET	1		<i>Ry</i> \$780.00
19	FRONT GRILLE <i>351.80</i>	1		<i>CM</i> \$405.90
20	FRONT GRILLE GARNISH COVER <i>380</i>	1		<i>CM</i> \$448.50
21	FRONT GRILLE CHROME MOULDING LH	1		<i>Re</i> \$50.00
22	FRONT GRILLE CLIP	8	\$5.80	<i>Re</i> \$46.40
23	FRONT GRILLE SUPPORT BRACKET LH	1		<i>R</i> \$16.00
24	FRONT GRILLE SUPPORT BRACKET RH	1		<i>R</i> \$16.00
25	FRONT BUMPER	1		<i>Re</i> \$358.20
26	FRONT BUMPER LOWER GRILLE	1		<i>Re</i> \$97.60
27	FRONT BUMPER LOWER SPOILER (LOWER LIP)	1		<i>Re</i> \$546.00
28	FRONT BUMPER CLIP	10	\$6.50	<i>Re</i> \$65.00
29	FRONT BUMPER FOG LAMP GARNISH LH	1		<i>Re</i> \$68.25
30	FRONT BUMPER SIDE BRACKET LH	1		<i>R</i> \$19.50
31	FRONT BUMPER REINFORCEMENT <i>321.00</i>	1		<i>Ry</i> \$360.75
32	FRONT HEADLAMP LH <i>1784.50</i>	1		<i>Re</i> <i>CM</i> \$1,895.45

Head office

6 Rong Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

8A Sarongon North Ave 5 Singapore 554500
Tel: (+65) 6488 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574416
Tel: (+65) 6452 6848 Fax: (+65) 6452 9223



Date: 16.07.2019
 Vehicle No: SLG6962E
 Model: HONDA VEZEL 1.5
 Chassis: RU31210781 - 2016
 Reg. Year: 2016

Third Party Insurer: AIG
 Third Party Veh No: SMC6109L
 Date of Accident: 16.07.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
33	FRONT FENDER LH	1		REPAIR
34	REAR FLOOR PANEL	1		REPAIR
			SUB TOTAL	\$11,313.30
			LESS 20%	-\$2,262.66
			PARTS TOTAL	\$9,050.64

8,368.85
 - 1,673.77

 6,695.08

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE INNER TRIM CLIP (SET)	1		re \$40.00 ✓
2	REAR WINDSCREEN SEALANT	1	re	400ml \$80.00 ✓
3	REAR WINDSCREEN STOPPER	2	re \$15.00	\$30.00 ✓
4	REAR FLOOR PANEL SEALANT	1		re \$60.00 X
5	REAR END PANEL JOINT SEALANT	1	re	300ml \$60.00
6	REAR FLOOR PANEL PAD SEALANT	1	re	\$120.00 X
7	REAR BUMPER REVERSE SENSOR (SET)	1	CM 2000ml	\$250.00
8	FRONT NUMBER PLATE WITH HOLDER	1	CM 455ml	\$80.00
			S/N TOTAL	\$720.00 285

Date: 16.07.2019
Vehicle No: SLG6962E
Model: HONDA VEZEL 1.5
Chassis: RU31210781 - 2016
Reg. Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SMC6109L
Date of Accident: 16.07.2019

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST FRONT & REAR ACCIDENT AREAS & ETC. *900* \$1,300.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT & REAR ACCIDENT AREAS & ETC. *1400* \$1,800.00

TO TUFF KOTE / ANTI-RUST & UNDERSEAL MATERIALS. *900* \$200.00

TO REMOVE, REFIX & REPLACE REAR REVERSE CAMERA, REAR REVERSE SENSOR & ETC. *800* \$120.00

TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT GUM, REAR WINDSCREEN MOULDING & ETC. TO EFFECT REPLACE OF REAR TAILGATE. *1200* \$150.00

TO REMOVE & REPLACE REAR EXHAUST PIPE ASSY & ETC. *600* \$180.00

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS. *600* \$120.00

TO CHECK WIRING & ELECTRICAL & TO DIAGNOSIS FAULTY CODE & ETC. *400* \$150.00

LABOUR TOTAL \$4,020.00 *2750*

ONG	TOTAL	\$13,790.64
-----	-------	-------------

P - \$16,695.00
EN - \$385.00 ✓
L - \$2,720.00 ✓
P/P \$9,830.00

Date: 16.07.2019
 Vehicle No: SLG6962E
 Model: HONDA VEZEL 1.5
 Chassis: RU31210781 - 2016
 Reg.Year: 2016

Not Notarized
Assembly Bk painting

Third Party Insurer: AIG
 Third Party Veh No: SMC6109L
 Date of Accident: 16.07.2019

9 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	REAR TAILGATE	1		<i>B₁</i> \$953.30	✓
2	REAR TAILGATE "VEZEL" EMBLEM	1		<i>Ac</i> \$45.80	✓
3	REAR TAILGATE "RS" EMBLEM	1		<i>Ac</i> \$54.60	✓
4	REAR TAILGATE "HYBRID" EMBLEM	1		<i>Ac</i> \$76.80	✓
5	REAR TAILGATE INNER LOCK	1		<i>Ac</i> \$216.20	✓
6	REAR TAILGATE RUBBER	1		<i>Ac</i> \$198.00	✓
7	REAR WINDSCREEN RUBBER	1		<i>Ac</i> \$35.00	✓
8	REAR END PANEL	1		<i>B₁</i> \$530.90	✓
9	REAR END PANEL UPPER TRIM COVERING	1		<i>CM</i> \$208.80	✓
10	REAR END PANEL UPPER TRIM COVERING CLIP	6	\$6.50	<i>Ac</i> \$39.00	✓
11	REAR FLOOR PANEL UPPER BOARD	1		<i>Ac form</i> \$590.80	✓
12	REAR FLOOR PANEL BOOT TRAY	1		\$1,140.75	✓
13	REAR FLOOR PANEL UNDER COVER	1		\$284.85	✓
14	REAR FLOOR PANEL UNDER COVER CLIP	4	\$11.50	\$46.00	✓
15	REAR EXHAUST PIPE	1		\$709.50	✓
16	REAR EXHAUST PIPE TAIL	1		<i>Ac</i> \$73.85	✓
17	REAR BUMPER	1		<i>B₁</i> \$935.60	✓
18	FRONT BONNET	1		<i>B₁</i> \$780.00	✓
19	FRONT GRILLE	1		<i>CM</i> \$405.90	✓
20	FRONT GRILLE GARNISH COVER	1		<i>CM</i> \$448.50	✓
21	FRONT GRILLE CHROME MOULDING LH	1		<i>Ac</i> \$50.00	✓
22	FRONT GRILLE CLIP	8	\$5.80	<i>Ac</i> \$46.40	✓
23	FRONT GRILLE SUPPORT BRACKET LH	1		\$16.00	✓
24	FRONT GRILLE SUPPORT BRACKET RH	1		\$16.00	✓
25	FRONT BUMPER	1		<i>B₁</i> \$358.20	✓
26	FRONT BUMPER LOWER GRILLE	1		\$97.60	✓
27	FRONT BUMPER LOWER SPOILER (LOWER LIP)	1		\$546.00	✓
28	FRONT BUMPER CLIP	10	\$6.50	<i>Ac</i> \$65.00	✓
29	FRONT BUMPER FOG LAMP GARNISH LH	1		\$68.25	✓
30	FRONT BUMPER SIDE BRACKET LH	1		\$19.50	✓
31	FRONT BUMPER REINFORCEMENT	1		<i>B₁</i> \$360.75	✓
32	FRONT HEADLAMP LH	1		<i>Ac CM</i> \$1,895.45	✓

Date: 16.07.2019
 Vehicle No: SLG6962E
 Model: HONDA VEZEL 1.5
 Chassis: RU31210781 - 2016
 Reg.Year: 2016

Third Party Insurer: AIG
 Third Party Veh No: SMC6109L
 Date of Accident: 16.07.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
33	FRONT FENDER LH	1		REPAIR
34	REAR FLOOR PANEL	1		REPAIR
			SUB TOTAL	\$11,313.30
			LESS 20%	-\$2,262.66
			PARTS TOTAL	\$9,050.64

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE INNER TRIM CLIP (SET)	1		Re \$40.00 ✓
2	REAR WINDSCREEN SEALANT	1	Re	40sn \$80.00
3	REAR WINDSCREEN STOPPER	2	Re \$15.00	\$30.00 ✓
4	REAR FLOOR PANEL SEALANT	1		Re \$60.00 X
5	REAR END PANEL JOINT SEALANT	1	Re	30sn \$60.00
6	REAR FLOOR PANEL PAD SEALANT	1		Re \$120.00 X
7	REAR BUMPER REVERSE SENSOR (SET)	1	CM 200sn	\$250.00
8	FRONT NUMBER PLATE WITH HOLDER	1	CM 45sn	\$80.00
			S/N TOTAL	\$720.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Head office

6 Keng Chong Road Singapore 159143
 Tel: (+65) 6472 1313 : Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554506
 Tel: (+65) 6484 9919 : Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 : Fax: (+65) 6452 9223



Date: 16.07.2019
 Vehicle No: SLG6962E
 Model: HONDA VEZEL 1.5
 Chassis: RU31210781 - 2016
 Reg.Year: 2016

Third Party Insurer: AIG
 Third Party Veh No: SMC6109L
 Date of Accident: 16.07.2019

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST FRONT & REAR ACCIDENT AREAS & ETC. 900 \$1,300.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT & REAR ACCIDENT AREAS & ETC. 1400 \$1,800.00

TO TUFF KOTE / ANTI-RUST & UNDERSEAL MATERIALS 90 \$200.00

TO REMOVE, REFIX & REPLACE REAR REVERSE CAMERA, REAR REVERSE SENSOR & ETC. 80 \$120.00

TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT GUM, REAR WINDSCREEN MOULDING & ETC. TO EFFECT REPLACE OF REAR TAILGATE. 120 \$150.00

TO REMOVE & REPLACE REAR EXHAUST PIPE ASSY & ETC. 60 \$180.00

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS. 60 \$120.00

TO CHECK WIRING & ELECTRICAL & TO DIAGNOSIS FAULTY CODE & ETC. 40 \$150.00

LABOUR TOTAL \$4,020.00

ONG TOTAL \$13,790.64

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5238I

Vehicle Details

Vehicle No.: SLG6962E
Vehicle to be Exported: Yes
Intended Deregistration Date: 17 Jul 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL HYBRID 1.5RS A
Primary Colour: White
Manufacturing Year: 2016
Engine No.: LEB5910791
Chassis No.: RU31210781
Maximum Power Output: 112.0 kW (150 bhp)
Open Market Value: \$28,478.00
Original Registration Date: 11 Oct 2016
First Registration Date: 11 Oct 2016
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 10 Oct 2026
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 10 Oct 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$53,001.00
COE Rebate Amount: \$38,317.00
Total Rebate Amount: \$42,067.00

The information contained herein is correct as at 16 Jul 2019

OK

Print Received Message

This mail is associated with :

***SLG6962E (6210808709SG)
[SMC6109L]**

TP

TANG CHEE KEONG

Jul 16 2019 12:00AM

[ENG YUAN XIN (WENG YUANXIN)]

Optima Werkz Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 08/11/2019 09:57 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11027.02) - SLG6962E - Claim Handler: Chan, Kian-Meng

Approved:11027.02.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jul 2019 Edit Reg		17 Jul 2019 00:00 Edit Adj Rpt	\$9,503.76 Edit Estimates	\$9,503.76 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: ENG YUAN XIN (WENG YUANXIN) , ID: S85220813									
Main Claimant: TANG CHEE KEONG , ID: S69252381									
Vehicle Reg. No.: SLG6962E		Date of Loss: 16/07/2019 00:00 - :59 [33 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6210808709SG		Policy/Cover Note No.: (Comprehensive) Coverage: 12/07/2019 - 11/07/2020							
Vehicle Reg. No. (Insured): SMC6109L		Policy No. (Claimant): 5084717596-02							
		Excess:							
Repairer: Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road, 159143 Leng Kee - Tel: 64721313									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/07/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (08/11/2019): Alert - Adj Mandate Approved (\$11027.02) - SLG6962E - Claim Handler: Chan, Kian... - AIG_SG (19/07/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLG6962E (6210808709SG)
[SMC6109L]
TP
TANG CHEE KEONG
Jul 16 2019 12:00AM
[ENG YUAN XIN (WENG YUANXIN)]
Optima Werkz Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Photos/Images										3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	30/07/19 19:04	Odometer Reading						Load JPG	☒		
2	30/07/19 19:04	Chassis Number						Load JPG	☒		
3	30/07/19 19:04	General View						Load JPG	☒		
4	30/07/19 19:04	General View						Load JPG	☒		
5	30/07/19 19:04	General View						Load JPG	☒		
6	30/07/19 19:04	General View						Load JPG	☒		
7	30/07/19 19:04	General View						Load JPG	☒		
8	30/07/19 19:04	General View						Load JPG	☒		
9	30/07/19 19:04	General View						Load JPG	☒		
10	30/07/19 19:04	General View						Load JPG	☒		
11	30/07/19 19:04	General View						Load JPG	☒		
12	30/07/19 19:04	General View						Load JPG	☒		
13	30/07/19 19:04	General View						Load JPG	☒		
14	30/07/19 19:04	General View						Load JPG	☒		
15	30/07/19 19:04	General View						Load JPG	☒		
16	30/07/19 19:04	General View						Load JPG	☒		
17	30/07/19 19:04	General View						Load JPG	☒		
18	30/07/19 19:04	General View						Load JPG	☒		
19	30/07/19 19:04	General View						Load JPG	☒		
20	30/07/19 19:04	General View						Load JPG	☒		
21	30/07/19 19:04	General View						Load JPG	☒		
22	30/07/19 19:04	General View						Load JPG	☒		
23	30/07/19 19:04	General View						Load JPG	☒		
24	30/07/19 19:04	General View						Load JPG	☒		
25	30/07/19 19:04	General View						Load JPG	☒		
26	30/07/19 19:04	General View						Load JPG	☒		
27	30/07/19 19:04	General View						Load JPG	☒		
28	30/07/19 19:04	General View						Load JPG	☒		
29	30/07/19 19:04	General View						Load JPG	☒		
30	30/07/19 19:04	General View						Load JPG	☒		
31	30/07/19 19:04	General View						Load JPG	☒		
32	30/07/19 19:04	General View						Load JPG	☒		
33	30/07/19 19:04	General View						Load JPG	☒		
34	30/07/19 19:04	General View						Load JPG	☒		
35	30/07/19 19:04	General View						Load JPG	☒		
36	30/07/19 19:04	General View						Load JPG	☒		
37	30/07/19 19:04	General View						Load JPG	☒		
38	30/07/19 19:04	General View						Load JPG	☒		
39	30/07/19 19:04	General View						Load JPG	☒		
40	30/07/19 19:04	General View						Load JPG	☒		

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					☒
41	30/07/19 19:10	Reinspection Photo		Load JPG	☒
42	30/07/19 19:10	Reinspection Photo		Load JPG	☒
43	30/07/19 19:10	Reinspection Photo		Load JPG	☒
44	30/07/19 19:10	Reinspection Photo		Load JPG	☒
45	30/07/19 19:10	Reinspection Photo		Load JPG	☒
46	30/07/19 19:10	Reinspection Photo		Load JPG	☒
47	30/07/19 19:10	Reinspection Photo		Load JPG	☒
48	30/07/19 19:10	Reinspection Photo		Load JPG	☒
49	30/07/19 19:10	Reinspection Photo		Load JPG	☒
50	30/07/19 19:10	Reinspection Photo		Load JPG	☒
51	30/07/19 19:10	Reinspection Photo		Load JPG	☒
52	30/07/19 19:10	Reinspection Photo		Load JPG	☒
53	30/07/19 19:10	Reinspection Photo		Load JPG	☒
54	30/07/19 19:10	Reinspection Photo		Load JPG	☒
55	30/07/19 19:10	Reinspection Photo		Load JPG	☒
56	30/07/19 19:10	Reinspection Photo		Load JPG	☒
57	30/07/19 19:10	Reinspection Photo		Load JPG	☒
58	30/07/19 19:10	Reinspection Photo		Load JPG	☒
59	30/07/19 19:10	Reinspection Photo		Load JPG	☒
60	30/07/19 19:10	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/07/19 10:28	TP ESTIMATE-MARKED		Load PDF	
2	22/07/19 10:28	TP GIA REPORT		Load PDF	
3	30/07/19 18:39	TP ESTIMATE - FINALIZED		Load PDF	
4	30/07/19 19:01	LETTER TO OI		Load PDF	
5	27/09/19 15:15	RENTAL RECEIPT		Load PDF	
6	27/09/19 15:15	LOD		Load PDF	
7	27/09/19 15:15	GIA SEARCH		Load PDF	
8	18/12/19 09:36	WORKSHOP INVOICE		Load PDF	
9	18/12/19 09:36	AUTHORISATION TO ACT FORM		Load PDF	
10	18/12/19 09:36	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	19/07/19 09:09	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SMC6109L (Insd veh)	Model:	HONDA VEZEL 1.5 HYBRID
	SLG6962E (TP veh)		(A)
Date of Accident:	16/07/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	14,755.98
Final Repair Cost	:	\$	10,169.02
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	856.00 8 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	11,027.02
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____100____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____(%)		Assessed Liability (*): ____100____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Optima Werkz Pte Ltd	:	\$ 11,027.02
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

18 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19012724/KHA3Q2

Date: 18/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SLG6962E

Insured Vehicle No : SMC6109L

Date of Loss: 16/07/2019

Nature of Claim: TP

Claim No: 6210808709SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG6962E

Make & Model: HONDA VEZEL, 1.5 HYBRID (A)

Engine No: LEB5910791

Reg. Date: 11/10/2016 (Man. Year: 2016)

Chassis No: RU31210781

Colour: Metallic Pearl White

Odometer: 102570 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50Z R18

Rear Tyre Size: 225/50Z R18

Front Left Side: Kumho 8 mm

Rear Left Side: Kumho 8 mm

Front Right Side: Kumho 8 mm

Rear Right Side: Kumho 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,770.64	6,753.76	3,016.88	30.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	2,750.00	1,270.00	31.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,790.64	9,503.76	4,286.88	31.09
+ GST 7.00/7.00% (S\$)	965.34	665.26	300.08	31.09
Nett Amount (S\$)	14,755.98	10,169.02	4,586.96	31.09
+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$)		856.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,027.02		

INSPECTION

Date of Assignment: 17/07/2019

Date Inspected: 17/07/2019 Inspected At:

Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	953.30 FL	*953.30 FL
2	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	45.80 FL	*45.80 FL
3	1		*REAR TAILGATE RS EMBLEM	Necessary	54.60 FL	*54.60 FL
4	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	76.80 FL	*76.80 FL
5	1		*REAR TAILGATE INNER LOCK	Dented	216.20 FL	*216.20 FL
6	1		*REAR TAILGATE RUBBER	Cut	198.00 FL	*198.00 FL
7	1		*REAR WINDSCREEN RUBBER	Necessary	35.00 FL	*35.00 FL
8	1		*REAR END PANEL	Bent	530.90 FL	*530.90 FL
9	1		*REAR END PANEL UPPER TRIM COVERING	Cracked	208.80 FL	*208.80 FL
10	6		*REAR END PANEL UPPER TRIM COVERING CLIP	Necessary	39.00 FL	*39.00 FL
11	1		*REAR FLOOR PANEL UPPER BOARD	Deformed	590.80 FL	*590.80 FL
12	1		*REAR FLOOR PANEL BOOT TRAY	Serviceable	1,140.75 FL	*- FL
13	1		*REAR FLOOR PANEL UNDER COVER	Serviceable	284.85 FL	*- FL
14	4		*REAR FLOOR PANEL UNDER COVER CLIP	Not Necessary	46.00 FL	*- FL
15	1		*REAR EXHAUST PIPE	Repair	709.50 FL	*- FL
16	1		*REAR EXHAUST PIPE TAIL	Dented	73.85 FL	*73.85 FL
17	1		*REAR BUMPER	Buckled	935.60 FL	*801.00 FL
18	1		*FRONT BONNET	Buckled	780.00 FL	*780.00 FL
19	1		*FRONT GRILLE	Cracked	405.90 FL	*351.80 FL
20	1		*FRONT GRILLE GARNISH COVER	Cracked	448.50 FL	*380.00 FL
21	1		*FRONT GRILLE CHROME MOULDING LH	Dented	50.00 FL	*50.00 FL
22	8		*FRONT GRILLE CLIP	Necessary	46.40 FL	*46.40 FL
23	1		*FRONT GRILLE SUPPORT BRACKET LH	Repair	16.00 FL	*- FL
24	1		*FRONT GRILLE SUPPORT BRACKET RH	Repair	16.00 FL	*- FL
25	1		*FRONT BUMPER	Buckled	358.20 FL	*358.20 FL
26	1		*FRONT BUMPER LOWER GRILLE	Serviceable	97.60 FL	*- FL
27	1		*FRONT BUMPER LOWER SPOILER (LOWER LIP)	Serviceable	546.00 FL	*- FL
28	10		*FRONT BUMPER CLIP	Necessary	65.00 FL	*65.00 FL
29	1		*FRONT BUMPER FOG LAMP GARNISH LH	Serviceable	68.25 FL	*- FL
30	1		*FRONT BUMPER SIDE BRACKET LH	Repair	19.50 FL	*- FL
31	1		*FRONT BUMPER REINFORCEMENT	Bent	360.75 FL	*321.00 FL
32	1		*FRONT HEADLAMP LH	Mtg Cracked	1,895.45 FL	*1,784.50 FL
33	1		*FRONT FENDER RH (NPA)	Repair	0.00 FL	*- FL
34	1		*REAR FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
35	1		*SET REAR TAILGATE INNER TRIM CLIP	Necessary	40.00 FS	*40.00 FS
36	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
37	2		*REAR WINDSCREEN STOPPER	Necessary	30.00 FS	*30.00 FS
38	1		*REAR FLOOR PANEL SEALANT	Not Necessary	60.00 FS	*- FS
39	1		*REAR END PANEL JOINT SEALANT	Necessary	60.00 FS	*30.00 FS
40	1		*REAR FLOOR PANEL PAD SEALANT	Not Necessary	120.00 FS	*- FS
41	1		*SET REAR BUMPER REVERSE SENSOR	Cracked	250.00 FS	*200.00 FS
42	1		*FRONT NUMBER PLATE WITH HOLDER	Cracked	80.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,033.30	8,345.95
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,262.66	1,592.19
Total Parts (\$\$)	9,770.64	6,753.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,READJUST FRONT & REAR ACCIDENT AREAS & ETC	New	1,300.00	900.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT & REAR ACCIDENT AREAS & ETC	New	1,800.00	1,400.00
3	TO TUFF KOTE/ANTI-RUST & UNDERSEAL MATERIALS	New	200.00	90.00
4	TO REMOVE,REFIX REPLACE REAR REVERSE CAMERA ,REAR REVERSE SENSOR & ETC	New	120.00	80.00
5	TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN SEALANT GUM ,REAR WINDSCREEN MOULDING & ETC .TO EFFECT REPLACE OF REAR TAILGATE	New	150.00	120.00
6	TO REMOVE & REPLACE REAR EXHAUST PIPE ASSY & ETC	New	180.00	60.00
7	LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS	New	120.00	60.00
8	TO CHECK WIRING & ELECTRICAL & TO DIAGNOSIS FAULT CODE & ETC	New	150.00	40.00
Gross Labour Cost (S\$)			4,020.00	2,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >