

Date: 16.07.2019
Vehicle No: SLG6962E
Model: HONDA VEZEL 1.5
Chassis: RU31210781 - 2016
Reg. Year: 2016

Not Notarized
Recovery B4 painting

Third Party Insurer: AIG
Third Party Veh No: SMC6109L
Date of Accident: 16.07.2019

9 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Bu</i> \$953.30
2	REAR TAILGATE "VEZEL" EMBLEM	1		<i>Re</i> \$45.80
3	REAR TAILGATE "RS" EMBLEM	1		<i>Re</i> \$54.60
4	REAR TAILGATE "HYBRID" EMBLEM	1		<i>Re</i> \$76.80
5	REAR TAILGATE INNER LOCK	1		<i>Re</i> \$216.20
6	REAR TAILGATE RUBBER	1		<i>Re</i> \$198.00
7	REAR WINDSCREEN RUBBER	1		<i>Re</i> \$35.00
8	REAR END PANEL	1		<i>Bu</i> \$530.90
9	REAR END PANEL UPPER TRIM COVERING	1		<i>CM</i> \$208.80
10	REAR END PANEL UPPER TRIM COVERING CLIP	6	\$6.50	<i>Re</i> \$39.00
11	REAR FLOOR PANEL UPPER BOARD	1		<i>Reform</i> \$590.80
12	REAR FLOOR PANEL BOOT TRAY	1		\$1,140.75
13	REAR FLOOR PANEL UNDER COVER	1		\$284.85
14	REAR FLOOR PANEL UNDER COVER CLIP	4	\$11.50	\$46.00
15	REAR EXHAUST PIPE	1		\$709.50
16	REAR EXHAUST PIPE TAIL	1		<i>Re</i> \$73.85
17	REAR BUMPER	1		<i>Bu</i> \$935.60
18	FRONT BONNET	1		<i>Bu</i> \$780.00
19	FRONT GRILLE	1		<i>CM</i> \$405.90
20	FRONT GRILLE GARNISH COVER	1		<i>CM</i> \$448.50
21	FRONT GRILLE CHROME MOULDING LH	1		<i>Re</i> \$50.00
22	FRONT GRILLE CLIP	8	\$5.80	<i>Re</i> \$46.40
23	FRONT GRILLE SUPPORT BRACKET LH	1		\$16.00
24	FRONT GRILLE SUPPORT BRACKET RH	1		\$16.00
25	FRONT BUMPER	1		<i>Bu</i> \$358.20
26	FRONT BUMPER LOWER GRILLE	1		\$97.60
27	FRONT BUMPER LOWER SPOILER (LOWER LIP)	1		\$546.00
28	FRONT BUMPER CLIP	10	\$6.50	<i>Re</i> \$65.00
29	FRONT BUMPER FOG LAMP GARNISH LH	1		\$68.25
30	FRONT BUMPER SIDE BRACKET LH	1		\$19.50
31	FRONT BUMPER REINFORCEMENT	1		<i>Bu</i> \$360.75
32	FRONT HEADLAMP LH	1		<i>Re & CM</i> \$1,895.45

Date: 16.07.2019
Vehicle No: SLG6962E
Model: HONDA VEZEL 1.5
Chassis: RU31210781 - 2016
Reg.Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SMC6109L
Date of Accident: 16.07.2019

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST FRONT & REAR
ACCIDENT AREAS & ETC. *900* \$1,300.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS
AT FRONT & REAR ACCIDENT AREAS & ETC. *1400* \$1,800.00

TO TUFF KOTE / ANTI-RUST & UNDERSEAL MATERIALS *900* \$200.00

TO REMOVE, REFIX & REPLACE REAR REVERSE CAMERA, REAR REVERSE SENSOR & ETC. *800* \$120.00

TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT GUM,
REAR WINDSCREEN MOULDING & ETC. TO EFFECT REPLACE OF REAR TAILGATE. *1200* \$150.00

TO REMOVE & REPLACE REAR EXHAUST PIPE ASSY & ETC. *600* \$180.00

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM &
ETC. BACK TO ORIGINAL OPERATIONS. *600* \$120.00

TO CHECK WIRING & ELECTRICAL & TO DIAGNOSIS FAULTY CODE & ETC. *400* \$150.00

LABOUR TOTAL \$4,020.00

ONG TOTAL \$13,790.64