

ACCIDENT REPAIR ESTIMATES

Our Ref: TP / YN5376M

Type of Claim : TP

Vehicle No. : YN5376M

Make & Model : ISUZUNJR85AUE6W

Year of Manufacture : 2014

Chassis No. : NJR857036687

Ins Company : AIG ASIA PACIFIC
INSURANCE PTE LTD

Engine No. : 4JJ11E8464

Excess : 0

Policy No. : 0

Date of Accident : 29.06.2019

Time of Accident : 15:50

Suggested Days of Repair : 0

Case Owner : POWERGAS LIMITED

TP Vehicle No. : GBC8621R

Repair Estimates

Parts (a) List Price Items \$ 207.00

Plus/Less 15% \$ 31.05

Total of Cost / List \$ 175.95

(b) Nett Price Items \$ -

Less 5% \$ -

Total of Nett Item \$ -

(c) Special Nett Items \$ 800.00

Total Parts Cost (Appendix A) \$ 975.95

Labour (Appendix B) \$ 1,600.00

Total Repair Cost \$ 2,575.95

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Guo Qiang - 82880282

Company : LKK.

Survey conducted on : 14/10/19 at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 3 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : Date:

ESTIMATED REPAIR COST DETAILS

1

POWERGAS LIMITED

Vehicle No : YN5376M Case Owner : _____

Make & Model : ISUZUNJR85AUE6W Year Manufacture : 2014

Chassis No : NJR857036687 Engine No : 4JJ11E8464

Date & Time : _____ - Supplier : _____ -

Order By : _____ - Type of Claim : TP

S/No	Part Description	QTY	Unit Price	List Price	Nett Price	S/N	Remarks
1	TAIL GATE LOWER STOPPER 2 / <u>CRA</u>	1	\$ 207.00	\$ 207.00	\$ -	\$ -	-
2	LHR CARGOBOX ARTWORK <u>1</u> / <u>CRA</u>	1	\$ -	\$ -	\$ -	\$ 800.00	? -
3	0	1	\$ -	\$ -	\$ -	\$ -	-
4	0	1	\$ -	\$ -	\$ -	\$ -	-
5	0	1	\$ -	\$ -	\$ -	\$ -	-
6	0	1	\$ -	\$ -	\$ -	\$ -	-
7	0	1	\$ -	\$ -	\$ -	\$ -	-
8	0	1	\$ -	\$ -	\$ -	\$ -	-
9	0	1	\$ -	\$ -	\$ -	\$ -	-
10	0	1	\$ -	\$ -	\$ -	\$ -	-
11	0	1	\$ -	\$ -	\$ -	\$ -	-
12	0	1	\$ -	\$ -	\$ -	\$ -	-
13	0	1	\$ -	\$ -	\$ -	\$ -	-
14	0	1	\$ -	\$ -	\$ -	\$ -	-
15	0	1	\$ -	\$ -	\$ -	\$ -	-
16	0	1	\$ -	\$ -	\$ -	\$ -	-
17	0	1	\$ -	\$ -	\$ -	\$ -	-
18	0	1	\$ -	\$ -	\$ -	\$ -	-
19	0	1	\$ -	\$ -	\$ -	\$ -	-
20	0	1	\$ -	\$ -	\$ -	\$ -	-
21	0	1	\$ -	\$ -	\$ -	\$ -	-
22	0	1	\$ -	\$ -	\$ -	\$ -	-
23	0	1	\$ -	\$ -	\$ -	\$ -	-
24	0	1	\$ -	\$ -	\$ -	\$ -	-
25	0	1	\$ -	\$ -	\$ -	\$ -	-
26	0	1	\$ -	\$ -	\$ -	\$ -	-
27	0	1	\$ -	\$ -	\$ -	\$ -	-
28	0	1	\$ -	\$ -	\$ -	\$ -	-
29	0	1	\$ -	\$ -	\$ -	\$ -	-
30	0	1	\$ -	\$ -	\$ -	\$ -	-

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$207.00 \$ 207.00 \$ - \$ 800.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

2014

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.