

Our Ref:

No . 39 DEFU LANE 12, SINGAPORE 539139

**VEHICLES & EQUIPMENT DIVISION** Tel: (65) 382 2736 FAX: (65) 6382 2817

## **ACCIDENT REPAIR ESTIMATES**

Type of Claim	TP		Vehicle No. :	YN 5376 M			
**			Make & Model :	ISUZU NJR 85			
			Year of Manufacture :	· ·			
			Chassis No.	NJR857036687			
Ins Company :			Engine No. :				
Excess :			Policy No. :				
Date of Accident :			Time of Accident :				
Suggested Days of Repair :							
Repair Estimates							
Parts (a) Cost / List Price Items	\$	207.00					
Plus/Less 15%	\$	31.05					
Total of Cost / List		175.95					
(b) Nett Price Items	\$	-					
Less	\$	=					
Total of Nett Item							
(c) Special Nett Items	\$	800.00					
Total Parts Cost (Appendix A)	\$	975.95					
Labour (Appendix B)	_\$_	1,600.00					
Total Repair Cost	\$	2,575.95					
The above total will be subjected to 7%	G.S.T	•					
Name of Surveyor	:						
Company		<u> </u>					
Survey conducted on			at				
Remarks By Surveyor							
(a) The repair of this vehicle is auth	orized	/ is not authori	zed until further notice.				
(b) Recommended Days of Repair	:		day(s)				
(c) Resurvey	•	Required / No	ot Required				
(d) Excess	:\$						
(e) Signature of surveyor	:		Date:				



No . 39 DEFU LANE 12, SINGAPORE 539139 Tel: (65) 382 2736 FAX: (65) 6382 2817

FAX TO 62860908

## **ESTIMATED REPAIR COST DETAILS**

Vehicle No	: YN 5376 M	Case Owner : 0
Make & Model	: ISUZU NJR 85	Year Manufacture :
Chassis No	: NJR857036687	Engine No : 0
Date & Time	:	Supplier :
Order By	:	Type of Claim : <u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price		S/N
1	TAIL GATE LOWER STOPPER	1		\$ 207.00		1	
2	LHR CARGOBOX ARTWORK	1				\$	800.00
3	0	0				<u> </u>	
4	0	0					
5	0	0					
6	0	0					
7	0	0					
8	0	0					
9	0	0					
10	0	0					
11	0	0					
12	0	0					
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0				Ť.	
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## **VEHICLES & EQUIPMENT DIVISION**

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

## <u>Labour</u>

Vehicle No.	:	YN 5376 M	Case Owner	· · · · · · · · _	0
Make & Model	:	ISUZU NJR 85	Year of Manufacture	:	0

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO REPAIR LHR CARGO BOX AND AFFECTED AREA	\$800.00	
2	TO PUTTY AND RESPRAY LHF CARGO BOX AND AFFECTED AREA	\$800.00	
	TOTAL	\$1,600.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.