

INS. CAS. OWNER:

Arda

CC 4, III 190 12728, TI 903

LKK:

IDAC:

Surveyor:

MTH

DOI:

ASSIGNMENT

12/12/2019

Date / Time:

12/1/19

Registered in Merimen:

18/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 3441R

Name of Insured:

CTPL

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A:

16/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VA: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

PA 56605



INSRS:

WSP:

Tel:

Liability:

RMKS:

WTS



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: TAMARH

Repair Cost:

LIS \$5 10,950.00 (10 days) Reduction: \$7698.00 % 41

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost:

(W/EST) \$5 11,716.50

Loss of Rental (LOR):

\$5 - (5/30 x 10 days)

Loss of Use (LOU):

\$5 1300 (5/30 x 10 days)

Loss of Income (LOI):

\$5 - (5 x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

\$5 -

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

Total:

\$5 13,016.50

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5 13,016.50

Name 1:

WTS Engineering Pte Ltd

Payee 2: (Strike if N.A.)

\$5 -

Name 2:

Payee 3: (Strike if P.A.)

\$5 -

Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

III

Col 2020 Oct.

PAS660S

2005 Out

Woodlands Transport.

Bus.

Toyota Coaster

4/08

white

230646

5T6795388 02 000310

215/75R17.5
- (D)

Aurstone

6

6/6

6

6/6

12/7/190 4pm

Woodlands Transport.

\$24K.

LA

10

20

Mo Chan.

45 \$10,950/- (Red - \$7698 / 41.1)

MV: \$24K

Rebate: \$5950

NV: \$18050.



WTS Engineering Pte Ltd
8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68822163
Company Registration Number: 200505706E

Quotation

DATE: 16/07/19
VEHICLE NO: PA5660S
DRIVER: MUHAMMAD RAZALI BIN ABDUL RAHIM
ATTENTION TO:
PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
Q REF No: Q19/07/1042
DEPARTMENT: WTS Bus Department
ACCIDENT DATE: 16/07/19
REF No: JW-0719-426

Tanpa 7+745701

Wf
17/7/19 4pm

Repairing ref. for repair.

10 days

Surf the auto car

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	REAR BUMPER	1	1600	1,600.00
2	REAR NUMBER PLATE	1	20	20.00
3	REAR NUMBER PLATE LAMP	1	84.3	84.30
4	REAR LHS TAIL LAMP	1	693.7	693.70
5	REAR LHS DOOR PANEL	1	3500	3,500.00
6	REAR LHS DOOR INNER PANEL <i>Cover</i>	1	350	350.00
7	REAR LHS DOOR INNER COVER	1	400	400.00
8	LHS REAR SIDE BODY PANEL	1	4000	4,000.00
Labour Costs				
1	TO DISMANTLE, REMOVE AND RE-INSTALL REAR LHS BODY GLASS AND LHS SIDE PASSENGER SEATS FOR FACILITATE REPAIR REAR LHS BODY PANEL DAMAGED AREA	1	1400	1,400.00
2	TO WELDING AND CUT LHS SIDE BODY PANEL ACCIDENT AREA AND INSTALL NEW PARTS.	1	1000	1,000.00
3	TO DISMANTLE AND REMOVE REAR PASSENGER SEATS AND REAR LHS DOOR AND BUMPER FOR FACILITATE REPAIR AND REPLACE DAMAGED PARTS REAR LHS DOOR, DOOR INNER PANEL AND BUMPER	1	1200	1,200.00
4	TO CHECK WIRING AND REMOVE AND PLACE REAR LHS TAIL LAMP TO CHECK TV CONDITION AND TV STAND. TO CHECK AIR CON CONDITION.	1	450	450.00
5	TO CHECK ENGINE CANNOT START.	1	350	350.00
6	TO SPRAY PAINTING LHS BODY PANEL, REAR BUMPER AND REAR LHS DOOR PANEL AND LHS DOOR.	1	1500	1,500.00
7	SUPPLY LABOUR AND MATERIAL TO REPLACE LHS BODY STICKER, REAR LHS DOOR AND REAR BUMPER STICKER.	1	2000	2,000.00
8	TOWING SERVICE FROM T3 TO GUL CIRCLE (NET PRICE)	1	120	120.00
TOTAL:				18,648.00
Total Amount				SGD 18,648.00

10628
25/- 7971

5720

Remarks:

LXX Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts (if any) and
- Parts prices are subject to confirmation.

Signature of LXX Auto Consultants

No illegal modification is allowed

Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Surveyor Sign: *Tanpa*

Surveyor Name: *Tanpa*

Date: *17/7/19*

Signature of Department Head

Signature of Claim Department

13691
459/10,950 #
10 days

WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

Quotation

DATE: 16/07/19
 VEHICLE NO: PA5660S
 DRIVER: MUHAMMAD RAZALI BIN ABDUL RAHIM
 ATTENTION TO:
 PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
 Q REF No: Q19/07/1042
 DEPARTMENT: WTS Bus Department
 ACCIDENT DATE: 16/07/19
 REF No: JW-0719-426

7 Aug 17 19 57
Wf
17/7/19 4pm
Impsue
Repair after repair.
10 days
Surf the amount

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	REAR BUMPER	1	1600	bt ✓ 1,600.00
2	REAR NUMBER PLATE	1	20	bt ✓ 20.00
3	REAR NUMBER PLATE LAMP	1	64.3	ans ✓ 64.30
4	REAR LHS TAIL LAMP	1	693.7	ans ✓ 693.70
5	REAR LHS DOOR PANEL	1	3500	bt ✓ 3,500.00
6	REAR LHS DOOR INNER PANEL <i>cover</i>	1	350	de ✓ 350.00
7	REAR LHS DOOR INNER COVER	1	400	de ✓ 400.00
8	LHS REAR SIDE BODY PANEL	1	4000	bui ✓ 4,000.00
Labour Costs				
1	TO DISMANTLE, REMOVE AND RE-INSTALL REAR LHS BODY GLASS AND LHS SIDE PASSENGER SEATS FOR FACILITATE REPAIR REAR LHS BODY PANEL DAMAGED AREA	1	1400	800 ✓ 1,400.00
2	TO WELDING AND CUT LHS SIDE BODY PANEL ACCIDENT AREA AND INSTALL NEW PARTS.	1	1000	700 ✓ 1,000.00
3	TO DISMANTLE AND REMOVE REAR PASSENGER SEATS AND REAR LHS DOOR AND BUMPER FOR FACILITATE REPAIR AND REPLACE DAMAGED PARTS REAR LHS DOOR, DOOR INNER PANEL AND BUMPER	1	1200	900 ✓ 1,200.00
4	TO CHECK WIRING AND REMOVE AND PLACE REAR LHS TAIL LAMP. TO CHECK TV CONDITION AND TV STAND. TO CHECK AIR CON CONDITION.	1	450	100 ✓ 450.00
5	TO CHECK ENGINE CANNOT START.	1	350	✓ 350.00
6	TO SPRAY PAINTING LHS BODY PANEL, REAR BUMPER AND REAR LHS DOOR PANEL AND LHS DOOR.	1	1500	1300 ✓ 1,500.00
7	SUPPLY LABOUR AND MATERIAL TO REPLACE LHS BODY STICKER, REAR LHS DOOR AND REAR BUMPER STICKER.	1	2000	1800 ✓ 2,000.00
8	TOWING SERVICE FROM T3 TO GUL CIRCLE. (NET PRICE)	1	120	✓ 120.00
			TOTAL:	18,648.00
			Total Amount	SGD 18,648.00

Remarks:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Signature of Workshop Dpt *republic* basis

- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Surveyor Sign: *tauphi*
 Surveyor Name: *Tauphi*
 Date: *17/7/19* *16/7/19*
4pm
Jeff Lim
 Signature of Department Head

16/7/19
 Signature of Claim Department

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 721M

Vehicle Details

Vehicle No.: PA5660S

Vehicle to be Exported: No

Intended Deregistration

Date:

19 Jul 2019

Vehicle Make: TOYOTA

Vehicle Model: COASTER HR D

Primary Colour: White

Manufacturing Year: 2005

Engine No.: 15B1777816

Chassis No.: JTGFG538802000310

Maximum Power

Output:

-

Open Market Value: \$66,100.00

Original Registration

Date:

17 Oct 2005

First Registration Date: 17 Oct 2005

Transfer Count: 0

Actual ARF Paid: \$3,305.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry

Date:

-

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 16 Oct 2020

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$23,992.00

COE Rebate Amount: \$5,951.00

Total Rebate Amount: \$5,951.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 19 Jul 2019

OK

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 17 July 2019 1:37 PM
To: kenjilee@woodlandstransport.com.sg; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Zuhaidah Samsuri
Subject: RE: PRI PA5660S VS SHA3441R DOA 16/07/19
Attachments: GIA.PDF; PRI.PDF; QUOTATION.PDF

Dear Sir / Mdm,

Please conduct a survey on TP vehicle **PA5660S** and let us have your report urgently.

This claim will be handled by **Ms Aida**.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street, #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: kenjilee@woodlandstransport.com.sg [mailto:kenjilee@woodlandstransport.com.sg]
Sent: 17 July, 2019 10:43 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: goo@woodlandstransport.com.sg; slchan@woodlandstransport.com.sg
Subject: RE: PRI PA5660S VS SHA3441R DOA 16/07/19

Dear Sir / Mdm,

We choose LKK Auto Consultants Pte Ltd as the single joint expert for this PRI.

Please contact **Mr Chan at Tel: 6559 8984 / 9299 4122** for an appointment to view the vehicle.

Thank you.

Thanks and Regards,

Kenji Lee 李东仁

Claims Department

Veh In - Taubik

Woodlands Transport Service Pte Ltd

8, Gul Circle, Singapore 629564

Main Line : +65 6559 8988 Fax : +65 6898 2394

Direct Line : +65 6559 8954

www.woodlandstransport.com.sg

Group of Companies:

WTS



CASHBOX

From: Motor Claim - III <motorclaim@iii.com.sg>

Sent: Wednesday, 17 July 2019 9:26 AM

To: kenjilee@woodlandstransport.com.sg

Cc: goo@woodlandstransport.com.sg; slchan@woodlandstransport.com.sg

Subject: RE: PRI PA5660S VS SHA3441R DOA 16/07/19

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



INDIA
INTERNATIONAL
INSURANCE
SINGAPORE
Serving the region since 1987

64 Cecil Street, #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

From: kenjilee@woodlandstransport.com.sg [<mailto:kenjilee@woodlandstransport.com.sg>]

Sent: 16 July, 2019 5:45 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: goo@woodlandstransport.com.sg; slchan@woodlandstransport.com.sg

Subject: PRI PA5660S VS SHA3441R DOA 16/07/19

Dear Sir

We are instructed by **Woodlands Transport Service Pte Ltd** to notify you of a road traffic accident on **16/07/2019** at about **0042HRS hrs** at **AIRPORT BOULEVARD** involving our client's/customer's vehicle registration number and vehicle registration number **SHA3441R** driven by you at the material time. A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's/customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Please send your surveyor to our premises at **No. 8 Gul Circle, Singapore 629564**.

Please contact **Mr Chan at Tel: 6559 8984 / 9299 4122** for an appointment to view the vehicle.

For your immediate attention and action, please.

Thank you.

Thank you.

Thanks and Regards,

Kenji Lee 李东仁

Claims Department



Woodlands Transport Service Pte Ltd

8, Gul Circle, Singapore 629564

Main Line : +65 6559 8988 Fax : +65 6898 2394

Direct Line : +65 6559 8954

www.woodlandstransport.com.sg

Group of Companies: WTS  PTSTOR  CASHBOX

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

WTS ENGINEERING PTE LTD

No 8 Gul Circle Singapore 629564.

TEL : 6559 8983 FAX : 6898 2394

CO. REG. NO. : 200505706E

Cecil check done

ATTN: CECILIA CHONG (LEK)

FROM ADA (III)

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
SINGAPORE 049711

GST REG NO : 200505706E

INVOICE NO. : A2001001
DATE : 07/01/2020
TERMS : COD
A/C CODE : 3000/C01

ATTENTION : MOTOR CLAIMS DEPT

ITEM	DESCRIPTION	LOCATION	QTY	U.PRICE	AMOUNT
1	REPAIR WORKS OF PA5660S ACCIDENT DATE:16/07/2019		1	10950.00	10,950.00



SINGAPORE DOLLAR : ELEVEN THOUSAND SEVEN HUNDRED SIXTEEN AND CENTS FIFTY ONLY

SUB-TOTAL	SS	10,950.00
7 % GST	SS	766.50
TOTAL	SS	11,716.50

Please note that a late payment of charge of 0.05% per day will be levied on all overdue amounts from date of invoice

* Kindly issue cheque payable to "WTS Engineering Pte Ltd"

WTS ENGINEERING PTE LTD

Signature

WTS ENGINEERING PTE LTD 200505706E

COMPANY & GST REGISTRATION NO:200505706E

NO 8 GUL CIRCLE

SINGAPORE 629564.

TEL:6559-8983 FAX:6898-2394

X

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET
#04-05 IOB BUILDING
SINGAPORE 049711

ATTN. : MOTOR CLAIMS DEPT
TEL. :
FAX :
A/C NO. : 3000/C01

DEBIT NOTE

NO. : DN200101
DATE : 07/01/2020
TERM : COD
PAGE : 1/1

ITEM NO.	DESCRIPTION	QTY	U.PRICE	DIS.	TAX	AMOUNT
1	CC-REIM LOSS OF USE OF PA5660S ACCIDENT DATE:16/07/2019	1	1300.00			1,300.00

SINGAPORE DOLLAR : ONE THOUSAND THREE HUNDRED ONLY

TOTAL QUANTITY

1

TOTAL	1,300.00
DISCOUNT	0.00
NET	1,300.00
TAX	0.00
GROSS	SS 1,300.00

AUTHORISED SIGNATURE(S)

RECEIVED BY

Print Received Message

This mail is associated with :

***PA5660S (MCT19070418)**

[SHA3441R]

TP

WOODLANDS TRANSPORT SERVICE PTE LTD

Jul 16 2019 12:00AM

[-]

WTS Automotive Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 23/10/2019 10:13 AM,
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$13016.50) - PA5660S - Claim Handler: Zuhaidah Bte Samsuri

Approved:13016.50:Please negotiate LOU @ \$120/130 per day.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jul 2019 Edit Reg		17 Jul 2019 00:00 Edit Adj Rpt	\$510,950.00 Edit Estimates	\$510,950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	WOODLANDS TRANSPORT SERVICE PTE LTD, Co. Reg. No.: 198102721M								
Vehicle Reg. No.:	PA5660S	Date of Loss:	16/07/2019 00:00 - :59 [164 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19070418	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA3441R	Policy No. (Claimant):	SD18V07061						
		Excess:							
Repairer:	Wts Automotive Services Pte Ltd (tuas) (HQ) 8 Gul Circle, 629564 Tuas - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 29/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (04/11/2019): Alert - Adj Mandate Maintained - PA5660S - Claim Handler: Zuhaidah Bte Samsuri III_SG (23/10/2019): Alert - Adj Mandate Approved (\$513016.50) - PA5660S - Claim Handler: Zuhaidah Bt... III_SG (19/08/2019): Alert - Adj Mandate Approved (\$40.00) - PA5660S - Claim Handler: Zuhaidah Bte Sa... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PA5660S (MCT19070418)
[SHA3441R]










































TP

WOODLANDS TRANSPORT SERVICE PTE LTD

Jul 16 2019 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

Wts Automotive Services Pte Ltd (tuas)

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
2	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
3	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
4	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
5	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
6	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
7	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
8	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
9	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
10	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
11	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
12	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
13	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
14	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
15	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
16	08/10/19 17:16	General View						Load JPG	<input checked="" type="checkbox"/>	
17	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
18	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
19	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
20	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
21	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
22	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
23	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
24	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
25	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
26	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
27	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
28	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
29	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
30	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
31	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
32	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
33	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
34	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
35	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
36	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
37	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
38	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
39	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
40	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
41	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
42	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	
43	08/10/19 17:17	General View						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
44	08/10/19 17:17	General View		Load JPG	<input checked="" type="checkbox"/>
45	08/10/19 17:17	General View		Load JPG	<input checked="" type="checkbox"/>
46	08/10/19 17:17	General View		Load JPG	<input checked="" type="checkbox"/>
47	08/10/19 17:17	General View		Load JPG	<input checked="" type="checkbox"/>
48	08/10/19 17:17	General View		Load JPG	<input checked="" type="checkbox"/>
49	08/10/19 17:17	General View		Load JPG	<input checked="" type="checkbox"/>
50	08/10/19 17:17	General View		Load JPG	<input checked="" type="checkbox"/>
51	08/10/19 17:17	General View		Load JPG	<input checked="" type="checkbox"/>
52	08/10/19 17:17	General View		Load JPG	<input checked="" type="checkbox"/>
53	08/10/19 17:17	General View		Load JPG	<input checked="" type="checkbox"/>
54	08/10/19 17:17	General View		Load JPG	<input checked="" type="checkbox"/>
55	08/10/19 17:17	General View		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/07/19 19:09	TP ESTIMATE		Load PDF	
2	18/07/19 19:09	TP GIA REPORT		Load PDF	
3	18/07/19 19:09	ACKNOWLEDGEMENT EMAIL TO III DD 18.07.2019		Load PDF	
4	18/07/19 19:09	NOTIFICATION FROM WORKSHOP		Load PDF	
5	22/07/19 09:39	TP ESTIMATE-MARKED		Load PDF	
6	21/10/19 13:57	WORKSHOP INVOICE		Load PDF	
7	21/10/19 13:57	LOD		Load PDF	
8	10/02/20 09:21	DISCHARGE VOUCHER		Load PDF	
9	10/02/20 09:21	AUTHORISATION TO ACT FORM		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	19/07/19 08:46	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19012728/T1GA3Q2

Date: 10/02/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: PA5660S Insured Vehicle No: SHA3441R
 Date of Loss: 16/07/2019 Nature of Claim: TP Claim No: MCT19070418

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PA5660S
 Make & Model: TOYOTA COASTER, 4.1 D (M) Engine No: 15B1777816
 Reg. Date: 17/10/2005 (Man. Year: 2005) Chassis No: JTGFG538802000310
 Colour: White Odometer: 230646 km
 Engine Capacity: 4104 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/75 R17.50 Rear Tyre Size: 215/75 R17.5 (D)
 Front Left Side: Austone 6 mm Rear Left Side: Austone 6/6 mm
 Front Right Side: Austone 6 mm Rear Right Side: Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,628.00	7,971.00	2,657.00	25.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,020.00	5,720.00	2,300.00	28.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,648.00	13,691.00	4,957.00	26.58
Approved Total (Overridden) (S\$)		10,950.00		
(S\$)	18,648.00	10,950.00	7,698.00	41.28
+ GST 7.00/7.00% (S\$)	1,305.36	766.50	538.86	41.28
Nett Amount (S\$)	19,953.36	11,716.50	8,236.86	41.28
+ Loss of Use (10.0 x S\$130.00/day) (S\$)		1,300.00		
Nett Liability (S\$)		13,016.50		

INSPECTION

Date of Assignment: 17/07/2019
 Date Inspected: 17/07/2019 Inspected At: WTS Automotive Services Pte Ltd (HQ)
 8 Gul Circle
 Singapore 629564
 Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 07 Feb 2020)
Parts:	N/A	TOYOTA COASTER 4.1 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for PA5660S)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,600.00 F	*1,600.00 FL
2	1		*REAR NUMBER PLATE	Bent	20.00 F	*20.00 FL
3	1		*REAR NUMBER PLATE LAMP	Cracked	64.30 F	*64.30 FL
4	1		*REAR LHS TAIL LAMP	Cracked	693.70 F	*693.70 FL
5	1		*REAR LHS DOOR PANEL	Bent	3,500.00 F	*3,500.00 FL
6	1		*REAR LHS DOOR INNER PANEL COVER	Deformed	350.00 F	*350.00 FL
7	1		*REAR LHS DOOR INNER COVER	Deformed	400.00 F	*400.00 FL
8	1		*LHS REAR SIDE BODY PANEL	Buckled	4,000.00 F	*4,000.00 FL
					Sub Total (\$\$)	10,628.00 10,628.00
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 2,657.00
					Total Parts (\$\$)	10,628.00 7,971.00

F=Franchise part, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE ,REMOVE AND REINSTALL REAR LHS BODY GLASS AND LHS SIDE PASSENGER SEATS FOR FACILITATE REPAIR REAR LHS ,BODY PANEL DAMAGED AREA	New	1,400.00	800.00
2	TO WELDING AND CUT LHS SIDE BODY PANEL ACCIDENT AREA AND INSTALL NEW PARTS	New	1,000.00	700.00
3	TO DISMANTLE AND REMOVE REAR PASSENGER SEATS AND REAR LHS DOOR AND BUMPER FOR FACILITATE REPAIR AND REPLACE DAMAGED PARTS REAR LHS DOOR ,DOOR INNER PANEL AND BUMPER	New	1,200.00	900.00
4	TO CHECK WIRING AND REMOVE AND PLACE REAR LHS TAIL LAMP TO CHECK TV CONDITION AND TV STAND TO CHECK AIR CON CONDITION	New	450.00	100.00
5	TO CHECK ENGINE CANNOT START	New	350.00	0.00
6	TO SPRAY PAINTING LHS BODY PANEL.REAR BUMPER AND REAR LHS DOOR PANEL AND LHS DOOR	New	1,500.00	1,300.00
7	SUPPLY LABOUR AND MATERIAL TO REPLACE LHS BODY STICKER ,REAR LHS DOOR AND REAR BUMPER STICKER	New	2,000.00	1,800.00
8	TOWING SERVICE FROM T3 TO GUL CIRCLE	New	120.00	120.00
Gross Labour Cost (S\$)			8,020.00	5,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >