

WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

Quotation

DATE: 16/07/19

VEHICLE NO: PA5660S

DRIVER: MUHAMMAD RAZALI BIN ABDUL RAHIM

ATTENTION TO:

PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop

Q REF No: Q19/07/1042

DEPARTMENT: WTS Bus Department

ACCIDENT DATE: 16/07/19

REF No: JW-0719-426

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	REAR BUMPER	1	1600	1,600.00
2	REAR NUMBER PLATE	1	20	20.00
3	REAR NUMBER PLATE LAMP	1	64.3	64.30
4	REAR LHS TAIL LAMP	1	693.7	693.70
5	REAR LHS DOOR PANEL	1	3500	3,500.00
6	REAR LHS DOOR INNER PANEL	1	350	350.00
7	REAR LHS DOOR INNER COVER	1	400	400.00
8	LHS REAR SIDE BODY PANEL.	1	4000	4,000.00
Labour Costs				
1	TO DISMANTLE , REMOVE AND RE-INSTALL REAR LHS BODY GLASS AND LHS SIDE PASSENGER SEATS FOR FACILITATE REPAIR REAR LHS BODY PANEL DAMAGED AREA.	1	1400	1,400.00
2	TO WELDING AND CUT LHS SIDE BODY PANEL ACCIDENT AREA AND INSTALL NEW PARTS.	1	1000	1,000.00
3	TO DISMANTLE AND REMOVE REAR PASSENGER SEATS AND REAR LHS DOOR AND BUMPER FOR FACILITATE REPAIR AND REPLACE DAMAGED PARTS REAR LHS DOOR , DOOR INNER PANEL AND BUMPER	1	1200	1,200.00
4	TO CHECK WIRING AND REMOVE AND PLACE REAR LHS TAIL LAMP. TO CHECK TV CONDITION AND TV STAND. TO CHECK AIR CON CONDITION,	1	450	450.00
5	TO CHECK ENGINE CANNOT START.	1	350	350.00
6	TO SPRAY PAINTING LHS BODY PANEL , REAR BUMPER AND REAR LHS DOOR PANEL AND LHS DOOR,	1	1500	1,500.00
7	SUPPLY LABOUR AND MATERIAL TO REPLACE LHS BODY STICKER, REAR LHS DOOR AND REAR BUMPER STICKER.	1	2000	2,000.00
8	TOWING SERVICE FROM T3 TO GUL CIRCLE. (NET PRICE)	1	120	120.00
TOTAL:				18,648.00
Total Amount				SGD 18,648.00

Remarks:

Signature of Workshop Dpt

Signature of Department Head

Signature of Claim Department