

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 19 July 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : FBB 184T
ACCIDENT DATE: 12 July 2019

Honda CB400

Description	Qty	Quotation \$
1 Handle Bar <i>A.67</i>	1	195.00 ✓
2 Mirror <i>Cut</i>	1 set	220.00 ✓
3 Handle Bar Grip <i>HN</i>	1	190.00 X
4 Balancer <i>Cut</i>	1 set	180.00 ✓
5 Brake Lever <i>Cut</i>	1	135.00 ✓
6 Front RH Signal <i>Cut</i>	1	170.00 ✓
7 Front Mudguard <i>new</i>	1	330.00 X
8 Front Rim <i>Cut</i>	1	650.00 ✓
9 Fork Tube <i>A. distribute</i>	1 set	650.00 ✓
10 Fork Oil Seal <i>A. Huc</i>	1	135.00 ✓
11 Head Lamp <i>BT</i>	1	480.00 ✓
12 Head Lamp Rim <i>BT</i>	1	220.00 ✓
13 Brake Disc <i>A. distribute</i>	1	320.00 ✓
14 Crash Bar <i>Cut</i>	1	300.00 ✓
15 Engine Cover RH <i>Cut</i>	1	220.00 ✓
16 Exhaust Pipe <i>Cut</i>	1	1,100.00 ✓
17 Brake Reservoir Bracket RH <i>broken</i>	1	250.00 ✓

Sub-Total 5,745.00

Less 10% 574.50

Sub-Total 5,170.50

19/7/19

Approved by Repairs

Signature:

Date:

LKK Auto Consultants hence notify the Repairs of the following:

- To receive delivery of parts during survey
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification is allowed
- Supplementary items must be reviewed and is subject to final approval from Insurance Company

VEHICLE NO : FBB 184T

Honda CB400

Nett Items

1	Front number plate NW	15.00 X
2	Rear box cut	350.00 180/-
3	RH Side box - centre NW	190.00 X
4	Towing fee	45.00 30/-
5	Remove & replace necessary parts, align & etc	350.00 200/-
6	Remove & replace fork tube, top up fork oil	250.00 80/-
7	To respray & touch up paint	350.00 180/-
8	Electrical wiring connection	40.00 30/-
9	Replace exhaust & labour	60.00 20/-

Special Nett Items

1	Meter Assy broken	1,500.00 ✓
---	-------------------	------------

Sub-Total 3,150.00
Nett Total 8,320.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you


SG 98 MOTOR PTE LTD

19/07/2014 10:00am
NA Andrew

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2/Sm 4 days. Check MV
R
gm
LKK Auto