

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022767
Rioli

Page 1 of 1
Your ref. TP-SLL 882R AXA
Job No. 70697
Our ref. 19.07.30
Payment
Date 18/7/2019

Attn

Vehicle No ... SGA 8222K
Vehicle Model : Mazda 6
Accident on ... 15/7/2019

Not Withonw
Repair by paint
2 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear bumper	1,152.90	25.00	<i>CM</i> 864.68 ✓
1.00	Pc	Rear bumper reflector LH	52.65	25.00	<i>CM</i> 39.49 ✓
1.00	Pc	Rear bumper reinforcement	492.70	25.00	<i>R</i> 369.53 X
Special nett item:					
1.00	Set	Rear reversing sensor + installation (4 pcs)	250.00		<i>RM</i> 250.00 ✓
Labour & Misc:					
1.00		To knock dents on rear end panel and renew of parts	350.00		<i>350</i> 350.00
1.00		To spray paint (including rear bumper reinforcement)	400.00		<i>350</i> 400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Sub-Total 2,273.70
GST 7.00% 159.16
Total S\$ 2,432.86

本公司拥有最先进的 **CAROLINER MARK IV** 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 **SAICO Deluxe** 喷漆烘炉。

"Our services include the latest and reliable **CAROLINER MARK IV** repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced **SAICO Deluxe** oven heater for re-spraying all motor vehicles."