

Kg

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022767
Rioli

Page 1 of 1
Your ref. TP-SLL 882R AXA
Job No 70697
Our ref 19.07.30
Payment
Date 18/7/2019

Attn

Vehicle No SGA 8222K
Vehicle Model Mazda 6
Accident on 15/7/2019

Not Authorised

Return By paint

81804.17

3 Days

Quantity	Unit	Description	Unit price	Disc pct	Amount
Supply of Parts					
1.00	Pc	Rear bumper	1,152.90	25.00	864.68 ✓
1.00	Pc	Rear bumper reflector LH	52.65	25.00	39.49 ✓
1.00	Pc	Rear bumper reinforcement	402.70	25.00	302.03 ✗
Special nett item.					
1.00	Set	Rear reversing sensor + installation (4 pcs)	250.00		250.00 ✓
Labour & Misc					
1.00		To knock dents on rear end panel and renew of parts	350.00		350.00
1.00		To spray paint (including rear bumper reinforcement)	400.00		400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Sub Total 2,273.70
GST 7.00% 159.16
Total S\$ 2,432.86

本公司拥有先进的 SAICO Deluxe 喷漆烘炉。机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."