

ASS. REC. BY:

REF:

05/CT#19012738/Atd3⁷⁴

Special Instruction:

Survivor

Adrian

ASSIGNMENT (Office)

From (Person):

chong soon sen

of

CTI

Date/Time:

18/7/19 @ 11:50am

Estimated Cost:

Bill to:

OD / IT WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 9810A

Insured:

GIBB5059P

at Workshop m/s

Sk Automobile

Tel:

81210178

of

8 Teluk Bukit Ave 4 # 08-16

Policy No:

DmCVSN30186919000

Claim No:

SNM19D203340C03

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:58am @ 18/7/19

Person Contacted:

Xiong

Vehicle

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKQ 9810A-NBA/NC16002758/y
	UX3244]-X
	lump sum \$10,000 (Red: 34310.50, 17%), 9 days.

DOA: 14/2/2016

REF:

Action

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKQ9810A Yr Regn: 2011 AprilType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E200C41cc 1796Colour: Silver A/C: Insured / Std / Nil / NASp. Reading: 123252 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WDD2120482 A386810Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/45R17R: 245/45R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 18/07/19Survey held at SKDes. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chua

RECEIVED 2 MAY 2020

MV: 50K

PV: 39.7K

Nett: 10.3K

Date/Time, File Pass to?

Date/Time, File Return to?

1) 213 Typist

2)

3)

4)

5)

6)

File Report

File Report

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

120

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 2 March 2020 11:37 AM
To: JING XIONG KHOO; SUR
Subject: RE: SKQ9810 ESTIAMTE

Dear Xiong,

Refer to our conversation

Hereby confirm figure at \$10,000/-, 9days

Please submit your documents to China Taiping directly

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: JING XIONG KHOO <xionskauto@gmail.com>
Sent: Wednesday, 26 February 2020 10:19 AM
To: SUR <sur@lkkauto.com>
Subject: SKQ9810 ESTIAMTE

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 18 July 2019 11:54 AM
To: admin@skauto.com.sg
Cc: 'assignments'
Subject: RE: OUR REF :SNM19D203340/CHONGBS - FW: Arrange surveyor for GX3244J & SKQ9810A - Your Ref:GBB5059P

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chong Boon Sen
Sent: Thursday, 18 July, 2019 11:53 AM
To: admin@skauto.com.sg
Subject: RE: OUR REF :SNM19D203340/CHONGBS - FW: Arrange surveyor for GX3244J & SKQ9810A - Your Ref:GBB5059P

WITHOUT PREJUDICE

Dear Sir,

We refer to your email below.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN

XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Wednesday, 17 July, 2019 2:37 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; admin@skauto.com.sg

Subject: OUR REF :SNM19D203340/CHONGBS - FW: Arrange surveyor for GX3244J & SKQ9810A - Your Ref:GBB5059P

Dear Boon Sen,

Please conduct PRS for GX3244J & SKQ9810A.

Note: Officer in charge – Boon Sen 63896171.

Thanks,
shumin

From: SK Admin [<mailto:admin@skauto.com.sg>]

Sent: Tuesday, July 16, 2019 4:28 PM

To: Claims Dept of CTI; Ong Chin Kiat

Cc: JING XIONG KHOO; md daud nadzim

Subject: Arrange surveyor for GX3244J & Your Ref:GBB5059P

Dear Sir/Mdm,

We the repairers of motor vehicle no. GX3244J
Please provide a list of surveyor for further inspection.

Location : 8 Kaki Bukit Ave 4#08-46
Premier @ Kaki Bukit
Singapore 415875

Contact No : 8121 0478 Xiong

We appreciate your early reply.
Thanks.

--

Regards,
Huey Lee
SK Automobile Pte Ltd
Tel: 6789 5155 Fax: 6783 5155

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

EXPERIENCE AMAZING WITH LEXUS

LUXURY REIMAGINED


LEXUS
[BOOK A TEST DRIVE](#)

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Mercedes-Benz A190 1000 Coupe (1982-1983)



Used and only well maintained
engine Super Run around
Highly 100% worth
wanted


[Browse by Category](#)
[Back \(1 2 \) Next](#)
[Sort by Date Posted](#)
[20 results/page](#)

26 vehicles

Mercedes-Benz 200

[Advanced Search](#)


	Model	Price	Depreciation	Reg. Info	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mercedes-Benz 200	Any	Any	2011	Any	Any	Any	Available
	Mercedes-Benz E-Class E200 CGI	\$50,555	\$15,740 /yr	14-Jan-2011	1,796 cc	-	Luxury	Available
Down \$5000.00 Only, Mthly At \$1517.00 Under Balloon Scheme, Good For Short Term Or Grab Use.								
Posted: 02-Jul-2019 Tags: 2011 Mercedes-Benz E200, 2011 mercedes-benz e200, Mercedes-Benz E200, mercedes-benz e200, Mercedes-Benz, E200, e200, Used Mercedes-Benz								
	Mercedes-Benz E-Class E200 CGI Cabriolet (New 10-yr COE)	\$105,888	\$10,580 /yr	26-Jan-2011	1,796 cc	72,189 km	Sports	Available
With New 10 Yrs COE, C&C Unit, Full Service Records In C&C, Low Mileage, High OHV, Superb Condition, View It You Will Never Be Disa...								
Posted: 06-Jul-2019 Tags: 2011 Mercedes-Benz E200, 2011 mercedes-benz e200, Mercedes-Benz E200, mercedes-benz e200, Mercedes-Benz, E200, e200, Used Mercedes-Benz								
	Mercedes-Benz E-Class E200 CGI Coupe	\$49,800	\$14,670 /yr	28-Jan-2011	1,796 cc	91,000 km	Sports	Available
(70% Loan Of The Car Price Available) Best For Short Term Usage Or Renewing COE, Accident Free, Low Mileage Done 109000km Annual...								
Hin Lung Auto Pte Ltd								
Posted: 12-Jul-2019 Tags: 2011 Mercedes-Benz E200, 2011 mercedes-benz e200, Mercedes-Benz E200, mercedes-benz e200, Mercedes-Benz, E200, e200, Used Mercedes-Benz								
	Mercedes-Benz E-Class E200 CGI Coupe	\$48,300	\$14,470 /yr	10-Feb-2011	1,796 cc	79,800 km	Sports	Available
Architect Owner, Extremely Well Maintained, Brand New Throttle Body Worth \$1,000, Beautiful Condition, Nice Number Plate.								
Posted: 05-Jul-2019 Tags: 2011 Mercedes-Benz E200, 2011 mercedes-benz e200, Mercedes-Benz E200, mercedes-benz e200, Mercedes-Benz, E200, e200, Used Mercedes-Benz								
	Mercedes-Benz E-Class E200 CGI Elegance	\$49,000	\$13,890 /yr	15-Feb-2011	1,796 cc	77,000 km	Luxury	Available
Very Faithful Owner Since Day 1! Authentic Mileage, Fully Maintained By Agent Since Day 1 Until 2018! Can Be Verified At C&C! Piece...								
Posted: 15-Jul-2019 Tags: 2011 Mercedes-Benz E200, 2011 mercedes-benz e200, Mercedes-Benz E200, mercedes-benz e200, Mercedes-Benz, E200, e200, Used Mercedes-Benz								
	Mercedes-Benz E-Class E200 CGI Elegance	\$49,555	\$14,170 /yr	18-Feb-2011	1,796 cc	-	Luxury	Available

Continue

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

EXPERIENCE AMAZING WITH LEXUS LUXURY REIMAGINED



LEXUS

BOOK A TEST DRIVE

SEARCH e200

Price Range

Depreciation

2011

Vehicle Type

Search

View All

Advanced Search

Used Car Comparison

— Comparing 4 Vehicles —

Mercedes-Benz E-Class E200 CGI Elegance



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Mercedes-Benz E-Class E200 CGI



Add to Shortlist

Mercedes-Benz E-Class E200 CGI



Add to Shortlist

Mercedes-Benz E-Class



Add to Shortlist

CAR DETAILS

Price	\$49,000	\$51,000	\$53,666	\$59,800
Instalment	\$1,991	\$1,874	\$1,801	\$1,924
Registration Date	15-Feb-2011	13-Apr-2011	30-May-2011	14-Jul-2011
Manufactured	2010	2010	2011	2011
Mileage	77,000 km	70,000 km	-	180,885 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,796 cc	1,796 cc	1,796 cc	1,796 cc
Road Tax	\$974 /yr	\$974 /yr	\$974 /yr	\$974 /yr
Power	135.0 kW (181 bhp)	135.0 kW (181 bhp)	135.0 kW (181 bhp)	135.0 kW (181 bhp)
Curb Weight	1,615 kg	1,615 kg	1,615 kg	1,615 kg
Features	-	1.8L 4 Cylinder Inline Turbocharged, 181Bhp, 5G-Tronic Auto Transmission, Multi Function Steering, Cruise Control, Speed Limiter, Keyless Start Engine	1.8L Turbocharged CGI Engine, 5 Speed Auto, Cruise Control, Memory Seats, Multi Function Steering, ABS, EPS.	Powerful, Smooth i Turbo Charged CG Entry/ Start, ABS, i Fog Lamps.
Accessories	-	17 Inch Rims, Keyless Entry/Start/Stop, ABS, Cruise Control, Bluetooth Telephony, Reverse Camera, All Round Parktronic, Comfort Access.	Factory Fitted Audio, Reverse Sensors/Camera, Retractable Mirrors, Memory Seats, Bluetooth, Sports Rims, Electric Auto Tailgate	Beautiful Interior, i Reverse Sensors/C Mirrors, Memory 5i Rims, Electric Auto
Description	1 Very Faithful Owner Since Day 1! Authentic Mileage. Fully Maintained By Agent Since Day 1 Until 2010! Can Be Verified At C&C! Piece Of Mind Ensure You Get A Genuine KM Car! Superb Nice Condition! Good For COE Renewal. Don't Miss It Before It's Too Late.	Low Mileage Done. Well Maintained By Previous Owner. No Need More Explanation, The Brand Speak For Itself And No Repairs Needed, Lastly Accident Free. Contact Our Friendly Sales Consultant Today For Enquiries.	Promo 100% Loan Available. Promo 1.99%. C&C Unit, Well Taken Care By The Previous Owner. High Loan With High Trade In. Price Negotiable. Call Now.	Extremely Well Mai Serviced And Maint Popular Mercedes i A Refined And Pow Engine Giving You. Drive! Powerful Yet Flexible Bank/ In-i Trade In Most Web Before It's Gone!
COE	\$53,400	\$62,001	\$56,300	\$68,501
OMV	\$53,923	\$53,923	\$51,151	\$51,151
ARF	\$53,923	\$53,923	\$51,151	\$51,151
Depreciation	\$13,940 /yr	\$13,840 /yr	\$15,060 /yr	\$17,210 /yr
No. of Owners	1	2	2	3
Type of Vehicle	Luxury	Luxury	Luxury	Luxury
Category	PARF Car, Low Mileage Car	PARF Car, Premium Ad Car, Low Mileage Car	PARF Car	PARF Car, Premium
Availability	Available	Available	Available	Available

SELLER INFORMATION

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

8859J

Vehicle Details

Vehicle No.:

5KQ9810A

Vehicle to be Exported:

No

Intended Deregistration Date:

16 Jul 2019

Vehicle Make:

MERCEDES BENZ

Vehicle Model:

E 200CGI

Primary Colour:

Silver

Manufacturing Year:

2010

Engine No.:

27186030188184

Chassis No.:

WDD2120482A386810

Maximum Power Output:

135.0 kW (181 bhp)

Open Market Value:

\$53,923.00

Original Registration Date:

01 Apr 2011

First Registration Date:

01 Apr 2011

Transfer Count:

1

Actual ARF Paid:

\$53,923.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

31 Mar 2021

PARF Rebate Amount:

\$29,657.00

Intended COE Rebate Details

COE Expiry Date:

31 Mar 2021

COE Category:

E - Open Category

COE Period(Years):

10

QP Paid:

\$67,009.00

COE Rebate Amount:

\$10,055.00

Total Rebate Amount:

\$39,712.00

The information contained herein is correct as at 16 Jul 2019

OK

349886
39712
67009
10055
39712

Chany

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 15/07/2019 12:13
Date Of Accident 13/07/2019 16:50
Exact Location Of Accident PIONEER CENTRE SOON LEE STREET LEVEL 2
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKQ9810A
Insured/Policyholder
Name Of Registered Owner LEE KIM SIA
NRIC No S6938859J
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96221571
Alternative Phone No OFFICE-NOPHONE
Vehicle Particulars
Manufacturer MERCEDES-BENZ
Model E 200CGI
Exact Purpose for which vehicle was being used at time of accident PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number MT/00605992
Cover Note Number
Driver
Name of Driver HOU JINMEI
NRIC No S7683263C
Date Of Birth 07/11/1976
Occupation INDOOR
Date Of Driving Pass 10/05/2004
Driving Experience 15 YEARS AND 2 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-97723883
Fax Number
Contact Number
Email Address NOEMAIL

Address 197D BOON LAY DR #06-121
 Postcode 644197
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle
 Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TRAFFIC POLICE DIVISION HQ
 Police Station Address ROAD: 10 UBI AVENUE 3, POSTCODE: 408665, COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 65470000 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH AND POLICE REPORT T/20190715/7002

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBB5059P
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage



No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GX3244J
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name HOU JINMEI
Approximate Age 42
Injuries Sustain NECK BACK PAIN
Injured person in which vehicle? SKQ9810A
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address BLK 197D BOON LAY DR #05-121
Postcode 644197

SKETCH PLAN

SKQ9810A
13/07/2019

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13-07-2019 at about 16:00hrs I parked my vehicle at Pioneer Centre Unit No: 02-63. I was inside the vehicle waiting for customer. While waiting inside the vehicle, all of a sudden I felt an hard impact from the rear. then I realised a van GBX 5059P had collided onto my vehicle. Due to the hard impact, the said vehicle had collided onto another van that on stationing of GX 3244J.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

19-07-2019 16:00hrs

Sketch Plan #3 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180715/7002

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

1 of 3
Report No. T/20180715/7002

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/07/2019 10:28		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: HOU JINMEI			Address: APT BLK 197D BOON LAY DRIVE #06-121 SINGAPORE 844197		
ID Type / ID No.: NRIC NO / S7683263C			Contact No.: Home/Office: Mobile: 97723853		
Nationality: CHINESE			Email: houjinmei@gmail.com		
Sex: Female	Age: 42	Date of Birth: 07/11/1976	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Administration manager			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 13/07/2019 18:50	Type of Location: Straight Road
Location: SOON LEE STREET				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBB6059P	Van					1
GX3244J	Van					0
SKQ9810A	Car					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
-------------	-------------------	---------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20190715/7002

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190715/7002

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
GX3244J	MSIG INSURANCE (SINGAPORE) PTE. LTD.			

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver:			
Name	HOU JINMEI	ID No.	S7683263C
Related Vehicle	SKQ9810A (Car)	Contact No.	97723853
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details:

On said and time stated, i parked my vehicle at Pioneer Centre Unit No. 02-63. I was inside the vehicle waiting for customer. While waiting inside the vehicle, all of the sudden I felt an hard impact from the rear. Then I realised a van GBB6059P had collided onto my vehicle. Due to the hard impact, the said vehicle had swerve and collided onto another stationary vehicle of GX3244J. Due to the impact, I was given 5 days of mc



**SINGAPORE
POLICE FORCE**



T/20190715/7002

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

3 of 3
Report No. T/20190715/7002

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
ONG YONG HOCK
Contact No.: 65476436

Authentication Stamp
NP166

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
15/07/2019 10:28

Classification Of Case:

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO : CHINA TAIPING DATE : 15-Jul-19
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM
ESTIMATE REPORT :

OWNER'S PARTICULAR VEHICLE DETAILS
NAME : VEHICLE NO : SKQ9810A
ADDRESS : MODEL : MERCEDES E200
TEL. NO. : CHASSIS NO :
OWNER'S INSURANCE : WPD120422A386810
POLICY NO. :

ACCIDENT DETAILS DATE :
TIME :
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID Distorted	1	\$ 1,845.00	\$ 1,845.00
2	BOOTLID NUMBER INNER HANDLE Not New	1	\$ 54.00	\$ 54.00
3	BOOTLID LOGO ?	1	\$ 87.00	\$ 87.00
4	BOOTLID EMBLEM 'CGI' New	1	\$ 107.00	\$ 107.00
5	BOOTLID EMBLEM 'E200' ✓	1	\$ 87.00	\$ 87.00
6	BOOTLID STOPPER Not New	2	\$ 45.00	\$ 90.00
7	BOOTLID HINGE Bent	2	\$ 184.00	\$ 368.00
8	BOOTLID HINGE GARNISH Not New	2	\$ 159.00	\$ 318.00
9	BOOTLID TOP LOCK Damaged	1	\$ 589.00	\$ 589.00
10	BOOTLID LOWER LOCK Bent	1	\$ 48.00	\$ 48.00
11	BOOTLID WEATHER STRIP Lit	1	\$ 354.00	\$ 354.00
12	BOOTLID LAMP Not New	2	\$ 589.00	\$ 1,178.00
13	BOOTLID INNER TRIM Not New	1	\$ 554.00	\$ 554.00
14	BOOTLID CHROME MOULDING Curled	1	\$ 452.00	\$ 452.00
15	REAR NUMBER PLATE LAMP Not New	1	\$ 94.00	\$ 94.00
16	REAR BUMPER Distorted	1	\$ 2,154.00	\$ 2,154.00
17	REAR BUMPER LOWER Distorted	1	\$ 698.00	\$ 698.00

✓
x
✓
✓
✓
x
✓
x
297
✓
x
x
233
x
153
385

18	REAR BUMPER LOWER BRACKET <i>Not here</i>	2	\$ 78.00	\$ 156.00	x
19	REAR BUMPER TOWING COVER <i>Missing</i>	1	\$ 59.00	\$ 59.00	/
20	REAR BUMPER TOP CHROME (CENTER) <i>2</i>	1	\$ 198.00	\$ 198.00	/
21	REAR BUMPER TOP CHROME (SIDE) <i>1</i>	2	\$ 152.00	\$ 304.00	/
22	REAR BUMPER CENTER BRACKET <i>could</i>	1	\$ 187.00	\$ 187.00	/
23	REAR BUMPER CENTRE FRAME <i>Not here</i>	1	\$ 342.00	\$ 342.00	x
24	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 845.00	\$ 845.00	✓ 155
25	REAR BUMPER REINFORCEMENT BRACKET <i>Not here</i>	2	\$ 120.00	\$ 240.00	x
26	REAR BUMPER LOWER COVER <i>Not here</i>	2	\$ 331.00	\$ 662.00	x
27	TAILLAMP <i>LH could</i>	2	\$ 898.00	\$ 1,796.00	898.652
28	TAILLAMP PANEL <i>Repair</i>	2	\$ 699.00	\$ 1,398.00	x
29	TAILLAMP LOWER BRACKET <i>Not here</i>	2	\$ 112.00	\$ 224.00	x
30	REAR FENDER <i>Repair</i>	2	\$ 2,566.00	\$ 5,132.00	x
31	REAR FENDER TOP GARNISH <i>Not here</i>	2	\$ 159.00	\$ 318.00	x
32	REAR FENDER COWLING <i>Not here</i>	2	\$ 258.00	\$ 516.00	T
33	REAR FENDER INNER TRIM <i>Not here</i>	2	\$ 784.00	\$ 1,568.00	T
34	REAR WINDSCREEN WITH MOULDING <i>Not here</i>	1	\$ 2,144.00	\$ 2,144.00	T
35	REAR END PANEL <i>Distorted</i>	1	\$ 1,025.00	\$ 1,025.00	/
36	REAR END INNER PANEL <i>Distorted</i>	1	\$ 689.00	\$ 689.00	/
37	REAR END PANEL INNER GARNISH <i>Distorted</i>	1	\$ 321.00	\$ 321.00	/
38	REAR FLOOR PANEL <i>2 Not here</i>	1	\$ 2,487.00	\$ 2,487.00	x
39	REAR FLOOR PANEL TOP BOARD <i>1 Not here</i>	1	\$ 597.00	\$ 597.00	x
40	REAR FLOOR SIDE PANEL LH <i>Repair</i>	1	\$ 487.00	\$ 487.00	x
41	REAR EXHAUST BOX WITH CHROME PIPE <i>Not here</i>	1	\$ 2,894.00	\$ 2,894.00	x
42	REAR EXHAUST INSULATOR <i>2 Not here</i>	1	\$ 358.00	\$ 358.00	x
43	REAR EXHAUST MOUNTING <i>1 Not here</i>	4	\$ 97.00	\$ 388.00	x
44	REAR CHASSIS FRAME LH <i>Repair</i>	1	\$ 1,598.00	\$ 1,598.00	T
45	REVERSE SENSOR <i>2 Not here</i>	4	\$ 254.00	\$ 1,016.00	/
46	REVERSE SENSOR WIREHARNESS <i>Not here</i>	1	\$ 689.00	\$ 689.00	T

10443
9398.70

TOTAL PRICE \$ 37,715.00
LESS 10% \$ 3,771.50
SUB TOTAL PRICE \$ 33,943.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Not here</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP <i>Not here</i>	10	\$ 6.50	\$ 65.00
3	BOOTLID SEALANT <i>Not here</i>	1	\$ 80.00	\$ 80.00
4	BOOTLID INSULATOR CLIP <i>Not here</i>	10	\$ 6.50	\$ 65.00
5	BOOTLID MOULDING CLIP <i>Not here</i>	4	\$ 6.50	\$ 26.00
6	BOOTLID NUMBER PLATE GARNISH CLIP <i>Not here</i>	6	\$ 6.50	\$ 39.00
7	TAILLAMP CLIPS <i>Not here</i>	4	\$ 8.00	\$ 32.00

8	TAILLAMP PANEL SEALANT	2	\$ 80.00	\$ 160.00	X
9	REAR FENDER TOP GARNISH CLIP	8	\$ 6.50	\$ 52.00	X
10	REAR FENDER COWLING CLIPS	8	\$ 6.50	\$ 52.00	X
11	REAR FENDER INNER TRIM CLIPS	18	\$ 6.50	\$ 117.00	X
12	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	X
13	REAR WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	X
14	REAR END PANEL TOP GARNISH CLIPS	6	\$ 6.50	\$ 39.00	X
15	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00	X
16	REAR FLOOR PANEL INSULATION SEAL	1	\$ 250.00	\$ 250.00	X
17	REVERSE CAMERA	1	\$ 450.00	\$ 450.00	X

158 TOTAL \$ 1,817.00
1767

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 3,200.00	1200	
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,200.00	1200	
3	TUFF COAT	\$ 600.00	80	
4	WIRING CHECK	\$ 200.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 400.00	80	
6	TRANSFER BOOTLID MECHANISM	\$ 200.00	60	
7	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X	
8	REMOVE AND REFIX REAR WINDSCREEN GLASS	\$ 250.00	X	
9	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 150.00	X	
10	REAR CHASSIS ALIGNMENT	\$ 600.00	X	
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	150	

12 To repair and reset Handrest system.

TOTAL

\$8,550.00

TOTAL PARTS COST : \$ 35,760.50
TOTAL LABOUR COST : \$ 8,550.00
TOTAL REPAIR COST : \$ 44,310.50

APPROVED DETAILS

44860.50

Total 12706.70
4/5 10K (Nett Value)
09 Days

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19012738/ATD3N2
Date: 03/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30186919000
Claimant Vehicle No: SKQ9810A Insured Vehicle No: GBB5059P
Date of Loss: 13/07/2019 Nature of Claim: TP Claim No: SNM19D203340C03

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKQ9810A
Make & Model: MERCEDES-BENZ E200, 1.8 CGI (A) Engine No: 27186030188184
Reg. Date: 01/04/2011 (Man. Year: 2010) Chassis No: WDD2120482A386810
Colour: Silver Odometer: 123252 km
Engine Capacity: 1796 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45R17 Rear Tyre Size: 245/45R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,710.50	9,635.00	26,075.50	73.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,150.00	3,150.00	6,000.00	65.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,860.50	12,785.00	32,075.50	71.50
Approved Total (Overridden) (S\$)		10,000.00		
(S\$)	44,860.50	10,000.00	34,860.50	77.71
+ GST 7.00/7.00% (S\$)	3,140.24	700.00	2,440.24	77.71
Nett Amount (S\$)	48,000.74	10,700.00	37,300.74	77.71

INSPECTION

Date of Assignment: 02/03/2020
Date Inspected: 18/07/2019 Inspected At: 8 KAKI BUKIT AVE 4 #08-46 SK AUTOMOBILE PTE LTD
Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Mar 2020)	
Parts:	N/A	MERCEDES-BENZ E200 1.8 CGI (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ9810A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Distorted	1,845.00 FL	*1,845.00 FL
2	1		*BOOTLID NUMBER INNER HANDLE	Not Necessary	54.00 FL	*- FL
3	1		*BOOTLID LOGO	Necessary	87.00 FL	*87.00 FL
4	1		*BOOTLID EMBLEM CGI	Necessary	107.00 FL	*107.00 FL
5	1		*BOOTLID EMBLEM E200	Necessary	87.00 FL	*87.00 FL
6	2		*BOOTLID STOPPER	Not Necessary	90.00 FL	*- FL
7	2		*BOOTLID HINGE	Bent	368.00 FL	*368.00 FL
8	2		*BOOTLID HINGE GARNISH	Not Necessary	318.00 FL	*- FL
9	1		*BOOTLID TOP LOCK	Damaged	589.00 FL	*297.00 FL
10	1		*BOOTLID LOWER LOCK	Bent	48.00 FL	*48.00 FL
11	1		*BOOTLID WEATHER STRIP	Cut	354.00 FL	*354.00 FL
12	2		*BOOTLID LAMP	Not Necessary	1,178.00 FL	*- FL
13	1		*BOOTLID INNER TRIM	Not Necessary	554.00 FL	*- FL
14	1		*BOOTLID CHROME MOULDING	Cracked	452.00 FL	*233.00 FL
15	1		*REAR NUMBER PLATE LAMP	Not Necessary	94.00 FL	*- FL
16	1		*REAR BUMPER	Distorted	2,154.00 FL	*1,513.00 FL
17	1		*REAR BUMPER LOWER	Distorted	698.00 FL	*385.00 FL
18	2		*REAR BUMPER LOWER BRACKET	Not Necessary	156.00 FL	*- FL
19	1		*REAR BUMPER TOWING COVER	Missing	59.00 FL	*59.00 FL
20	1		*REAR BUMPER TOP CHROME (CENTER)	Necessary	198.00 FL	*198.00 FL
21	2		*REAR BUMPER TOP CHROME (SIDE)	Necessary	304.00 FL	*304.00 FL
22	1		*REAR BUMPER CENTER BRACKET	Cracked	187.00 FL	*187.00 FL
23	1		*REAR BUMPER CENTRE FRAME	Not Necessary	342.00 FL	*- FL
24	1		*REAR BUMPER REINFORCEMENT	Bent	845.00 FL	*755.00 FL
25	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	240.00 FL	*- FL
26	2		*REAR BUMPER LOWER COVER	Not Necessary	662.00 FL	*- FL
27	1		*TAILLAMP	N/s Cracked	1,796.00 FL	*652.00 FL
28	2		*TAILLAMP PANEL	Repair	1,398.00 FL	*- FL
29	2		*TAILLAMP LOWER BRACKET	Not Necessary	224.00 FL	*- FL
30	2		*REAR FENDER	Repair	5,132.00 FL	*- FL
31	2		*REAR FENDER TOP GARNISH	Not Necessary	318.00 FL	*- FL
32	2		*REAR FENDER COWLING	Not Necessary	516.00 FL	*- FL
33	2		*REAR FENDER INNER TRIM	Not Necessary	1,568.00 FL	*- FL
34	1		*REAR WINDSCREEN WITH MOULDING	Not Necessary	2,144.00 FL	*- FL
35	1		*REAR END PANEL	Distorted	1,025.00 FL	*1,025.00 FL
36	1		*REAR END INNER PANEL	Distorted	689.00 FL	*689.00 FL
37	1		*REAR END PANEL INNER GARNISH	Deformed	321.00 FL	*321.00 FL
38	1		*REAR FLOOR PANEL	Not Necessary	2,487.00 FL	*- FL
39	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	597.00 FL	*- FL
40	1		*REAR FLOOR SIDE PANEL LH	Repair	487.00 FL	*- FL
41	1		*REAR EXHAUST BOX WITH CHROME PIPE	Not Necessary	2,894.00 FL	*- FL
42	1		*REAR EXHAUST INSULATOR	Not Necessary	358.00 FL	*- FL
43	4		*REAR EXHAUST MOUNTING	Not Necessary	388.00 FL	*- FL
44	1		*REAR CHASSIS FRAME LH	Repair	1,598.00 FL	*- FL
45	4		*REVERSE SENSOR	Damaged	1,016.00 FL	*1,016.00 FL
46	1		*REVERSE SENSOR WIREHARNES	Not Necessary	689.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
48	10		*REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
49	1		*BOOTLID SEALANT	Not Necessary	80.00 FS	*- FS
50	10		*BOOTLID INSULATOR CLIP	Not Necessary	65.00 FS	*- FS
51	4		*BOOTLID MOULDING CLIP	Necessary	26.00 FS	*26.00 FS
52	6		*BOOTLID NUMBER PLATE GARNISH CLIP	Not Necessary	39.00 FS	*- FS
53	4		*TAILLAMP CLIPS	Necessary	32.00 FS	*32.00 FS
54	2		*TAILLAMP PANEL SEALANT	Not Necessary	160.00 FS	*- FS
55	8		*REAR FENDER TOP GARNISH CLIP	Not Necessary	52.00 FS	*- FS
56	8		*REAR FENDER COWLING CLIPS	Not Necessary	52.00 FS	*- FS
57	18		*REAR FENDER INNER TRIM CLIPS	Not Necessary	117.00 FS	*- FS
58	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
59	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
60	1		*REAR END PANEL TOP GARNISH CLIPS (6 Pcs)	Necessary	39.00 FS	*10.00 FS
61	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
62	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	250.00 FS	*- FS
63	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	39,482.00	10,688.00
- List Item Discount on L Items 10.00/10.00% (S\$)	3,771.50	1,053.00
Total Parts (S\$)	35,710.50	9,635.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	3,200.00	1,200.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,200.00	1,200.00
3	TUFF COAT	New	600.00	80.00
4	WIRING CHECK	New	200.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	400.00	80.00
6	TRANFER BOOTLID MECHANISM	New	200.00	60.00
7	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
8	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	250.00	0.00
9	REMOVE AND REFIX REAR EXHAUST PIPE	New	150.00	0.00
10	REAR CHASSIS ALIGNMENT	New	600.00	0.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	650.00	150.00
12	TO REPAIR AND RESET HEAD REST SYSTEM	New	600.00	350.00
Gross Labour Cost (\$\$)			9,150.00	3,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >