

22/07/2019

ASS. REC. BY:

REF: CS/FCI 190/2753/K+A3

n2

Special Instructions:

Surveyor: Kenneth

## ASSIGNMENT (Office)

CWS

From (Person): Joanne Yang

of

FCI

Date/Time: 5:48pm @ 18/7/19

Estimated Cost:

Bill to:

OD / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 9420X

Insured:

SHA 7827K

at Workshop m/s

Trans-Cab Auto

Tel:

62876666

of

No. 2 Amk st. 63

Policy No:

Claim No:

D19004609 MP&amp;H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12/7/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:10am @ 19/7/19

Person Contacted:

zhenei

Vehicle IN/OUT

Date/Time

Action/Instruction Estimate (✓)

SHD 9420X NA/INC17001453/h4

SHA 7827K CS/FCI18011703/T1rd 3n2 DOA=22/6/18

22/7-11:21am sent preli advise via email.

confirm with wai yin.

lump sum \$5150/- (Red 30 32072.43; 86%)

ASS. REC. BY:

REF:

F021

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S11D9402XYr Regn: 05, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy

c.c

1798Colour mp. white / Red

A/C: Insured / Std / NI / NA

Sp. Reading 11163

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKB3FU103080776Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD / Rlm or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 12/7/19D.O.I. 19/7/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 21 OCT 2019

Date/Time, File Pass to?

1) 21/10 Typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Prel. Report☒ : Final ReportDays Of Repair: 5

Resurvey No. of Trlp: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

) \$ - RS. SI

) Parking

) Others

Report Format: TP

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

5150

TOTAL

350



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004609MFSH

Date: 22/7/2019

Our Ref: CS/FCI19012753/Ktf3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 9420X

Please be informed that we had conducted the inspection of the abovementioned vehicle 19/7/2019 at the premises of M/s Trans-Cab Auto have the following to report: -

|                          |                                   |
|--------------------------|-----------------------------------|
| Workshop Estimate Amount | : S\$ <u>37,222.43</u>            |
| Revised Estimate Amount  | : S\$ <u>5,234.85</u>             |
| "Check" Items Amount     | : S\$ <u>3,877.25</u>             |
| Market Value             | : S\$ <u>                    </u> |
| LTA Reimbursement Value  | : S\$ <u>                    </u> |
| Nett Value               | : S\$ <u>                    </u> |

Description of Damage:

The vehicle sustained damages at the rear portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully  
Kenneth  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

|                    |                              |                               |
|--------------------|------------------------------|-------------------------------|
| Date               | 15-07-2019                   | Our Ref No. D19004609MFSH     |
| Accident Date      | 12-07-2019                   | Claim Type. Third Party       |
| Insured Vehicle    | SHA7827K                     | Third Party Vehicle. SHD9420X |
| Survey Location    | NO. 2 ANG MO KIO STREET 63   |                               |
| Contact Person.    | KEK ZHEWEI                   |                               |
| Contact No.        | 62876666/ 0                  | Fax No. 62571330              |
| Survey Type        | WITHOUT PREJUDICE:           |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD |                               |
| Contact Person     | NA                           | Fax No. 68416315              |
| Contact Number.    | NA                           |                               |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |                                 |                         |
|-------------------|---------------------------------|-------------------------|
| Cc : Workshop     | TRANS-CAB AUTO SERVICES PTE LTD | Attention. NIL          |
| Cc : TP Solicitor | NA                              | TP Solicitor Fax No. NA |
| Officer Incharge  | JOANNEY                         |                         |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Monday, 22 July 2019 11:21 AM  
**To:** Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments  
**Cc:** 'Joanne Yong'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19004609MFSH/1  
**Attachments:** PRELI ADVISED SHD 9420X.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 9420X**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Friday, 19 July 2019 10:12 AM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Joanne Yong' <[Joanneyong@msfirstcapital.com.sg](mailto:Joanneyong@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D19004609MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Thursday, 18 July 2019 5:48 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Joanne Yong <[Joanneyong@msfirstcapital.com.sg](mailto:Joanneyong@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19004609MFSH/1

## Denise Tay (LKKAUTO)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Thursday, 17 October 2019 4:44 PM  
**To:** Denise Tay (LKKAUTO)  
**Subject:** FW: SHD 9420X / FIRST CAPITAL / DOA: 12/7/2019 -- AAD1907-136  
**Attachments:** image002.wmz; shd 9420x estimate.pdf; FW: SHD 9420X / FIRST CAPITAL / DOA: 12/7/2019 -- AAD1907-136

Hi Denise

Amount confirmed \$ 5,150 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



### TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Denise Tay (LKKAUTO) [mailto:[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)]  
**Sent:** Thursday, 17 October, 2019 11:29 AM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** RE: SHD 9420X / FIRST CAPITAL / DOA: 12/7/2019 -- AAD1907-136

Dear Wai Yin,  
Can confirm?

Best Regards,  
**Denise Tay** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Friday, 11 October 2019 10:24 AM  
**To:** 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>  
**Subject:** RE: SHD 9420X / FIRST CAPITAL / DOA: 12/7/2019 -- AAD1907-136

Dear Wai Yin,

[> Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

|                |         |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID:      | 3878K   |

#### Vehicle Details

|                               |                            |
|-------------------------------|----------------------------|
| Vehicle No.:                  | SHD9420X                   |
| Vehicle to be Exported:       | Yes                        |
| Intended Deregistration Date: | 15 Jul 2019                |
| Vehicle Make:                 | TOYOTA                     |
| Vehicle Model:                | PRIUS 5DR HATCHBACK (AUTO) |
| Primary Colour:               | Red                        |
| Manufacturing Year:           | 2018                       |
| Engine No.:                   | 2ZR2C19940                 |
| Chassis No.:                  | JTDKB3FU103080776          |
| Maximum Power Output:         | 90.0 kW (120 bhp)          |
| Open Market Value:            | \$26,605.00                |
| Original Registration Date:   | 31 May 2019                |
| First Registration Date:      | 31 May 2019                |
| Transfer Count:               | 0                          |
| Actual ARF Paid:              | \$14,247.00                |

#### Intended PARF Rebate Details

|                               |             |
|-------------------------------|-------------|
| PARF Eligibility:             | Yes         |
| PARF Eligibility Expiry Date: | 30 May 2027 |
| PARF Rebate Amount:           | \$10,685.00 |

#### Intended COE Rebate Details

|                             |                                      |
|-----------------------------|--------------------------------------|
| COE Expiry Date:            | 30 May 2027                          |
| COE Category:               | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):          | 8                                    |
| PQP Paid:                   | \$22,309.00                          |
| COE Rebate Amount:          | \$17,847.00                          |
| <b>Total Rebate Amount:</b> | <b>\$28,532.00</b>                   |

#### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Jul 2019

OK

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9420X****AAD1907-136***Not Authorized  
Personnel By paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

19 JUL 2019

**SHD 9420X**

JTDKB3FU103080776

TOYOTA

PRIUS

12.7.19

**FIRST CAPITAL**

31/5/2019

|    |   | PART                                          | LIST     |          |   |
|----|---|-----------------------------------------------|----------|----------|---|
| 1  | 1 | REAR BUMPER                                   | \$ Bu    | 458.60   | ✓ |
| 2  | 1 | REAR BUMPER RE-INFORCEMENT                    | \$ B1    | 318.80   | ✓ |
| 3  | 1 | REAR BUMPER TOWING COVER                      | \$ 7d    | 14.70    | ✓ |
| 4  | 1 | REAR BUMPER UNDER COVER (BLACK)               | \$ BT12u | 552.60   | ✓ |
| 5  | 1 | REAR BUMPER SIDE RETAINER LH                  | \$ D11   | 112.70   | ✓ |
| 6  | 1 | REAR BUMPER SIDE RETAINER RH                  | \$ D11   | 112.70   | ✓ |
| 7  | 1 | REAR TAILGATE                                 | \$ B1    | 1,547.27 | ✓ |
| 8  | 1 | REAR TAILGATE OUTER GARNISH                   | \$ mg1m  | 905.10   | ✓ |
| 9  | 1 | ANTENNA, ELECTRICAL KEY                       | \$ Su    | 61.40    | X |
| 10 | 1 | COVER, REAR COMBINATION LAMP, RH              | \$ Su    | 54.70    | X |
| 11 | 1 | COVER, REAR COMBINATION LAMP, RH              | \$ Su    | 54.70    | ✓ |
| 12 | 1 | GARNISH, BACK DOOR SIDE, LH                   | \$ Su    | 93.60    | X |
| 13 | 1 | GARNISH, BACK DOOR SIDE, RH                   | \$ Su    | 93.60    | ✓ |
| 14 | 1 | MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH | \$ Su    | 55.40    | X |
| 15 | 1 | MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH | \$ Su    | 55.40    | X |
| 16 | 1 | BOARD ASSY, BACK DOOR TRIM                    | \$ Su    | 254.40   | X |
| 17 | 1 | PANEL ASSY, BACK DOOR TRIM, UPPER             | \$ Su    | 51.20    | X |
| 18 | 1 | REAR TAILGATE WEATHERSTRIP                    | \$ Su    | 365.20   | ✓ |
| 19 | 1 | REAR END PANEL                                | \$ B1    | 602.10   | ✓ |
| 20 | 1 | TAILLAMP LOWER RH                             | \$ Su    | 548.40   | X |
| 21 | 1 | TAILLAMP UPPER RH                             | \$ Su    | 557.90   | X |
| 22 | 1 | REAR BUMPER SIDE RH                           | \$ Su    | 232.00   | X |
| 23 | 1 | REAR BUMPER SIDE LH                           | \$ Su    | 232.00   | X |
| 24 | 1 | TAILLAMP LOWER LH                             | \$ Su    | 548.40   | X |
| 25 | 1 | TAILLAMP UPPER LH                             | \$ mg1m  | 557.90   | ✓ |
| 26 | 1 | REAR FENDER RH                                | \$ R     | 817.50   | X |
| 27 | 1 | REAR FENDER LH                                | \$ R     | 817.50   | X |
| 28 | 1 | LINER, REAR WHEEL HOUSE, LH                   | \$ R     | 138.10   | X |
| 29 | 1 | LINER, REAR WHEEL HOUSE, RH                   | \$ R     | 138.10   | X |

**Trans-cab Auto Services Pte Ltd****AAD1907-136**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9420X**

|              |   |                                                |           |    |                  |   |
|--------------|---|------------------------------------------------|-----------|----|------------------|---|
| 30           | 1 | BOARD, BACK DOOR TRIM                          | \$        | PH | 220.70           |   |
| 31           | 1 | PANEL ASSY, DECK TRIM SIDE, RH                 | \$        | SH | 351.10           |   |
| 32           | 1 | PANEL ASSY, DECK TRIM SIDE, LH                 | \$        | PH | 351.10           |   |
| 33           | 1 | PANEL SUB-ASSY, QUARTER, LH                    | \$        | N  | 836.70           |   |
| 34           | 1 | PANEL, QUARTER WHEEL HOUSE, OUTER LH           | \$        | N  | 290.50           |   |
| 35           | 1 | PANEL SUB-ASSY, QUARTER, RH                    | \$        | N  | 836.70           |   |
| 36           | 1 | PANEL, QUARTER WHEEL HOUSE, OUTER RH           | \$        | N  | 290.50           |   |
| 37           | 1 | COVER, FLOOR UNDER, NO.1                       | \$        | SH | 172.60           |   |
| 38           | 1 | COVER, FLOOR UNDER, NO.2                       | \$        | SH | 238.70           |   |
| 39           | 1 | COVER, REAR FLOOR                              | \$        | PH | 226.80           |   |
| 40           | 1 | PAN, REAR FLOOR                                | \$        | N  | 572.10           |   |
| 41           | 1 | EXTENSION, REAR FLOOR SIDE PANEL, RH           | \$        | N  | 77.00            |   |
| 42           | 1 | EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH | \$        | N  | 192.90           |   |
| 43           | 1 | EXTENSION, REAR FLOOR SIDE PANEL, LH           | \$        | N  | 77.00            |   |
| 44           | 1 | EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH | \$        | N  | 192.90           |   |
| 45           | 1 | PANEL SUB-ASSY, BODY LOWER BACK                | \$        | N  | 641.50           |   |
| 46           | 1 | PIPE ASSY, EXHAUST, TAIL                       | \$        | N  | 1,409.20         | X |
| 47           | 1 | SUPPORT, EXHAUST PIPE, NO.4                    | \$        | N  | 41.90            | X |
| 48           | 1 | SUPPORT, EXHAUST PIPE, NO.5                    | \$        | N  | 41.90            | X |
| <b>TOTAL</b> |   |                                                | <b>\$</b> |    | <b>17,413.77</b> |   |
| <b>25%</b>   |   |                                                | <b>\$</b> |    | <b>4,353.44</b>  |   |
|              |   |                                                | <b>\$</b> |    | <b>13,060.33</b> |   |

**Special Nett**

|    |      |                                   |    |    |          |      |
|----|------|-----------------------------------|----|----|----------|------|
| 1  | 1SET | PARKING AID                       | \$ | PH | 700.00   | 2000 |
| 2  | 1SET | REAR BUMPER CLIP                  | \$ | N  | 66.00    | —    |
| 3  | 2    | REAR WINDSCREEN SEALANT           | \$ | N  | 80.00    | 4000 |
| 4  | 1    | WINDSCREEN MOULDING               | \$ | N  | 100.00   | —    |
| 5  | 1    | REAR WINDSCREEN INNER SPONGE SEAL | \$ | N  | 100.00   | 3000 |
| 6  | 1    | REAR TAILGATE TOYOTA LOGO         | \$ | N  | 47.00    | —    |
| 7  | 1    | REAR TAILGATE WORDING 'PRIUS'     | \$ | N  | 52.90    | —    |
| 8  | 1    | REAR TAILGATE WORDING 'HYBRID'    | \$ | N  | 53.50    | —    |
| 9  | 1    | REAR TAILGATE STICKER 'TRANS-CAB' | \$ | N  | 80.00    | 3000 |
| 10 | 1    | REAR TAILGATE STICKER '6555-3333' | \$ | N  | 80.00    | 3000 |
| 11 | 1    | REAR BUMPER PROTECTOR             | \$ | N  | 100.00   | 4000 |
| 12 | 1    | REAR WHEEL RIM                    | \$ | SH | 1,570.55 | X    |
| 13 | 1    | REAR WHEEL RIM COVER              | \$ | SH | 175.80   | X    |
| 14 | 1    | SPARE WHEEL RIM                   | \$ | SH | 1,570.55 | X    |

**Trans-cab Auto Services Pte Ltd****AAD1907-136**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9420X**

|              |      |                               |    |           |                 |   |
|--------------|------|-------------------------------|----|-----------|-----------------|---|
| 15           | 1    | SPARE WHEEL RIM COVER         | \$ | <i>ph</i> | 175.80          | X |
| 16           | 1SET | FENDER WHEELARCH REAR LH CLIP | \$ | <i>nn</i> | 35.00           | X |
| 17           | 1SET | FENDER WHEELARCH REAR RH CLIP | \$ | <i>nn</i> | 35.00           | X |
| <b>TOTAL</b> |      |                               | \$ |           | <b>5,022.10</b> |   |

**TOTAL PARTS \$ 18,082.43****LABOUR**

|                                                                                                                           |    |                  |             |
|---------------------------------------------------------------------------------------------------------------------------|----|------------------|-------------|
| To transfer of Tailgate fittings, attachments and perform water seepage test.                                             | \$ | 170.00           | <i>601</i>  |
| To Rust-Proofing Of The Affected Areas.                                                                                   | \$ | 170.00           | <i>601</i>  |
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$ | 7,500.00         | <i>8801</i> |
| To transfer of Rear Bumper fittings, attachments and perform water seepage test.                                          | \$ | <i>nn</i> 170.00 | X           |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 7,500.00         | <i>6001</i> |
| To reinstall rear bumper parking sensor.                                                                                  | \$ | 170.00           | <i>501</i>  |
| To transfer of rear windscreen fittings and conduct water seepage test.                                                   | \$ | 170.00           | <i>1201</i> |
| To transfer of rear end panel fittings, attachment and perform water seepage test.                                        | \$ | 170.00           | <i>601</i>  |
| To check steering geometry and computer wheel alignment                                                                   | \$ | <i>nn</i> 220.00 | X           |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$ | <i>nn</i> 170.00 | X           |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 170.00           | <i>201</i>  |
| To transfer of rear fender fittings, attachment and perform water seepage test.                                           | \$ | <i>nn</i> 380.00 | X           |

**Trans-cab Auto Services Pte Ltd**

AAD1907-136

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9420X

To apply paint protection system (PPS) maintain and enhancement

\$ *nn* 380.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

To supply and re-do rear luggage floor panel insulation padding.

\$ *nn* 380.00 X

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.

\$ *nn* 170.00 X

Towing Fees

\$ *nn* 150.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.

\$ *nn* 170.00 ?

To repair and realign rear exhaust pipe.

\$ *Repeater* 170.00 X**TOTAL \$ 19,140.00****Over All Total \$ 37,222.43****(PART-BY-PART) Repair Days**~~25 Days~~

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |                                                                       |                                 |                                                                                     |
|-------------------------------------------------------------------|-----------------------------------------------------------------------|---------------------------------|-------------------------------------------------------------------------------------|
| MS FIRST CAPITAL INSURANCE LTD                                    |                                                                       | Ref : CS/FCI19012753/Ktf3n2     |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877             |                                                                       | Date : 24-10-2019               |  |
|                                                                   |                                                                       | Code : FCI2                     |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                 |                                                                       |                                 |                                                                                     |
|                                                                   | Insured Veh.                                                          | SHA 7827K                       | Veh. Inspected                                                                      |
|                                                                   |                                                                       |                                 | SHD 9420X                                                                           |
|                                                                   | Policy No.                                                            |                                 | Coverage (\$)                                                                       |
|                                                                   |                                                                       |                                 | 0.00                                                                                |
|                                                                   | Claim No.                                                             | D19004609MFSH                   | Excess (\$)                                                                         |
|                                                                   |                                                                       |                                 | 0.00                                                                                |
|                                                                   | Assign From                                                           | JOANNE YONG                     | Assign Date                                                                         |
|                                                                   |                                                                       |                                 | 18/07/2019                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                     |                                                                       |                                 |                                                                                     |
|                                                                   | Make & Model                                                          | TOYOTA PRIUS (A)                | c.c                                                                                 |
|                                                                   |                                                                       |                                 | 1798                                                                                |
|                                                                   | Engine No.                                                            | HIDDEN                          | Year of Reg.                                                                        |
|                                                                   |                                                                       |                                 | 2019                                                                                |
|                                                                   | Chassis No.                                                           | JTDKB3FU103080776               | Colour                                                                              |
|                                                                   |                                                                       |                                 | M.P.WHITE / RED                                                                     |
|                                                                   | Odometer                                                              | 11163                           | Steering                                                                            |
|                                                                   |                                                                       |                                 | IN ORDER                                                                            |
|                                                                   | Brakes                                                                | IN ORDER                        | Modification                                                                        |
|                                                                   |                                                                       |                                 | STANDARD ALLOY RIM                                                                  |
|                                                                   | General                                                               | GOOD                            |                                                                                     |
|                                                                   |                                                                       |                                 |                                                                                     |
| <b>3. Conditions of Tyres</b>                                     |                                                                       |                                 |                                                                                     |
|                                                                   |                                                                       | Size                            | Make                                                                                |
|                                                                   |                                                                       |                                 | Balance                                                                             |
|                                                                   | R/H Front Tyre                                                        | 195/65 R15                      | YOKOHAMA                                                                            |
|                                                                   |                                                                       |                                 | 9 mm                                                                                |
|                                                                   | L/H Front Tyre                                                        | 195/65 R15                      | YOKOHAMA                                                                            |
|                                                                   |                                                                       |                                 | 9 mm                                                                                |
|                                                                   | R/H Rear Tyre                                                         | 195/65 R15                      | YOKOHAMA                                                                            |
|                                                                   |                                                                       |                                 | 9 mm                                                                                |
|                                                                   | L/H Rear Tyre                                                         | 195/65 R15                      | YOKOHAMA                                                                            |
|                                                                   |                                                                       |                                 | 9 mm                                                                                |
| <b>4. Description of Damages</b>                                  |                                                                       |                                 |                                                                                     |
|                                                                   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.                    |                                 |                                                                                     |
|                                                                   | DAMAGES SEE DETAILS.                                                  |                                 |                                                                                     |
| <b>5. General Information</b>                                     |                                                                       |                                 |                                                                                     |
|                                                                   | Accident Date                                                         | 12/07/2019                      | Inspection Date                                                                     |
|                                                                   |                                                                       |                                 | 19/07/2019                                                                          |
|                                                                   | Survey held at                                                        | TRANS-CAB AUTO SERVICES PTE LTD |                                                                                     |
|                                                                   |                                                                       | NO.2 ANG MO KIO ST 63           |                                                                                     |
|                                                                   |                                                                       | SINGAPORE 569111                |                                                                                     |
| <b>5a. Remarks</b>                                                |                                                                       |                                 |                                                                                     |
|                                                                   | A)DAMAGES CONSISTENT TO ACCIDENT REPORT.                              |                                 |                                                                                     |
|                                                                   | B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.         |                                 |                                                                                     |
|                                                                   | C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                 |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                |                                                                       |                                 |                                                                                     |
|                                                                   | ESTIMATED NORMAL PERIOD FOR REPAIR:                                   |                                 | <b>5 Working Days</b>                                                               |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9420X

| Qty | Description of Parts                        | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>                 |                      |                           |                   |
| 1   | REAR BUMPER                                 | BUCKLED              | 458.60                    | 458.60            |
| 1   | REAR BUMPER RE-INFORCEMENT                  | BENT                 | 318.80                    | 318.80            |
| 1   | REAR BUMPER TOWING COVER                    | DENTED               | 14.70                     | 14.70             |
| 1   | REAR BUMPER UNDER COVER (BLACK)             | BENT / DENTED        | 552.60                    | 552.60            |
| 1   | REAR BUMPER SIDE RETAINER LH                | DISTORTED            | 112.70                    | 112.70            |
| 1   | REAR BUMPER SIDE RETAINER RH                | DISTORTED            | 112.70                    | 112.70            |
| 1   | REAR TAILGATE                               | BENT                 | 1,547.27                  | 1,547.27          |
| 1   | REAR TAILGATE OUTER GARNISH                 | MTG CRACKED          | 905.10                    | 905.10            |
| 1   | ANTENNA,ELECTRICAL KEY                      | SERVICEABLE          | 61.40                     | -                 |
| 1   | COVER,REAR COMBINATION LAMP,RH              | SERVICEABLE          | 54.70                     | -                 |
| 1   | COVER,REAR COMBINATION LAMP,RH              | SERVICEABLE          | 54.70                     | -                 |
| 1   | GARNISH,BACK DOOR SIDE,LH                   | SERVICEABLE          | 93.60                     | -                 |
| 1   | GARNISH,BACK DOOR SIDE,RH                   | SERVICEABLE          | 93.60                     | -                 |
| 1   | MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER RH | SERVICEABLE          | 55.40                     | -                 |
| 1   | MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER LH | SERVICEABLE          | 55.40                     | -                 |
| 1   | BOARD ASSY,BACK DOOR TRIM                   | SERVICEABLE          | 254.40                    | -                 |
| 1   | PANEL ASSY,BACK DOOR TRIM,UPPER             | SERVICEABLE          | 51.20                     | -                 |
| 1   | REAR TAILGATE WEATHERSTRIP                  | SERVICEABLE          | 365.20                    | -                 |
| 1   | REAR END PANEL                              | BENT                 | 602.10                    | 602.10            |
| 1   | TAILLAMP LOWER RH                           | SERVICEABLE          | 548.40                    | -                 |
| 1   | TAILLAMP UPPER RH                           | SERVICEABLE          | 557.90                    | -                 |
| 1   | REAR BUMPER SIDE RH                         | SERVICEABLE          | 232.00                    | -                 |
| 1   | REAR BUMPER SIDE LH                         | SERVICEABLE          | 232.00                    | -                 |
| 1   | TAILLAMP LOWER LH                           | SERVICEABLE          | 548.40                    | -                 |
| 1   | TAILLAMP UPPER LH                           | MTG CRACKED          | 557.90                    | 557.90            |
| 1   | REAR FENDER RH                              | TO REPAIR SEE LABOUR | 817.50                    | -                 |
| 1   | REAR FENDER LH                              | TO REPAIR SEE LABOUR | 817.50                    | -                 |
| 1   | LINER,REAR WHEEL HOUSE,LH                   | TO REPAIR SEE LABOUR | 138.10                    | -                 |

Report Ref No. CS/FCI19012753/Ktf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

| Qty | Description of Parts                         | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | LINER,REAR WHEEL HOUSE,RH                    | TO REPAIR SEE LABOUR | 138.10                    | -                 |
| 1   | BOARD,BACK DOOR TRIM                         | SERVICEABLE          | 220.70                    | -                 |
| 1   | PANEL ASSY,DECK TRIM SIDE,RH                 | SERVICEABLE          | 351.10                    | -                 |
| 1   | PANEL ASSY,DECK TRIM SIDE,LH                 | SERVICEABLE          | 351.10                    | -                 |
| 1   | PANEL SUB-ASSY,QUARTER,LH                    | TO REPAIR SEE LABOUR | 836.70                    | -                 |
| 1   | PANEL,QUARTER WHEEL HOUSE,OUTER LH           | TO REPAIR SEE LABOUR | 290.50                    | -                 |
| 1   | PANEL SUB-ASSY,QUARTER,RH                    | TO REPAIR SEE LABOUR | 836.70                    | -                 |
| 1   | PANEL,QUARTER WHEEL HOUSE,OUTER RH           | TO REPAIR SEE LABOUR | 290.50                    | -                 |
| 1   | COVER,FLOOR UNDER,NO 1                       | SERVICEABLE          | 172.60                    | -                 |
| 1   | COVER,FLOOR UNDER,NO 2                       | SERVICEABLE          | 238.70                    | -                 |
| 1   | COVER,REAR FLOOR                             | SERVICEABLE          | 226.80                    | -                 |
| 1   | PAN,REAR FLOOR                               | TO REPAIR SEE LABOUR | 572.10                    | -                 |
| 1   | EXTENSION,REAR FLOOR SIDE PANEL,RH           | TO REPAIR SEE LABOUR | 77.00                     | -                 |
| 1   | EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,LH | TO REPAIR SEE LABOUR | 192.90                    | -                 |
| 1   | EXTENSION,REAR FLOOR SIDE PANEL,LH           | TO REPAIR SEE LABOUR | 77.00                     | -                 |
| 1   | EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,RH | TO REPAIR SEE LABOUR | 192.90                    | -                 |
| 1   | PANEL SUB-ASSY,BODY LOWER BACK               | TO REPAIR SEE LABOUR | 641.50                    | -                 |
| 1   | PIPE ASSY,EXHAUST,TAIL                       | TO REPAIR SEE LABOUR | 1,409.20                  | -                 |
| 1   | SUPPORT,EXHAUST PIPE,NO 4                    | TO REPAIR SEE LABOUR | 41.90                     | -                 |
| 1   | SUPPORT,EXHAUST PIPE,NO 5                    | TO REPAIR SEE LABOUR | 41.90                     | -                 |
|     | LESS 25% DISCOUNT                            |                      | -4,353.44                 | -1,295.62         |
|     |                                              |                      | 13,060.33                 | 3,886.85          |
|     | <b>SPECIAL NETT ITEMS</b>                    |                      |                           |                   |
| 1   | SET PARKING AID (SN)                         | DENTED               | 700.00                    | 200.00            |

Report Ref No. CS/FCI19012753/Ktf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

| Qty                                                                                                                                                                                     | Description of Parts                   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|---------------|---------------------------|-------------------|
| 1                                                                                                                                                                                       | SET REAR BUMPER CLIP (SN)              | NECESSARY     | 66.00                     | 66.00             |
| 2                                                                                                                                                                                       | REAR WINDSCREEN SEALANT (SN)           | NECESSARY     | 80.00                     | 40.00             |
| 1                                                                                                                                                                                       | WINDSCREEN MOULDING (SN)               | NECESSARY     | 100.00                    | 100.00            |
| 1                                                                                                                                                                                       | REAR WINDSCREEN INNER SPONGE SEAL (SN) | NECESSARY     | 100.00                    | 30.00             |
| 1                                                                                                                                                                                       | REAR TAILGATE TOYOTA LOGO (SN)         | NECESSARY     | 47.00                     | 47.00             |
| 1                                                                                                                                                                                       | REAR TAILGATE WORDING "PRIUS" (SN)     | NECESSARY     | 52.90                     | 52.90             |
| 1                                                                                                                                                                                       | REAR TAILGATE WORDING "HYBRID" (SN)    | NECESSARY     | 53.50                     | 53.50             |
| 1                                                                                                                                                                                       | REAR TAILGATE STICKER "TRANS-CAB" (SN) | NECESSARY     | 80.00                     | 30.00             |
| 1                                                                                                                                                                                       | REAR TAILGATE STICKER "6555-3333" (SN) | NECESSARY     | 80.00                     | 30.00             |
| 1                                                                                                                                                                                       | REAR BUMPER PROTECTOR (SN)             | NECESSARY     | 100.00                    | 40.00             |
| 1                                                                                                                                                                                       | REAR WHEEL RIM (SN)                    | SERVICEABLE   | 1,570.55                  | -                 |
| 1                                                                                                                                                                                       | REAR WHEEL RIM COVER (SN)              | SERVICEABLE   | 175.80                    | -                 |
| 1                                                                                                                                                                                       | SPARE WHEEL RIM (SN)                   | SERVICEABLE   | 1,570.55                  | -                 |
| 1                                                                                                                                                                                       | SPARE WHEEL RIM COVER (SN)             | SERVICEABLE   | 175.80                    | -                 |
| 1                                                                                                                                                                                       | SET FENDER WHEELARCH REAR LH CLIP (SN) | NOT NECESSARY | 35.00                     | -                 |
| 1                                                                                                                                                                                       | SET FENDER WHEELARCH REAR RH CLIP (SN) | NOT NECESSARY | 35.00                     | -                 |
|                                                                                                                                                                                         |                                        |               | 5,022.10                  | 689.40            |
| <b>LABOUR</b>                                                                                                                                                                           |                                        |               |                           |                   |
| TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.                                                                                                           |                                        |               | 170.00                    | 60.00             |
| TO RUST-PROOFING OF THE AFFECTED AREAS.                                                                                                                                                 |                                        |               | 170.00                    | 60.00             |
| PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.                                                                                                                                       |                                        |               | 7,500.00                  | 880.00            |
| TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.                                                                                                        |                                        | NOT NECESSARY | 170.00                    | -                 |
| PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR FENDER RH, REAR FENDER LH. } |                                        |               | 7,500.00                  | 600.00            |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

| Qty | Description of Parts                                                                                                                                                                                                                                                                                                                                                                                                                                                          | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|     | LINER,REAR WHEEL HOUSE,LH,LINER,REAR WHEEL HOUSE,RH,PANEL SUB-ASSY,QUARTER,LH,PANEL,QUARTER WHEEL HOUSE,OUTER LH,PANEL SUB-ASSY,QUARTER,RH,PANEL,QUARTER WHEEL HOUSE,OUTER RH,PAN,REAR FLOOR,EXTENSION,REAR FLOOR SIDE PANEL,RH,EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,LH,EXTENSION,REAR FLOOR SIDE PANEL,LH,EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,RH,PANEL SUB-ASSY,BODY LOWER BACK,PIPE ASSY,EXHAUST,TAIL,SUPPORT, EXHAUST PIPE,NO 4 AND SUPPORT,EXHAUST PIPE,NO 5.) |               | -                         | -                 |
|     | TO REINSTALL REAR BUMPER PARKING SENSOR.                                                                                                                                                                                                                                                                                                                                                                                                                                      |               | 170.00                    | 50.00             |
|     | TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.                                                                                                                                                                                                                                                                                                                                                                                                       |               | 170.00                    | 120.00            |
|     | TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                                                                                                                                                                                                                                                                                                                                                                             |               | 170.00                    | 60.00             |
|     | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.                                                                                                                                                                                                                                                                                                                                                                                                                      | NOT NECESSARY | 220.00                    | -                 |
|     | TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.                                                                                                                                                                                                                                                                                                                                                                                                                               | NOT NECESSARY | 170.00                    | -                 |
|     | TO CHECK ELECTRICAL LIGHTING CONCERNED.                                                                                                                                                                                                                                                                                                                                                                                                                                       |               | 170.00                    | 20.00             |
|     | TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                                                                                                                                                                                                                                                                                                                                                                                | NOT NECESSARY | 380.00                    | -                 |
|     | TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.                                                                                                                                                                                                                                                                                                                                                                                                              | NOT NECESSARY | 380.00                    | -                 |
|     | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.                                                                                                                                                                                                                                                                                                                                                                                  | NOT NECESSARY | 380.00                    | -                 |
|     | TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.                                                                                                                                                                                                                                                                                                                                                                                                              | NOT NECESSARY | 380.00                    | -                 |
|     | TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                                                                                                                                                                                                                                                                                                                                                                   | NOT NECESSARY | 170.00                    | -                 |
|     | TOWING FEES.                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | NOT NECESSARY | 150.00                    | -                 |
|     | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.                                                                                                                                                                                                                                                                                                                                                                                                | NOT NECESSARY | 380.00                    | -                 |
|     | TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.                                                                                                                                                                                                                                                                                                                                                                                            | NOT NECESSARY | 170.00                    | -                 |

Report Ref No. CS/FCI19012753/Ktf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

| Qty                                                                     | Description of Parts                     | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-------------------------------------------------------------------------|------------------------------------------|-----------|---------------------------|-------------------|
|                                                                         | TO REPAIR AND REALIGN REAR EXHAUST PIPE. | REPEATED  | 170.00                    | -                 |
|                                                                         |                                          |           | 19,140.00                 | 1,850.00          |
| GRAND TOTAL                                                             |                                          |           | 37,222.43                 | 6,426.25          |
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |                                          |           |                           | 5,150.00          |

Report Ref No. CS/FCI19012753/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.