

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Jul 2019 Edit Reg		18 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: MR LOW FIE WAH , ID: S0010256C									
Main Claimant: ROSET LIMOUSINE SERVICES OTE LTD , Co. Reg. No.: 200406722Z									
Vehicle Reg. No.: SMK3793M		Date of Loss: 17/07/2019 09:00 - :59 [3 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1178839903SG		Policy/Cover Note No.: 1700044706 (Comprehensive)							
Vehicle Reg. No. (Insured): SLR1909K		Policy No. (Claimant): SD18V12322/VPZ/R00							
Excess:									
Repairer: Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng]									
Claimant's Insurer: Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 30/07/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (25/07/2019): Re: Request To Upload TP GIA Report - AIG_SG (22/07/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMK3793M (1178839903SG)**
[SLR1909K]
TP
ROSET LIMOUSINE SERVICES OTE LTD
Jul 17 2019 9:00AM
[MR LOW FIE WAH]
Teamwork Garage Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Assessment Reports					1 per page	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	25/07/19 14:32	Accident Statement From:OD - Reg. No: SLR1909K, Claimant: LOW FIE WAH		Load HTM		

Photos/Images					3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	20/08/19 14:45	General View		Load JPG		
2	20/08/19 14:45	General View		Load JPG		
3	20/08/19 14:45	General View		Load JPG		
4	20/08/19 14:45	General View		Load JPG		
5	20/08/19 14:45	General View		Load JPG		
6	20/08/19 14:45	General View		Load JPG		
7	20/08/19 14:45	General View		Load JPG		
8	20/08/19 14:45	General View		Load JPG		
9	20/08/19 14:45	General View		Load JPG		
10	20/08/19 14:45	General View		Load JPG		
11	20/08/19 14:45	General View		Load JPG		
12	20/08/19 14:45	General View		Load JPG		
13	20/08/19 14:45	General View		Load JPG		
14	20/08/19 14:45	General View		Load JPG		
15	20/08/19 14:45	General View		Load JPG		
16	20/08/19 14:45	General View		Load JPG		
17	20/08/19 14:45	General View		Load JPG		
18	20/08/19 14:45	General View		Load JPG		
19	20/08/19 14:45	General View		Load JPG		
20	20/08/19 14:45	General View		Load JPG		
21	20/08/19 14:45	General View		Load JPG		
22	20/08/19 14:45	General View		Load JPG		
23	20/08/19 14:46	General View		Load JPG		
24	20/08/19 14:46	General View		Load JPG		
25	20/08/19 14:46	General View		Load JPG		
26	20/08/19 14:46	General View		Load JPG		
27	20/08/19 14:46	General View		Load JPG		
28	20/08/19 14:46	General View		Load JPG		
29	20/08/19 14:46	General View		Load JPG		
30	20/08/19 15:00	Chassis Number		Load JPG		
31	20/08/19 15:10	Odometer Reading		Load JPG		
32	20/08/19 15:13	Reinspection Photo		Load JPG		
33	20/08/19 15:13	Reinspection Photo		Load JPG		
34	20/08/19 15:13	Reinspection Photo		Load JPG		
35	20/08/19 15:13	Reinspection Photo		Load JPG		
36	20/08/19 15:13	Reinspection Photo		Load JPG		

Assessment Reports				1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
37	20/08/19 15:13	Reinspection Photo		Load JPG	✓
38	20/08/19 15:13	Reinspection Photo		Load JPG	✓
39	20/08/19 15:13	Reinspection Photo		Load JPG	✓
40	20/08/19 15:13	Reinspection Photo		Load JPG	✓
41	20/08/19 15:13	Reinspection Photo		Load JPG	✓
42	20/08/19 15:13	Reinspection Photo		Load JPG	✓
43	20/08/19 15:13	Reinspection Photo		Load JPG	✓
44	20/08/19 15:14	Reinspection Photo		Load JPG	✓
45	20/08/19 15:14	Reinspection Photo		Load JPG	✓
46	20/08/19 15:14	Reinspection Photo		Load JPG	✓
47	20/08/19 15:14	Reinspection Photo		Load JPG	✓
48	20/08/19 15:14	Reinspection Photo		Load JPG	✓
49	20/08/19 15:14	Reinspection Photo		Load JPG	✓
50	20/08/19 15:14	Reinspection Photo		Load JPG	✓
51	20/08/19 15:14	Reinspection Photo		Load JPG	✓
52	20/08/19 15:14	Reinspection Photo		Load JPG	✓
53	20/08/19 15:14	Reinspection Photo		Load JPG	✓
54	20/08/19 15:14	Reinspection Photo		Load JPG	✓

Documentation				1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/07/19 14:25	EMAIL FROM AIG DD 18072019		Load PDF	
2	25/07/19 10:12	TP GIA REPORT		Load PDF	
3	06/08/19 13:53	LETTER TO OI		Load PDF	
4	26/03/20 11:15	EMAIL FROM AIG DD 260320		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG19012776/HEA3S2**Date:** 09/04/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700044706
Claimant Vehicle No :	SMK3793M	Insured Vehicle No :	SLR1909K
Date of Loss:	17/07/2019	Nature of Claim:	TP
		Claim No:	1178839903SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK3793M		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Standard (A)	Engine No:	1ZR0D42198
Reg. Date:	08/04/2019 (Man. Year: 2019)	Chassis No:	MR053REH604596278
Colour:	Silver	Odometer:	35422 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	18/07/2019	
Date Inspected:	19/08/2019	Inspected At: Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	3.0 days	

Adjuster: LEE HOCK ANN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Repair	0.00 F	*- F
2	1		*REAR LH DOOR	Bent	0.00 F	*- F
3	1		*REAR LH DOOR GLASS REGULATOR (NOT NECESSARY)	Not Consistent With The Impact	0.00 F	*- F
4	1		*REAR LH DOOR GLASS REGULATOR MOTOR (NOT NECESSARY)	Not Consistent With The Impact	0.00 F	*- F
5	1		*REAR LH DOOR LOCK (NOT NECESSARY)	Not Consistent With The Impact	0.00 F	*- F
6	1		*REAR LH DOOR INNER TRIM BOARD	Damaged	0.00 F	*- F
7	1		*REAR LH DOOR OUT TOP STICKER BLACK	Necessary	0.00 F	*- F
					Total Parts (\$\$)	0.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >