

AXA/LKK - Kenneth

23/7



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLG 8847 S

Not Authorized

Parts	(a) Cost / List Price Items	\$	6,538.54
	Plus/Less 25%	\$	1,634.64
	Total of Cost / List	\$	4,903.91
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	700.00
Total Parts Cost		\$	5,603.91
Labour		\$	3,420.00
Total		\$	9,023.91

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 23/7/19 at 12:00

Remarks By Surveyor

- (a) The repair of this vehicle is authorized / is not authorized until further notice.
- (b) Recommended Days of Repair : 04 day(s)
- (c) Resurvey : Required / Not Required
- (d) Excess : \$
- (e) Signature of surveyor : L Date: 23/7/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLG 8847 S**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FUX03536385**

Submit By : **SERENGE**
Year Manufacture : **2016**
Engine No. : **2ZRR956950**

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front fender	1	\$868.70		X
2	LH front fender undershield	1	\$195.60		✓
3	LH front fender undershield clip	10	\$25.00		X
4	LHF fender wording "HYBRID"	1	\$44.17		✓
5	LH front door	1	\$1,121.75		X
6	LH front door hinge top	1	\$78.30		X
7	LH front door hinge bottom	1	\$78.30		X
8	LH front door weatherstrip	1	\$211.69		X
9	LHF door glass outer moulding	1	\$121.75		X
10	LH rear door	1	\$1,211.40		X
11	LH rear door hinge top	1	\$78.34		X
12	LH rear door hinge bottom	1	\$78.34		X
13	LH rear door weatherstrip	1	\$198.70		X
14	LHR door glass outer moulding	1	\$107.80		X
15	LH rear fender	1	\$883.60		X
16	LH rear fender undershield	1	\$92.30		X
17	LH rear fender undershield clip	10	\$30.00		X
18	LH side skirt	1	\$721.50		X
19	LH rear tyre	1	\$350.00	S.N	X
20	LH rear hub cap	1	\$195.65		X
21	LH front tyre	1	\$350.00	S.N	X
22	LH front hub cap	1	\$195.65		X
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLG 8847 S** Submit By : **SERENCE**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (LHF FENDER, LHF DOOR, LHR DOOR, LH SIDE SKIRT, LHR FENDER)	\$1,200.00	500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (LHF FENDER, LHF DOOR, LHR DOOR, LH SIDE SKIRT, LHR FENDER)	\$1,200.00	880
3	To tuff coat. <i>nn</i>	\$250.00	X
4	TO Check wiring	\$50.00	200
5	To remove & refit Door trim, door glass, window regulator, door lock to assist work load. <i>nn</i>	\$300.00	X
6	To do wheel alignment. <i>nn</i>	\$120.00	X
7	To remove & refit inner seat & upholstery to assist work load. <i>nn</i>	\$150.00	X
8	To remove & refit petrol tank to assist work load. <i>nn</i>	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.