

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19012782/T1PA3Q2

**Date:** 17/04/2020

### REFERENCE

|   |                             |                       |
|---|-----------------------------|-----------------------|
| Handling Insurer: India International Insurance Pte Ltd | Policy No:                  | MCOM0015              |
| <b>Claimant</b>   |                             |                       |
| <b>Vehicle No :</b> SHC924Z                             | <b>Insured Vehicle No :</b> | SHA7641D              |
| Date of Loss: 17/07/2019                                | Nature of Claim: TP         | Claim No: MCT19070440 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |  |             |                   |
|-----------------------------|--|-------------|-------------------|
| Reg No:                     | <b>SHC924Z</b>                                 |             |                   |
| Make & Model:               | HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) | Engine No:  | D4DFDU566590      |
| Reg. Date:                  | 04/03/2016 (Man. Year: 2015)                   | Chassis No: | KMHLB41UMGU081073 |
| Colour:                     | Yellow   | Odometer:   | 479820 km         |
| Engine Capacity:            | 1685 cc  |             |                   |
| Market Value/New Car Price: | N/A  |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>              |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 205/60R16     | Rear Tyre Size:  | 205/60R16     |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 7,562.78          | 2,872.30          | 4,690.48          | 62.02         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour  | 2,800.00          | 1,690.00          | 1,110.00          | 39.64         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>10,362.78</b>  | <b>4,562.30</b>   | <b>5,800.48</b>   | <b>55.97</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>3,600.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 10,362.78         | 3,600.00          | 6,762.78          | 65.26         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 725.39            | 252.00            | 473.39            | 65.26         |
| <b>Nett Amount (S\$)</b>                        | <b>11,088.17</b>  | <b>3,852.00</b>   | <b>7,236.17</b>   | <b>65.26</b>  |
| <b>+ Loss of Use (5.0 x S\$40.00/day) (S\$)</b> |                   | 200.00            |                   |               |
| <b>+ Car Rental (5.0 x S\$109.30/day) (S\$)</b> |                   | 546.50            |                   |               |
| <b>(S\$)</b>                                    |                   | 4,598.50          |                   |               |
| <b>Liabe Amount (50.00%) (S\$)</b>              |                   | <b>2,299.25</b>   |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 7.45              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>2,306.70</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>2,300.00</b>   |                   |               |

### INSPECTION

Date of Assignment: 18/07/2019

Date Inspected: 19/07/2019 Inspected At: Ding Automotive Pte Ltd (HQ)  
31 CORPORATION ROAD  
Singapore 649825

Estimated Period of Repair: 6.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |  |   |
|----------------------|--|---|
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 05 Dec 2019)                                   |
| <b>Parts:</b>        | 143  | HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)   |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SHC924Z)   |   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                       | Condition | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------|-----------|-------------|--------------|
| 1   | 1   |          | *FRONT LHS DOOR ASSY              | Repair    | 2,256.00 FL | *- FL        |
| 2   | 1   |          | *REAR LHS DOOR ASSY               | Bent      | 2,201.00 FL | *2,201.00 FL |
| 3   | 1   |          | *REAR LHS FENDER ASSY             | Repair    | 2,171.50 FL | *- FL        |
| 4   | 1   |          | *LHS ROCKER PANEL                 | Repair    | 1,310.60 FL | *- FL        |
| 5   | 1   |          | *REAR LHS INNER FENDER PANEL ASSY | Bent      | 178.00 FL   | *178.00 FL   |
| 6   | 1   |          | *LHS ROCKER SKIRT                 | Distorted | 695.88 FL   | *695.88 FL   |
| 7   | 1   |          | *DOOR STICKER -COMFORT DELGRO     | Necessary | 150.00 FS   | *100.00 FS   |
| 8   | 1   |          | *DOOR STICKER -65521111           | Necessary | 150.00 FS   | *100.00 FS   |
| 9   | 1   |          | *REAR WHEEL RIM COVER LH          | Cut       | 265.50 FL   | *265.50 FL   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>9,378.48</b> | <b>3,540.38</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 1,815.70        | 668.08          |

|                           |                 |                 |
|---------------------------|-----------------|-----------------|
| <b>Total Parts (\$\$)</b> | <b>7,562.78</b> | <b>2,872.30</b> |
|---------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                            | Particulars  | Lab.Type | Repairer's      | Amount          |
|-------------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>           |  |          |                 |                 |
| 1                             | REMOVE & STRAIGHTEN DOOR PARTS   | New      | 400.00          | 60.00           |
| 2                             | STRAIGHTEN & LHS ROCKER PANEL ,LHR FENDER<br>PANEL & DAMAGE AREA               | New      | 1,000.00        | 800.00          |
| 3                             | RESPRAY LHS ROCKER PANEL ,LHS ROCKER PANEL<br>SKIRT ,LHR FENDER & DAMAGED AREA | New      | 1,250.00        | 800.00          |
| 4                             | CHECK WIRING SYSTEM  | New      | 150.00          | 30.00           |
| <b>Gross Labour Cost (\$)</b> |  |          | <b>2,800.00</b> | <b>1,690.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >