

MULTILATERAL SERVICES  
160, Sin Ming Drive, Sin Ming Auto City,  
#06-01 Singapore 575722  
Tel: 6453 5654, 6459 1630 Fax: 6459 1698  
Reg. No. 46956800/C

*Not Authorized*  
*1/2 Day @ 7*  
*Recovery After Painting*  
*4 days*

Date : '17/07/2019

QUOTATION -THIRD PARTY CLAIM

LONPAC INSURANCE BERHAD

Attn: Motor Claim Department . Officer In Charge

Accident on : 16/07/2019

Claim : Third Party Claim  
Veh. No : SGY 2572 M  
Model : TOYOTA RUSH  
Insured Ins: AXA INSURANCE

| QTY    | PARTICULARS                                | AMOUNT             | SURVEYOR |
|--------|--------------------------------------------|--------------------|----------|
|        | <b>Your Insurer Vehicle No : GBC 837 M</b> |                    |          |
| 1      | TAILGATE <i>B</i>                          | \$ 1,848.50        | ✓        |
| 1      | TAILGATE RUSH EMBLEM <i>me</i>             | \$ 65.00           | —        |
| 1      | TAILGATE W/SCREEN MOULDING <i>me</i>       | \$ 180.00          | —        |
| 1      | TAILLAMP RH                                | \$ 580.60          | ?        |
| 1      | TAILLAMP PANEL RH                          | \$ 228.00          | x        |
| 1      | TAILLAMP SIDE CLIP RH                      | \$ 20.00           | ?        |
| 1      | TAILLAMP LOWER BRACKET RH                  | \$ 161.45          | ·?       |
| 1      | REAR FENDER RH                             | REPAIR             |          |
| 1      | REAR FENDER UNDERSHIELD RH <i>me</i>       | \$ 228.00          | x        |
| 1      | REAR BUMPER <i>Bu</i>                      | \$ 1,348.50        | ✓        |
| 1      | REAR BUMPER RH SIDE RETAINER               | \$ 181.45          | ✓        |
| 1      | REAR BUMPER REFLECTOR RH                   | \$ 141.50          | ?        |
| 1      | REAR BUMPER CLIPS <i>me</i>                | \$ 35.00           | —        |
| 1      | REAR BUMPER BRACKET RH                     | \$ 191.00          | x        |
| 1      | END PANEL                                  | \$ 580.60          | x        |
|        |                                            | \$ 5,789.60        |          |
|        | Less 25%                                   | \$ 1,447.40        |          |
|        |                                            | <b>\$ 4,342.20</b> |          |
|        | <b>S/NETT PARTS :</b>                      |                    |          |
| 1SET   | REVERSE SENSORS                            | \$ 280.00          | ?        |
| 2 TUBE | REAR W/SCREEN SEALANT <i>me</i>            | \$ 240.00          | 405m     |
|        | TOTAL S/NETT :                             | <b>\$ 520.00</b>   |          |
|        | TOTAL PARTS :                              | <b>\$ 4,862.20</b> |          |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

160, Sin Ming Drive, Sin Ming Auto City,  
#06-01 Singapore 575722  
Tel: 6453 5654, 6459 1630 Fax: 6459 1698  
Reg. No. 40956800/C

Page 2