

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5216B**AAD1907-169***Not Authored
1 Sep 2020*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

18 JUL 2019

SHC 5216B

VF1ABL15AUC276169

RENAULT

LATITUDE

17.7.19

AIG

19/2/2014

PART**LIST**

1	BUMPER COVER FRT	\$	<i>Bulldo</i> 1,259.42	✓
1	BUMPER SPOILER FRT	\$	<i>S</i> 181.75	}
1	BUMPER ABSORBER FRT	\$	<i>S</i> 394.68	
1	BUMPER RETAINER FRT RH	\$	<i>S</i> 151.41	
1	BUMPER SUPPORT FRT	\$	<i>S</i> 123.88	
1	BUMPER UNDERTRAY FRT	\$	<i>S</i> 472.83	
1	BUMPER GRILLE LOWER FRT	\$	<i>S</i> 266.80	
1	BUMPER FOG LAMP GRILLE RH	\$	<i>S</i> 207.21	}
1	BUMPER BEAM FRT	\$	<i>N</i> 914.08	
1	HEADLAMP RH	\$	<i>S</i> 1,184.43	}
1	HEADLAMP PANEL FRT RH	\$	<i>N</i> 152.15	
1	FENDER PANEL FRT RH	\$	<i>B</i> 783.83	✓
1	WHEELARCH FRT RH	\$	<i>S</i> 278.84	}
1	FENDER BRACKET LOWER RH	\$	<i>S</i> 15.79	
1	FENDER INSULATOR RH	\$	<i>S</i> 130.84	
1	TOW COVER FRT	\$	<i>S</i> 28.61	
1	FRONT BRACE PANEL	\$	<i>N</i> 177.22	}
1	RADIATOR GRILLE	\$	<i>S</i> 1,707.78	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>S</i> 225.36	
1	RADIATOR GRILLE FRAME	\$	<i>S</i> 1,353.75	
1	FRAME FULL SUPPORT PANEL	\$	<i>S</i> 615.90	
1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i> 89.79	
1	BONNET	\$	<i>N</i> 1,941.63	}
1	BONNET INSULATOR	\$	<i>S</i> 405.73	
1	BONNET STRUT LH	\$	<i>S</i> 88.61	
1	BONNET STRUT RH	\$	<i>S</i> 88.61	
1	BONNET HINGE LH	\$	<i>N</i> 348.31	
1	BONNET HINGE RH	\$	<i>N</i> 348.31	}
1	BONNET LOCK	\$	<i>N</i> 305.48	

Trans-cab Auto Services Pte Ltd

AAD1907-169

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5216B

1	BONNET CABLE	\$	S ₂	119.19	}	X
1	BONNET CABLE COVER	\$	S ₂	161.03		
1	BONNET SEAL OUTER	\$	S ₂	92.36		
1	BONNET SEAL INNER	\$	S ₂	157.28		
1	WIPER RESERVOIR MOTOR	\$	S ₂	270.06		
1	WIPER RESERVOIR	\$	S ₂	348.25		
1	WIPER RESERVOIR NECK	\$	S ₂	136.11		
TOTAL		\$		15,527.30		
10%		\$		1,552.73		
		\$		13,974.57		

Special Nett

1	BUMPER CLIP FRT	\$	na	66.00	}	X
1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00		
1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50		
1	BUMPER GRILLE LOWER CLIP	\$	na	69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00		
1	WHEELARCH CLIP FRT RH	\$	na	30.50		
1	FRONT RIGHT TYRE	\$	S ₂	300.00		
1	FRONT RIGHT TYRE RIM	\$	S ₂	380.00		
1SET	Front licence plate with holder	\$	S ₂	80.00		
1SET	RADIATOR GRILLE SCREW	\$	na	16.00		
1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00		
1	WINDSCREEN SEALANT	\$	na	253.80		
1	FRONT WINDSCREEN MOULDING	\$	na	120.00		
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00		
6	BONNET INSULATOR CLIP L70Y	\$	na	7.30		
2	BONNET STRUT L70Y	\$	S ₂	88.61		
2	BONNET CABLE CLIP L70Y	\$	na	6.31		
2	BONNET CABLE COVER SCREW L70Y	\$	na	10.85		
TOTAL		\$		1,722.88		

TOTAL PARTS \$ 15,697.45**LABOUR**

Putty and spray painting of the affected portion.

\$

4401
6,000.00

Trans-cab Auto Services Pte Ltd**AAD1907-169**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5216B

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4001 6,000.00
To rust-proofing of the affected areas.	\$	170.00 301
To transfer of front windscreen fittings and conduct water seepage test.	\$	na 170.00 X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	3 380.00 X
To check steering geometry and computer wheel alignment	\$	3 220.00 X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	3 380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	3 380.00 X
To transfer of tire, rim and on wheel balancing.	\$	3 170.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	3 380.00 X
To Check Electrical Lighting Concerned.	\$	170.00 101
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	na 380.00 X

TOTAL \$ 15,180.00**Over All Total \$ 30,877.45****LUMP SUM (REPAIR DAY)****20 DAYS****2 days**

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be purchased and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: