



萬 春 摩 哆

## BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GSTReg. No. 351915/00A

**GST Regn No. 35191500A**

19/07/2019

India International Insurance Pte Ltd  
#04-02 IOB Building  
64 Cecil Street  
Singapore 049711

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. PA 5442 E  
MODEL: TOYOTA HIACE  
DATE OF ACCIDENT: 18/07/2019  
YOUR INSURED VEHICLE NO. SHB 4081 J

1 pc	RH headlamp	\$	624.00
1 pc	Front bumper		484.00
1 pc	RH front bumper side bracket		29.00
1 pc	Front bumper reinforcement		314.00
1 pc	Front grille		458.00
1 pc	Support panel		383.00
1 pc	Tow cover		32.00
		\$	2,324.00
	Less: 25% discount		581.00
		\$	1,743.00
1 pc	Front number plate		35.00 SN

### LABOUR CHARGES:

To dismantle and reassemble of air con unit and refill of air con gas.	120.00
To knocking and straightening of all necessary damaged parts.	
To changing of above part.	800.00
To putty and spray painting on accident damaged parts.	600.00
	\$ <u>3,298.00</u>

Yours fathfully,

*Peelintoy*