

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9796Y*Not Authored
L/Sing & 2250/***AAD1906-170**

19 JUN 2019

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHB 9796Y

VF1ABL15AUC273399

RENAULT

LATITUDE

16.6.19

AIG

31/7/2013

PART		LIST	
1	BUMPER COVER FRT	\$	1,259.42
1	BUMPER SPOILER FRT	\$	181.75
1	BUMPER ABSORBER FRT	\$	394.68
1	BUMPER RETAINER FRT RH	\$	151.41
1	BUMPER SUPPORT FRT	\$	123.88
1	BUMPER UNDERTRAY FRT	\$	472.83
1	BUMPER GRILLE LOWER FRT	\$	266.80
1	BUMPER FOG LAMP GRILLE RH	\$	207.21
1	BUMPER BEAM FRT	\$	914.08
1	HEADLAMP RH	\$	1,184.43
1	HEADLAMP PANEL FRT RH	\$	152.15
1	FENDER PANEL FRT RH	\$	783.83
1	WHEELARCH FRT RH	\$	278.84
1	FENDER BRACKET LOWER RH	\$	15.79
1	FENDER INSULATOR RH	\$	130.84
1	TOW COVER FRT	\$	28.61
1	FRONT BRACE PANEL	\$	177.22
1	RADIATOR GRILLE	\$	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	225.36
1	RADIATOR GRILLE FRAME	\$	1,353.75
1	FRAME FULL SUPPORT PANEL	\$	615.90
1	FRAME FULL SUPPORT BRACKET	\$	89.79
1	BONNET	\$	1,941.63
1	BONNET INSULATOR	\$	405.73
1	BONNET STRUT LH	\$	88.61
1	BONNET STRUT RH	\$	88.61
1	BONNET HINGE LH	\$	348.31
1	BONNET HINGE RH	\$	348.31
1	BONNET LOCK	\$	305.48

Trans-cab Auto Services Pte Ltd**AAD1906-170**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9796Y

1	BONNET CABLE	\$	SL 119.19	X
1	BONNET CABLE COVER	\$	SL 161.03	X
1	BONNET SEAL OUTER	\$	SL 92.36	X
1	BONNET SEAL INNER	\$	SL 157.28	X
1	DOOR PANEL FRT RH	\$	N 2,844.66	X
1	DOOR MIRROR ASSY RH	\$	mgmt 1,483.40	✓
1	DOOR MIRROR GLASS RH	\$	SL 148.20	X
1	DOOR MIRROR BACK COVER RH	\$	SL 218.46	X
1	ROCKER PANEL INNER GARNISH RH	\$	SL 466.51	} X
1	ROCKER PANEL INNER RH	\$	N 1,024.79	
1	ROCKER PANEL OUTER RH	\$	N 1,184.99	
1	ROCKER PANEL CENTER RH	\$	N 990.25	
1	LOWER ARM RH L70Y	\$	SL 685.76	
1	KNUCKLE ARM RH L70Y	\$	SL 846.98	
1	ABSORBER FRT RH L70Y	\$	SL 360.54	
1	DRIVESHAFT RH	\$	N 1,747.45	
1	STABILIZER BAR FRT	\$	SL 604.65	} X
1	WIPER RESERVOIR MOTOR	\$	SL 270.06	
1	WIPER RESERVOIR	\$	SL 348.25	
1	WIPER RESERVOIR NECK	\$	SL 136.11	} X
1	DOOR HARNESS WIRE RH	\$	SL 2,670.00	
TOTAL		\$	30,803.94	
10%		\$	3,080.39	
		\$	27,723.55	

Special Nett

1	FRONT DOOR ADVERTISEMENT STICKER	\$	na 300.00	X
1	FRONT FENDER ADVERTISEMENT STICKER	\$	na 300.00	X
1	BUMPER CLIP FRT	\$	na 66.00	} X
1	BUMPER BRACKET CLIP FRT RH	\$	na 12.00	
1	BUMPER SUPPORT CLIP FRT RH	\$	na 10.50	
1	BUMPER GRILLE LOWER CLIP	\$	na 69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	na 20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	na 30.00	
1	WHEELARCH CLIP FRT RH	\$	na 30.50	
1	FRONT RIGHT TYRE	\$	SL 300.00	} X
1	FRONT RIGHT TYRE RIM	\$	SL 380.00	

Trans-cab Auto Services Pte Ltd**AAD1906-170**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9796Y

1SET	Front licence plate with holder	\$	SL	80.00	}	X
1SET	RADIATOR GRILLE SCREW	\$	SL	16.00		
1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00		
1	WINDSCREEN SEALANT	\$	na	253.80		
1	FRONT WINDSCREEN MOULDING	\$	na	120.00		
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00		
6	BONNET INSULATOR CLIP L70Y	\$	na	7.30		
2	BONNET STRUT L70Y	\$	na	88.61		
2	BONNET CABLE CLIP L70Y	\$	na	6.31		
2	BONNET CABLE COVER SCREW L70Y	\$	na	10.85		
TOTAL		\$		2,322.88		

TOTAL PARTS	\$	30,046.42
--------------------	-----------	------------------

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00	4401
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	301
To rust-proofing of the affected areas.	\$	170.00	301
To transfer of front windscreen fittings and conduct water seepage test.	\$	na	170.00 X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	na	380.00 X
To check steering geometry and computer wheel alignment	\$	na	220.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	na	380.00 X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	na	380.00 X

Trans-cab Auto Services Pte Ltd**AAD1906-170**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9796Y

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To Check Electrical Lighting Concerned.	\$	<i>na</i> 170.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i> 380.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	<i>na</i> 380.00 X

TOTAL \$ 15,940.00**Over All Total \$ 45,986.42****LUMP SUM (REPAIR DAY)**~~20 DAYS~~
2 day,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: