

Section A - Accident Details

Registration Number	SHB706S
Case Reference Number	TAX/07/19/2063
Registration Date	12/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	GIAM HO KEAT DONALD
Type of Accident	Side Swipe
Accident Date and Time	16/7/2019 4:00 PM
Accident Reported Date and Time	17/7/2019 11:25 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24102443
Special Instruction to ARC, if any	RIGHT REAR PORTION
Prepared Date and Time	17/7/2019 2:39 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$800.00
Total Spray Cost	\$1,674.00	\$880.00
Total Spare Part Cost	\$5,268.99	\$1,185.91
Total Other Cost	\$1,140.00	\$250.00
TOTAL COST	\$9,116.99	\$3,115.91 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	6.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / ERGO
ARC / Surveyor Sign Off Date	17/07/2019 3:30 PM	19/07/2019 2:52 PM
Signature		
Remarks	P/P repair, take before spray. Finalize sent to stevechen@lkkauto.com.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0022	Invoice Number	
Quotation Date	04.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	\$1,014.00	\$800.00
Total Labour	\$1,014.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$150.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$80.00
Total Spray Painting & Panel Beating	\$1,674.00	\$880.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE / REFIT SEAT	\$120.00	\$50.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$30.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,140.00	\$250.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		6700347210	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair
		6877052031	HINGE ASSY, REAR DOOR, LOWER RH	0.00	\$73.30	0.00	\$0.00	Replace	Not Given
		6875020122	HINGE ASSY, REAR DOOR, UPPER RH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given
		6863047050	CHECK ASSY, REAR DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given
		6905052250	DOOR LOCK REAR, RH	0.00	\$544.70	0.00	\$0.00	Replace	Not Given
		6941020110	DOOR LOCK STRIKER	0.00	\$36.00	0.00	\$0.00	Replace	Not Given

NN

NN

NN

NN

NN

75850479 10	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$576.00	100.00	\$0.00	Replace	Repair	R	
61601471 50	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	25.00	\$618.60	Replace	Replace		DD
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	NN
42611474 50	WHEEL, DISC	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair	R	
65637470 60	LINER, REAR FENDER, RH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X	NN
52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace		CUT
52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace		NEC
52462470 30	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace		NEC
52462470 20	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace		NEC
52462470 10	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace		NEC
52191470 30	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00	25.00	\$16.50	Replace	Replace		NEC
52565479 00	FILLER, RR BUMPER, RH	1.00	\$119.90	100.00	\$0.00	Replace	Repair	R	
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace		NEC
52575470 40	RETAINER, RR BUMPER, RH	1.00	\$112.70	25.00	\$84.53	Replace	Replace		BR
52591470 50	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X	NN
81581470 10	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Check	X	NN
Total			\$6,667.54		\$1,185.91				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1185.91
+ 800.00
+ 1130.00

3115.91

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: