

ASS. REC. BY:

REF:

CS/MSG19012836/Ug+3/72

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Pauline Thum

of

MSG

Date/Time:

22/7/19

Estimated Cost:

Bill to:

OD / ☒ TP / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKC 5664E

Insured:

GBA 14965

at Workshop m/s

Premium Carz Services Pte Ltd

Tel:

of

1 Icali Bulq + Ave 6 #01-90 Autobay

Policy No:

29117440 MKC

Claim No:

600503

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/7/19

CA / REV / REP. / REV 24 HRS

Date/Time: 22.7.2019 10.05U.m

Person Contacted:

Aun Tong

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	SKC 5664E X
	GBA 14965 CCL/AIG14006725/KPM392 DUA = 13/3/14
22/7/19 @	Now revised to Pauline Thum via Meritum.

08/1/13) wef
ASS. REC. BY: Marcus

REF:

MS16/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD (TP) WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SKC5604E
at Workshop m/s Premium Core
of 01-90
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SKC5604E Yr Regn: 9.11
Type: CA / M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Hyundai Elantra cc 1.5-91
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 31488 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: KMH DH 41CMCU 237991
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40 R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. <u>7</u> mm	R/Bal. <u>7</u> mm
L/Bal. <u>7</u> mm	L/Bal. <u>7</u> mm
D.O.A. <u>18/7/19</u>	D.O.I. <u>22/7/19</u>

Survey held at: _____

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 251k

IDAC Accident Report: Consistent? : Yes or No

GA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LT A19198

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

26/7/19 4/5 2.15 hrs.
*3500 confirmed with Amtey.
(Ref. 4906.74, 58%)

26/7/2019

Date/Time. File Pass to?

☐ : Prel. Report

29/7/2019

☐ : Final Report

Date/Time. File Return to?

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

\$ + RS \$

Photos

Others

Report Format: MER-TP

Lump Sum / I.B.I: (\$ 3500)

TOTAL

150
11
161

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 23 Jul 2019

Preliminary Advice

Insured Vehicle No	: GBA1496S	Accident Date	: 18/07/2019
TP Vehicle No	: SKC5664E	Assignment Date	: 22/07/2019
Make	: HYUNDAI ELANTRA	Est. Duration of Repair	: 4.00
Date of Inspection	: 22/07/2019		
Inspection At	: PREMIUM CARZ SERVICES PTE LTD (HQ) 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY@KAKI SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,406.24
Revised Amount	:S\$	3,173.20
Check Items (Estimated)	:S\$	2,790.00
Total	:S\$	5,963.20

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jul 2019		22 Jul 2019 09:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		Nam Ann Machinery Works, Co. Reg. No.: 52859801E [Created by insurer]							
Main Claimant:		ZEROI PASSION, Co. Reg. No.: 53341852							
Vehicle Reg. No.:		SKC5664E	Date of Loss:	18/07/2019 11:00 - :59 [94 Months and 8 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP	Policy/Cover Note No.:	29117440MKC (TP, Fire & Theft) Coverage: 08/03/2019 - 07/03/2020					
Vehicle Reg. No. (Insured):		GBA1496S	Policy No. (Claimant):						
		Excess:							
Repairer:		Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki, 417883 Kaki Bukit - Tel: 66369100							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/07/2019]							
Adj Asg. Remarks:		on WP. Liab: Dispute(NR). Agree on SJE. Assign: Marcus Chua from LKK Auto Consultants Pte Ltd. Contact: Aun Teng @ 6636 9100.							
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

sgCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



CLEARANCE SALE NOW ON!

40% OFF ALL SELECTED ITEMS

Locus Habitat

SINGAPORE

elantra

Price Range

Depreciation

2011

Vehicle Type

Submit

Advanced Search

Home » Used Cars » New Way Leasing Pte Ltd » Hyundai Elantra 1.6A

Hyundai Elantra 1.6A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price

\$28,200

Depreciation

\$9,670 /yr

View models with similar depre

Mileage

106,000 km (13.6k /yr)

Road Tax

\$738 /yr

Dereg Value

\$18,965 as of today (change)

COE

\$48,006

Engine Cap

1,591 cc

Curb Weight

1,267 kg

Type of Vehicle

Mid-Sized Sedan

Reg Date

28-Sep-2011

(2yrs 2mths 5days COE left)

Manufactured

2011

Transmission

Auto

OMV

\$14,115

ARF

\$14,115

Power

95.6 kW (128 bhp)

No. of Owners


2







Price Chart



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

New Way Leasing Pte Ltd

» dealer's pricelist

» 14 vehs sold | 15 vehs available

Address

32 Old Toh Tuck Road #02-12

Search cars nearby this location

Location

L.Biz Centre

Office No

62622030

Features

Fuel Efficient 1.6L 4 Cylinder 16 Valve Dual CVVT Engine. ABS, Cruise Control,Rear Seats Knock Down. Rear Aircon. View specs of the Hyundai Elantra (2011-2014)

Accessories

Factory Fitted Audio System. Reverse Sensors. Leather Seats. Retractable Side Mirrors.

Description

Electric Seat, Sunroof, Push Start, Low Mileage With Service Record.

Category

PARF Car

Status

Available

Resources

 Car Valuation - Free

Find out the market value of your existing car for free. Get started

 Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 19-Jul-2019 | Last Updated on: 19-Jul-2019

Upfront Payment

» more Financial info

Transfer Fee

\$25

Compare

https://www.sgcarmart.com/used_cars/info.php?ID=840180&DL=2952

22-Jul-19

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	852J
Vehicle Details	
Vehicle No.:	SKC5664E
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jul 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR SR
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	G4FGBU297353
Chassis No.:	KMHDH41CMCU237991
Maximum Power Output:	95.6 kW (128 bhp)
Open Market Value:	\$13,873.00
Original Registration Date:	10 Sep 2011
First Registration Date:	10 Sep 2011
Transfer Count:	1
Actual ARF Paid:	\$13,873.00 6936
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Sep 2021
PARF Rebate Amount:	\$8,323.00
Intended COE Rebate Details	
COE Expiry Date:	09 Sep 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$51,000.00
COE Rebate Amount:	\$10,875.00
Total Rebate Amount:	\$19,198.00

The information contained herein is correct as at 22 Jul 2019

OK

Date : 18/07/2019

TO: MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581

Attn : Motor Claims Department
Fax : 6225 7402

Our Customer : Zeroi Passion
Vehicle No : SKC5664E
Model : Hyundai Elantra 1.6AT

Manufacture Year : 2011

Date of Accident : 18/07/2019

Total Estimate Repair Days : 7

Total Pages : 2

Re: Repair Estimate For Third Party Claim against GBA1496S

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front bumper side retainer RH	1	\$59.00	\$59.00	Ref ✓
2	Headlamp RH 673	1	\$850.00	\$850.00	Cr ✓
3	Headlamp lower bracket RH	1	\$39.00	\$39.00	Pl ✓
4	Front fender RH 460	1	\$753.00	\$753.00	3rd Sm ✓
5	Front fender lining RH	1	\$92.00	\$92.00	Pl ✓
6	Front wheelhouse panel RH	1	\$581.30	\$581.30	Pl ✓
7	Front shock absorber RH	1	\$387.00	\$387.00	Pl ✓
8	Front shock absorber top mounting RH	1	\$175.00	\$175.00	Pl ✓
9	Front knuckle arm RH 363	1	\$532.00	\$532.00	Pl ✓
10	Front knuckle arm bearing RH 113	1	\$381.00	\$381.00	Pl ✓
11	Front lower arm RH	1	\$471.00	\$471.00	Pl ✓
	Total			\$4,320.30	
				Less 20%	
				\$864.06	P-1760
	Sub Total 1			\$3,456.24	
B.	Spare Parts (S/Nett)				
1	Front bumper	1	\$1,500.00	\$1,500.00	cr 1100
2	Front bumper clip	10	\$5.00	\$50.00	Pl ✓
3	Front fender lining clip	8	\$5.00	\$40.00	Pl ✓
4	Front tyre RH	1	\$400.00	\$400.00	Pl ✓
5	Front sports rim RH	1	\$450.00	\$450.00	Pl ✓
	Sub-Total 2			\$2,440.00	
	Total for Parts			\$5,896.24	
C.	Labour				
1	To check wiring and refocus headlamp.			\$80.00	20
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1200.00	\$20
3	Spray painting all affected parts & areas.			\$800.00	600
4	To check wheels with computerize wheel alignment.			\$120.00	80
5	To spray anti-rust undercoating.			\$60.00	30
6	To remove and replace front undercarriage RH.			\$250.00	720
	Total Labour			\$2,310.00	
	Total Repair Cost			\$8,406.24	1370

P-1760
20%
P-1408
S.N-1640
L-1370
TOTAL 4418
202
3534.40



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	PREMIUM CARZ	DATE	Jul 22, 2019 11:42:33 AM
LICENSE NO.	SKC 5664 E		
MILEAGE	314889		
REFERENCE	CUSTOM	MODEL	HYUNDAI ELANTRA (DH4

Front Wheel SPECS DIAGNOSIS ADJUSTMEN

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.00	0.00	1.00			3.40				3.40		
PARTIAL TOE	-0.50	0.00	0.50		-0.20		3.60		0.00		3.40	*
SETBACK	---	---	---			0°00'				0°00'		
CAMBER	-0°44"	0°00"	0°44"		-1°26"		-3°12' 1°46"		-1°28"		-3°12' 1°44"	
CASTER	3°30"	4°30"	5°30"		4°00"		4°16" 0°14"		4°00"		4°16" 0°14"	
KING-PIN	---	---	---		14°24"		14°00" 0°22"		14°24"		14°00" 0°22"	
INCL ANGLE	---	---	---		12°58"		10°48"		12°56"		10°48"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel SPECS DIAGNOSIS ADJUSTMEN


	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	---	---	---			5.60				6.60		
PARTIAL TOE	---	---	---		4.70		1.90		4.70		1.90	
SETBACK	---	---	---			0°06"				0°06"		
CAMBER	---	---	---		-1°14"		-1°42" 0°26"		-1°14"		-1°42" 0°26"	
THRUST ANGLE	-0°08"	0.00	0°08"			0°12"				0°12"		



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646

Attn: Marcus

Fax: 62564315



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	PREMIUM CARZ.	DATE	Jul 23, 2019 10:58:08 AM
LICENSE NO.	SKC 5664 E		
MILEAGE	314899		
REFERENCE	CUSTOM	MODEL	HYUNDAI ELANTRA (DH4

Front Wheel SPECS DIAGNOSIS ADJUSTMEN

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.00	0.00	1.00			-1.30				0.00		
PARTIAL TOE	-0.50	0.00	0.50		0.50		-1.80		0.00		0.00	
SET BACK	---	---	---			0°14"				0°14"		
CAMBER	-0°44"	0°00"	0°44"		-1°12"		-0°44" 0°28"		-1°12"		-0°48" 0°24"	
CASTER	3°30"	4°30"	5°30"		4°00"		4°16" 0°14"		4°00"		4°16" 0°14"	
KING-PIN	---	---	---		14°24"		14°00" 0°22"		14°24"		14°00" 0°22"	
INCL ANGLE	---	---	---		13°10"		13°16"		13°10"		13°12"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel SPECS DIAGNOSIS ADJUSTMEN

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	---	---	---			6.30				6.30		
PARTIAL TOE	---	---	---		4.10		2.10		4.10		2.10	
SET BACK	---	---	---			-0°02"				-0°02"		
CAMBER	---	---	---		-1°30"		-1°54" 0°24"		-1°30"		-1°54" 0°24"	
THRUST ANGLE	-0°08"	0.00	0°08"			0°08"				0°08"		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19012836/UQF3N2

Date: 30/07/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29117440
Claimant Vehicle No :	SKC5664E	Insured Vehicle No :	GBA1496S
Date of Loss:	18/07/2019	Nature of Claim:	TP
		Claim No:	600503

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC5664E	Engine No:	G4FGBU297353
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHDH41CMCU237991
Reg. Date:	10/09/2011 (Man. Year: 2011)	Odometer:	314885 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,896.24	3,048.00	2,848.24	48.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	1,370.00	1,140.00	45.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,406.24	4,418.00	3,988.24	47.44
Approved Total (Overridden) (\$\$)		3,500.00		
Nett Amount (\$\$)	8,406.24	3,500.00	4,906.24	58.36

INSPECTION

Date of Assignment:	22/07/2019	
Date Inspected:	22/07/2019	Inspected At:
		Premium Carz Services Pte Ltd (HQ)
		1 Kaki Bukit Ave 6 #01-90
		Autobay@Kaki
		Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Jul 2019)
Parts: 143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC5664E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER SIDE RETAINER RH	Bent	59.00 FL	*59.00 FL
2	1	*HEADLAMP RH	Cracked	850.00 FL	*673.00 FL
3	1	*HEADLAMP LOWER BRACKET RH	Not Necessary	39.00 FL	*- FL
4	1	*FRONT FENDER RH	Badly Dented	753.00 FL	*460.00 FL
5	1	*FRONT FENDER LINING RH	Torn	92.00 FL	*92.00 FL
6	1	*FRONT WHEELHOUSE PANEL RH	Repair	581.30 FL	*- FL
7	1	*FRONT SHOCK ABSORBER RH	Not Necessary	387.00 FL	*- FL
8	1	*FRONT SHOCK ABSORBER TOP MOUNTING RH	Not Necessary	175.00 FL	*- FL
9	1	*FRONT KNUCKLE ARM RH	Bent	532.00 FL	*363.00 FL
10	1	*FRONT KNUCKLE ARM BEARING RH	Necessary	381.00 FL	*113.00 FL
11	1	*FRONT LOWER ARM RH	Not Necessary	471.00 FL	*- FL
12	1	*FRONT BUMPER	Cracked	1,500.00 FS	*1,100.00 FS
13	10	*FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
14	8	*FRONT FENDER LINING CLIP	Necessary	40.00 FS	*40.00 FS
15	1	*FRONT TYRE RH	Serviceable	400.00 FS	*- FS
16	1	*FRONT SPORTS RIM RH	Cut	450.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,760.30	3,400.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	864.06	352.00
Total Parts (\$\$)	5,896.24	3,048.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND REFOCUS HEADLAMP.	New	80.00	20.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS.	New	1,200.00	520.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.	New	800.00	600.00
4	TO CHECK WHEELS WITH COMPUTERIZE WHEEL ALIGNMENT.	New	120.00	80.00
5	TO SPRAY ANTI-RUST UNDERCOATING.	New	60.00	30.00
6	TO REMOVE AND REPLACE FRONT UNDERCARRIAGE RH.	New	250.00	120.00
Gross Labour Cost (S\$)			2,510.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >