

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 17 July 2019

To : NTUC

By Fax: 6338-1500

Attn: Motor Claims Dept

Tel:

VEHICLE NO : FBF 9152E

Yamaha FZ16

ACCIDENT DATE: 6 June 2019

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Front Mudguard <i>new</i>	1	220.00 X
2 Handle Bar <i>new</i>	1	235.00 X X
3 Clutch Lever <i>cut</i>	1	125.00 ✓
4 Head Lamp Assy <i>new</i>	1	350.00 X
5 Mirror <i>LH cut</i>	1	95.00 ✓
6 Front LH Signal <i>cut</i>	1	95.00 ✓
7 Handle Grip <i>tom</i>	1	98.00 ✓
8 Balancer <i>distorted</i>	1 set	170.00 ✓
9 Tank Cover LH <i>Dented / distorted</i>	1	190.00 ✓
10 Front Rim <i>new</i>	1	450.00 X
11 Fork Tube <i>new</i>	1 set	480.00 X
12 Fork Oil Seal <i>new</i>	1	125.00 X
13 Rear LH Signal Light <i>cut</i>	1	95.00 ✓
14 Rear LH Side Tail Cover <i>cut</i>	1	185.00 ✓
15 Rider Seat <i>tom</i>	1	105.00 ✓
16 Chair Guard <i>broken</i>	1	135.00 X ✓

Sub-Total 3,153.00

Less 10% 315.30

Sub-Total 1443.00 2,837.70

Exhaust Guard X 1 150.00 ✓
cut

10% 1298.70

ACKNOWLEDGED BY REPAIRER

Signature _____

Date _____

LR Auto Consultants hence notify the Repairer of the following:

- To receive relevant survey report
- To supply damaged parts using genuine
- Parts prices are subject to confirmation
- Third party survey is done "Without Prejudice" basis
- No liability modification is allowed
- Supplementary terms must be reviewed and is subject to final approval from Insurance Company

VEHICLE NO : FBF 9152E

Yamaha FZ16

Nett items

- 1 Rear box *broken*
- 2 Rear box rack *dam*
- 3 Towing fee *NH*
- 4 Remove & replace necessary parts, align & etc
- 5 Remove & replace fork assy, top up fork oil & front rim
- 6 Putty & respray, touch up paint work

~~280.00~~ *250.00*

185.00 X

40.00 X

~~250.00~~ *180/-*

580.00

120.00 *NH*

~~250.00~~ *180/-*

Sub-Total

1,125.00

Nett Total

3,962.70

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

1878.70
4/s 1500/-

Kindly revert upon completion

Thank you

[Signature]
SG 98 MOTOR PTE LTD

:LG

22/07/2014 e 1300m
Not Author

2/sun 3 day.

[Signature]

2kk And

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: