

22/03/2012

ASS. REC. BY:

REF:

CS/SMO19012847/Usf3ⁿ²

Special Instruction:

Surveyor:

marcus

ASSIGNMENT (Office)

From (Person):

Hwang Shiang Yi

of

SMO

Date/Time: 22.7.19 10.37a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBO 4333T

Insured:

SJY 9543R

at Workshop m/s

Lin's Brother

Tel:

674 11730

of Block 1 Kaki Bukit Ave 6 #01-01

Policy No:

D18MTP01017561

Claim No:

CMTD 1902732

Sum Insured:

Excess:

Make of Veh:

D.O.A

6.6.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 22.7.19 10.47a.m

Person Contacted:

Susan

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBO 4333T NA/INC15015874/14 MA = 14/9/15

SJY 9543R X

24/07/19

@ 10:44 am revised IA to Hwang Shiang Yi

vis mermer

(08/11/13) wef

REF:

ASS. REC. BY: *Marcus*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 2020 S

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GRD 43337

Yr Regn:

10/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

Toyota Dyna freezer

C.C

2982

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

18863

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT 354 60K203790

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-115

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Austone

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

6/6/19

D.O.I.

22/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MSL.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/7/19

Syst 4ml.

1/3 + 3100 confirmed with Susan.

(\$ 3,454.80 Red. 53%)

RECEIVED 26 JUL 2019

Date/Time, File Pass to?

26/07/19
Type

Preli. Report



Final Report

Date/Time, File Return to?

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

Transportation:

250
11

Add Fee:



Site Insp (\$

) \$ + RS. \$



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

) TOTAL

261

Report Format :

Lump Sum / I.B.I. (\$ 3,100/- 45)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hwang Shiang Yi

Date: 24 Jul 2019

Preliminary Advice

Insured Vehicle No	: SJY9543R	Accident Date	: 06/06/2019
TP Vehicle No	: GBD4333T	Assignment Date	: 22/07/2019
Make	: TOYOTA DYNA 1.5T	Est. Duration of Repair	: 3 days
Date of Inspection	: 22/07/2019		
Inspection At	: Liu's Brother Auto Workshop (HQ) BLOCK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,554.80
Revised Amount	:S\$	3,881.22
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,881.22
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2019		22 Jul 2019 10:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LOW YIN JYE, ID: S8040055A								
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N								
Vehicle Reg. No.:	GBD4333T	Date of Loss:	06/06/2019 11:00 - :59						
Claim Type:	TP / CMTD1902738	Policy/Cover Note No.:	D18MTPV01017561 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJY9543R	Policy No. (Claimant):							
		Excess:							
Repairer:	Liu's Brother Auto Workshop (HQ) BLOCK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 67411730								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/07/2019]								
Driver/Custodian (Insured):	LEE MEI AN (), NRIC: S8635878F, Tel: +6584485261 Email:								
Adj Asg. Remarks:	WS: SUSAN LOW 6741 1730								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



CLEARANCE SALE NOW ON!
40% OFF ALL SELECTED ITEMS

Locus Habitat
SINGAPORE

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Down \$200,000 Monthly \$1300++! Only \$10k Deprecia...



5 Years Warranty With Agent!
Free Servicing!
StarAd



Browse by Category

Sort by Date Posted

20 results/page

18 vehicles

toyota dyna

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota dyna		Any	Any	2014	Any	Any	Any	Available
	Toyota Dyna	150 3.0M	\$41,800	\$7,930 /yr	27-Oct-2014	2,982 cc	82,245 km	Truck	Available
Fuel Type: Diesel \$800+ Monthly! Under Utilised Lorry For Sale! Toyota Borneo Agent Full Service Records. Smooth Manual Transmission, No Further Rep... Ezy-1 Pte Ltd Posted: 22-Jul-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$38,800	\$7,240 /yr	28-Nov-2014	2,982 cc	-	Truck	Available
Fuel Type: Diesel One Owner Only, With Canopy, New Paintwork, Excellent Condition, No Repair Needed, Loan Available, Trade In Welcome And Call For... Posted: 21-Jul-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$42,800	\$7,990 /yr	28-Nov-2014	2,982 cc	118,000 km	Truck	Available
Fuel Type: Diesel 1 Owner Only! Well Maintained, Excellent Condition! In House Loan Available. Call For More Enquiries! Posted: 20-Jul-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$39,800	\$7,440 /yr	26-Nov-2014	2,982 cc	-	Truck	Available
Fuel Type: Diesel Cheapest In The Market. New Paintwork. No Parts Needed To Replace. All In Good Condition To Serve You, Trade In Welcome! Full Cash... Car (S) Pte Ltd Posted: 19-Jul-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	The Toyota Previa is the de facto MPV The Toyota Previa is an MPV that excels with its space, practicality and a level of luxury some may not reach. Find out more!								
	Toyota Dyna	150 3.0M	\$44,800	\$8,780 /yr	28-Aug-2014	2,982 cc	-	Truck	Available
Fuel Type: Diesel Best Selling 10 Ft Lorry In The Market, Trusted And Reputable Model For Its Fuel Consumption And Maintenance As Well As Resale Valu... ABWIN (1994) Pte Ltd Posted: 19-Jul-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$37,800	\$7,010 /yr	11-Dec-2014	2,982 cc	101,030 km	Truck	Available
Fuel Type: Diesel This Unit At Super Low Mileage (101030KM) Only! Please Call To Arrange For Viewing, Thanks! Posted: 18-Jul-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
Compare	Toyota Dyna	150 3.0M	\$39,800	\$7,960 /yr	21-Jul-2014	2,982 cc	-	Truck	Available
Fuel Type: Diesel									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 196N

Vehicle Details

Vehicle No.: GBD4333T
Vehicle to be Exported: No
Intended Deregistration Date: 19 Jul 2019
Vehicle Make: TOYOTA
Vehicle Model: TOYOTA DYNA 150 MANUAL
Primary Colour: White
Manufacturing Year: 2014
Engine No.: 1KD2455532
Chassis No.: JTFAT35Y60K203790
Maximum Power Output: -
Open Market Value: \$27,856.00
Original Registration Date: 27 Oct 2014
First Registration Date: 27 Oct 2014
Transfer Count: 1
Actual ARF Paid: \$1,393.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Oct 2024
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
PQP Paid: \$38,349.00
COE Rebate Amount: \$20,205.00
Total Rebate Amount: \$20,205.00

The information contained herein is correct as at 19 Jul 2019

OK

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 731, Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBD433T190606

Estimate

Customer		Date:	19-07-19
Name:	Sompo Insurance Singapore Private Limited	Vehicle No:	GBD433T
Address	Motor Claims Department 50 Raffles Place #05-01 / 06 Singapore Land Tower Singapore 048623	Model/Make:	Toyota Dyna 150 Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bumper <i>Bent/Buc</i>	\$ 481.60	✓
2	Bumper Clips 1 set <i>11</i>	\$ 65.00	SN X
3	Head Lamp <i>1/1 one 922.10</i>	\$ 988.60	+
4	Head Lamp Clips 1 set <i>11</i>	\$ 48.00	SN X
5	Step Panel <i>11</i>	\$ 312.60	X
6	Corner Panel <i>1/1</i>	\$ 376.50	X
7	Corner Panel Garnish <i>one</i>	\$ 199.80	X
8	Grille <i>11</i>	\$ 488.30	X
9	Grille Clips 1 set <i>11</i>	\$ 50.00	SN X
10	"Toyota" Motif <i>11</i>	\$ 78.10	X
11	Door <i>1/1 10/Bent</i>	\$ 1,568.30	+
12	Door LTA "Corporate" ROC Detail Sticker <i>11</i>	\$ 48.00	SN 305.11
To check all wiring & electrical component for proper function		\$ 50.00	- 20
Remove and refix rear bumper reverse sensor		\$ 120.00	X
Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc		\$ 800.00	- 520
To putty & spray painting & including touch up paint on accident affected area		\$ 800.00	- 600
To apply Rust Proofing, reseal tuff-coating treatment on accident area		\$ 80.00	- 50

Total Parts & Labour of estimate for damaged vehicle

\$6,554.80

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

9-354830
3861.22

Liability

1. The amount of the estimate is based on the survey of the damaged vehicle.

2. The amount of the estimate is based on the survey of the damaged vehicle.

3. The amount of the estimate is based on the survey of the damaged vehicle.

4. The amount of the estimate is based on the survey of the damaged vehicle.

5. The amount of the estimate is based on the survey of the damaged vehicle.

6. The amount of the estimate is based on the survey of the damaged vehicle.

7. The amount of the estimate is based on the survey of the damaged vehicle.

8. The amount of the estimate is based on the survey of the damaged vehicle.

9. The amount of the estimate is based on the survey of the damaged vehicle.

10. The amount of the estimate is based on the survey of the damaged vehicle.

Acknowledged by Repairer

Signature

Date

Not Authorized

22/7/19

The photo Attached

3 day.

2/5 \$3100

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19012847/USF3N2

Date: 30/07/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01017561
Claimant Vehicle No :	GBD4333T	Insured Vehicle No :	SJY9543R
Date of Loss:	06/06/2019	Nature of Claim:	TP
		Claim No:	CMTD1902738

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD4333T	Engine No:	1KD2455532
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (M)	Chassis No:	JTFAT35Y60K203790
Reg. Date:	27/10/2014 (Man. Year: 2014)	Odometer:	188863 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15 (D)
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6/6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,704.80	2,691.22	2,013.58	42.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,190.00	660.00	35.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,554.80	3,881.22	2,673.58	40.79
Approved Total (Overridden) (\$\$)		3,100.00		
Nett Amount (\$\$)	6,554.80	3,100.00	3,454.80	52.71

INSPECTION

Date of Assignment:	22/07/2019	
Date Inspected:	22/07/2019	Inspected At: Liu's Brother Auto Workshop (HQ) BLOCK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Jul 2019)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD4333T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent/Buckled	481.60 F	*481.60 FL
2	1		*FRONT STEP PANEL	Not Necessary	312.60 F	*- FL
3	1		*FRONT N/S HEAD LAMP	Cracked	988.60 F	*922.10 FL
4	1		*FRONT N/S CORNER PANEL	Distorted	376.50 F	*376.50 FL
5	1		*FRONT N/S CORNER PANEL GARNISH	Cracked	199.80 F	*199.80 FL
6	1		*FRONT GRILLE	Repair	488.30 F	*- FL
7	1		*FRONT TOYOTA MOTIF	Not Necessary	78.10 F	*- FL
8	1		*FRONT N/S DOOR	Dented/Bent	1,568.30 F	*1,568.30 FL
9	1		*SET FRONT BUMPER CLIPS	Not Necessary	65.00 FS	*- FS
10	1		*SET FRONT HEAD LAMP CLIPS	Not Necessary	48.00 FS	*- FS
11	1		*SET FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
12	1		*FRONT DOOR LTA CORPORATE ROC DETAIL STICKER	Necessary	48.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,704.80	3,578.30
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	887.08
Total Parts (\$\$)	4,704.80	2,691.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	120.00	0.00
3	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCs	New	800.00	520.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	800.00	600.00
5	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	50.00
Gross Labour Cost (S\$)			1,850.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >