3 ,	ASS, REC. BY:	Him	ASSIGNMEN	T (Office)		ime:
	From (Person):	Chang GOON SEM	OI.	Bill to:		
	Estimated Cost OD/TP/WS/	TP RES / OD RES / E	VA/INV/MV/CS			Sau 7930B
	at Workshop m/	Igna buert Av	E 7 #01-36	KARLI B	WET MUTO	707354CD2
	Policy No: DW Sum Insured:	APCSN302836	019044	Claim No: Excess:		A 15.07-2019
	Make of Veh: (Client's Record) CA / REV / Date/Time:	REP. / REV 24 HRS	Person Contacted;		H. Vehic	O.D. Endorsement:
	Date/Time	Action/Instruction () Estimat	٤		
		564 7930B	NKCT	1 (910 12/52)	24 99A	: 13/1/19
		Jump Sun	1 \$6000	CREd: 11	वविक : २५%	66%)
	- Y					

Nivitha (LKK Auto)

From:

Jerome Soh < jeromesoh@visionlawllc.com>

Sent:

Monday, 22 July 2019 10:15 AM

To:

'Chong Boon Sen'; 'Admin-D (LKKAuto)'

Cc:

'assignments'

Subject:

RE: OUR REF: SNM19D203354-CHONGBS & YR REF: S125.111018.19 -PRS

Dear Celine,

Sheng Li Lai 2 Kaki Bukit Avenue 2 #01-36 Kaki Bukit Auto Hub 2 Singapore 417921

Contact Person: Mr Low 9111-9222

Jerome Soh Assistant Secretary Vision Law LLC 133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Tel: 6534-2811 Fax: 6535-6802

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

Sent: Monday, 22 July, 2019 10:20 AM

To: Admin-D (LKKAuto); jeromesoh@visionlawllc.com

Cc: assignments

Subject: RE: OUR REF: SNM19D203354-CHONGBS & YR REF: S125.111018.19 -PRS

Without Prejudice

Dear Jerome.

Appreciate providing workshop details.

Chong Boon Sen

Claims Executive Department

Veh In- Advan

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909 DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ |

WeChat: 太平狮城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Monday, 22 July, 2019 9:59 AM

To: Chong Boon Sen <booksen.chong@sg.cntaiping.com>; jeromesoh@visionlawllc.com

Cc: assignments <assignments@lkkauto.com>

Subject: RE: OUR REF: SNM19D203354-CHONGBS & YR REF: S125.111018.19 -PRS

Dear Boon Sen.

Please provide workshop details.

Best Regards

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

Sent: Friday, 19 July 2019 5:40 PM To: jeromesoh@visionlawllc.com

Cc: 'assignments' <assignments@lkkauto.com>

Subject: RE: OUR REF: SNM19D203354-CHONGBS & YR REF: S125.111018.19 -PRS

WITHOUT PREJUDICE

Dear Sir.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chong Boon Sen

Sent: Thursday, 18 July, 2019 3:25 PM

To: jeromesoh@visionlawllc.com

Subject: RE: OUR REF: SNM19D203354-CHONGBS & YR REF: S125.111018.19 -PRS

Without Prejudice

Dear Sir,

We refer to your email below.

> We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey

as a single joint expert.

> ADRIAN LING	
> Kelvin Ang	
> SEE CHEW SENG	
> MOHD FADHILAH BIN OSMAN	Q
> XING QUO QIANG	
> KENNETH KONG	
> SIMON HO	
> CHUA WEIJIE	
> MARCUS CHUA	
> HENRY NG	

> Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

> You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert

Chong Boon Sen

Claims Executive Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909 DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Thursday, 18 July, 2019 3:16 PM

To: Chong Boon Sen < boonsen.chong@sg.cntaiping.com>; jeromesoh@visionlawllc.com

Cc: Chee So Chow < sochow.chee@sg.cntaiping.com>; Alfred Toh < alfred.toh@sg.cntaiping.com>

Subject: OUR REF: SNM19D203354-CHONGBS & YR REF: S125.111018.19 -PRS

Dear Boon Sen,

Please conduct PRS -SQ1160A soonest possible.

File with officer-in charge -Chong Boon Sen -DID- 6389 6171

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email: claimsdept@sg.cntaiping.com

Website:www.sq.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Jerome Soh [mailto:jeromesoh@visionlawllc.com]

Sent: Thursday, 18 July, 2019 11:14 AM To: Chong Boon Sen; Claims Dept of CTI

Subject: Our ref: S125.111018.19 Your Ref: SGU 7930 B

Dear Chong Boon Sen,

Refer to the above matter, let us have the surveyor list. Thank you.

Jerome Soh Assistant Secretary Vision Law LLC 133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Tel: 6534-2811 Fax: 6535-6802

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any

person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email

transmission or any illegal or unauthorised usage or tampering of its email system.

his email has been scanned by the Symantec Email Security.cloud service. for more information please visit http://www.symanteccloud.com				
	This email has been checked for viruses by AVG antivirus software. www.avg.com			
This email For more in	has been scanned by the Symantec Email Security.cloud service. formation please visit http://www.symanteccloud.com			
VISION LAW	LLC Solicitors ded with limited liability)			
	Ou Hibit IIIII			

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

B+ ...

- Please report <u>correctly</u> the details of the accident to speed up the claims process,
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the loadgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available
- aforesaid.

aforesaid.	ACCIDENT STATEMENT
	16/07/2019 12:02
Date Of Report	15/07/2019 20:10
Date Of Accident	SENG KANG WEST ROAD TRAFFIC JUNCTION
Exact Location Of Accident	SINGAPORE
Country/State of Loss	ETAILS OF OWN VEHICLE
	Company of the Compan
Vehicle Registration Number	SQ1160A
Insured/Policyholder	19 10 10 10 10 10 10 10 10 10 10 10 10 10
Name Of Registered Owner	LIEW SHENG MING
NRIC No	S7630876D
Email Address	WESTONLIEW@YAHOO.COM
Mobile Phone No	(LOCAL) +65-81112332
Alternative Phone No	OTHERS-81112332
Vehicle Particulars	是一个是一种是我们的是一个工作。这是一个一种的数据,但是他们的
Manufacturer	BMW
Model	520I-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	及其中,在自然的特别。在 5 · 20 · 20 · 20 · 20 · 20 · 20 · 20 ·
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5085281013-02
Cover Note Number	DRIVO CLASSIC
Driver	which is a second of the secon
Name of Driver	LIEW SHENG MING
NRIC No	S7630876D
Date Of Birth	25/09/1976
Occupation	INDOOR
Date Of Driving Pass	02/01/1996
Driving Experience	23 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81112332
Fax Number	
Contact Number	OTHERS-81112332
EMail Address	WESTONLIEW@YAHOO.COM
	*

A. 1.

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKE8217H

Vehicle Make/Model/Colour

BLACK AUDI

Details Of Properties

FRONT PORTION

Vehicle Category

PRIVATE CAR

Name of Driver

ER VICTOR

NRIC/Passport Number

S8628145G

Contact Number

96918759

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Passenger 1

NAME:

: PASSENGER

GENDER:

: FEMALE

DETAILS OF INJURED PERSON 1

Name

LIEW SHENG MING

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SQ1160A

Were seat belts worn?

YES

Was this injured conveyed to hospital by

NO

ambulance?

Address Postcode

DETAILS OF INJURED PERSON 2

Name

ZHANG SHU MEI

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SQ1160A

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan Pg. 2

\$			<u>+</u>
	SENG KANG WES	T ROAD TRAFFIC JUNCTION	-
	Face and Politication	Vehicle B: SKE8217H	
CRIBE CIRCUMSTANCES	S OF THE ACCIDENT		THE REAR PORTION OF VEHIC
CRIBE CIRCUMSTANCES OPPED AT THE TRAFFIND PROPELLED TO HIT	S OF THE ACCIDENT C JUNCTION STATIONARY W INTO THE REAR PORTION OF	HEN VEHICLE C HIT INTO	THE REAR PORTION OF VEHICL KING SCENE PHOTO, MY CAR
CRIBE CIRCUMSTANCES	S OF THE ACCIDENT	HEN VEHICLE C HIT INTO	THE REAR PORTION OF VEHIC KING SCENE PHOTO, MY CAR
CRIBE CIRCUMSTANCES	S OF THE ACCIDENT C JUNCTION STATIONARY W INTO THE REAR PORTION OF	HEN VEHICLE C HIT INTO	THE REAR PORTION OF VEHIC KING SCENE PHOTO, MY CAR
CRIBE CIRCUMSTANCES	S OF THE ACCIDENT C JUNCTION STATIONARY W INTO THE REAR PORTION OF	HEN VEHICLE C HIT INTO	THE REAR PORTION OF VEHIC KING SCENE PHOTO, MY CAR
CRIBE CIRCUMSTANCES	S OF THE ACCIDENT C JUNCTION STATIONARY W INTO THE REAR PORTION OF	HEN VEHICLE C HIT INTO	THE REAR PORTION OF VEHIC KING SCENE PHOTO, MY CAR
CRIBE CIRCUMSTANCES	S OF THE ACCIDENT C JUNCTION STATIONARY W INTO THE REAR PORTION OF	HEN VEHICLE C HIT INTO	THE REAR PORTION OF VEHICL KING SCENE PHOTO, MY CAR
CRIBE CIRCUMSTANCES	S OF THE ACCIDENT C JUNCTION STATIONARY W INTO THE REAR PORTION OF	HEN VEHICLE C HIT INTO	THE REAR PORTION OF VEHICLE IN CARE
CRIBE CIRCUMSTANCES	S OF THE ACCIDENT C JUNCTION STATIONARY W INTO THE REAR PORTION OF	HEN VEHICLE C HIT INTO	THE REAR PORTION OF VEHICLE IN THE PORTION OF
CRIBE CIRCUMSTANCES	S OF THE ACCIDENT C JUNCTION STATIONARY W INTO THE REAR PORTION OF	HEN VEHICLE C HIT INTO	THE REAR PORTION OF VEHICLE IN THE PORTION OF VEHICLE IN THE P

DECLARATION

47 17.

I/We declare the foregoing particulars are true in every respect.

16/7/2019 12:17

Driver's Signature (If driver is not the policyholder) Date & Time:

16/7/2019 12:17

Reporting Centre Personnel's Signature Name: Eric Woo Jun Klat NRIC/ Fin No: \$992753

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	Singapore NRIC
Owner ID Type:	876D
Owner ID: Vehicle Details	
Vehicle No.:	SQ1160A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Jul 2019
Vehicle Make:	B.M.W.
Vehicle Model:	5201 2.0L AT D/AB 2WD 4DR GAS/D NAV
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	A3350366N20B20B
Chassis No.:	WBAXG12010DX52275
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$41,292.00
Original Registration Date:	31 Jan 2013
First Registration Date:	31 Jan 2013
Transfer Count:	1
Actual ARF Paid:	\$36,292.00
Intended PARF Rebate Details	2. [1] A. M.
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jan 2023
PARF Rebate Amount:	\$23,589.00
Intended COE Rebate Details	201-2022
COE Expiry Date:	30 Jan 2023
COE Category:	E - Open Category 10
COE Period(Years):	77
QP Paid:	\$97,000.00
COE Rebate Amount:	\$31,860.00
Total Rebate Amount:	\$55,449.00

The information contained herein is correct as at 18 Jul 2019

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources





Bidded Car Plate Number for sale Looking for auspicious numbers?

Browse our list of hottest bidded car plate numbers for sale.





Post an Advertisement Sell it vourself! Advertise it at just \$58 until it's SOLD!



PRIME MOTOR & LEASING With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.



On The Move .







Car Aftermarket •



Model

\$70,800

\$14,590 /yr 28-Dec-2012

1,997 cc 121,100 km Luxury Available

Offer 1.99% Interest! Vehicle Well Maintained By Owner, Full Servicing Records With PML. Buy With A Peace Of Mind! Attractive Trade In And Flexible Loan Available. Viewing Available Daily From 9am To 7pm, Call Us Now!

RW Automobiles

Posted, 14-july 2010. Took: 2012 BMW 53th, 2012 bmw 52th, IntW 52th, Immw 52th, BMW, 52th, Lised BMW

Pedyo: 03-sa-2007 - Tagy 2012 MW 525, 2012 for \$30, 0102 \$33, 54W \$20, 04W, \$20, 04M BMW



BMW 5 Series 520i

\$73,888

\$15,510 /yr

28-Dec-2012

1 997 cc


75,000 km

Luxury

Available

OF ZOTTOT STORE

PML Unit, 1 Owner Only! Low Mileage, Very Well Maintained Interior And Exterior! Well Taken Care Of! Flexible Loan Packages Available! Trade In Welcome!





Price ▼ ② Depreciation ▼ ② Reg Date ▼ ③ Eng Cap ▼ ② Mileage ▼ ② Veh Type ▼

SHENG LI LAI

WBAX G12010 DX52275

2 Kaki Bukit Ave 2 (Kaki Bukit Auto Hub), #01-36, Singapore 417921

H/P: 9111 9222 (Low Eng Chong)

Tel: 6842 0302

Fax: 6746 0295

Email: sllshenglilai@gmail.com

Vehicle number: SQ1160A

serise.

Vehicle Made & Model: BMW 520i

Qty	List Items	Amount \$
1	Rear boot lid Devted	1655 2,210.42
1	Rear hoot RMW logo 2	68.85
1	Rear boot emblem "520i"	89.95
2	Rear boot lamps - L/R @ 383.35 M	766.70
1	Rear boot inner lock	541.32
1	Rear boot w/strip	211.93
1	Rear humper Distorter	/5631,815.93
1	Rear bumper tow cover	28 85
2	Rear bumper reflectors - L/R @ 86.50 LH wt	173.00 86.50
1	Rear bumper CTR guide	189.63
1	Rear bumper reinforcement	693.93
1	Rear bumper reinforcement pad could	153.55
1	Rear bumper lower guide could	126.10
2	Poor humperside guides - 1/R @ 89 95 New	179.90
4	Rear bumper PDC sensors @ 363.05 3 Pieus dans	1,452.20 840
1	Rear bumper PDC sensor wire	313.54 🖈
1	Rear bumper PDC sensor control unit	581.60 -
1	Rear end panel	1,018.43
1	Rear end panel trim Quela	199.62
1	Rear exhaust silencer 3 2 2	1,695.80 +
2	Rear exhaust mountings @ 42.20 608	6.8) 84.40 ~
1		12.46 460.20 +
1	Rear floor compartment panel	841.55 7
1	Rear smart keyless antenna	199.65 🗡
2	Rear taillamps - L/R @ 591.35 Me Me	1,182.70 *.
2	Rear kick sensor	241.55 +
-		-total 15,521.30
	Le	ss 5% 776.07
	Tota	al List 14,745.24

Vehicle number: SQ1160A

Vehicle Made & Model: BMW 520i

Labour charge

Labour charges		50.06 30
To check rear electrical wiring		50,00 30.
To remove, refix rear inteior trims to assist repair	10/0	
To remove, refix rear exhaust systems	1760	150.00
To diagnos, erase fault memory after repair		380.00-153
To respray undercoating		120.00
To respray painting and etc		1,200.00 750
Panel beating, cut, weld remove & replacing above pa	rts	1,200:00 750:
1 41151 2541110)	Total Labour	3,250.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

17,995.24

total: 7542.46 6/5: 6/6.

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation.
- * Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	CKING Est Submitted	Adj Assigned	Adj Rpt	1	Adj Subr	nitted	Ins Auth'ed	Pending for Survey Report Cancel Case	
Main	22 Jan 2020	Edc Dabineces	22 Jan 2020 11:27 Edit Adj Rpt	S\$6,000.0 Edit Estima		\$\$6,000 View Rp				
	Main	Re	ference		Claim D	etails		Document	ts	Show All
CLAIM SU	BFOLDER DE	TAILS	Control of the same				[Create	d by insurer]		
Insured:	-, Co. Re									
Main Claimant:	LIEW SH	ENG MING, ID:	S7630876D				1	0.00 00 FO		
Vehicle Reg	SQ1160	A			10000000	of Loss:	15/07/20 [77 Mon	019 20:00 - :59 ths and 15 Days F	rom LTA Reg Date	(Man Yr)]
Claim Type	: TP / SNI	M19D203354C0	2		Policy Note I	/Cover No.:	DMPCSN	DMPCSN30283019044		
Vehicle Reg No. (Insured):	SGU7930	В			Policy (Clain	No. nant):	5085281	1013-02		
(msureu).					Exces		\$\$0.00			
Repairer:	Sheng Li	Lai (KAKI BUKI) NO. 2 KAKI BI	JKIT AVE 2,	# 01-36	AUTOHU	JB KAKI B	UKIT, 417921 Kaki	Bukit - Tel: 91119	222
Handling Insurer:	China Ta	iping Insurance	(Singapore) Pt	e. Ltd. (HQ) - Tel: 6	389 611	1 [Han	dled by Chong Bo	on Sen]	
Claimant's Insurer:	NTUC Inc	come Insurance	Co-operative L	td (HQ) - Te	d:			THE [Final	Pnt due 03/02/	20201
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel	6256-3561	[Hand	dled by A	ADRIAN	LING] [Final		
ASSOCIA	TED MAIL RI	ECEIVED							View All Compo	se Case Mail
There are	no mail for this	s case.								
ALL ASS	OCIATED TA	sks=					View A	All Search Tasks	Create New Task	Complete
Due Da No results	te Priority		Group Sub	ject Har	dler	Assign	ned By	Completed Or	Created Or	Done

Claim Documents

*SQ1160A (SNM19D203354C02)
[SGU7930B]
TP
LIEW SHENG MING
Jul 15 2019 8:00PM
[-]
Sheng Li Lai

	essment Reports		1 per	page ▼	~
0.00000		NTUC Income Insurance Co-operative Ltd (HQ)		Thumbnail	Print
No 1	04/09/19 01:42	Accident Statement	0	Load HTM	
1	04/03/13 01.42				179
Pho	tos/Images		3 per	page ▼ Thumbnail	Print
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)		CONTRACTOR AND ADDRESS OF	
1	16/07/19 12:08	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
2	16/07/19 12:08	Accident Photo [Linked Accident Report Documents]	0	Load JPG	₹
3	16/07/19 12:08	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
4	16/07/19 12:08	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
5	16/07/19 12:08	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
6	16/07/19 12:08	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
7	16/07/19 12:08	Accident Photo [Linked Accident Report Documents]	0	Load JPG	•
8	16/07/19 12:08	Accident Photo [Linked Accident Report Documents]	0	Load JPG Thumbnail	Print
No:	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	0	Load JPG	2
1	22/01/20 11:58	General View		100000000000000000000000000000000000000	-
2	22/01/20 11:58	General View	0	Load JPG	•
3	22/01/20 11:58	General View	0	Load JPG	
4	22/01/20 11:58	General View	0	Load JPG	V
5	22/01/20 11:58	General View	0	Load JPG	•
6	22/01/20 11:58	General View	0	Load JPG	•
7	22/01/20 11:58	General View	0	Load JPG	Y
8	22/01/20 11:58	General View	0	Load JPG	•
9	22/01/20 11:58	General View	0	Load JPG	S
10	22/01/20 11:58	General View	0	Load JPG	8
11	22/01/20 11:58	General View	0	Load JPG	•
12	22/01/20 11:58	General View	0	Load JPG	•
13	22/01/20 11:58	General View	0	Load JPG	~
14	22/01/20 11:58	General View	0	Load JPG	•
15	22/01/20 11:58	General View	0	Load JPG	
16	22/01/20 11:58	General View	0	Load JPG	
17	22/01/20 11:58	General View	0	Load JPG	€
18	22/01/20 11:58	General View	0	Load JPG	•
11.00	22/01/20 11:58	General View	0	Load JPG	•
19	22/01/20 11:58	General View	0	Load JPG	1

20	essment Reports		1 per	page ▼	~
	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)		Thumbnail	Print
1	22/01/20 11:58	General View	0	Load JPG	4
	22/01/20 11:58	General View	0	Load JPG	4
2		General View	0	Load JPG	1
3	22/01/20 11:58		0	Load JPG	1
4	22/01/20 11:58	General View	0	Load JPG	1
5	22/01/20 11:58	General View	0	Load JPG	~
6	22/01/20 11:58	General View	0	Load JPG	~
7	22/01/20 11:58	General View	0	Load JPG	4
8	22/01/20 11:58	General View	0	Load JPG	1
9	22/01/20 11:58	General View	0	Load JPG	1
0	22/01/20 11:58	General View	0	Load JPG	~
1	22/01/20 11:58	General View	0	Load JPG	~
12	22/01/20 11:58	General View	0	Load JPG	•
13	22/01/20 11:58	General View	0	Load JPG	
34	22/01/20 11:58	General View	0	Load JPG	•
5	22/01/20 11:58	General View	0	Load JPG	•
36	22/01/20 11:58	Reinspection Photo	0	Load JPG	•
37	22/01/20 11:58	Reinspection Photo	0	Load JPG	
18	22/01/20 11:58	Reinspection Photo	0	Load JPG	4
19	22/01/20 11:58	Reinspection Photo	0		·
10	22/01/20 11:58	Reinspection Photo		Load JPG	•
1	22/01/20 11:58	Reinspection Photo	0	Load JPG	4
12	22/01/20 11:58	Reinspection Photo	0	Load JPG	-
13	22/01/20 11:58	Reinspection Photo	0	Load JPG	4
14	22/01/20 11:58	Reinspection Photo	0	Load JPG	•
15	22/01/20 11:58	Reinspection Photo	0	Load JPG	•
16	22/01/20 11:58	Reinspection Photo	0	Load JPG	~
47	22/01/20 11:58	Reinspection Photo	0	Load JPG	4
18	22/01/20 11:58	Reinspection Photo	0	Load JPG	4
19	22/01/20 11:58	Reinspection Photo	0	Load JPG	4
50	22/01/20 11:58	Reinspection Photo	0		4
51	22/01/20 11:58	Reinspection Photo	0		1
52	22/01/20 11:58	Reinspection Photo	0	and the second	-
53	22/01/20 11:58	Reinspection Photo	0		1000
54	22/01/20 11:58	Reinspection Photo	0		~
55	22/01/20 11:58	Reinspection Photo	0		1 200
56	22/01/20 11:58	Reinspection Photo	0	-	-
57	22/01/20 11:58	Reinspection Photo	0		
58	22/01/20 11:58	Reinspection Photo	0		
59	22/01/20 11:58	Reinspection Photo	0	_	
60	22/01/20 11:58	Reinspection Photo	0		
61	22/01/20 11:58	Reinspection Photo	0	_	
62	22/01/20 11:58	Reinspection Photo	0		-
63	22/01/20 11:58	Reinspection Photo	0		
64	22/01/20 11:58	Reinspection Photo	0		-
65	22/01/20 11:58	Reinspection Photo	0	_	-
66	22/01/20 11:58	Reinspection Photo	0	Load JPG	
67	22/01/20 11:58	Reinspection Photo	0	Load JPG	
68	22/01/20 11:59	After Repair Photo	0	Load JPG	4

Assessment Reports		1 per s	1 per page ▼		
			Thumbnail	Print	
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	0	Load JPG	4
69	22/01/20 11:59	After Repair Photo	0	Load JPG	~
70	22/01/20 11:59	After Repair Photo			•
71	22/01/20 11:59	After Repair Photo	0	Load JPG	3
Documentation		1 per page ▼		1	
7000		NTUC Income Insurance Co-operative Ltd (HQ)		Thumbnail	Print
No	Finalized On		0	Load TIF	
1	16/07/19 12:24	Sketch Plan [Linked Accident Report Documents]	0	Lodd 111	

Linked Accident Report Documents

			View	View in Brow	v in Browser ▼	
A	ocement Deports		1 per	page 🔻	•	
2000	Assessment Reports			Thumbnail	Print	
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ) Accident Statement	0	Load HTM		
1	04/09/19 01:42	Accident Statement				
Dho	otos/Images		3 per	page 🔻	1	
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	at a principal of the p	Thumbnail		
	16/07/19 12:08	Accident Photo	0	Load JPG	1	
1	2007	Accident Photo	0	Load JPG	•	
2	16/07/19 12:08		0	Load JPG	~	
3	16/07/19 12:08	Accident Photo	0	Load JPG	•	
4	16/07/19 12:08	Accident Photo	0	Load JPG	•	
5	16/07/19 12:08	Accident Photo	1000		•	
6	16/07/19 12:08	Accident Photo	0	Load JPG	1.00	
7	16/07/19 12:08	Accident Photo	0	Load JPG	•	
8	16/07/19 12:08	Accident Photo	0	Load JPG	•	
			1 per	page v	•	
Do	cumentation		1 pc	Thumbnail	-	
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	0	Load TIF		
1	16/07/19 12:24	Sketch Plan	0	2000 111		

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19012852/ATF3S2

Date:

05/02/2020

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore) Pte.

Nature of Claim:

DMPCSN30283019044

Engine No:

Chassis No:

Odometer:

Claimant Vehicle

SQ1160A

Insured Vehicle No:

SGU7930B

Date of Loss:

No:

15/07/2019

TP

Claim No:

SNM19D203354C02

A3350366N20B20B

95571 km

WBAXG12010DX52275

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SQ1160A

Make & Model:

BMW 5201, 2.0 (A)

Reg. Date: Colour:

31/01/2013 (Man. Year: 2012)

White

Engine Capacity:

1997 cc N/A

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good Yes

Steering (Serviceable): Engine Modification:

Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: Front Left Side: Front Right Side: 225/55 R17

Pirelli 6 mm Pirelli 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 225/55 R17

Pirelli 6 mm Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
		14,745.23	5,782.47	8,962.76	60.78
Parts Miscellaneous Items		0.00	0.00	0.00	
		3,250.00	1,760.00	1,490.00	45.85
Labour Deightwork Labour		0.00	0.00	0.00	
Paintwork Labour Towing		0.00	0.00	0.00	
Towning	Calculated Gross Total (S\$)	17,995.23	7,542.47	10,452.76	58.09
A	approved Total (Overridden) (S\$)		6,000.00		
	Nett Amount (S\$)	17,995.23	6,000.00	11,995.23	66.66

INSPECTION

Date of Assignment:

22/01/2020

Sheng Li Lai

Date Inspected:

18/07/2019 Inspected At:

NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI

Singapore 417921

Estimated Period of Repair:

5.0 days

ADRIAN LING Adjuster:

Manager:

DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printrpt&caseid=909170&extid=329407&CFID=66567139&C... 1/4

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 05 Feb 2020)

Parts:

143

BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SQ1160A)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Qty Par	t No. Particulars	Condition	Repairer's	Amount
	•	*REAR BOOT LID	Dented	2,210.42 FL	*1,655.00 FL
1	1	*REAR BOOT BMW LOGO	Necessary	68.85 FL	*68.85 FL
2	1	*REAR BOOT EMBLEM 520I	Necessary	89.95 FL	*89.95 FL
3	2	*REAR BOOT LAMPS - L/R	Not Necessary	766.70 FL	*- FL
4	1	*REAR BOOT INNER LOCK	Not Necessary	541.32 FL	*- FL
5	1	*REAR BOOT W/STRIP	Necessary	211.93 FL	*211.93 FL
6		*REAR BUMPER	Distorted	1,815.93 FL	*1,563.00 FL
0	1	*REAR BUMPER TOW COVER	Deformed	28.85 FL	*28.85 Fl
8	1	*REAR BUMPER REFLECTORS - L/R	N/s Cut	173.00 FL	*86.50 Fl
9	1	*REAR BUMPER CTR GUIDE	Cracked	189.63 FL	*189.63 Fl
10	1	*REAR BUMPER REINFORCEMENT	Bent	693.93 FL	*693.93 FI
11	1	*REAR BUMPER REINFORCEMENT PAD	Cracked	153.55 FL	*153.55 FI
12	1	*REAR BUMPER LOWER GUIDE	Cracked	126.10 FL	*126.10 FI
13	2	*REAR BUMPER SIDE GUIDES - L/R	Necessary	179.90 FL	*179.90 FI
14		*REAR BUMPER PDC SENSORS	Damaged 3pcs Only	1,452.20 FL	*840.00 FI
15	4	*REAR BUMPER PDC SENSOR WIRE	Not Necessary	313.54 FL	*-FI
16		*REAR BUMPER PDC SENSOR CONTROL UNIT	Not Necessary	581.60 FL	*- FI
17	1	*REAR END PANEL	Repair	1,018.43 FL	*-F
18		*REAR END PANEL TRIM	Deformed	199.62 FL	*199.62 F
19	1	*REAR EXHAUST SILENCER	Not Necessary	1,695.80 FL	*- F
20	1	*REAR EXHAUST MOUNTINGS	Not Necessary	84.40 FL	*- F
21 22	1	*REAR FLOOR BOARD	Not Necessary	460.20 FL	*-F
	1	*REAR FLOOR COMPARTMENT PANEL	Not Necessary	841.55 FL	*-F
23	1	*REAR SMART KEYLESS ANTENNA	Not Necessary	199.65 FL	*- F
	2	*REAR TAILLAMPS - L/R	Not Necessary	1,182.70 FL	*-F
25	2	*REAR KICK SENSOR	Not Necessary	241.55 FL	*-F
26		L=ListItemDisc.	-		
r=r	гапспіве рак.	L-Lioutomore,	Sub Total (S\$)	15,521.30	6,086.81
		- List Item Disco	unt on L Items 5.00/5.00% (S\$)	776.07	304.34
			Total Parts (S\$)	14,745.23	5,782.47

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Re	commended Labour Particulars	Lab.Type	Repairer's	Amount
Lab	our Items	New	50.00	30.00
1	TO CHECK REAR ELECTRICAL WIRING.	New	150.00	80.00
2	TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR.	New	150.00	0.00
3	TO REMOVE, REFIX REAR EXHAUST SYSTEMS.	New	380.00	150.00
4	TO DIAGNOS, ERASE FAULT MEMORY AFTER REPAIR.	New	120.00	0.00
5	TO RESPRAY UNDERCOATING. TO RESPRAY PAINTING AND ETC.	New	1,200.00	750.00
7	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS.	New	1,200.00	750.00
	Gross Labo	ur Cost (S\$)	3,250.00	1,760.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >