

15/3/2010

INS. CASE OWNER:

Stacey Lim Khong

CC 4, Ass 190 12862, E pa352

LKK:

IDAC:

127812

Surveyor:

Steve

DOI:

ASSIGNMENT

m7/2019

Date / Time:

m7/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKT 2331 X

Name of Insured:

Ng Wai Fong

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

18/07/2019

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

20k hu chuan

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

S9m01114

Policy No.:

Make / Model:

Place of Accident:

SKT 2331 X

SJL 1366 L

SLR 4313 J

SLV 2460 J → SLm6332



INSRS:

WSP:

Tel:

Liability:

RMKS:

m



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kah Motor

7p



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

SJ25561

Date/ Time

SJL 1366 L - X;

SKT 2331 X - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

XIA BY (25/7/19)

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

28 (see above)

NO or B 28, Ass. Lia:

127812

Repair Cost:

SS

21562.85

Loss of Rental (LOR):

SS

days)

Loss of Use (LOU):

SS

950.00 (\$50)

x

19 days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

22512.85

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

22512.85

Name 1:

Kah Motor Co. Sdn. Bhd.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT 31/10/19

371.00

Warrant

Steve

REF:


ASM (AXA)

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop mis: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 15 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJK 1366L Yr Regn: 8/10/18
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Jazz C.C. 1318
 Colour: Silver A/C Insured / Std / NI / NA
 Sp. Reading: 007379 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHMGK 3FSJX2 17990
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 175/65R15 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 18/7/19 D.O.I. 22/7/19
 Survey held at Kah Mohr
 Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MK- 66000
 PV- 34467
 NV- 31533

-PIP \$ 20152.21 (Red # 63829/240)

15.4 2Sun + 2APRS = 20day.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Y S + RS \$

Y Photos

Y Other

Y

2019

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech Invs (\$)

☐ Weekend (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	864C
Vehicle Details	
Vehicle No.:	SJK1366L
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3 CVT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	L13B11031279
Chassis No.:	JHMGK3850JX227000
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,812.00
Original Registration Date:	08 Oct 2018
First Registration Date:	08 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$5,812.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Oct 2028
PARF Rebate Amount:	\$4,359.00
Intended COE Rebate Details	
COE Expiry Date:	07 Oct 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,699.00
COE Rebate Amount:	\$30,108.00
Total Rebate Amount:	\$34,467.00

The information contained herein is correct as at 22 Jul 2019

OK



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SJK1366L

Chassis No : JHMGK3850JX227000

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : CHUNG CHOON CHEN

Ins Policy No. :

Date of Accident : 18/7/2019

Document No. : SQT19003173

Date : 19. Jul 2019

Customer No. : WZA006

Svc Advisor : IVAN TEO BOON KIAT

Engine No : L13B11031279

Date | Time : 19. Jul 2019 3:01:42 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: CHUNG CHOON CHEN						
	OWNER INSURER: LIBERTY INSURANCE						
	ACC DATE: 18/07/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA						
	TP VEH: SKT2331X						
04711-T5A-J50ZZ	FACE.FR.BUMPER / CH	1	504.60	25	378.45	26.49	404.94
71193-T5A-000	SPACERR.FR.BUMPER / MC	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER / MC	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER / MC	19	2.30	25	32.77	2.29	35.06
60261-T5R-A00ZZ	PANELL.FR.FENDER / DD	1	398.60	25	298.95	20.93	319.88
33150-T5A-J81	HEADLIGHT ASSY.L. / MC	1	479.70	25	359.77	25.18	384.95
67050-T5A-U00ZZ	PANEL COMPL.FR.DOOR X R (Try to repair first)	1	772.30	25	579.22	40.55	619.77
67364-T5A-003	TAPE SETL.FR.DOOR X / MC	1	33.60	25	25.20	1.76	26.96
72950-T5A-003	MOLDING ASSYL.RR.DOOR X / MC	1	33.60	25	25.20	1.76	26.96
72326-T5A-003	SEALFR.DOOR LOWER X / MC	1	19.70	25	14.77	1.03	15.80
72450-TD4-003	MOLDING ASSYL.FR.DOOR / MC	1	43.00	25	32.25	2.26	34.51
76258-T5A-J32	MIRROR ASSY.L. / BR	1	506.50	25	379.87	26.59	406.46
76251-T5A-J31ZG	CAPL.SKULL (COL) / BR	1	52.00	25	39.00	2.73	41.73
67550-T5A-N10ZZ	PANEL COMP.L.RR.DOOR X R	1	717.50	25	538.12	37.67	575.79
67865-T5A-003	TAPEL.RR.DOOR SASH X / MC	1	15.40	25	11.55	0.81	12.36
04646-TAR-320ZZ	PANEL SET.L.RR.OUTSIDE / DD	1	570.50	25	427.87	29.95	457.82
63720-T5A-900ZZ	GUTTER COMP.L.RR.PILLAR LOWER / DD	1	88.60	25	66.45	4.65	71.10
66100-TAR-T00ZZ	PANEL COMPRR. / DD	1	320.40	25	240.30	16.82	257.12
74592-T5B-003	FENDER.L.RR.INNER X / MC	1	79.00	25	59.25	4.15	63.40

Printed on 19/7/2019 5:10:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJK1366L
Chassis No : JHMGK3850JX227000
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : CHUNG CHOON CHEN
Ins Policy No. :
Date of Accident : 18/7/2019

Document No. : SQT19003173 Page 2
Date : 19. Jul 2019
Customer No. : WZA006
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L13B11031279
Date | Time : 19. Jul 2019 3:01:42 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
74591-T5A-N00	COVER,L.RR.FENDER / CR	1	42.60	25	31.95	2.24	34.19
84651-TAR-Z03ZA	LINING ASSYL.TRUNK X ✓ CR	1	169.00	25	126.75	8.87	135.62
04715-T5A-J50ZZ	FACE,RR.BUMPER / PR	1	492.70	25	369.52	25.87	395.39
71502-T5A-J60	COVER,R.RR.BUMPER X NN	1	20.70	25	15.52	1.09	16.61
71507-T5A-J60	COVER,L.RR.BUMPER 3 MIS	1	20.70	25	15.52	1.09	16.61
71505-T5A-J50	GARNISH,RR.BUMPER / MIS	1	38.30	25	28.72	2.01	30.73
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE / PR	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE / DR	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER / RC	7	2.30	25	12.07	0.84	12.91
93903-25320	SCREWTAPPING 5X16 / RC	4	0.40	25	1.20	0.08	1.28
33550-T5A-J02	TAILLIGHT ASSYL. 2 BR	1	223.90	25	167.92	11.75	179.67
34155-T5A-J01	LIGHT ASSYL.LID X NN	1	81.70	25	61.27	4.29	65.56
68100-T5A-U10ZZ	TAIL GATE COMP / DO	1	730.60	25	547.95	38.36	586.31
75722-T5L-T01	EMBLEMRR. / RC	1	10.90	25	8.17	0.57	8.74
73561-T5A-003	GLASSL.QUARTER / RC	1	153.60	25	115.20	8.06	123.26
73525-SYY-000	RUBBERRR QTR W/SHIELD / RC	1 2	9.70	25	14.55	7.27	7.78
91501-T5A-003	CLIPQUARTER WINDSHIELD A / RC	1	3.70	25	2.77	0.19	2.96
91502-T5A-003	CLIPQUARTER WINDSHIELD B / RC	1	3.70	25	2.77	0.19	2.96
91503-T5A-003	CLIPQUARTER WINDSHIELD C / RC	1	2.50	25	1.87	0.13	2.00
BO-WS-SEALANT	WINDSCREEN SEALANT (N) / RC	1	60.00		60.00	4.20	64.20
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR / DR	1	320.00		320.00	22.40	342.40
42100-T5A-J15	BEAM ASSYRR.AXLE / DO	1	911.00	25	683.25	47.83	731.08
90164-SMG-E00	BOLTFLANGE 14X128 / RC	2 1	13.80	25 10.35	20.70	1.45	22.15
57475-T5A-003	SENSOR ASSYRR. / NN	1	51.60	25	38.70	2.71	41.41
52611-T5A-J12	DAMPER UNITRR. X NN	2	217.20	25	325.80	22.81	348.61
52722-T5A-J02	RUBBERRR.BUMP STOPPER X NN	1	29.00	25	21.75	1.52	23.27
52686-T5A-J01	COVERRR.UPPER DUST X NN	1	5.90	25	4.42	0.31	4.73
52673-T5A-J01	RUBBERRR.SHOCK ABSORBER MTG X NN	1	1.50	25	1.12	0.08	1.20
42700-TAR-E91	DISK ALUMINIUM WHEEL,16X6 X BT	2 1	772.30 418.40	25	1158.45 313.90	81.09	1239.54

Printed on 19/7/2019 5:10:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19003173	Page	3
	8 SHENTON WAY	Date	: 19. Jul 2019		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: IVAN TEO BOON KIAT		
Registration No	: SJK1366L	Engine No	: L13B11031279		
Chassis No	: JHMGK3850JX227000	Date Time	: 19. Jul 2019 3:01:42 PM		
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	Surveyor Name	:		
Owner's Name	: CHUNG CHOON CHEN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 18/7/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
YH-175/65R15-AE50	YOKOHAMA TYRE X NN	1	114.00		114.00	7.98	121.98
73127-TY0-000	RUBBER CWINDSHIELD DAMPER / NC	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER / NC	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5 / NC	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N) / NC	1	60.00		60.00	4.20	64.20
Sum Item					7899.23	552.95	8,452.18
BOSUN	SUNDRIES	net 1	100.00 80		100.00	7.00	107.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BG51R	REPLACE RR. L QTR GLASS.(N)	1	380.00 200		380.00	26.60	406.60
BODAMKIT	WINDSCREEN DAM KIT.	net 1	100.00 80		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 150		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4PCS (N)	1	180.00		180.00	12.60	192.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00		560.00	39.20	599.20
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	450.00 (Car 1 phit)		450.00	31.50	481.50
BOBC	BODY UNDERSIDE COATING (N)	1	450.00 200		450.00	31.50	481.50
BOJSE	BODY JOINT SEALANT	1	100.00 80		100.00	7.00	107.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	480.00 450		480.00	33.60	513.60
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	480.00 450		480.00	33.60	513.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00 380		560.00	39.20	599.20
BKDR11R	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	1	560.00 X		560.00	39.20	599.20
BMU21R	REMOVE & REPLACE RR L UNDERCARRIAGE PARTS. (N)	1	1680.00 1120 560 x 2		1680.00	117.60	1797.60
BKOT00A	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT	1	1800.00 1200 13w-w (Car 1 phit)		1800.00	126.00	1926.00
BKFE21R	CUT & RENEW RR L FENDER. STRAIGHTEN INNER PANEL	1	4480.00 3920 560 x 7		4480.00	313.60	4793.60
BP08R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (8P)	1	4050.00 3600 450 x 8		4050.00	283.50	4333.50

Printed on 19/7/2019 5:10:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJK1366L
Chassis No : JHMGK3850JX227000
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : CHUNG CHOON CHEN
Ins Policy No. :
Date of Accident : 18/7/2019

Document No. : SQT19003173
Date : 19. Jul 2019
Customer No. : WZA006
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L13B11031279
Date | Time : 19. Jul 2019 3:01:42 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 4

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Sum Labor					17150.00	1,200.50	18,350.50
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT-X4	1	180.00	/ acc	180.00	12.60	192.60
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS.	1	250.00	/ acc	250.00	17.50	267.50
BO-TOW-SW	TOWING SERVICE	1	200.00	/ acc	200.00	14.00	214.00
Sum Ext. Service					630.00	44.10	674.10

Survey By

Date & Time

Excess

Status

Signature

Steve (LKK) 8329 8813

22/7/19, 11.15 am

WHL Air/wake

P/P

Reg before spray

15 days

Steve.chm@lkkauto.com

Total Amount 25,679.23 1,797.55 27,476.78

Total (Inclusive of GST) 27,476.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

25686.81

26542.42

Printed on 19/7/2019 5:33:22 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

Supplementary

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651 Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937 Tel: +65 6471 5458 Fax: +65 6471 5460

Customer: CU0096419 / AXA INSURANCE
Chassis No: JHMGK3850JX227000
License No: SJK1366L
Mileage: 7379
Engine No: L13B11031279 (Supp)

Document No: SVO19047548
Printed By: IVANTEO
Order Date: 25 July 2019
Order Time: 8:10:39 AM
Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHUNG CHOON CHEN OWNER INSURER: LIBERTY INSURANCE ACC DATE: 18/07/2019 SURVEYED BY: STEVE / LKK DATE: 22/07/2019 REF NO: TP INSURER: AXA TP VEH: SKT2331X						
64700-TAS-J25ZZ	PANEL COMP L RR INSIDE / <i>DD</i>	1	520.00	25	390.00	27.30	417.30
65590-T5A-N00ZZ	STIFFENER COMP L RR SIDE / <i>DD</i>	1	86.90	25	65.17	4.56	69.73
42200-T5B-J51	BEARING ASSY RR HUB UNIT / <i>DD</i>	1	287.50	25	215.62	15.09	230.71
52611-T5A-J12	DAMPER UNIT RR / <i>BT</i>	1	217.20	25	162.90	11.40	174.30
75450-SAA-013	OUTLETRR AIR / <i>BR</i>	1	25.20	25	18.90	1.32	20.22
90650-SZT-003	GROMMETRR COMBINATION LIGHT / <i>MC</i>	1	2.50	25	1.87	0.13	2.00
90650-TX6-A01	CLIPRR COMBINATION LIGHT / <i>MC</i>	1	2.00	25	1.50	0.11	1.61

GST Amount is calculated from individual line(s)

26535.19

Hoon Tong

CU4/ASMI 9072862/1/3



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No: M200050223

Company Ref No: S60FC1380G

Customer: CU0096419 / AXA INSURANCE
 Chassis No: JHMGK3850JX227000
 License No: SJK1366L
 Mileage: 7379
 Engine No: L13B11031279

Document No: SVO19047548
 Printed By: IVANTEO
 Order Date: 25 July 2019
 Order Time: 8:10:39 AM
 Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHUNG CHOON CHEN OWNER INSURER: LIBERTY INSURANCE ACC DATE: 18/07/2019 SURVEYED BY: STEVE / LKK DATE: 22/07/2019 REF NO TP INSURER: AXA TP VEH: SKT2331X						
04711-T5A-J50ZZ	FACE,FR.BUMPER	1	504.60	25	378.45	26.49	404.94
71193-T5A-000	SPACERR,FR.BUMPER	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL,FR.BUMPER	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER	19	2.30	25	32.77	2.29	35.06
60261-T5R-A00ZZ	PANELL,FR.FENDER	1	398.60	25	298.95	20.93	319.88
67364-T5A-003	TAPE SETL,FR.DOOR	1	33.60	25	25.20	1.76	26.96
72950-T5A-003	MOLDING ASSYL,RR.DOOR	1	33.60	25	25.20	1.76	26.96
72450-TD4-003	MOLDING ASSYL,FR.DOOR	1	43.00	25	32.25	2.26	34.51
76258-T5A-J32	MIRROR ASSY,L	1	506.50	25	379.87	26.59	406.46
76251-T5A-J31ZG	CAPL,SKULL	1	52.00	25	39.00	2.73	41.73
04646-TAR-320ZZ	PANEL SET,L,RR.OUTSIDE	1	570.50	25	427.87	29.95	457.82
63720-T5A-900ZZ	GUTTER COMP,L,RR.PILLAR LOWER	1	88.60	25	66.45	4.65	71.10
66100-TAR-T00ZZ	PANEL COMPR	1	320.40	25	240.30	16.82	257.12
74591-T5A-N00	COVER,L,RR.FENDER	1	42.60	25	31.95	2.24	34.19
84651-TAR-Z03ZA	LINING ASSYL,TRUNK	1	169.00	25	126.75	8.87	135.62
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	492.70	25	369.52	25.87	395.39
71507-T5A-J60	COVER,L,RR.BUMPER	1	20.70	25	15.52	1.09	16.61
71505-T5A-J50	GARNISH,RR.BUMPER	1	38.30	25	28.72	2.01	30.73
71593-T5A-J50	SPACER,R,RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L,RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
93903-25320	SCREW TAPPING 5X16	4	0.40	25	1.20	0.08	1.28
33550-T5A-J02	TAILLIGHT ASSYL	1	223.90	25	167.92	11.75	179.67
68100-T5A-U10ZZ	TAIL GATE COMP	1	730.60	25	547.95	38.36	586.31
75722-T5L-T01	EMBLEMRR	1	10.90	25	8.17	0.57	8.74
73561-T5A-003	GLASSL,QUARTER	1	153.60	25	115.20	8.06	123.26
73525-SYY-000	RUBBERRR,QTR.WSHIELD	2	9.70	25	14.55	1.02	15.57
91501-T5A-003	CLIP,QUARTER WINDSHIELD A	1	3.70	25	2.77	0.19	2.96
91502-T5A-901	CLIP B,QUARTER WINDSHIELD	1	3.70	25	2.77	0.19	2.96
91503-T5A-003	CLIP,QUARTER WINDSHIELD C	1	2.50	25	1.87	0.13	2.00
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
NMRS-4P-TM3040L	4PCS ACT,RR.SENSOR	1	320.00		320.00	22.40	342.40
42100-T5A-J15	BEAM ASSY,RR AXLE	1	911.00	25	683.25	47.83	731.08
90164-SMG-E00	BOLT,FLANGE 14X128	1	13.80	25	10.35	0.72	11.07
42700-T5S-M72	WHEEL DISK AL 15X7	1	418.40	25	313.80	21.97	335.77
73127-TY0-000	RUBBER,CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBER,WINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPER,STD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408551 Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937 Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0096419 / AXA INSURANCE
Chassis No: JHMGK3850JX227000
License No: SJK1366L
Mileage: 7379
Engine No: L13B11031279

Document No: SVO19047548
Printed By: IVANTEO
Order Date: 25 July 2019
Order Time: 8:10:39 AM
Service Advisor: IVAN TEO BOON KIAT

64700-TAS-325ZZ	PANEL COMP.L.RR.INSIDE	1	520.00 /	25	390.00	27.30	417.30
65590-T5A-N00ZZ	STIFFENER COMP.L.RR.SIDE	1	86.90 /	25	65.17	4.56	69.73
42200-T5B-J51	BEARING ASSY.RR.HUB UNIT	1	287.50 /	25	215.62	15.09	230.71
52611-T5A-J12	DAMPER UNITRR.	1	217.20 /	25	162.90	11.40	174.30
75450-SAA-013	OUTLETRR AIR	1	25.20 /	25	18.90	1.32	20.22
90650-SZT-003	GROMMETRR.COMBINATION LIGHT	1	2.50 /	25	1.87	0.13	2.00
90650-TX6-A01	CLIPRR.COMBINATION LIGHT	1	2.00 /	25	1.50	0.11	1.61
	SUM PARTS:				5,762.21	403.34	6,165.55
BOSUN		1	80.00 /		80.00	5.60	85.60
	SUNDRIES						
BG02R	1438	1	560.00 /		560.00	39.20	599.20
	REPLACE RR. WINDSCREEN (N)						
BG51R	1438	1	200.00 /		200.00	14.00	214.00
	REPLACE RR. L QTR GLASS (N)						
BODAMKIT		1	80.00 /		80.00	5.60	85.60
	WINDSCREEN DAM KIT.						
BML02I	1438	1	150.00 /		150.00	10.50	160.50
	INSPECT RR LIGHTING MECHANISMS						
	PERFORM WATER						
	TEST (N)						
BA02R	1466	1	180.00 /		180.00	12.60	192.60
	REMOVE & RENEW REVERSE						
	SENSORS-4 PCS (N)						
BMI03D	1438	1	560.00 /		560.00	39.20	599.20
	REMOVE & INSTALL REAR						
	COMPARTMENT LININGS						
	GARNISHES (N)						
BMF00D	1438	1	450.00 /		450.00	31.50	481.50
	RREMOVE & INSTALL FUEL TANK FUEL						
	PIPES (N)						
BOBC	1718	1	200.00 /		200.00	14.00	214.00
	BODY UNDERSIDE COATING (N)						
BOJSE	1718	1	80.00 /		80.00	5.60	85.60
	BODY JOINT SEALANT						
BC012R		1	450.00 /		450.00	31.50	481.50
	RESET VEHICLE SMART ENTRY						
	SYSTEM						
BC011R	1438	1	450.00 /		450.00	31.50	481.50
	REMOVE INSTALL & CALIBRATE REAR						
	VIEW CAMERA						
BKTG02R	1466	1	380.00 /		380.00	26.60	406.60
	REMOVE & TRANSFER ITEMS TO NEW						
	TAILGATE. ADJUST &						
	ALIGN TAILGATE (N)						
BMU21R	1438	1	1,120.00 /		1,120.00	78.40	1,198.40
	REMOVE & REPLACE RR L						
	UNDERCARRIAGE PARTS.(N)						
BKOT00A	1466	1	1,800.00 /		1,800.00	126.00	1,926.00
	PLACE VEHICLE TO BENCH FOR						
	CHASSIS FRAME ALIGNMENT						
BKFE21R	1466	1	3,920.00 /		3,920.00	274.40	4,194.40
	CUT & RENEW RR L FENDER.						
	STRAIGHTEN INNER PANEL						
	INCLUDING FITTING ON ATTACHMENT						
	ITEMS.						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0096419 / AXA INSURANCE
Chassis No: JHMGK3850JX227000
License No: SJK1366L
Mileage: 7379
Engine No: L13B11031279

Document No: SVO19047548
Printed By: IVANTEO
Order Date: 25 July 2019
Order Time: 8:10:39 AM
Service Advisor: IVAN TEO BOON KIAT

BP08R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (8P)	1	3,600.00 /	3,600.00	252.00	3,852.00
		SUM LABOUR:		14,260.00	998.20	15,258.20
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00 /	180.00	12.60	192.60
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS	1	250.00 /	250.00	17.50	267.50
BO-TOW-SW	TOWING SERVICE	1	200.00 /	200.00	14.00	214.00
		SUM EXT SERVICE:		630.00	44.10	674.10
		TOTAL SGD		20,652.21	1,445.64	22,097.85

Total Payable (SGD) 20,152.21 22,097.85

GST Amount is calculated from individual line(s)

Hsiao Tong (LKKAuto)

From: Steve Chen (LKK Auto)
Sent: Tuesday, 10 September 2019 4:20 PM
To: Ivan Teo
Cc: Hsiao Tong (LKKAuto)
Subject: FINALISE SJK1366L AGAINST AXA DOA 18/07/2019

Dear Ivan,

As per our communication earlier. Revised the finalize \$20,152.21 (before GST).

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Steve Chen (LKK Auto)
Sent: Friday, August 30, 2019 9:31 AM
To: Ivan Teo
Cc: Hsiao Tong (LKKAuto)
Subject: FINALISE SJK1366L AGAINST AXA DOA 18/07/2019

Dear Ivan,

We confirm the finalize \$20,652.21 (P/P, before GST). 15 repair days.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ivan Teo [<mailto:ivanteo@honda.com.sg>]
Sent: Thursday, August 29, 2019 2:14 PM
To: Steve Chen (LKK Auto)
Subject: FINALISE SJK1366L AGAINST AXA DOA 18/07/2019

Dear Steve,

Kindly assist to finalise cost of repair \$20,652.21
15 working days

Thank you

Warmest Regards

Ivan Teo

Kah Motor Co. Sdn Bhd

6A Mandai Estate / 255 Alexandra Road

Singapore 729903 / Singapore 159937

DID : 97317842

Email: ivanteo@honda.com.sg



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Service Request Details

Claim

S9M01UIY

Reference

None 

Loss Date

July 18, 2019

Report Date

Jul 22, 2019 8:22:00 AM

Request Date

July 22, 2019

Due Date

July 29, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

p. Ivan
T: 9.38a.m
V: 14
E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration

SJK1366L

MODEL

JAZZ

Service Address

P P P

Primary Contact/Insured

NG WAI FONG

BLK 758 CHOA CHU KANG NORTH 5, #05-129, 680758, Singapore

97232029

TOKWC@OUTLOOK.COM

Claim Handler

KHONG Lynn

68804892

lynn.khong@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents6](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Ivan Teo <ivanteo@honda.com.sg>
Sent: Friday, 19 July, 2019 5:21 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: ARRANGE FOR 3RD PARTY PRI SURVEY SJK1366L AGAINST SKT2331X (AXA) DOA 18/07/2019
Attachments: SAS2637742.PDF; Service Quote.pdf
Categories: Mateen

Dear Motor Claims,

Kindly arrange for 3rd party PRI survey at 6A Mandai Estate.

Please advise on direct settlement liability.

Thank you

Warmest Regards

Ivan Teo
Kah Motor Co. Sdn Bhd
6A Mandai Estate / 255 Alexandra Road
Singapore 729903 / Singapore 159937
DID : 86680608
Email: ivanteo@honda.com.sg



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Hsiao Tong (LKKAUTO)

From: WU CHUAN TOK <tokwc@outlook.com>
Sent: Thursday, 29 August 2019 7:39 PM
To: cst@axa.com.sg
Cc: Hsiao Tong (LKKAUTO); Admin A; tokwc88@gmail.com; WU CHUAN TOK
Subject: RE: [Reported] AXA Ref No S9M01UIY MC/ JY Accident Involving SKT2331X & SLR4313J on 18-07-2019

<<It appears that the attachment size are too big to be sent over the email. Here's the link to google drive where you can download the pictures>>

https://drive.google.com/open?id=1kZXFT5Rmammujq9VO-bZ_xOIUuyPrOLp
<https://drive.google.com/open?id=1CUMUJQKZZy2aaLtRCdNoQpkcDZaUBUEg>
<https://drive.google.com/open?id=1B9vG96ejUPFPWVpbMUf33kE2y9UbPAD7>
<https://drive.google.com/open?id=1rVqwsYxTmi8YpZVRG6USzHNtTZzNR-rl>
<https://drive.google.com/open?id=1HD3byhGAjb6GmD9qO2KTeASUEDeBlcKV>
<https://drive.google.com/open?id=1yLeUkApXWQpWbpJHh5vysYCsYDPX5xVE>
<https://drive.google.com/open?id=10CFVpa-WJuiljw4HwtoUlhgeTo6sY8lw>
<https://drive.google.com/open?id=14DVjMd0-ufL4bftGyKZ-6NiaXGaB11Oe>
<https://drive.google.com/open?id=1yNDYVMLG6Py41LUN3mp21NvUzyPsTZoi>

Hi,
I have just receive a stack of mail containing from this vehicle legal reps to claim for the big sum of pain and sufferings for 4 pax. I will deliver by hand to the customer care centre. Appreciate if you could let me know your customer care centre address?

On top of this, i would like to note that

- a) There is absolutely zero contact between my vehicle and SLR4313J (SKT2331X -> SJK1366L -> SLR4313J).
- b) I did not observe any damage to SLR4313J caused by SJK1366L. The driver of SJK1366L told me that he averted SLR4313J with his left mirror merely scratching SLR4314J. All these happened before i hit into SJK1366L, which based on my description and scene of pic that i provided to LKK Auto (see below), that SJK1366L has already come to complete stop before i hit SJK1366L.
- c) At the accident scene, firstly, I did not observe that there are 4 pax in SLR4313J. Secondly, the driver also appear to be well and walking around taking particulars and pictures. Thirdly, SJK1366L only touched SLR4313J with his left side mirror with no observable damage (very minor if any) and finally, there is absolutely zero contact between my car and SLR4313J. Under such near zero impact from the rear situation, I am very surprised that now there are 4 pax including the driver claim for pain and suffering? Is there a foul play here?

Here's the email that i responded to LKK Auto (cc-ed too) on 25 July as well as the picture that I sent with the email..

From: WU CHUAN TOK
Sent: Thursday, 25 July 2019 12:09 PM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A; tokwc88@gmail.com; WU CHUAN TOK
Subject: RE: ACCIDENT INVOLVING SKT 2331X(AXA) / SJK 1366L / OTHERS ALONG/AT PIE TOWARD BKE JUST BEFORE EXIT TO BKE ON 18/07/2019
Importance: High

Hi,
As indicated in my earlier mail, the documents that you requested have been provided at the Performance Motors Reporting Centre.

Followings are additional details that I would like to bring to your attention, not sure if this will help as I was the last car in this accident (<last car> SKT233X -> SJK1366L -> SLR4313J -> {gap, no contact/damage between these 2 car} -> SLV2460 -> SLM6332S -> SLZ556H <first car>) and unfortunately with the worst damage.

As mentioned in the report, I was checking my left side mirror in order to filter to the left lane (I believe the chain accident amongst the rest of the 5 car happen that this point of time) just before I hit into SJK1366L. It happened so fast that when I look in front after the quick check on the left mirror, SJK1366L was already right in front of my car, I reacted by braking and turn to left but still collided into SJK1366L. This was only possible in that the chain collision of the cars in front had already happened and they have emergency brake to a near stop just a split seconds before my contact with SJK1366L.

In summary, my accident with SJK1366L happened because of two events (I) chain accident happening right in front of my car (before I hit SJK1366L) causing SJK1366L and other cars involved to emergency brake (II) myself checking the left side mirror to filter to the left lane and too late to react when I put my eyes back in front. If one of the two events did not occur, my accident with SJK1366L would have not occurred.

Again, I am not sure how this will help but I just want to put up a good fight in that I should not held fully responsible for this accident, not to mention that my car suffered the worst damage amongst the 6 cars.

I am attaching additional photo that I have taken at the accident scene.. btw, I don't have any in car camera installed 😞

Cheers!

From: do not reply

Sent: Thursday, 22 August 2019 12:52 PM

To: 'TOKWC@OUTLOOK.COM'

Subject: [Reported] AXA Ref No S9M01UIY MC/ JY Accident Involving SKT2331X & SLR4313J on 18-07-2019

Dear Sir/Mdm

YOUR REF : SKT2331X

OUR REF : S9M01UIY MC/ JY

ACCIDENT INVOLVING SKT2331X & SLR4313J ON 18-07-2019 ALONG PIE TOWARD BKE JUST BEFORE EXIT TO BKE 21.50

CLAIMANT NAME: JASMI TALIB

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

You may wish to note that you shall be liable for any applicable excess under the policy following any settlement of third party claim(s).

We shall keep you informed of the third party claim settlement and thereafter kindly let us have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by us for the above subject matter, we expressly reserve all our rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

As Insurers, we shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 07 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following if not provided at our reporting centre. The list below is not all inclusive and further document may be required: