

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT19003173	Page	1
Registration No	: SJK1366L	Date	: 19. Jul 2019		
Chassis No	: JHMGK3850JX227000	Customer No.	: WZA006		
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	Svc Advisor	: IVAN TEO BOON KIAT		
Owner's Name	: CHUNG CHOON CHEN	Engine No	: L13B11031279		
Ins Policy No.	:	Date Time	: 19. Jul 2019 3:01:42 PM		
Date of Accident	: 18/7/2019	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHUNG CHOON CHEN OWNER INSURER: LIBERTY INSURANCE ACC DATE: 18/07/2019 SURVEYED BY: DATE: REF NO: TP INSURER: AXA TP VEH: SKT2331X						
04711-T5A-J50ZZ	FACE,FR.BUMPER / <i>CH</i>	1	504.60	25	378.45	26.49	404.94
71193-T5A-000	SPACERR.FR.BUMPER / <i>RC</i>	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER / <i>RC</i>	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER / <i>RC</i>	19	2.30	25	32.77	2.29	35.06
60261-T5R-A00ZZ	PANELL.FR.FENDER / <i>DD</i>	1	398.60	25	298.95	20.93	319.88
33150-T5A-J81	HEADLIGHT ASSY,L. ?	1	479.70	25	359.77	25.18	384.95
67050-T5A-U00ZZ	PANEL COMPL.FR.DOOR X <i>R (try to repair find)</i>	1	772.30	25	579.22	40.55	619.77
67364-T5A-003	TAPE SETL.FR.DOOR X	1	33.60	25	25.20	1.76	26.96
72950-T5A-003	MOLDING ASSYL.RR.DOOR <i>RC</i>	1	33.60	25	25.20	1.76	26.96
72326-T5A-003	SEALFR.DOOR LOWER X	1	19.70	25	14.77	1.03	15.80
72450-TD4-003	MOLDING ASSYL.FR.DOOR / <i>RC</i>	1	43.00	25	32.25	2.26	34.51
76258-T5A-J32	MIRROR ASSY,L. / <i>BR</i>	1	506.50	25	379.87	26.59	406.46
76251-T5A-J31ZG	CAPL.SKULL (COL) / <i>RR</i>	1	52.00	25	39.00	2.73	41.73
67550-T5A-N10ZZ	PANEL COMP,L.RR.DOOR X <i>R</i>	1	717.50	25	538.12	37.67	575.79
67865-T5A-003	TAPEL.RR.DOOR SASH X	1	15.40	25	11.55	0.81	12.36
04646-TAR-320ZZ	PANEL SET,L.RR.OUTSIDE / <i>DD</i>	1	570.50	25	427.87	29.95	457.82
63720-T5A-900ZZ	GUTTER COMP,L.RR.PILLAR LOWER / <i>DD</i>	1	88.60	25	66.45	4.65	71.10
66100-TAR-T00ZZ	PANEL COMPRR. / <i>DD</i>	1	320.40	25	240.30	16.82	257.12
74592-T5B-003	FENDER,L.RR.INNER ?	1	79.00	25	59.25	4.15	63.40

Printed on 19/7/2019 5:10:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SJK1366L

Chassis No : JHMGK3850JX227000

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : CHUNG CHOON CHEN

Ins Policy No. :

Date of Accident : 18/7/2019

Document No. : SQT19003173 Page 2

Date : 19. Jul 2019

Customer No. : WZA006

Svc Advisor : IVAN TEO BOON KIAT

Engine No : L13B11031279

Date | Time : 19. Jul 2019 3:01:42 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
74591-T5A-N00	COVER,L.RR.FENDER / CR4	1	42.60	25	31.95	2.24	34.19
84651-TAR-Z03ZA	LINING ASSYL.TRUNK X	1	169.00	25	126.75	8.87	135.62
04715-T5A-J50ZZ	FACE,RR.BUMPER / DR	1	492.70	25	369.52	25.87	395.39
71502-T5A-J60	COVER,R.RR.BUMPER X	1	20.70	25	15.52	1.09	16.61
71507-T5A-J60	COVER,L.RR.BUMPER ?	1	20.70	25	15.52	1.09	16.61
71505-T5A-J50	GARNISH,RR.BUMPER / MIS	1	38.30	25	28.72	2.01	30.73
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE / DR	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE / DR	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER / MC	7	2.30	25	12.07	0.84	12.91
93903-25320	SCREW TAPPING 5X16 / MC	4	0.40	25	1.20	0.08	1.28
33550-T5A-J02	TAILLIGHT ASSYL. ?	1	223.90	25	167.92	11.75	179.67
34155-T5A-J01	LIGHT ASSYL.LID X	1	81.70	25	61.27	4.29	65.56
68100-T5A-U10ZZ	TAIL GATE COMP / DO	1	730.60	25	547.95	38.36	586.31
75722-T5L-T01	EMBLEMRR. / MC	1	10.90	25	8.17	0.57	8.74
73561-T5A-003	GLASSL.QUARTER / MC	1	153.60	25	115.20	8.06	123.26
73525-SYY-000	RUBBERRR QTR W/SHIELD / MC	1	9.70	25	7.27	0.51	7.78
91501-T5A-003	CLIPQUARTER WINDSHIELD A / } MC	1	3.70	25	2.77	0.19	2.96
91502-T5A-003	CLIPQUARTER WINDSHIELD B / }	1	3.70	25	2.77	0.19	2.96
91503-T5A-003	CLIPQUARTER WINDSHIELD C / }	1	2.50	25	1.87	0.13	2.00
BO-WS-SEALANT	WINDSCREEN SEALANT (N) / MC	1	60.00		60.00	4.20	64.20
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR / DR	1	320.00		320.00	22.40	342.40
42100-T5A-J15	BEAM ASSYRR.AXLE / DO	1	911.00	25	683.25	47.83	731.08
90164-SMG-E00	BOLTFLANGE 14X128 / MC	2	13.80	25	20.70	1.45	22.15
57475-T5A-003	SENSOR ASSYRR. ?	1	51.60	25	38.70	2.71	41.41
52611-T5A-J12	DAMPER UNITRR. X	2	217.20	25	325.80	22.81	348.61
52722-T5A-J02	RUBBERRR.BUMP STOPPER X	1	29.00	25	21.75	1.52	23.27
52686-T5A-J01	COVERRR.UPPER DUST X	1	5.90	25	4.42	0.31	4.73
52673-T5A-J01	RUBBERRR.SHOCK ABSORBER MTG X	1	1.50	25	1.12	0.08	1.20
42700-TAR-E91	DISK ALUMINIUM WHEEL,16X6 X	2	772.30	25	1158.45	81.09	1239.54

Printed on 19/7/2019 5:10:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SJK1366L

Chassis No : JHMGK3850JX227000

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : CHUNG CHOON CHEN

Ins Policy No. :

Date of Accident : 18/7/2019

Document No. : SQT19003173

Date : 19. Jul 2019

Customer No. : WZA006

Svc Advisor : IVAN TEO BOON KIAT

Engine No : L13B11031279

Date | Time : 19. Jul 2019 3:01:42 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
YH-175/65R15-AE50	YOKOHAMA TYRE X	1	114.00		114.00	7.98	121.98
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER / 11K	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDOWSHIELD DAMPER / 11K	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5 / 11K	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N) / 11K	1	60.00		60.00	4.20	64.20
Sum Item					7899.23	552.95	8,452.18
BOSUN	SUNDRIES	1	100.00 80		100.00	7.00	107.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00 /		560.00	39.20	599.20
BG51R	REPLACE RR. L QTR GLASS.(N)	1	380.00 200		380.00	26.60	406.60
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00 80		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 150		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00 /		180.00	12.60	192.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00 /		560.00	39.20	599.20
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	450.00 / (change photo)		450.00	31.50	481.50
BOBC	BODY UNDERSIDE COATING (N)	1	450.00 200		450.00	31.50	481.50
BOJSE	BODY JOINT SEALANT	1	100.00 80		100.00	7.00	107.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	480.00 450		480.00	33.60	513.60
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	480.00 450		480.00	33.60	513.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00 380		560.00	39.20	599.20
BKDR11R	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	1	560.00 X		560.00	39.20	599.20
BMU21R	REMOVE & REPLACE RR L UNDERCARRIAGE PARTS. (N) 560 x 2	1	1680.00 1120		1680.00	117.60	1797.60
BKOT00A	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT 1200	1	1800.00 ? (change photo)		1800.00	126.00	1926.00
BKFE21R	CUT & RENEW RR L FENDER. STRAIGHTEN INNER PANEL 560 x 7	1	4480.00 3920		4480.00	313.60	4793.60
BP08R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (8P) 450 x 8	1	4050.00 3600		4050.00	283.50	4333.50

Printed on 19/7/2019 5:10:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SJK1366L

Chassis No : JHMGK3850JX227000

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : CHUNG CHOON CHEN

Ins Policy No. :

Date of Accident : 18/7/2019

Document No. : SQT19003173 **Page** 4

Date : 19. Jul 2019

Customer No. : WZA006

Svc Advisor : IVAN TEO BOON KIAT

Engine No : L13B11031279

Date | Time : 19. Jul 2019 3:01:42 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Sum Labor					17150.00	1,200.50	18,350.50
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	/ n/c	180.00	12.60	192.60
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS.	1	250.00	/ n/c	250.00	17.50	267.50
BO-TOW-SW	TOWING SERVICE	1	200.00	/ n/c	200.00	14.00	214.00
Sum Ext. Service					630.00	44.10	674.10

Survey By

Date & Time

Excess

Status

Signature

Steve (LKK) 8322 8813

22/7/19, 11.15 am

WHL Air/make

P/P

Reg before spray

15 days

Steve chin@lkkauto.com

Total Amount 25,679.23 1,797.55 27,476.78**Total (Inclusive of GST)** 27,476.78**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 19/7/2019 5:33:22 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.