

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651 Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937 Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICEGST Reg No. M200050223
Company Ref. No. S60FC1380GCustomer: CU0096419 / AXA INSURANCE
Chassis No: JHMGK3850JX227000
License No: SJK1366L
Mileage: 7379
Engine No: L13B11031279Document No: SVO19047548
Printed By: IVANTEO
Order Date: 25 July 2019
Order Time: 8 10.39 AM
Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	
						Amount	GST
	TP DIRECT SETTLEMENT (J/NO)						
	OWNER: CHUNG CHOON CHEN						
	OWNER INSURER: LIBERTY INSURANCE						
	ACC DATE: 18/07/2019						
	SURVEYED BY: STEVE / LKK						
	DATE: 22/07/2019						
	REF NO						
	TP INSURER: AXA						
	TP VEH: SKT2331X						
04711-T5A-J50ZZ	FACE FR BUMPER	1	504.60	25	378.45	26.49	404.94
71193-T5A-000	SPACERR FR BUMPER	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL FR BUMPER	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP BUMPER	19	2.30	25	32.77	2.29	35.06
60261-T5R-A00ZZ	PANELL FR FENDER	1	398.60	25	298.95	20.93	319.88
67364-T5A-003	TAPE SETL FR DOOR	1	33.60	25	25.20	1.76	26.96
72950-T5A-003	MOLDING ASSYL RR DOOR	1	33.60	25	25.20	1.76	26.96
72450-TD4-003	MOLDING ASSYL FR DOOR	1	43.00	25	32.25	2.26	34.51
76258-T5A-J32	MIRROR ASSY,L	1	506.50	25	379.87	26.59	406.46
76251-T5A-J31ZG	CAPL SKULL	1	52.00	25	39.00	2.73	41.73
04846-TAR-320ZZ	PANEL SET L RR OUTSIDE	1	570.50	25	427.87	29.95	457.82
63720-T5A-900ZZ	GUTTER COMP L RR PILLAR LOWER	1	88.60	25	66.45	4.65	71.10
66100-TAR-T00ZZ	PANEL COMPRR	1	320.40	25	240.30	16.82	257.12
74591-T5A-N00	COVER,L RR FENDER	1	42.60	25	31.95	2.24	34.19
84651-TAR-Z03ZA	LINING ASSYL TRUNK	1	169.00	25	126.75	8.87	135.62
04715-T5A-J50ZZ	FACE,RR BUMPER	1	492.70	25	369.52	25.87	395.39
71507-T5A-J60	COVER,L RR BUMPER	1	20.70	25	15.52	1.09	16.61
71505-T5A-J50	GARNISH,RR BUMPER	1	38.30	25	28.72	2.01	30.73
71593-T5A-J50	SPACER,R RR BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L RR BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP BUMPER	7	2.30	25	12.07	0.84	12.91
93903-25320	SCREW TAPPING 5X16	4	0.40	25	1.20	0.08	1.28
33550-T5A-J02	TAILLIGHT ASSYL	1	223.90	25	167.92	11.75	179.67
68100-T5A-U10ZZ	TAIL GATE COMP	1	730.60	25	547.95	38.36	586.31
75722-T5L-T01	EMBLEMRR	1	10.90	25	8.17	0.57	8.74
73561-T5A-003	GLASSL QUARTER	1	153.60	25	115.20	8.06	123.26
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.70	25	14.55	1.02	15.57
91501-T5A-003	CLIPQUARTER WINDSHIELD A	1	3.70	25	2.77	0.19	2.96
91502-T5A-901	CLIP B QUARTER WINDSHIELD	1	3.70	25	2.77	0.19	2.96
91503-T5A-003	CLIPQUARTER WINDSHIELD C	1	2.50	25	1.87	0.13	2.00
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
NMRS-4P-TM3040L	4PCS ACT RR SENSOR	1	320.00		320.00	22.40	342.40
42100-T5A-J15	BEAM ASSYRR AXLE	1	911.00	25	683.25	47.83	731.08
90164-SMG-E00	BOLTFLANGE 14X128	1	13.80	25	10.35	0.72	11.07
42700-T5S-M72	WHEEL DISK AL 15X7	1	418.40	25	313.80	21.97	335.77
73127-TY0-000	RUBBER C WINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBER WINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651 Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937 Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No. M200050223
Company Ref No. S60FC1380G

Customer: CU0096419 / AXA INSURANCE
Chassis No: JHMGK3850JX227000
License No: SJK1366L
Mileage: 7379
Engine No: L13B11031279

Document No: SVO19047548
Printed By: IVANTEO
Order Date: 25 July 2019
Order Time: 8:10:39 AM
Service Advisor: IVAN TEO BOON KIAT

64700-TAS-325ZZ	PANEL COMP.L RR INSIDE	1	520.00 /	25	390.00	27.30	417.30
65590-TSA-N00ZZ	STIFFENER COMP.L RR SIDE	1	86.90 /	25	65.17	4.56	69.73
42200-TSB-J51	BEARING ASSY.RR HUB UNIT	1	287.50 /	25	215.62	15.09	230.71
52611-TSA-J12	DAMPER UNITRR	1	217.20 /	25	162.90	11.40	174.30
75450-SAA-013	OUTLETRR AIR	1	25.20 /	25	18.90	1.32	20.22
90650-SZT-003	GROMMETRR COMBINATION LIGHT	1	2.50 /	25	1.87	0.13	2.00
90650-TX6-A01	CLIPRR COMBINATION LIGHT	1	2.00 /	25	1.50	0.11	1.61
	SUM PARTS:				5,762.21	403.34	6,165.55
BOSUN		1	80.00 /		80.00	5.60	85.60
	SUNDRIES						
BG02R	1438	1	560.00 /		560.00	39.20	599.20
	REPLACE RR WINDSCREEN (N)						
BG51R	1438	1	200.00 /		200.00	14.00	214.00
	REPLACE RR L QTR GLASS (N)						
BODAMKIT		1	80.00 /		80.00	5.60	85.60
	WINDSCREEN DAM KIT						
BML02I	1438	1	150.00 /		150.00	10.50	160.50
	INSPECT RR LIGHTING MECHANISMS						
	PERFORM WATER						
	TEST (N)						
BA02R	1466	1	180.00 /		180.00	12.60	192.60
	REMOVE & RENEW REVERSE						
	SENSORS-4 PCS (N)						
BMI03D	1438	1	560.00 /		560.00	39.20	599.20
	REMOVE & INSTALL REAR						
	COMPARTMENT LININGS						
	GARNISHES (N)						
BMF00D	1438	1	450.00 /		450.00	31.50	481.50
	RREMOVE & INSTALL FUEL TANK FUEL						
	PIPES (N)						
BOBC	1718	1	200.00 /		200.00	14.00	214.00
	BODY UNDERSIDE COATING (N)						
BOJSE	1718	1	80.00 /		80.00	5.60	85.60
	BODY JOINT SEALANT						
BC012R		1	450.00 /		450.00	31.50	481.50
	RESET VEHICLE SMART ENTRY						
	SYSTEM						
BC011R	1438	1	450.00 /		450.00	31.50	481.50
	REMOVE INSTALL & CALIBRATE REAR						
	VIEW CAMERA						
BKTG02R	1466	1	380.00 /		380.00	26.60	406.60
	REMOVE & TRANSFER ITEMS TO NEW						
	TAILGATE ADJUST &						
	ALIGN TAILGATE (N)						
BMU21R	1438	1	1,120.00 /		1,120.00	78.40	1,198.40
	REMOVE & REPLACE RR L						
	UNDERCARRIAGE PARTS (N)						
BKOT00A	1466	1	1,800.00 /		1,800.00	126.00	1,926.00
	PLACE VEHICLE TO BENCH FOR						
	CHASSIS FRAME ALIGNMENT						
BKFE21R	1466	1	3,920.00 /		3,920.00	274.40	4,194.40
	CUT & RENEW RR L FENDER.						
	STRAIGHTEN INNER PANEL						
	INCLUDING FITTING ON ATTACHMENT						
	ITEMS						

1300



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0096419 / AXA INSURANCE
Chassis No: JHMGK3850JX227000
License No: SJK1366L
Mileage: 7379
Engine No: L13B11031279

Document No: SVO19047548
Printed By: IVANTEO
Order Date: 25 July 2019
Order Time: 8 10:39 AM
Service Advisor: IVAN TEO BOON KIAT

BP08R	1718	1	3 600 00 /	3 600 00	252 00	3 852 00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (8P)					
			SUM LABOUR:	14,260.00	998.20	15,258.20
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180 00 /	180 00	12 60	192 60
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS.	1	250 00 /	250 00	17 50	267 50
BO-TOW-SW	TOWING SERVICE	1	200 00 /	200 00	14 00	214 00
			SUM EXT SERVICE:	630.00	44.10	674.10
			TOTAL SGD	20,552.20	1,445.64	22,097.85

Total Payable (SGD) 20,152.21 22,097.85

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.

Supplementary

GST Reg No.: M200050223
Company Ref No.: S60FC1360G

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408551 Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937 Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:	CU0096419 / AXA INSURANCE	Document No:	SVO19047548
Chassis No:	JHMGK3850JX227000	Printed By:	IVANTEO
License No:	SJK1366L	Order Date:	25 July 2019
Mileage:	7379	Order Time:	8:10:39 AM
Engine No:	L13B11031279 (Supp)	Service Advisor:	IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO.) OWNER: CHUNG CHOON CHEN OWNER INSURER: LIBERTY INSURANCE ACC DATE: 18/07/2019 SURVEYED BY: STEVE / LKK DATE: 22/07/2019 REF NO TP INSURER: AXA TP VEH: SKT2331X						
64700-TAS-325ZZ	PANEL COMP L RR INSIDE / ON	1	520.00	25	390.00	27.30	417.30
65590-T5A-N00ZZ	STIFFENER COMP L RR SIDE / ON	1	86.90	25	65.17	4.56	69.73
42200-T5B-J51	BEARING ASSY. RR HUB UNIT / journal	1	287.50	25	215.62	15.09	230.71
52811-T5A-J12	DAMPER UNIT RR / BT	1	217.20	25	162.90	11.40	174.30
75450-SAA-013	OUTLETRR AIR / BR	1	25.20	25	18.90	1.32	20.22
90650-SZT-003	GROMMETRR COMBINATION LIGHT / MC	1	2.50	25	1.87	0.13	2.00
90650-TX6-A01	CLIPRR COMBINATION LIGHT / MC	1	2.00	25	1.50	0.11	1.61

GST Amount is calculated from individual lines.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 86203838

QUOTATION

GST Reg No. M200050223

Company Ref. No. S60FC1380G

Customer	AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	SQT19003173	Page	1
Registration No	SJK1366L	Date	19 Jul 2019		
Chassis No	JHMGK58500X227000	Customer No.	WZA006		
Model	2017 HONDA CIVIC 1.8 VTEC EUROPE	Svc Advisor	IVAN TEO BOON KIAT		
Owner's Name	THE INVESTMENT SCHEM	Engine No	L13B11031279		
Ins Policy No.		Date Time	19 Jul 2019 3:01:42 PM		
Date of Accident	18/7/2019	Surveyor Name			
		Survey Date			
		Authorisation Date			

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (JNO)	1					
	OWNER: CHUNG CHOON CHEN						
	OWNER INSURER: LIBERTY INSURANCE						
	ACC DATE: 18/07/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA						
	TP VEH: SKT2331X						
04711-T5A-J50ZZ	FACE FR BUMPER / <i>OK</i>	1	504.60	25	378.45	26.49	404.94
71193-T5A-000	UPPER FRONT END Bumper <i>OK</i>	1	11.00	25	8.25	0.85	9.10
71198-T5A-000	SPARE TIRE BUMPER	1	16.40	25	12.30	1.35	13.65
91505-TM8-003	CLIP BUMPER	1	2.40	25	1.80	0.25	2.05
60261-T5R-A00ZZ	CAPL FRONT END <i>OK</i>	1	268.00	25	201.00	20.44	221.44
33150-T5A-J81	HEADLIGHT ASSY L <i>X NAI</i>	1	100.00	25	75.00	25.18	100.18
67050-T5A-U00ZZ	PANEL COMPLE RR DOOR <i>X R (Qty to up 1st)</i>	1	722.00	25	541.50	40.55	582.05
67304-T5A-003	TAPE SET L RR DOOR <i>X / NAI</i>	1	43.00	25	32.25	3.76	36.01
72950-T5A-003	MOLDING ASSYL RR DOOR <i>X NAI</i>	1	33.60	25	25.20	3.76	28.96
72326-T5A-003	SEALER DOOR LOWER <i>X NAI</i>	1	19.70	25	14.78	1.93	16.71
72450-TD4-003	MOLDING ASSYL RR DOOR <i>OK</i>	1	43.00	25	32.25	2.26	34.51
76255-T5A-J32	MIRROR ASSYL <i>OK</i>	1	506.50	25	379.88	26.59	406.47
76251-T5A-J312G	CAPL SKULL <i>OK / BR</i>	1	52.00	25	39.00	2.73	41.73
67550-T5A-N10ZZ	PANEL COMPLE RR DOOR <i>X R</i>	1	717.50	25	538.13	37.67	575.79
67865-T5A-003	TAPE RR DOOR SASH <i>X NAI</i>	1	15.40	25	11.55	0.81	12.36
04646-TAR-320ZZ	PANEL SET L RR OUTSIDE <i>OK</i>	1	570.50	25	427.88	29.95	457.83
63720-T5A-900ZZ	GUTTER COMPLE RR PILLAR LOWER <i>OK</i>	1	68.60	25	51.45	6.65	58.10
66100-TAR-T00ZZ	PANEL BUMPER <i>OK</i>	1	12.40	25	9.30	1.02	10.32
74592-T5B-003	FENDER L RR INNER <i>X NAI</i>	1	79.00	25	59.25	4.15	63.40

Printed on 19/7/2019 3:10:42 PM

This quotation is generated by the system.

It is not valid for more than 30 days.

It is not valid for more than 30 days.

It is not valid for more than 30 days.

It is not valid for more than 30 days.

It is not valid for more than 30 days.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 96203838

QUOTATION

GST Reg No. M200050223
Company Ref No. S60FC1380G

Customer	AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	SQT19003173	Page	2
Registration No	SJK1366	Date	19 Jul 2019		
Classis No	JHMGR3551XJ27000	Customer No.	WZA006		
Model	JAZZ 1.6 XR 7 JET 17V 1.6 EURO 4	Svc Advisor	EVAN TEO BOON KIAT		
Owner's Name	CHUNG CHOUN CHEN	Engine No	UJ811031279		
Ins Policy No.		Date / Time	19 Jul 2019 3:01:42 PM		
Date of Accident	18/7/2019	Surveyor Name			
		Survey Date			
		Authorisation Date			

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl'd GST
74591-T5A-N00	COVER, L RR FENDER / CR	1	42.60	25	31.95	2.24	34.19
84651-TAR-2032A	LINING ASSYL TRUNK X / CR	1	169.70	25	126.75	8.87	135.62
04715-T5A-J50Z2	FACE, RR BUMPER / BR	1	492.70	25	368.52	25.87	395.39
71502-T5A-J60	COVER, R RR BUMPER X NAI	1	20.70	25	15.52	1.09	16.61
71507-T5A-J60	COVER, L RR BUMPER X / MIS	1	20.70	25	15.52	1.09	16.61
71505-T5A-J50	GARNISH, RR, BUMPER X / MIS	1	38.30	25	28.72	2.01	30.73
71593-T5A-J50	SPACER, R RR, BUMPER SIDE / CR	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER, L RR, BUMPER SIDE / CR	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP, BUMPER X	2	2.00	25	1.20	0.84	1.20
93903-25320	SCREW TAPPING, SATE X	4	4.00	25	2.75	0.08	1.23
33550-T5A-J02	TAIL LIGHT ASSY X / BR	1	225.90	25	169.92	11.75	179.67
34155-T5A-J01	LIGHT ASSY, L X NAI	1	45.70	25	33.27	4.29	45.96
68100-T5A-U10Z2	TAIL GATE LOCK X / CR	1	78.75	25	57.95	38.36	96.31
75722-T5L-T01	EMBLEM, RR X	1	10.90	25	8.17	0.57	8.74
73561-T5A-003	GLASS, QUARTER X / MIS	1	153.00	25	113.20	8.06	121.26
73525-SYY-000	RUBBER, RR QTR W/SHIELD X / MIS	2	9.70	25	6.55	0.51	7.06
91501-T5A-003	CLIP, QUARTER WINDSHIELD A X / MIS	1	3.70	25	2.77	0.19	2.96
91502-T5A-003	CLIP, QUARTER WINDSHIELD B X / MIS	1	3.70	25	2.77	0.19	2.96
91503-T5A-003	CLIP, QUARTER WINDSHIELD C X / MIS	1	2.50	25	1.87	0.13	2.00
BO-WS-SEALANT	WINDSCREEN SEALANT (N) X / CR	1	60.00		60.00	4.20	64.20
NMRS-4P-TM3040L	4PCS ACT RR SENSOR X / BR	1	320.00		320.00	22.40	342.40
42100-T5A-J15	BEAM ASSY, RR AXLE X / CR	1	911.00	25	683.25	47.83	731.08
90164-SMG-E00	BOLT, FLANGE 14X128 X / CR	1	13.80	25	10.35	1.45	22.15
57475-T5A-003	SENSOR ASSY, RR X / NAI	1	51.60	25	38.70	2.71	41.41
52611-T5A-J12	DAMPER UNIT, RR X / NAI	2	211.20	25	325.80	22.81	348.61
52722-T5A-J02	RUBBER, RR BUMP STOPPER X / NAI	1	28.00	25	21.00	1.52	23.27
52686-T5A-J01	COVER, RR UPPER DUST X / NAI	1	5.90	25	4.42	0.31	4.73
52673-T5A-J01	RUBBER, RR SHOCK ABSORBER MTC X / NAI	1	1.50	25	1.12	0.08	1.20
42700-TAR-E91	DISK ALUMINIUM WHEEL 16X6 X / CR	2	72.50	25	53.75	61.99	125.54

Printed on 19/7/2019 5:10:42 PM

This quotation is generated from the system and is for reference only.

Our prices are subject to change without notice.

The above estimated cost of repairs do not include any vehicle wear & damages.

GST Amount is calculated from the above prices.

Our maximum of \$655 for each GST will be required for the original of this quote quotation for estimate above \$2,000.00.

If vehicle is repaired, the repair cost will be refunded to the customer.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel : +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No: M200050223
Company Ref No: S60FC1380G

Customer	AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	SQT19003173	Page	3
Registration No	SJK1366L	Date	19 Jul 2019		
Chassis No	JHMGK3850JX227000	Customer No.	WZA006		
Model	JAZZ 1.3LXR CVT 18YM (EURO 6)	Svc Advisor	IVAN TEO BOON KIAT		
Owner's Name	CHUNG CHOON CHEN	Engine No	L13B11031279		
Ins Policy No		Date Time	19 Jul 2019 3:01:42 PM		
Date of Accident	18/7/2019	Surveyor Name			
		Survey Date			
		Authorisation Date			

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
YH-175/65R15-AE50	YOKOHAMA TYRE X <i>NN</i>	1	114.00		114.00	7.98	121.98
73127-TY0-000	RUBBER WINDSHIELD DAMPER <i>AL</i>	1	11.15	20	8.92	0.60	9.52
73214-T5A-013	RUBBER WINDSHIELD DAMPER <i>AL</i>	2	11.15	20	17.76	0.68	18.43
73226-SZW-000	DAMPER STD 5X5 <i>AL</i>	1	6.16	20	4.93	0.45	5.38
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>AL</i>	1	60.00		60.00	4.20	64.20
Sum Item					7899.23	552.95	8452.18
BOSUN	TUNDRAS	1	100.00 <i>80</i>		100.00	7.00	107.00
BG02R	REPLACE RR WINDSCREEN (N)	1	560.00		560.00	39.20	599.20
BG51R	REPLACE RR L OTR GLASS (N)	1	380.00 <i>300</i>		380.00	26.60	406.60
BODAMKIT	WINDSCREEN DAM KIT	1	100.00 <i>80</i>		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	1	180.00 <i>150</i>		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BM103D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00		560.00	39.20	599.20
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES (N)	1	450.00 <i>(by photo)</i>		450.00	31.50	481.50
BOBC	BODY UNDERSIDE COATINGS (N)	1	450.00 <i>300</i>		450.00	31.50	481.50
BOJSE	BODY JOINT SEALANT	1	100.00 <i>80</i>		100.00	7.00	107.00
BC012R	REMOVE VEHICLE SMART ENTRY SYSTEM	1	480.00 <i>400</i>		480.00	33.60	513.60
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	480.00 <i>400</i>		480.00	33.60	513.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST X	1	560.00 <i>480</i>		560.00	39.20	599.20
BKDR11R	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	1	560.00 X		560.00	39.20	599.20
BMU21R	REMOVE & REPLACE RR L UNDERCARRIAGE PARTS (N) <i>500 x 2</i>	1	1680.00 <i>1100</i>		1680.00	117.60	1797.60
BK0T00A	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT <i>1100</i>	1	1800.00 <i>1300 (R1 1st)</i>		1800.00	126.00	1926.00
BKFE21R	CUT & RENEW RR L FENDER STRAIGHTEN INNER PANEL <i>500 x 2</i>	1	4480.00 <i>2400</i>		4480.00	313.60	4793.60
BP08R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (BP) <i>500 x 2</i>	1	4050.00 <i>1000</i>		4050.00	283.50	4333.50

Printed on 19/7/2019 5:10:42 PM

This is a computer generated quotation. Signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair does not include any accessories or damages.

(GST Amount is calculated from individual items)

An amount of \$50.00 (incl GST) will be applicable for the request of the above quotation for estimates above \$1,000.00.

However, if the repairs are not being carried out, the amount will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hour Roadside Assistance: Call 98203838

QUOTATION

GST Reg No: M200050223

Company Ref No: S60FC13854

Customer	AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 668811	Document No.	SQT19003173	Page	4
Registration No	SJK1366L	Date	19 Jul 2019	Customer No	WZA006
Chassis No	JHMGR38501X227100	Svc Advisor	IVAN TEO BOON KIAT	Engine No	L13B11031279
Model	JAZZ 1.3LXR CVT 18YM (EURO 6)	Date / Time	19 Jul 2019 3:01:42 PM	Surveyor Name	
Owner's Name	CHUNG CHOON CHEN	Survey Date		Authorisation Date	
Ins Policy No.					
Date of Accident	18/7/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
					Sum Labor	17,150.00	17,150.00
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS	1	250.00		250.00	17.50	267.50
BO-TOW-SW	TOWING SERVICE	1	200.00		200.00	14.00	214.00
					Sum Ext. Service	630.00	630.00

Survey By

Date & Time

Remarks

Signature

Signature

Total Amount 25,679.21 1,797.55 27,476.76

Total (Inclusive of GST)

27,476.76

KAH Auto Consultants hereby notify the Reparer of the following:

- To remedy repairable spray painting
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- The repair must be completed within 14 days of the date of the report
- The repair must be completed within 14 days of the date of the report
- Support the fact that the repair is done and is subject to the approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

Printed on 18/7/2019 5:33:22 PM

This is a computer generated invoice. No signature is required.

Prices are subject to change without notice.

The above estimates are subject to inspection and unforeseen damages.

All amounts are calculated from individual items.

An amount of \$20.00 (incl GST) will be applied as the expense of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at KAH Motor Co. Sdn Bhd, this will be refunded.