

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

*Not withain
Running After Repair
3 days*

PYRO CARS PTE LTD
c/o 46 Lentor Plain
Singapore 786548

Date: 22/7/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: SLW 6065 K / MAZDA 3	
1 pc	rear bumper	<i>n</i> 986.50 <i>X</i>
1 pc	rear bumper dust cover	<i>sn</i> 136.20 <i>X</i>
1 pc	rear fender	<i>n</i> 1,075.30 <i>X</i>
1 pc	alloy rim	<i>lip</i> <i>sn</i> 1,075.80 <i>50</i>
1 pc	rear shock absorber	<i>sn</i> 253.80 <i>X</i>
1 pc	rear lower arm	<i>sn</i> 328.90 <i>X</i>
	Sub-total	3,856.50
	Less 10%	385.65
	Sub-total	3,470.85
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	<i>400</i> 700.00
	To check wiring system.	<i>100</i> 30.00
	To apply putty and spray painting on affected areas.	<i>500</i> 600.00
	To apply waterproof sealant on affected areas.	<i>nn</i> 50.00 <i>X</i>
	To apply rust proofing on affected areas.	<i>nn</i> 50.00 <i>X</i>
	To remove rear windscreen glass to enable repair.	<i>nn</i> 150.00 <i>X</i>
	To remove carpet, trimming and seats to enable repair.	<i>nn</i> 160.00 <i>X</i>
	To remove and install rear undercarriage parts to enable repair.	<i>nn</i> 120.00 <i>X</i>
	To replace alloy rim(s) and perform wheel balancing.	<i>150</i> 80.00
	To perform 4 wheels computerised alignment	<i>600</i> 80.00
	To install reverse sensors.	<i>nn</i> 50.00 <i>X</i>
	Total	5,540.85

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: