

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



Date : 19/07/2019
TP Vehicle Number : YP1119E
To : AXA INSURANCE PTE LTD
Attn : Motor Claim Department

STK AUTO (S) PTE LTD
DID : 63860669
Fax : 63860669
HP : 97519596

Owner : SINCHONG MEHECO LTD
AIG ASIA PACIFIC INSURANCE PTE LTD

Certificate Number : 1700042883-01 Accident Date : 18/07/2019
Vehicle Number : GBG4794E
Make & Model : NISSAN NV350

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
List Item			
1	FRONT BUMPER / Cut	\$ 534.70	
10	FRONT BUMPER RETAINER RH X <i>NN</i>	\$ 147.00	
2	FRONT BUMPER RETAINER LH / <i>mis</i>	\$ 147.00	
2	FRONT BUMPER BRACKET RH X	\$ 104.70	
1	FRONT BUMPER BRACKET LH X	\$ 104.70	
1	FRONT BUMPER FOG LAMP X	\$ 311.80	
1	FRONT BUMPER FOG LAMP COVER X	\$ 107.00	
1	FRONT BUMPER TOWING X	\$ 55.00	
1	FRONT BUMPER REINFORCEMENT X	\$ 630.00	
1	FRONT BUMPER LOWER GRILLE X	\$ 165.80	
2	FRONT GRILLE X	\$ 495.00	
1	FRONT GRILLE LOGO X	\$ 59.70	
2	LH HEADLAMP / Cut	\$ 403.00	
3	LH HEADLAMP BRACKET X	\$ 98.50	
4	LH FRONT DOOR / <i>BT</i> X	\$ 1,350.00	
1	LH FRONT DOOR STEP PANEL X <i>Repair</i>	\$ 123.00	
1	LH FRONT DOOR STEP PANEL GARNISH / <i>mis</i>	\$ 94.30	
1	LH FRONT DOOR PILLAR X <i>Repair</i>	\$ 143.50	
1	LH FRONT DOOR INNER TRIM BOARD ?	\$ 550.70	
1	LH FRONT DOOR LOCK X	\$ 216.70	
1	FRONT SUPPORT PANEL X	\$ 1,450.60	
1	LH WING MIRROR WITH MOTOR / <i>dis</i>	\$ 520.50	
1	LH WING MIRROR MOTOR COVER / <i>mis</i>	\$ 150.80	
1	LH WING MIRROR BASE COVER / <i>cut</i>	\$ 190.40	
1	WASH TANK X	\$ 222.10	
1	RH CORNER PANEL X <i>Repair</i>	\$ 240.00	
	Sub Total	\$ 8,081.80	
	Discount 10% on Parts	\$ (808.18)	
		\$ 7,273.62	

PAGE : 1

A19

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



Date : 19/07/2019

STK AUTO (S) PTE LTD

DID : 63860669

Fax : 63860669

HP : 97519596

TP Vehicle Number : YP1119E

To : AXA INSURANCE PTE LTD

Attn : Motor Claim Department

Owner : SINCHONG MEHECO LTD

AIG ASIA PACIFIC INSURANCE PTE LTD

Certificate Number : 1700042883-01

Accident Date : 18/07/2019

Vehicle Number : GBG4794E

Make & Model : NISSAN NV350

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
Special Nett Item			
	LH FRONT DOOR COMPANY TELEPHONE STICKER X	\$ 220.00	
	LH FRONT DOOR COMPANY STICKER ?	\$ 50.00	
	FRONT BUMPER CLIPS / MC	\$ 50.00	
	LH FRONT DOOR GLASS SEALANT X	\$ 50.00	
	SUB TOTAL :	\$ 370.00	
Labour & Misc			
	TO CHECK ALL NECESSARY WIRINGS	\$ 50.00	30
	TO RUST PROOF ON AFFECTED AREAS	\$ 100.00	X
	TO REMOVE & REFIX LH FRONT DOOR	\$ 60.00	
	TO REMOVE & REFIX LH FRONT DOOR GLASS	\$ 150.00	60
	TO REMOVE & REFIX LH FRONT DOOR TERIOR	\$ 150.00	
	COMPONENTS TO FACILITATE REPAIRS	\$ 100.00	X
	LABOUR TO FACILITATE REPAIR	\$ 1,200.00	400
	LABOUR & SPRAY PAINTING	\$ 1,200.00	600
	Sub Total	\$ 3,010.00	
	Sub Total	\$ 10,653.62	
	7% GST	\$ 745.75	
	Total	\$ 11,399.37	

PAGE : 2

STK AUTO (S) PTE LTD 8 KAKI BUKIT AVENUE 4 #03-21 SINGAPORE 415875 | Tel: 63860669 |

Company Registration No. : 201539883N

4 Days.
Unpsum repair.
After repair photos.
Eno Qian - 8288 0282
Not Authorised.
22/7/19.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: