

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711

Estimate No: EST1900227
Date: 20 Jul 2019

TEL: 63476100 FAX: 62244174
 ATTN: Motor Claim Department

Veh Reg No: SKR6239P
Make/Model: TOYOTA
 VIOSJGRADEMT

Vivian

Chasis No: MHFBT9F3306027765
Reg. Date: 26/02/2015
Your Ref No: SHC8244A

Claim Type: Third Party
Accident Date: 18/07/2019
TP Veh Reg No: SHC8244A

Estimate Repair Cost to Vehicle No :SKR6239P

| Quantity | Description | List Price S\$ | Amount S\$ |
|--------------------|---------------------------------------------------------------------------------------------------------------|-----------------------|---------------|
| List Price | | | |
| 1 | 1 PC REAR BUMPER <i>del d</i> | 482.70 | ✓ |
| 2 | 1 PC REAR BUMPER SIDE RETAINER <i>nc</i> | 113.20 | ✓ |
| 3 | 1 PC REAR BUMPER RETAINER (SMALL) RH <i>nc</i> | 23.10 | + |
| 4 | 1 PC REAR BUMPER REFLECTOR - RH <i>del d</i> 1671 | 179.80 | ✓ |
| 5 | 1 PC REAR BUMPER REINFORCEMENT <i>Best</i> 1253.25 | 316.70 | ✓ |
| 6 | 1 PC TAIL LAMP - RH <i>del d</i> | 346.50 | ✓ |
| 7 | 1 PC BOOT LID RUBBER <i>2 nc</i> | 166.40 | + |
| 8 | 1 PC BOOT LID PANEL <i>rear panel</i> <i>front</i> <i>Refr</i> | 620.10 | + |
| 9 | 1 PC BOOT LID INNER TRIM <i>del d</i> <i>rear panel</i> | 232.10 | ✓ |
| | | 2,480.60 | |
| | | Less 25% | 1,860.48 |
| Special Net | | | |
| 10 | 1 PC "L" PLATE BRACKET <i>nc</i> | 40.00 | ✓ |
| 11 | 1 SET REAR BUMPER STICKER <i>nc</i> 285 | 195.00 | ✓ |
| 12 | 1 SET REAR BUMPER CLIPS <i>nc</i> | 60.00 40 | ✓ |
| | | 295.00 | 295.00 |
| Labour | | | |
| 13 | 1 TO CHECK WIRING | 50.00 30 | . |
| 14 | 1 TO REPLACE REAR BUMPER STICKER | 80.00 40 | . |
| 15 | 1 TO SPRAY UNDERSEAL | 80.00 | + |
| 16 | 1 TO REMOVE AND REFIT INNER TRIM 960 | 100.00 40 | . |
| 17 | 1 (REAR) TO SPRAY PAINTING | 800.00 300 | . |
| 18 | 1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS. | 800.00 350 | . |
| | | 1,910.00 | 1,910.00 |

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department

Estimate No: EST1900227
Date: 20 Jul 2019
Veh Reg No: SKR6239P
Make/Model: TOYOTA
VIOSJGRADEMT
Chasis No: MHFBT9F3306027765
Reg. Date: 26/02/2015
Your Ref No: SHC8244A

Claim Type: Third Party
Accident Date: 18/07/2019
TP Veh Reg No: SHC8244A

Estimate Repair Cost to Vehicle No :SKR6239P

| Quantity | Description | List Price S\$ | Amount S\$ |
|----------|-------------|----------------------|---------------|
| | | Total | S\$ 4,065.48 |
| | | Add GST @ 7% | 284.58 |
| | | Total Amount Payable | S\$ 4,350.06 |

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND THREE HUNDRED FIFTY AND CENTS SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adnan Lj
L/S 22/07/19.

07 Days.

total: 2488.26

L/S 2K

(2K) (04077)