- 0	(centerth :	ASSI	GNMENT (Office)	1479		
	a); Sevence	OĒ	PCL	Date/Time: 2017 2019		
Estimated Co			Bill to:			
DO TP/W	8/TP RES / OD RES	EVA/INV/	MV/CS			
To Inspect V	ehicle No: SKS	CLOO		Insured: SHC 3989 D		
it Workshop	IN/s Autoroox Ho	use		Tel: 64538311 .		
r 176 0	10-CO# M					
olicy No:			Claim No:	D19004738MFSA		
insured:	ia .		Excess:			
dake of Veh Client's Recer			LIAVOID.	D.O.A. 18 7 0019		
CA / REV	/ REP. / REV 24 HR	8		11.0.10.10.1		
Onte/Time:		Person Cont	ected:	H.O.D. Endopment		
ate/Time	Action/Instruction	Felianda G	/			
	545 70018 X					
	Stc 31570 x					
. 4	11 Pm 8 48	od enci	/			



MS First Capital Insurance Limited to Reg No. 1950001000 CST Neg No. H2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877
Tel: (65) 6507 3848 | Fax: (65) 6507 3849
www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

19-07-2019

Our Ref No. D19004738MFSH

Accident Date

18-07-2019

Claim Type. Third Party

Insured Vehicle

SHC3959D

Third Party Vehicle. SKS2001D

Survey Location

C/O 176 SIN MING DRIVE #02-01 SING MING AUTOCARE

Contact Person.

NA

Contact No.

64528211/0

Fax No. 64517420

Survey Type

WITHOUT PREJUDICE: NO DISPUTE ON LIABILITY (AS PER BOLA) BUT

QUANTUM TO BE AGREED

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

AUTOWORX HOUSE

Attention, NIL

Cc : TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

SERENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veh Out

Denise Tay (LKKAuto)

From:

admin @ AutoworxHouse <claim.autoworxhouse@gmail.com>

Sent:

Thursday, 12 March 2020 2:28 PM

To:

Denise Tay (LKKAuto)

Subject:

Re: SKS 2001D / TP / DOA: 18/7/2019 / FIRST CAPITAL

Dear Denise.

We accept your offer of lump sum @ \$5,900.00, 4 days for the COR.

Thank you.

Best regards, Ms. Lee Autoworx House No.176 Sin Ming Drive #02-01 Singapore 575721 Tel: 96725547 / 87668115

Fax: 64517423

On 3/12/2020 2:03 PM, Denise Tay (LKKAuto) wrote:

Dear Ms Lee,

Rear exhaust tip cutter Kenneth only allowed 1 piece(\$321.50).

Correction for this - 2 pieces of rear bumper parking sensor @ \$262.10 each

Therefore final calculation for lump sum is \$5,900/-

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: admin @ AutoworxHouse <claim.autoworxhouse@gmail.com>

Sent: Thursday, 12 March 2020 12:21 PM

To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Subject: Re: SKS 2001D / TP / DOA: 18/7/2019 / FIRST CAPITAL

Dear Denise,


We have calculated your marked estimate prices and the adjusted prices.

However, we have come to a lump sum of \$6141.01 for the cost of repair.

There are 2 pieces of rear bumper parking sensor @ \$262.20 each and 2 pieces of rear exhaust tip cuter @ \$321.50 each.



(Supremne) Filter



(Supreme) (§Hee



(Supreme) Filhee



A Forwarded List price \$1370.00 No stock, indent ETA 2-4 weeks \$1000.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	18/07/2019 21:12
Date Of Accident	18/07/2019 11:40
Exact Location Of Accident	GUILLEMARD ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKS2001D
Insured/Policyholder	
Name Of Registered Owner	AIK SUN DEMOLITION & ENGINEERING PTE LTD
Co Reg No	199407828C
Email Address	TANSY:TAN@AIKSUN.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-63829659
Vehicle Particulars	
Manufacturer	VOLVO
Model	S60-1.6 D2 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA330889
Cover Note Number	
Driver	
Name of Driver	TANCY TAN HIMEE LING

Name of Driver TANSY TAN HWEE LING

 NRIC No
 S7418272J

 Date Of Birth
 09/06/1974

 Occupation
 INDOOR

 Date Of Driving Pass
 13/07/1993

Driving Experience 26 YEARS AND 0 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-96741989

Fax Number Contact Number

EMail Address TANSY.TAN@AIKSUN.COM.SG

Address

3 LORONG PUNTONG #17-12

Postcode

576444

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

5

Was any body injured in the Accident?

NO NO

Was any injured conveyed to hospital by

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO.

Number of Passengers (Including Driver)

4

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHC3959D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

KOH TENG HOCK

NRIC/Passport Number

S1443803C

Contact Number

97880234

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBG4794E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

98815780

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

YP1119E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

93586996

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SKN8860C

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

98522907

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and accurate as <u>possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident (all insurers) awyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

出极是不幸

Oriver's Signature (If driver is not the policyholder)

Date & Time

18/7/19 B5-30pm

Reporting Centre Personnel's Signature


NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN
Relu Attach ekcetch
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT
I was travelling along buillenard Food towards
Changi for a meeting.
4
As I was warting at the traffic junction. I
suddenly heard & loud bong. I som a taxi had collided into my year from my rear View morn Then I turn into
a snall road slightly ahead in order not to obstruct the traffic
a small road slightly ahead in order not to obstruct the trappy
After I parked my car safely I alighted my car and realised that I was the dirst vehicle involved in a chain collision.
Nobody was injured during the accident
& Repair other workshop*
We declare the foregoing particulars are true in every respect. All To Im All To Im Centre Personnel's Signature Reporting Centre Personnel's Signature
ate & Time: (If driver is not the policyholder) Name: ompany Chop (if applicable) Date & Time: NRIC/FIN No.:

Company Chop (if applicable)

A=SKS2001D B=S4C3959D C=6894794E D=YP1119E E=SKN8860C





AUTOWORX HOUSE

TEL: 6452 8211 FAX: 6451 7423

ESTIMATE

AIK SUN DEMOLITION & ENGINEERING PTE LTD

c/o 46 Lentor Plain Singapore 786548

Not Northard (18mm 84800/2 Perny Afre Valley Goday

Date: 23/7/2019

QUANTITY	PARTICULA	RS	AMOUNT (\$)
	RE: VOLVO S60 / SKS2001D		
1 pc	rear boot emblem "VOLVO"		May 98.00
1 pc	rear boot emblem "S60"		Me 66.00
1 pc	rear boot emblem "D2"		Ma 70.00
1 pc	rear boot weatherstrip		/ 265.00
1 pc	rear boot lid		4 2,150.20
1 pc	rear boot lock		₹ 275.30 ×
1 pc	rear boot lock catch		M 116.90
1 pc	rear bumper 1440-70	Bu	2,364.00
1 pc	rear bumper lower protector 36/-60		465.00
1 pc	rear bumper garnish 486-40		7cm 567.00
2 pcs	rear bumper side retainer	@ 65.00	130.00
1 pc	rear bumper reinforcement		765.00
2 pcs	rear bumper park sensor @ 162-15	@ 478.00	1,434.00
2 pcs	rear tail lamp lower bracket	@ 143.00	5 286.00
1 pc	rear end panel		7 674.10
1 pc	rear end panel garnish		365.80
2 pcs	rear exhaust tip cutter 321-50	MIDU/10:00 376.00	ONJUX 752.00
		sub-tota	10,844.30
		less 10%	6 1,084.43
		sub-tota	9,759.87
	To remove and replace all the parts men	ntioned above, knocking	45
	and straighten up the necessary affected		900.00
	To check wiring system.		20(40.00
	To spray painting on affected areas.		500 950.00
	To apply rust proofing on affected areas	Auto Consultants hence nonly	30(150.00
	To apply waterproof sealant on affected	areas.	150.00 .
	1,4702	to broke me success to committee a committee of the commi	80.00
		Total	12,029.87

Page 1 of 1

1502787

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721 TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

AIK SUN DEMOLITION & ENGINEERING PTE LTD c/o 46 Lentor Plain Singapore 786548

Date: 26/7/2019

QUANTITY	PARTICUL	ARS	AMOUNT (\$)
	RE: VOLVO S60 / SKS2001D / SUPP		
1 set	rear bumper lower sport kit assy special edition - special indent item	mych s.nett	(Bil) 3,000.00
		Total	3,000.00



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Inter	nationale Des Experts En Auton	nobile	
MS FIRST CAPITAL	INSURANCE LTD	Ref : CS/FCI190128	84/Ktf3e2	
86 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 18-03-2020 Code: FCI2		
	Policy Particu	lars :- THIRD PARTY CLA	IM	
Insured Veh.	SHC 3959D	Veh. Inspected	SKS 2001D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004738MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	22/07/2019	
2.	Vehicle P	Particulars & Condition		
Make & Mode	VOLVO S60 (A)	c.c	1560	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	YV1FS84ABF2349792	Colour	RED	
Odometer	105766	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3.	Co	nditions of Tyres		
	Size	Make	Balance	
R/H Front Tyr	e 235/40Z R18	DUNLOP	6 mm	
L/H Front Tyr	e 235/40Z R18	DUNLOP	6 mm	
R/H Rear Tyre	235/40Z R18	DUNLOP	4 mm	
L/H Rear Tyre	235/40Z R18	DUNLOP	4 mm	
4.	Desc	ription of Damages		
THE VEHICLE S	SUSTAINED DAMAGES AT THE DETAILS.	E REAR PORTION.		
5.	Ger	neral Information	-	
Accident Date	18/07/2019	Inspection Date	24/07/2019	
Survey held a	t AUTOWORX HOUSE			
	176 SIN MING DRIVE #02-01 SINGAPORE 575721			
5a.		Remarks		
B)THE INSPEC	ONSISTENT TO ACCIDENT RE TION WAS CONDUCTED ON A NICE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BAS		

Estimate Days of Repair

4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 2001D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT EMBLEM "VOLVO"	NECESSARY	98.00	98.00
1	REAR BOOT EMBLEM "S60"	NECESSARY	66.00	66.00
1	REAR BOOT EMBLEM "D2"	NECESSARY	70.00	70.00
1	REAR BOOT WEATHERSTRIP	SERVICEABLE	265.00	
1	REAR BOOT LID	BENT	2,150.20	2,150.20
1	REAR BOOT LOCK	TO REPAIR SEE LABOUR	275.30	
1	REAR BOOT LOCK CATCH	TO REPAIR SEE LABOUR	116.90	,
1	REAR BUMPER	BUCKLED / DENTED	2,364.00	1,440.70
1	REAR BUMPER LOWER PROTECTOR	DENTED / CUT	465.00	361.60
1	REAR BUMPER GARNISH	MTG CRACKED	567.00	486.40
2	REAR BUMPER SIDE RETAINER @\$65.00	SERVICEABLE	130.00	s
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	765.00	
3	REAR BUMPER PARK SENSOR @\$478.00	SHORTED (2 PCS ONLY)	1,434.00	524.20
2	REAR TAIL LAMP LOWER BRACKET @\$143.00	SERVICEABLE	286.00	9
1	REAR END PANEL	TO REPAIR SEE LABOUR	674.10	8
1	REAR END PANEL GARNISH	SERVICEABLE	365.80	
2	REAR EXHAUST TIP CUTTER @\$376.00	N/S DENTED / DISTORTED / O/S SERVICEABLE	752.00	321.50
	LESS 10% DISCOUNT		-1,084.43	-551.86
			9,759.87	4,966.74
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER LOWER SPORT KIT ASSYSPECIAL EDITION -SPECIAL INDENT ITEM. (ADDITIONAL)(SN)	MTG CRACKED	3,000.00	1,370.00
	A CONTRACTOR OF THE CONTRACTOR		3,000.00	1,370.00

Report Ref No. CS/FCI19012884/Ktf3e2



(TO ITS PRE-ACCIDENT CONDITION)

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR BOOT LOCK, REAR BOOT LOCK CATCH, REAR BUMPER REINFORCEMENT AND REAR END PANEL.		900.00	450.00
	TO CHECK WIRING SYSTEM.		40.00	20.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		950.00	500.00
	TO APPLY RUST PROOFING ON AFFECTED AREAS.		150.00	30.00
	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS.	NOT NECESSARY	150.00	31
	TO INSTALL REVERSE SENSOR.		80.00	50.00
			2,270.00	1,050.00
	GRAND TOTAL		15,029.87	7,386.74
	RECOMMENDED COST OF LUMP SUM REPAIRS		15766	5,900.00

Report Ref No. CS/FCI19012884/Ktf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report. In whole or in part, does so at his or her own risk.