inn	Surveyor : From (Person)	b		SIGNMENT (Office)	Date/Time:	MAIG	
18.00 0.0	Estimated Cos OD (*PP) Ws To inspect Ve	STTP RES / OD R		Bill to: V / MEV / CS R 3016 K	Insured:	FS 3024R	
	at Workshop i	m/s lud.	Jingkia Park 2A	Car services	Tel: 93	1	55
	Policy No: _ f	NMC2018-000		Claim No:	1201900	135000	
	Make of Veh:			Excess:	D.O.A	16/7/19	
	CA / REV	/ REP. / REV 24		Confacted;	H.O.D. En		
	Date/Time	Action/Instruction W.F. 3016 K F.S. 3074 F	×			,	
		Dismantle:	1/8/2019		-	77	

...CLAIM SUBFOLDER...(Pending for Survey Report)

	FOLDER TRA	The second secon	TARI Accional	Adi Rot	Adi Sut	mitted	This Auth'ed	Status	
Case Main	22 Jul 2019 Edit Reg	Est Submitted	Adj Assigned 22 Jul 2019 00:00 Edit Adj Rpt	Auj Rpt	Maj sui	initted	ins names	Pendir Report	ng for Survey t I Case
	Main	Re	ference		Claim Details		Docume	nts	Show All
CLAIM SU	BFOLDER D	ETAILS				[Create	ed by adjuster]		
Insured:						200	77 11.		
Main Claimant:	-								
Vehicle Re	SKR301	16K			Date of Loss:	16/07/2	2019 00:00 - :59		
Claim Type	: TP / 120	01900020781			Policy/Cover Note No.:	PNMC20	18-00005488		
Vehicle Re No. (Insured):	FS3024R				Policy No. (Claimant):				
(21122122)					Excess:	1			
Repairer:	Jingkia C	ar Services (HQ)	BLK 10 AMK IN	DUSTRIAL F	PARK 2A, #05-09	AMK AUT	O POINT, 568047	Ang Mo Kid	- Tel: 93822000
Handling Insurer:	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	gapore Pte. Ltd. (
Adjuster:	31/07/2	Consultants Pte 019]	Ltd (HQ) - Tel:	6256-3561	I [Handled by	PARASUI	RAM SHANMUGA	M] [Fir	nal Rpt due
ASSOCIA	TED MAIL RI	ECEIVED						View All	Compose Case Mail
There are	no mail for thi:	s case.							
ALL ASS	OCIATED TA	sks ⁼				View A	All Search Tasks	Create I	New Task Complete
Due Da		Type Task	Group Sub	ject Ha	ndler Assig	ned By	Completed 0	n Cr	eated On Done

Nivitha (LKK Auto)

From:

eileen.bay@fwd.com

Sent:

Monday, 22 July 2019 2:15 PM

To:

admin-d@lkkauto.com; assignments@lkkauto.com; sur@lkkauto.com; admin-

a@lkkauto.com

Cc:

motorclaims.sg@fwd.com

Subject:

FW: Accident Involving SKR 3016K & FS 3024R On 16 July 2019 | FWD ref:

1201900020781

Dear Celine,

Please refer to below.

Kind regards,

Eileen Bay

Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986


(65) 69217411

E

eileen.bay@fwd.com

W www.fwd.com.sg





App Store Google Play



From: Joseph Goh [mailto:joseph_goh@juseq.com.sg]

Sent: Monday, 22 July 2019 12:43 PM

To: Eileen Bay - SGUser

Subject: RE: Accident Involving SKR 3016K & FS 3024R On 16 July 2019 | FWD ref: 1201900020781

Your ref: 1201900020781 Our ref: JEQ/JG/7334-19.JCS

Dear Eileen

We refer to your email below.

Please have your surveyor contact our client's workshop (details appended below) directly to arrange for the prerepair inspection.

Jingkia Car Services 10 Ang Mo Kio Industrial Park 2A Ang Mio Kio Autopoint #05-09

Singapore 568047

Contact Person: Mr Tan 64814055 (o) / 9382 2000(hp)

Veh Out

Regards Joseph Goh M/s JusEquity Law Corporation 171 Chin Swee Road #02-06 Singapore 169877

Tel: 6536 9339 Fax: 6536 5368

Email: joseph_goh@juseq.com.sg

From: eileen.bay@fwd.com [mailto:eileen.bay@fwd.com]

Sent: Monday, 22 July 2019 12:19 PM

To: joseph_goh@juseq.com.sg Cc: motorclaims.sg@fwd.com

Subject: RE: Accident Involving SKR 3016K & FS 3024R On 16 July 2019 | FWD ref: 1201900020781

WITHOUT PREJUDICE

Dear Joseph,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK AUTO CONSULTANTS PTE LTD, to conduct the pre-repair survey (PRS) on your client's vehicle. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/or insurers. We hereby maintain full reservation of rights and all defences available to us.

*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.

Kind regards,

Eileen Bay

Executive, Claims

FWD Singapore Pte. Ltd.


6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 69217411

E eileen.bay@fwd.com

W www.fwd.com.sg







From: Joseph Goh [mailto:joseph_goh@juseq.com.sg]

Sent: Monday, 22 July 2019 12:15 PM

To: Eileen Bay - SGUser

Subject: RE: Accident Involving SKR 3016K & FS 3024R On 16 July 2019 | FWD ref: 1201900020781

Your ref: 1201900020781 Our ref: JEQ/JG/7334-19.JCS

Dear Eileen

We refer to your email of 18.7.17.

We write to inform that our client is unable to agree with your list of surveyors. Our client proposes Mr Nicky Seah from Absolute Appraisal Services Pte Ltd as the single joint expert to conduct the pre-repair inspection.

Please let us know if you have any objections to our client's proposal. If you are unable to agree with Mr Nicky Seah, our client proposes that each party conduct their respective pre-repair inspection.

Please let us have your early reply.

Regards
Joseph Goh
M/s JusEquity Law Corporation
171 Chin Swee Road #02-06
CES Centre
Singapore 169877

Tel: 6536 9339 Fax: 6536 5368

Email: joseph_goh@juseq.com.sg

From: eileen.bay@fwd.com [mailto:eileen.bay@fwd.com]

Sent: Thursday, 18 July 2019 5:54 PM

To: joseph_goh@juseq.com.sg Cc: motorclaims.sg@fwd.com

Subject: RE: Accident Involving SKR 3016K & FS 3024R On 16 July 2019 | FWD ref: 1201900020781

WITHOUT PREJUDICE

Dear Sir / Madam,

Please find our panel surveyors as follows: -

- 1. LKK Auto Consultants Pte Ltd
- 2. Infiniti Appraisal Service
- 3. AJAX Inspection Services Pte Ltd
- 4. RT Appraisal Pte Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receive your reply.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.

Eileen Bay

Executive, Claims

FWD Singapore Pte. Ltd.


6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 69217411

E eileen.bay@fwd.com

W www.fwd.com.sg





From: Joseph Goh [mailto:joseph_goh@juseq.com.sg]

Sent: Thursday, 18 July, 2019 5:05 PM

To: SG Corporate Contact

Subject: Accident Involving SKR 3016K & FS 3024R On 16 July 2019

Attention: Motor Claims Department

Your ref: To be advised

Our ref: JEQ/JG/7334-19.JCS

Dear Sirs

We refer to the above matter wherein we act for Mr Eng Pook Wei Derek, the owner of motorcar no. SKR 3016K which was involved in the above accident.

We understand that you are the insurers of motorcycle no. FS 3024R at the time of the accident.

Please find attached our Notice of Accident for your attention.

Please let us have your reply soon.

Regards
Joseph Goh
M/s JusEquity Law Corporation
171 Chin Swee Road #02-06
Singapore 169877

Tel: 6536 9339 Fax: 6536 5368

Email: joseph_goh@juseq.com.sg

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not

use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Eileen Bay

Date: 07 Aug 2019

Preliminary Advice

Insured Vehicle No : FS3024R

TP Vehicle No

: SKR3016K

Accident Date

: 16/07/2019

Make

: TOYOTA COROLLA ALTIS

Assignment Date

: 22/07/2019

Date of Inspection

: 01/08/2019

Est. Duration of Repair

: 2.00

Inspection At

: JINGKIA CAR SERVICES (HQ)

BLK 10 AMK INDUSTRIAL PARK 2A, #05-09 AMK AUTO POINT

SINGAPORE 568047

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,798.40
Revised Amount	:S\$	964.83
Check Items (Estimated)	:S\$	0.00
Total	:S\$	964.83

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

Other comments:

(The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT	THE CHARLES
Date Of Report	17/07/2019 11:25	
Date Of Accident	16/07/2019 08:05	
Exact Location Of Accident	CTE (AYE) 10KM	
Country/State of Loss	SINGAPORE	
	DETAILS OF CHALLETING	

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR3016K

Insured/Policyholder

Name Of Registered Owner

ENG POOK WEI DEREK

NRIC No

S7429524Z

Email Address

SPIDEY.ENG@GMAIL.COM

Mobile Phone No.

(LOCAL) +65-82180606

Alternative Phone No

OTHERS-82180606

Vehicle Particulars

Manufacturer TOYOTA Model ALTIS 1.6

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

S 90307072 SMF

Cover Note Number

Driver

Name of Driver ENG POOK WEI DEREK

NRIC No S7429524Z Date Of Birth 10/09/1974 Occupation INDOOR Date Of Driving Pass 12/09/1995

Driving Experience 23 YEARS AND 10 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-82180606

Fax Number

Contact Number OTHERS_82180606 Addre≈s

513 YIO CHU KANG ROAD

#02-43

Postcode

787067

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: ANG PUAY LI

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

KEBUN BARU NPP

Police Station Address

ROAD: 111 ANG MO KIO AVE 4 , POSTCODE: 560111 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FS3024R

Vehicle Make/Model/Colour

HONDA / SP / WHITE

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

PHOA TECK SHUEAN

NRIC/Passport Number

S9310599J

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers') who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	#10740HC030H4 @4124120
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	524Z
Vehicle No.:	SKR3016K
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	1ZRX484039
Chassis No.:	MR053REH104525378
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	29 Jan 2015
First Registration Date:	29 Jan 2015
Transfer Count:	0 (5092 - \$7,2945)
Actual ARF Paid: Intended PARF Rebate Details	29 Jan 2015 0 \$14,589.00 \$ 5090 = \$7,294.50
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2025
PARF Rebate Amount: Intended COE Rebate Details	\$10.931.00 × 50% = \$24 1050
COE Expiry Date:	28 Jan 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,001.00
COE Rebate Amount:	\$35,663.00
Total Rebate Amount:	\$46,604.00

The information contained herein is correct as at 02 Aug 2019

DOA: 16/07/2019

OK

47,586

Removers: 5 years 6 menths 12 days (66.4 months)
Depri: \$9100 (Yearly) \$758.33 (monthly)

66.4×\$758.33 = \$50353.33 \$50353.33+\$5470.50

-\$55823.83

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Forum

Resources

FLY TO OVER 60 CITIESI

ALL-IN FARE FROM 556*

ScootBiz from \$177*

New 5 Years Renewal Coe Honda Fit 1.3A G

Book Now

OX scoot

Articles

Post an Advertisement Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Advertiser Login Ways of Selling



3,08%p.a.y s0 Down,Monthly GV Credit Pte Ltd



Browse by Category 35 vehicles

Post an Ad

Toyota Corolla

« Back (1 2) Next »

Sort by Date Posted

20 results/page

Model

Price

\$60.888

Depreciation

02-Oct-2015

Eng Cap

Mileage

Veh Type

Search Selection

Toyota Corolla

Any

Any

\$8,430 /vr

2015

1,598 cc

42,000 km

Sedan

Available Available

Classic 1 Owner, Agent Maintained.

Toyota Corolla Altis 1.6A

Posted: 02-Aug-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, toyota corolla, Toyota, Corolla, Corolla, Used Toyota

1,598 cc

Toyota Corolla Altis 1.6A Classic

\$58,800

\$9,100 /yr

13-May-2015

56,800 km

Available Sedan

Low Mileage, No Repairs Needed, Well Maintained, Excellent Condition, Accident Free, Beautiful Interior And Exterior, Bank And In House Loan Available, Trade In Are Welcome, Powerful Engine And Smooth Transmission, A Real Joy To Drive! Buy With Confidence! Call Us N...

Posted: 01-Aug-2019 Tays: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, Corolla, Used



Toyota Corolla Altis 1,6A

\$67,800

\$9,610 /vr

16-Sep-2015

1.598 cc

30.080 km

Sedan

Available

PERMINAN

PREMIUM AD

Borneo Unit, Full Agent Maintained. Warranty Till Sept 2020. Grey Met Metallic Colour, Most Popular Sedan In The Market, Interest Rate From 1.99%. Please Call Our Sales Consultant For More Enquiries Now.

Inchcape Pre-Owned

Posted: 01-Aug-2019 Tays: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Corolla, Corolla, Used Toyota

Toyota Corolla Altis 1.6A Elegance

\$64,800

\$8,770 /vr

09-Nov-2015

1,598 cc

86,365 km

Available

Elegance Model With Push Start And Keyless Entry! Call For An Viewing Appointment Today! High Loan Welcome.

Mayfair Motoring

Posted: 29-Jul-2019

Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used



Bullsone Grasse Diffuser - Pure Cotton (105ml)

Contains 100% natural French oil, providing drivers with deep subtle scent for pleasant driving experience.

Find out more!



Toyota Corolla Altis 1.6A Elegance

Toyota Corolla Altis 1.6A

\$65,000

\$63,800

\$8,610 /yr

28-Dec-2015

1,598 cc

81,000 km

Sedan

Available

One Owner Only, Excellent Tip Top Car Condition, Almost Brand New, Clean And Beautiful Interior, Owner's Consignment Unit, Call To Arrange For A Viewing.

(CONNIGHMENT)

Posted: 28-Jul-2019

Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

\$8,760 /yr

29-Sep-2015

1,598 cc

83,147 km

Sedan.

Available

PREMIUM 10

Well Taken Care By 1 Owner Only. 100% Accident Free & Non Private Hirer Unit, Low Fuel Consumption And Maintenance. Transparent Deal With No Gimmicks & Hidden Cost, Flexible Bank Loan Package With Low Interest From 2.28%. In House Loan Available, Welcome T...

Ka-Hup Vehicles Trading

Elegance

- isted: 28-Jul-2019

Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

200

NACL INC. Item

	~ INC	Item	Too.	1.5	
1137		Rear Number Plate	CON	AC	Qt
1138		Rear Number Plate Base	-	_	
1139	7 2 2 2 2 4	Rear Number Plate Garnish	-		_
1140	993632	Rear Number Plate Garnish Rear Number Plate Lamp	-		_
1141	007058	Rear Bumper	-		1
1142	002006	Real Bumper	cra		
1143	993083	Rear Bumper Upper Rear Bumper Lower			
1144	993054	Rear Bumper Side	-		_
1145	993103	Peac Bulliper Side			
1146	992341	Rear Bumper Tow Cover			
1147		Rear Bumper Clips	na	/	6
1148	002000	Rear Bumper Bracket			
-	993068	Rear Bumper Side Retainer			-
1149	993045	Rear Bumper Reinforcement		-	-
1150	992970	Rear Bumper Beam		-	-
1151	993077	Rear Bumper Sponge	1		-
1152	992999	Rear Bumper Damper	-		-
1153	993040	Rear Bumper Protector	1	-	-
1154	993036	Rear Bumper Pad		-	-
1155	993026	Rear Bumper Moulding			-
1156	993044	Rear Bumper Reflector	1		
1158	993023	Rear Bumper Lower Spoiler	T	T.	
1159	994023	Reverse Sensor	92	1	
1160	993327	Rear End Panel			
1161	003333	Rear End Panel Top Garnish			
1162	000222	Rear End Panel Inner Trim			
1163	002061	Boot Compartment Inner Trim			
1164	993831	Rear LH Taillamp			
1165	993833	Rear LH Taillamp Garnish			
1166	995116	Rear LH Taillamp Panel Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	-		
1169	993554	Rear Apron Panel	-	_	
1170	992895	Bootlid	-	_	_
1171	991328	Bootlid Emblem	+-+	-	_
1172	990356	Bootlid Handle	-	_	1
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector	-	_	
1175	995222	Bootlid Lamp LH	-		_
1176	992899	Bootlid Lamp RH	-	-	_
1177	995243	Bootlid Lock	-	-	_
1178	990377	Bootlid Rubber		-	
1179	990382	Bootlid Hinge			-
1180	993877	Bootlid Spoiler	1		_
1181	994543	Tailgate			-
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994040	Tailgate Moulding			in
186	994640	Tailgate Gamish			box
	004540	Tailgate Reflector			
188	994549	Tailgate Lamp			
100	004656	Tailgate Protector			
189	994076	Tailgate Wiper Arm		7	
190	994077	Tailgate Wiper Blade			_
191	994679	Tailgate Wiper Nozzle			
192	994555	Tailgate Wiper Motor		+	-
193	994602	Tailgate Glass	-	+	-
194	994606	Tailgate Glass Rubber	1	-	-
195	994604	Tailgate Glass Moulding	1	+	-
190	994007	Failgate Glass Sealant		+	
197	994629	Tailgate Lock		+	-
198	994651	Tailgate Rubber	-	+	
199	994611	l'ailgate Hinge		+	0
200	994594	Failgate Damper	-	+	-
201		Tailgate Inner Board			

1	NAC	INC	Item	CON	AC	0
ĺ	1202	.993784	Spare Tyre Board	CON	AC	×
I	1203	994328	Spare Tyre Panel	-	-	-
l	1204	995065	Spare Tyre	-	-	-
ſ	1205	994326	Spare Tyre Lock Screw		-	-
Ī	1206	993787	Spare Tyre Cover	-	-	_
	1207	995323	Triangle Breakdown Sign	-	-	-
1	1208	990507	CD Changer Assy		-	-
l	1209	990164	Antenna	-	-	-
I	1210	990534	Centre Exhaust Pipe Assy	-		_
Ì	1211	990532	Centre Exhaust Mounting	-	_	_
I	1212		Rear Exhaust Pipe		_	
İ	1213	-	Page Palacida			
Ì	1214		Rear Exhaust Chrome Pipe Rear Exhaust Mounting			
Ì	1215	-	Pear Exhaust Mounting			
ł	1216		Rear Exhaust Heat Shield			200
ł	1217	993223	Rear LH Chassis Member Rear RH Chassis Member			
Ì	1218	993436	Rear LH Fender	-		
Ì	1219		Rear LH Fender Protector			_
Ì	1220	993420	Rear LH Fender Inner Panel	-	_	-
1	1221	993431	Rear LH Fender Inner Trim	-		-
I	1222	993415	Rear LH Fender Inner Garnich		-	-
1	1223	993425	Rear LH Fender Inner Shield		-	-
	1224	993621	Rear LH Mudflap			
l	1225	993933	Rear LH Wheel Rim		-	-
Ĺ	1226	994025	Rear LH Rim Cover		-	No.
l	1227	995065	Rear LH Tyre	-	-	
Į.	1228	993456	Rear RH Fender		-	-
ļ	1229		Rear RH Fender Protector		-	
ŀ	1230		Rear RH Fender Inner Panel			-
ŀ	1231	993431	Rear RH Fender Inner Trim			
ŀ	1232	993415	Rear RH Fender Inner Garnish			
ŀ	1233	993425	Rear RH Fender Inner Shield			
ŀ	1234	993022	Rear RH Mudflap			Ú.,
ŀ	1226	004005	Rear RH Wheel Rim			
ŀ	1237	005065	Rear RH Rim Cover Rear RH Tyre			
ŀ	1238	993003	Rear RH Tyre			
ŀ	1239	003401	Rear Fender Extension Panel LH			
t	1240	993430	Rear Fender Extension Panel RH			
t	1241		Rear Fender Inner Top Gamish Rear Fender 1/4 Glass		_	_
ľ	1242	993452	Rear Fender 1/4 Glass Rubber	-	-	_
L	1243	993453	Rear Fender 1/4 Glass Seplant	- 4	-	-
ŀ	1244	993949	Rear Windscreen Glass			
1	1245	993976	Rear Windscreen Rubber			
-	1246	993961	Rear Windscreen Moulding			
F	1247	993955	Rear Windscreen Sealant			
H	1248	994/29	Third Brake Light			
-	1250	992162	Rear Fender Air Grille Fuel Lid			
-	1251		Fuel Neck			
	1252	992170	Fuel Neck			
	1253	002104	Puel m. 1. P.			
_	1254	002101	Fuel Tank Bracket			
		990247	Fuel Tank Float			
Ľ	+4,00/1	330247	Sucker			200
-	-					
	-					Seits
	-					
3	-		2			
+						
-						(3)
-					1	1933
-	-					200
						-
	-				_	

JINGKIA CAR SERVICES

Blk 10,Ang Mo Kio Autopoint,#05-09 Ang Mo Kio Industrial Park 2A Singapore 568047
Tel:64814055 Fax:64811066 H/P:93822000
Epairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Re: Quotation of valide 10. 5KR 3 substant Coyate Atto.

01/08/19.

\$ 575-50 (m \$436.50 Ipc. Rear bumper any for Rear bumper reinforcement 246-2011/ 1pc- Rear bumper Lit retainer 75.10 NC 840 be bear bumper let reflector 55-60 mx I set Rear burger rev. sensor 220 - 60 Se/ / Bumper dips. 21-00 200 16-00 nec/ 1188-40 25% 178-32 \$ 552.98 Labour charge to regar the 280-00 \$2000 accident areas. To spraying rear bumper 28000 \$200 M To read sensor wiring front 50.00 \$30

Resulting Total: \$ (1798,4.00 \$982.98

4\$ 20%: \$ 750.06 50.00 \$30

仁佳汽车(维修)业 JINGKIA CAR SERVICES g Mo Kio Industrial Park 2A \$05-09, Ang Mo Kio Autopoint, Singapore 568047

JIK 10,7 mg	Tel: 6481 4055 Email: jing	Fax: 6481 1066 H/P: 9382 2000 kiacarservices@yahoo.com.sg	Cash Sa	le No 21	523
Specialist in: Acci	The second secon	ental, Engine, Air-con Repair, Spray painting	DATE	0/08/19	
MESSERS/MR _	FWD	Tingapore Ha Litel	REG NO_S		
			MAKE_To	yota Ald	<u>u.</u>
QTY	UNIT PRICE	DESCRIPTION		AMOUNT	
	*			\$	cts
		General Service Package			+-
		Beng lum sun regal	I.	750	65
		to vehicle no skip 3011	5/4		1
		on the accident affect	2400		
		areas . (By your surveyor	LKK)		
	24 - 31 (1423) - 3-2-	Loss of use so x	590tz	100 -	- 03
	CAR SERVICES		TOTAL: \$	A50.	63

JINGKIA CAR SERVICES

Blk 10,Ang Mo Kio Autopoint,#05-09 Ang Mo Kio Industrial Park 2A Singapore 568047 Tel:64814055 Fax:64811066 H/P:93822000

01/08/19.

Re: Quotation of vehicle no. SER 3016 K Toyota Atti.

Ve: Quetation of vence 10.311 2016	\$ 575-50 M \$436.
1 pc. Rear bumper any	
for Rear bumps reinforcement	246-20 MX
Ipc. Rear bumper Lit retainer	75.10 NEC \$40
for Rear bumper LH reflector	55-60 mx
1 set lear pumper rev. sonsor	220-6080
2ps Burper dips. 08-00	16-00 ne/
•	11188-40 8713.3
- Labour charge to regar the	\$ 552.
- Labour charge to repair the accident areas.	280-00 \$2000
- To spraying rear bumper	280-00 \$200
- To renew sensor wiring	50.00 \$30
(142)	\$ (,7924 2 \$982.9
RBMUNE Total:	# 75000

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed	Status	
Main	22 Jul 2019 Edit Reg		22 Jul 2019 00:00 Edit Adj Rpt	S\$750.00 Edit Estimate	S\$750. View R	and the state of t		Pending for Report Cancel Case	Survey
	Main	R	eference	CI	aim Details		Documen	ts	Show All
CLAIM SU	JBFOLDER DI	ETAILS		Distance of State Con-		[Create	ed by adjuster]		AND DESCRIPTION OF THE PARTY OF
Insured:	-, Co. Re	g. No.: -				***************************************			
Main Claimant:	-								
Vehicle Reg	SKR301	.6К			Date of Loss:		019 00:00 - :59 hths and 17 Days F	rom LTA Reg Da	te (Man Yr)]
Claim Type	Claim Type: TP / 1201900020781				Policy/Cover Note No.:	PNMC2018-00005488			
Vehicle Reg No. (Insured):	FS3024R				Policy No. (Claimant):				
					Excess:				
Repairer:	Jingkia C	ar Services (HQ) BLK 10 AMK IND	DUSTRIAL PAR	K 2A, #05-09	AMK AUT	O POINT, 568047 A	ng Mo Kio - Tel:	93822000
Handling Insurer:	FWD Sing	gapore Pte. Ltd.	(HQ) - Tel: 6727	5700 [Han	dled by Eileer	Bay]			
Adjuster:	31/07/2		e Ltd (HQ) - Tel:	6256-3561	[Handled by	PARASUR	RAM SHANMUGAM	1] [Final Rp	ot due
ASSOCIA	TED MAIL RE	CEIVED					<u> </u>	View All Com	pose Case Ma
There are	no mail for this	case.							
ALL ASS	OCIATED TAS	sks⊟				View A	II Search Tasks	Create New Tas	sk Comple
Due Dat	e Priority	Type Task	Group Subj	ect Handl	er Assign	ned By	Completed On	Created	On Don
No results.									

Claim Documents

*SKR3016K (1201900020781) [FS3024R]

Jul 16 2019 12:00AM [-] Jingkia Car Services

Up	load Documents Upk	ad Photos Compose New Letter	View	View in Brow	ser ▼
Ass	sessment Reports		1 per	page ▼	•
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/08/19 10:48	Adjuster Immediate Advice	0	Load HTM	
Pho	otos/Images		3 per	page ▼	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	05/08/19 18:12	General View	0	Load JPG	€
2	05/08/19 18:12	General View	0	Load JPG	•
3	05/08/19 18:12	General View	0	Load JPG	•
4	05/08/19 18:12	General View	0	Load JPG	•
5	05/08/19 18:12	General View	0	Load JPG	•
6	05/08/19 18:12	General View	0	Load JPG	
7	05/08/19 18:12	General View	0	Load JPG	•
8	05/08/19 18:12	General View	0	Load JPG	•
9	05/08/19 18:12	General View	0	Load JPG	•
10	05/08/19 18:12	General View	0	Load JPG	•
11	05/08/19 18:12	General View	0	Load JPG	•
12	05/08/19 18:12	General View	0	Load JPG	•
13	05/08/19 18:12	General View	0	Load JPG	•
14	05/08/19 18:12	General View	0	Load JPG	•
15	05/08/19 18:12	General View	0	Load JPG	•
16	05/08/19 18:12	General View	0	Load JPG	•
17	05/08/19 18:12	General View	0	Load JPG	•
18	05/08/19 18:12	General View	0	Load JPG	•
19	05/08/19 18:12	General View	0	Load JPG	•
20	05/08/19 18:12	General View	0	Load JPG	•
21	05/08/19 18:12	General View	0	Load JPG	•
22	05/08/19 18:12	General View	0	Load JPG	•
23	05/08/19 18:12	General View	0	Load JPG	•
24	05/08/19 18:12	General View	0	Load JPG	•
25	05/08/19 18:12	General View	0	Load JPG	•
26	05/08/19 18:12	General View	0	Load JPG	•
27	05/08/19 18:12	General View	0	Load JPG	•
28	05/08/19 18:12	General View	0	Load JPG	•
29	05/08/19 18:12	General View	0	Load JPG	•
30	05/08/19 18:12	General View	0	Load JPG	•
31	05/08/19 18:12	General View	0	Load JPG	•
32	05/08/19 18:12	General View	0	Load JPG	•

Ass	essment Reports		1 per	page ▼	•
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
33	05/08/19 18:12	General View	0	Load JPG	•
34	05/08/19 18:12	General View	0	Load JPG	•
35	05/08/19 18:12	General View	0	Load JPG	•
36	05/08/19 18:13	Photographs of Damaged Parts	0	Load JPG	•
37	05/08/19 18:13	Photographs of Damaged Parts	0	Load JPG	•
38	05/08/19 18:13	Photographs of Damaged Parts	0	Load JPG	•
39	05/08/19 18:13	Photographs of Damaged Parts	0	Load JPG	•
40	05/08/19 18:13	Photographs of Damaged Parts	0	Load JPG	•
41	05/08/19 18:13	Photographs of Damaged Parts	0	Load JPG	•
42	05/08/19 18:13	Photographs of Damaged Parts	0	Load JPG	•
43	05/08/19 18:13	Photographs of Damaged Parts	0	Load JPG	•
44	05/08/19 18:13	Photographs of Damaged Parts	0	Load JPG	
45	05/08/19 18:13	Photographs of Damaged Parts	0	Load JPG	•
46	05/08/19 18:13	Photographs of Damaged Parts	0	Load JPG	•
47	05/08/19 18:13	Photographs of Damaged Parts	0	Load JPG	•
48	05/08/19 18:13	Photographs of Damaged Parts	0	Load JPG	
49	05/08/19 18:13	Photographs of Damaged Parts	0	Load JPG	•
50	05/08/19 18:13	Photo After Spray	0	Load JPG	€
51	05/08/19 18:13	Photo After Spray	0	Load JPG	•
52	05/08/19 18:13	Photo After Spray	0	Load JPG	•
53	05/08/19 18:13	Photo After Spray	0	Load JPG	•
54	05/08/19 18:13	Photo After Spray	0	Load JPG	•
55	05/08/19 18:13	Photo After Spray	0	Load JPG	•
56	05/08/19 18:13	Photo After Spray	0	Load JPG	•
57	05/08/19 18:13	Photo After Spray	0	Load JPG	•
58	05/08/19 18:13	Photo After Spray	0	Load JPG	•
59	05/08/19 18:13	Photo After Spray	0	Load JPG	¥
Doc	cumentation		1 per	page ▼	•
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	22/08/19 11:14	OI GIA	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/FWD19012890/FQF3S2

Date:

27/08/2019

REFERENCE

Date of Loss:

Handling Insurer:

FWD Singapore Pte. Ltd.

Policy No:

PNMC2018-00005488

Claimant Vehicle

SKR3016K 16/07/2019 Insured Vehicle No:

Nature of Claim:

FS3024R

TP

Claim No: 1201900020781

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

No:

SKR3016K

Make & Model:

TOYOTA COROLLA ALTIS, 1.6 (A)

1ZRX484039 Engine No:

Reg. Date:

Grey

29/01/2015 (Man. Year: 2015)

Chassis No: Odometer:

MR053REH104525378

36776 km

Colour: Engine Capacity:

1598 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side:

Michelin 6 mm

Rear Left Side:

Michelin 5 mm

Front Right Side:

Michelin 6 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,188.40	534.82	653.58	55.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		610.00	430.00	180.00	29.51
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Ca	Iculated Gross Total (S\$)	1,798.40	964.82	833.58	46.35
Approve	ed Total (Overridden) (S\$)		750.00		
	Nett Amount (S\$)	1,798.40	750.00	1,048.40	58.30

INSPECTION

Date of Assignment:

22/07/2019

Jingkia Car Services (HQ)

Date Inspected:

01/08/2019 Inspected At:

BLK 10 AMK INDUSTRIAL PARK 2A, #05-09 AMK

AUTO POINT

Singapore 568047

Estimated Period of Repair:

2.0 days

PARASURAM SHANMUGAM Adjuster:

Manager:

SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$55,000.00 - PAPER VALUE: \$46,604.00 = NETT VALUE: \$8,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 27 Aug 2019)

Parts:

143

TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKR3016K)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

R	ecom	men	ded	Parts
1		111111111111	ucu	I CILCO

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER ASSY	Cracked	575.50 F	*436.50 FL
2	1	*REAR BUMPER REINFORCEMENT	Not Necessary	246.20 F	*-FL
3	1	*REAR BUMPER LH RETAINER	Necessary	75.10 F	*40.00 FL
4	1	*REAR BUMPER LH REFLECTOR	Not Necessary	55.00 F	*-FL
5	1	*SET REAR BUMPER REVERSE SENSOR	Short Circuit	220.60 F	*220.60 FL
6	2	*BUMPER CLIPS	Necessary	16.00 F	*16.00 FL
F=Fra	nchise part, L=ListIt		Sub Total (S\$) on L Items 0.00/25.00% (S\$)	1,188.40 0.00	713.10 178.28
		- List item Discount	Total Parts (S\$)	1,188.40	534.82
		Report was unsubmitted duri	ng this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR CHARGE TO REPAIR THE ACCIDENT AREAS.	New	280.00	200,00
2	TO SPRAYING REAR BUMPER.	New	280.00	200.00
3	TO RENEW SENSOR WIRING.	New	50.00	30,00
		Gross Labour Cost (S\$)	610.00	430.00
	Report was unsubmit	tted during this print-out.		

< END OF ESTIMATES >