

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

22 JUL 2019

E S T I M A T E

Estimate No. : b1 52072
Date Estimated : 22/07/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Ang Siok Kuwan Dominique
84 Corporation Road
#15-09

Singapore 649821

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME2996H	EB19009	26/09/2018	X2 sDrive20i	0

DESCRIPTION

To replace rear bumper and attachments.

Painting rear bumper.

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

VALUE

850 1,275.00

934 1,028.00

150 177.00

? 80.00

Total Labour 1: 2,570.00

DESCRIPTION

TAILPIPE TRIM BRIGHT CHROME D=90MM ?

REAR BUMPER LH SIDE INNER GUIDE ?

REAR BUMPER LH SIDE INNER GUIDE ?

MOUNTING SMART OPENER (M) ?

REAR BUMPER TOWING EYE COVER PRIMED X

REAR BUMPER PANEL PRIMED (M PDC/ICA) Repair de

REAR BUMPER TRIM BOTTOM PANEL PAINT de

SET MOUNTING PDC/PMA SENSOR REAR ?

REAR LH REAR REFLECTOR ?

QTY	PRIC	VALUE
1	116.05	116.05
1	61.50	61.50
1	61.50	61.50
1	45.30	45.30
1	51.45	51.45
1	1,185.70	1,185.70
1	1,602.60	1,602.60
1	60.35	60.35
1	37.90	37.90

Total Parts : 3,222.35

Claims Officer: _____
Regn No: _____ Claim No: _____
Date & Time: 05/08/19 @ 1425 Excess \$: _____
Surveyor's Name: RANU Sign: _____

Surveyor's Tel: 92060018 Authorised Yes / No
Authorised Date: _____ Time: _____
RES: PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
Surveyor's E-mail: _____
No. of Working Days Recommend: 3 days

Labour 1	:	2,570.00
Parts	:	3,222.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	405.46
Grand Total	:	6,197.81

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

BMW Dealer
A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52072**
Date Estimated : **22/07/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Ang Siok Kuwan Dominique
84 Corporation Road
#15-09

Singapore 649821

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME2996H	EB19009	26/09/2018	X2 sDrive20i	0

DESCRIPTION	ACCOUNT:			NETT
	ORIGINAL PRICE	DISC. %		
To replace rear bumper and attachments.	850.00	0		850.00 ✓
To respray rear bumper	934.00	0		934.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0		150.00 ✓
Sundries.	80.00	0		80.00
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (M PDC/ICA	1,185.70	1	0	1,185.70 ✓
REAR BUMPER TRIM BOTTOM PANEL PAINT	1,602.60	1	0	1,602.60 ✓
EXPANDING RIVET BLACK	1.35	10	0	13.50

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	2,801.80
Total Repair Costs less Excess:	4,815.80
GST @7%:	337.11
Grand Total :	5,152.91

OD	DATE	TIME
FAX TO	Rashid	26/9/19
FAX NO	UKK	3
FAX TO		
FAX NO		
FAX TO		
FAX NO		
CONFIRMED		

CAR RENTAL SUPPLIED BY AIG
GIA SEARCH FEE - \$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559V. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52072**
Date Estimated : **22/07/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Ang Siok Kuwan Dominique
84 Corporation Road
#15-09

Singapore 649821

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME2996H	EB19009	26/09/2018	X2 sDrive20i	0

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET BLACK <i>rec</i>	1.35	10	0	13.50
#				
#				

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	13.50
Total Repair Costs less Excess:	13.50