

PERFECT WERKZ

BLOCK 25 KAKI BUKIT ROAD 4 # 06-51 SYNERGY @ KB (S) 417800

TP Lon Pac.

Vic

cident date: 18.07.2019

Estimated repair cost for vehicle no: SJX7781M HYUNDAI AVANTE 1.6'10

n	Qty	Items	U/price	Amount
				\$882.00 ✓
				\$96.00 ✓
			\$0.00	\$32.00 ✓
1	1	Rear Boot Lid <i>Dented</i>		\$32.00 ✓
2	2	Rear Boot Lid Hinges <i>new</i>		\$32.00 ✓
1	1	Rear boot lid Emblem logo <i>3 new</i>		\$346.00 158 ✓
1	1	Rear Boot Lid Avante Logo	\$158.00	\$132.00 ✓
2	2	Rear Boot Lid side reflector <i>LH canled</i>		\$97.00 ✓
1	1	Rear Boot Lid Center Moulding <i>canled</i>	\$48.80	\$50.00 ✓
2	2	Rear Boot Lid Number Plate Lamp <i>3 new</i>		\$108.00 ✓
1	1	Rear Boot Lid Number Plate		\$82.00 ✓
1	1	Rear Boot lid Inner lock <i>new</i>		\$65.00 ✓
1	1	Rear boot lid inner rubber <i>new</i>	\$0.00	\$523.60 261.8 ✓
10	1	Rear Boot Lid Inner Trim board clips <i>new</i>	\$261.80	\$52.00 10 ✓
11	10	Rear Tail Lamp <i>LH canled</i>	\$6.50	\$300.00 X ✓
12	2	Rear tail lamp clips <i>new</i>	\$150.00	\$437.00 ✓
13	8	Rear Tail Lamp Panel <i>new</i>		\$70.00 ✓
14	2	Rear Tail Lamp Panel <i>new</i>	\$35.00	\$65.00 30 ✓
15	1	Rear Bumper <i>Defend</i>	\$6.50	\$350.00 245 ✓
16	2	Rear Bumper Side Bracket <i>new</i>		\$256.80 ✓
17	10	Rear Bumper Clips <i>new</i>		\$142.50 ✓
18	1	Rear Bumper Reverse Sensor <i>new</i>	\$28.50	\$133.60 66 ✓
19	1	Rear Bumper Reinforcement <i>canled</i>	\$66.80	\$110.00 ✓
20	5	Rear Bumper Reinforcement Top & Lower <i>new</i>		\$530.00 ✓
21	2	Rear Bumper Reinforcement Bracket <i>LH Bent</i>		\$158.00 ✓
22	1	Rear Bumper Inner Sponge <i>canled</i>		\$1,603.00 X ✓
23	1	Rear End Panel <i>Dented</i>		\$198.60 ✓
24	1	Rear End Panel Top Garnish <i>new</i>		\$65.00 X ✓
25	1	Rear Fender- LH <i>new</i>	\$6.50	\$178.00 X ✓
26	1	Rear Fender Inner Trim Board-LH <i>new</i>		\$250.00 X ✓
27	5	Rear Fender Inner Trim Board Clips <i>new</i>		
28	1	Rear Spare Tyre Panel Top Cover <i>new</i>		
29	1	Rear Spare Tyre Panel Sealant <i>new</i>		
			Subtotal :-	\$7,315.10

335640

268512

S.N : 200

Labour charges

To remove & refix rear windscreen

X \$120.00

Gum

X \$50.00

To remove & refix reverse sensor

50 ~~\$100.00~~

To remove & refix cushion

80 ~~\$150.00~~

To Check Wiring

30 ~~\$80.00~~

Tuff kote

60 ~~\$120.00~~

Panel beating

800 ~~\$1,000.00~~

Spray painting

800 ~~\$1,000.00~~

Subtotal :- \$2,620.00

Total:- \$9,935.10

total : 4705.12

4/5: 3750

06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: