

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0879/2019/NS
Date : 22-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Tan Kim Yian
Address : Blk 47 Jalan Tiga
#09-46
Singapore 390047
Telephone : (HP)+65 96730553
Type of Claim : Own Damage Claims
Policy No. : 1900004016
Vehicle No : **SMH 1239 B**
Model Code : Audi A5 SB 2.0 TFSI Quattro (A)
Model / Year : 11/1/2019
Engine No : CVK 073197
Chassis No : WAUZZZF58KA009883
Mileage : 6918
Date In : 19-Jul-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Jul-19
Place of Accident : Exit Of Shenton House Carpark Entrance

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMH 1239 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To remove and reinstall additional radiator and aircon condensor. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	X
3	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 300.00	✓
4	To dismantle and renew front bumper, bonnet, rhs front fender and rhs headlight. To repair rhs front door. To remove and renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 6,400.00	1250.
5	To respray front bumper, bonnet, rhs front fender and rhs front door	\$ 4,400.00	1650
6	To renew rhs front rim and carry out wheel alignment	S/N \$ 280.00	X
7	To carry out diagnostic check	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 13,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 1239 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>distorted</i>	\$ 2,073.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 368.00	+
3	FRONT BUMPER SECURING STRIP <i>?</i>	\$ 32.00	?
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	\$ 178.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	\$ 207.00	?
6	FRONT BUMPER SPOILER <i>from other</i>	\$ 489.00	+
8	FRONT BUMPER AIR GUIDE - RH <i>distorted</i>	\$ 56.00	✓
9	RADIATOR GRILLE <i>crushed</i>	\$ 2,131.00	✓
10	ULTRA SOUND SENSOR SUPPORT - LH / RH <i>new</i>	2 \$ 96.00	✓
11	RADIATOR GRILLE COVER - UPPER <i>?</i>	\$ 174.00	?
12	FRONT BUMPER AIR GUIDE GRILLE - RH <i>distorted</i>	\$ 431.00	✓
13	FRONT BUMPER CARRIER <i>?</i>	\$ 733.00	?
14	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>	\$ 113.00	✓
15	FRONT BUMPER TOP COVER <i>new?</i>	\$ 116.00	?
16	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$ 33.00	✓
17	FRONT BUMPER FOAM FILLER PIECE - RHS <i>?</i>	\$ 16.00	?
18	FRONT BUMPER BRACKET FOR LOCK CARRIER <i>crushed</i>	\$ 125.00	✓
19	REINFORCEMENT BEAM SUPPORT - LH / RH <i>new</i>	2 \$ 52.00	+
20	FRONT PARKING AID SENSOR - FRONT OUTER <i>new</i>	2 \$ 231.00	+
SUB-TOTAL SPARE PARTS		\$ 7,654.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 1239 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT PARKING AID SENSOR - FRONT INNER <i>new</i>	\$ 231.00	+
22	FRONT PARKING AID SENSOR SEAL RING <i>new</i> 4	\$ 12.00	+
23	BUMPER WIRING SET <i>new</i>	\$ 470.00	+
24	HORN - LOW TONE RIGHT <i>new</i>	\$ 262.00	+
25	HORN BRACKET - RH <i>new</i>	\$ 26.00	+
26	FRONT BUMPER BRACKET - RHS ?	\$ 195.00	?
27	FRONT FENDER - RH <i>Dented</i>	\$ 968.00	✓
28	FRONT FENDER ATTACHMENT PARTS ?	\$ 48.00	?
29	FRONT FENDER CLOSING ELEMENT - RH ?	\$ 68.00	?
30	FRONT FENDER BRACKET - RH <i>new</i>	\$ 32.00	+
31	POP RIVET <i>new</i> 5	\$ 15.00	✓
32	FRONT FENDER BRACKET - RH ?	\$ 32.00	?
33	FRONT FENDER BRACE - RIGHT FRONT ?	\$ 107.00	?
34	DEFORMATION ELEMENT BRACKET - RH <i>new</i>	\$ 45.00	✓
35	WHEEL HOUSING LINER - RH <i>to in</i>	\$ 256.00	✓
36	WHEEL HOUSING LINER ATTACHMENT PARTS FRONT AND RE ?	\$ 82.00	?
37	WHEEL SPOILER <i>new</i>	\$ 66.00	✓
38	SPOILER - RH <i>new</i>	\$ 33.00	✓
39	STONE CHIP GUARD - RH <i>new</i>	\$ 46.00	✓
40	FRONT FENDER TRIM - RH <i>new</i>	\$ 145.00	✓
SUB TOTAL SPARE PARTS		NEC \$ 3,139.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 1239 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	FRONT DOOR TRIM - RH <i>re</i>	\$ 145.00	✓
42	FENDER TOP LEDGE COVER - LONG RH <i>re</i>	\$ 32.00	✓
43	FENDER TOP LEDGE COVER - SHORT RH <i>re</i>	\$ 14.00	✓
44	BONNET <i>re</i>	\$ 2,602.00	+
45	IMPACT PROTECTION - CENTRE <i>re</i>	NEC \$ 25.00	+
46	IMPACT PROTECTION - LEFT <i>re</i>	NEC \$ 25.00	+
47	IMPACT PROTECTION - RIGHT <i>re</i>	NEC \$ 25.00	+
48	LED HEADLIGHT - RH <i>cut</i>	\$ 7,204.00	✓
49	MAIN LIGHT ELECTRONICS POWER MODULE <i>re</i>	\$ 693.00	+
50	LIGHT CONTROL SYSTEM CONTROL UNIT <i>re</i>	\$ 685.00	+
51	LED HEATS <i>re</i>	\$ 1,053.00	+
52	HEADLIGHT HOSE - RH <i>re</i>	\$ 32.00	+
53	LIFT CYLINDER - RH <i>?</i>	\$ 181.00	?
54	LIFT CYLINDER BRACKET <i>?</i>	\$ 13.00	?
55	LIFT CYLINDER HOSE LONG <i>re</i>	\$ 78.00	+
56	LIFT CYLINDER HOSE <i>re</i>	\$ 35.00	+
57	CAUTION SIGN <i>re</i>	NEC \$ 132.00	+
58	AIR COND STICKER <i>re</i>	NEC \$ 7.00	+
59	RADIATOR AIR GUIDE - RH <i>?</i>	\$ 28.00	?
60	RADIATOR AIR GUIDE - RH <i>?</i>	\$ 15.00	?
SUB TOTAL SPARE PARTS		\$ 13,024.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 1239 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	RADIATOR AIR GUIDE - UPPER }?	\$ 15.00	?
62	RADIATOR AIR GUIDE - LOWER	\$ 19.00	?
63	LOCK CARRIER new	\$ 928.00	+
64	RADIATOR COOLANT new	4 \$ 165.00	+
65	ALUMINIUM RIM - RH } new	\$ 943.00	+
66	RUBBER VALVE	4 \$ 13.00	+
67	FRONT NO. PLATE ne	S/N \$ 40.00	✓
68	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS		: \$ 26,340.00	
TOTAL LABOUR CHARGES		\$ 13,252.00	
GRAND TOTAL		<u>\$ 39,592.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Admin Lj
22/07/19.

: Not Authorised, 06 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant