

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chew Beng Kee

Date: 26 Aug 2019

## **Preliminary Advice**

Vehicle No	: YM8613P	Accident Date	: 19/07/2019
Make	: MITSUBISHI FE83PE6SRDEB	Policy No.	: Z19VC05002333
Assignment Date	: 22/07/2019	Excess	: S\$0.00
Date of Inspection	: 24/07/2019	Est. Duration of Repair	: 0.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages undercarriage and engine caught fire.

Repairer's Estimate (Gross)	:S\$	80.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	TOTAL LOSS
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	30,000.00
COE / PARF Rebate	:S\$	13,613.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,387.00

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. Vehicle recommended total loss.
- ( ) Other comments :