

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chew Beng Kee

Date: 25 Jul 2019

Preliminary Advice

Vehicle No	: YM8613P	Accident Date	: 19/07/2019
Make	: MITSUBISHI FE83PE6SRDEB	Policy No.	: Z19VC05002333
Assignment Date	: 22/07/2019	Excess	: S\$0.00
Date of Inspection	: 24/07/2019	Est. Duration of Repair	: -
Inspection At	: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages undercarriage and engine caught fire.

Repairer's Estimate (Gross)	:S\$ 80.00
Revised Amount	:S\$ TOTAL LOSS
Check Items (Estimated)	:S\$ 0.00
Total	:S\$ TOTAL LOSS
 Lump Sum Repair	:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 22,000.00
COE / PARF Rebate	:S\$ 13,613.00
Salvage Value	:S\$
Margin for Repair	:S\$ 8,387.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. Vehicle recommended total loss.
- () Other comments :