

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4537B

DATE 16/6/2016 16:57

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (LH)		2 x	\$ 1,935.90
	Rear Fender Inner Lining (LH)		one	\$ x 74.10
	Rear Windscreen Moulding		1/1	\$ x 60.00
	Rear Door (LH)		1	\$ 1,294.70
	Rear Door Outer Handle (LH)		1	\$ 39.60
	Rear Door Gear/Regulator (LH)		1	\$ 300.00
	Rear Protector(LH)		1	\$ 54.50
	Front Door (LH)		1	\$ 1,345.00
	Front Door Glass (LH)		1	\$ 363.70
	Front Door Gear / Regulator (LH)		1	\$ 203.30
	Front Door Mirror (LH)		1	\$ 545.50
	Front Door Power Motor		1	\$ 508.40
	Front Door Protector (LH)		1	\$ 74.90
	Front Fender (LH)		1	\$ 593.10
	Front Fender Shield (LH)		1	\$ 86.00
	Front Fender Signal Lamp (LH)		1	\$ 45.40
	SUB TOTAL			\$ 7,524.10
	LESS 20%			\$ 1,504.82
	DISCOUNTED TOTAL			\$ 6,019.28
	Rear Windscreen Sealant		1	\$ 46.00 Nett
	Rear Fender Advertisement Logo (LH)		1	\$ 100.00 Nett
	Rear Door Advertisement Logo (LH)		1	\$ 100.00 Nett
	Rear Door Tel No. Sticker (LH)		1	\$ 10.00 Nett
	Front Door Coloured Comfort Logo (LH)		1	\$ 75.00 Nett
	Front Fender Advertisement Logo(LH)		1	\$ 100.00 Nett
				\$ 431.00
	Labour Charge			
	Panel Beating			\$ 1,200.00 800
	Spray Painting Charge			\$ 900.00 850
	Wiring Charge			\$ 50.00 30
	Tuff Kote			\$ 50.00 ✓
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 60
	Remove/Refix Rear Windscreen Glass			\$ 120.00 x N/A
	Remove/Refix Reverse Sensor			\$ 120.00 x N/A
	Transfer of Door		\$ 120.00	\$ 240.00 120
	TOTAL LABOUR			\$ 2,830.00
	ESTIMATE TOTAL			\$ 9,280.28

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.