

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3368J

DATE 17/2/2016 11:12

MAKE :

LR Ins - LIS LK Henry

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>cr</i>			\$ 538.80
	Front Bumper Protector (RH) <i>slc</i>			\$ 29.20
	Front Bumper Bracket (RH) <i>cr</i>			\$ 20.10
	Front Bumper Side Bracket <i>gr</i>			\$ 14.30
	Front Bumper Retainer Mounting <i>cr</i>			\$ 9.20
	Headlamp (RH) <i>slc</i>			\$ 797.90
	Front Fender (RH) <i>dented</i>			\$ 593.00
	Front Fender Shield (RH) <i>tom</i>			\$ 86.00
	SUB TOTAL			\$ 2,088.50
	LESS 20%			\$ 417.70
	DISCOUNTED TOTAL			\$ 1,670.80
	Front Number Plate <i>nr</i>			\$ 25.00
				\$ 25.00
	Labour Charge			
	Panel Beating		<i>300</i>	\$ 450.00
	Spray Painting Charge		<i>360</i>	\$ 400.00
	Wiring Charge		<i>30</i>	\$ 50.00
	Tuff Kote		<i>X</i>	\$ 100.00
	TOTAL LABOUR			\$ 1,000.00
	ESTIMATE TOTAL			\$ 2,695.80

*3day LIS
LK Henry
97884060
17/2/16 1200hrs.*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.