

Trans-cab Auto Services Pte Ltd

AAD1907-150

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5557S*Not Authorised**Cl/Sing B ?*

Vehicle No.:
 Chassis No.: 22 JUL 2019
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

SHC 5557S

VF1ABL15AUC279248

RENAULT

LATITUDE

12.7.19

III

15/9/2014

PART**LIST**

1	1	BUMPER COVER FRT	\$	<i>Mr</i> 1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>Mr</i> 181.75	✓
3	1	BUMPER ABSORBER FRT	\$	<i>Mr</i> 394.68	✓
4	1	BUMPER RETAINER FRT LH	\$	<i>CM</i> 151.41	✓
5	1	BUMPER SUPPORT FRT	\$	<i>Mr</i> 123.88	✓
6	1	BUMPER RETAINER FRT RH	\$	<i>CM</i> 150.77	✓
7	1	BUMPER SUPPORT FRT	\$	<i>Mr</i> 123.88	✓
8	1	BUMPER UNDERTRAY FRT	\$	<i>CM</i> 472.83	✓
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Mr</i> 266.80	✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Mr</i> 207.21	✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Mr</i> 207.21	✓
12	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08	✓
13	1	TOW COVER FRT	\$	<i>Mr</i> 28.61	✓
14	1	RADIATOR GRILLE	\$	<i>Mr</i> 1,707.78	✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Mr</i> 225.36	✓
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i> 1,353.75	✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i> 615.90	✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79	✓
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22	✓
20	1	HORN	\$	<i>SVC</i> 314.17	X
21	1	HORN BRACKET	\$	<i>R</i> 40.45	X
22	1	HEADLAMP LH	\$	<i>CM</i> 1,184.43	✓
23	1	HEADLAMP RH	\$	<i>My CM</i> 1,184.43	✓
24	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	X
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	✓
26	1	BONNET	\$	<i>Be</i> 1,941.63	✓
27	1	BONNET INSULATOR	\$	<i>Sn</i> 405.73	X
28	1	BONNET STRUT LH	\$	<i>Sn</i> 88.61	X
29	1	BONNET STRUT RH	\$	<i>Sn</i> 88.61	X

Trans-cab Auto Services Pte Ltd**AAD1907-150**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5557S

30	1	BONNET HINGE LH	\$	<i>Di</i>	348.31	—
31	1	BONNET HINGE RH	\$	<i>Di</i>	348.31	—
32	1	BONNET LOCK	\$	<i>B</i>	305.48	—
33	1	BONNET CABLE	\$	<i>SL</i>	119.19	X
34	1	BONNET CABLE COVER	\$	<i>SL</i>	161.03	X
35	1	BONNET SEAL OUTER	\$	<i>Di</i>	92.36	—
36	1	BONNET SEAL INNER	\$	<i>SL</i>	157.28	X
37	1	FENDER PANEL FRT LH	\$	<i>B</i>	783.83	—
38	1	WHEELARCH FRT LH	\$	<i>CM</i>	278.84	—
39	1	FENDER BRACKET LOWER LH	\$	<i>R</i>	15.79	} X
40	1	FENDER INSULATOR LH	\$	<i>SL</i>	130.84	
41	1	FENDER PANEL FRT RH	\$	<i>R</i>	130.84	
42	1	WHEELARCH FRT RH	\$	<i>SL</i>	278.84	
43	1	FENDER BRACKET LOWER RH	\$	<i>SL</i>	36.11	
44	1	FENDER INSULATOR RH	\$	<i>SL</i>	130.84	
45	1	WIPER RESERVOIR	\$	<i>SL</i>	348.25	
46	1	WIPER RESERVOIR NECK	\$	<i>SL</i>	136.11	
47	1	WIPER RESERVOIR MOTOR	\$	<i>SL</i>	270.06	
48	1	AIR CLEANER LOWER	\$	<i>SL</i>	271.26	
49	1	AIR CLEANER HOSE	\$	<i>SL</i>	76.14	
50	1	BASE BATTERY TRAY	\$	<i>CM</i>	363.40	—
51	1	AIR CLEANER BOX	\$	<i>SL</i>	464.20	X
52	1	TURBO DUCT	\$	<i>SL</i>	1,027.80	X
53	1	A/C HEATER VALVE	\$	<i>SL</i>	484.50	X
54	1	SUBFRAME OUTER FRT	\$	<i>SL</i>	2,652.45	X
55	1	SUBFRAME BRACKET OUTER LH	\$	<i>R</i>	92.36	X
56	1	SUBFRAME BRACKET OUTER RH	\$	<i>R</i>	92.36	X
57	1	ENGINE UNDERTRAY	\$	<i>SL</i>	564.98	X
58	1	A/C CONDENSER	\$	<i>B</i>	2,020.37	—
59	1	A/C CONDENSER GARNISH LH UPPER	\$	<i>SL</i>	39.67	} X
60	1	A/C CONDENSER GARNISH RH UPPER	\$	<i>SL</i>	39.67	
61	1	A/C CONDENSER GARNISH LH	\$	<i>SL</i>	58.81	
62	1	A/C CONDENSER GARNISH RH	\$	<i>SL</i>	59.60	
63	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	<i>SL</i>	208.39	
64	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	<i>SL</i>	658.72	
65	1	A/C PIPE COMPRESSOR	\$	<i>SL</i>	334.29	
66	1	A/C PIPE	\$	<i>SL</i>	658.72	}
67	1	A/C COMPRESSOR	\$	<i>SL</i>	2,684.61	

Trans-cab Auto Services Pte Ltd**AAD1907-150**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5557S

68	1	AIR COOLER	\$	Bl/Pn	792.60	✓
69	1	AIR INTERCOOLER HOSE (LONG)	\$	Pn	1,014.13	X
70	1	AIR INTERCOOLER HOSE (Short)	\$	Sn	375.14	X
71	1	TRANSMISSION COOLER	\$	Sn	1,219.30	X
72	1	TRANSMISSION COOLER PAD	\$	Sn	17.96	X
73	1	RADIATOR	\$	Pn	1,202.20	✓
74	2	RADIATOR STUD UPPER	\$	Pn	14.41	X
75	2	RADIATOR BUSH UPPER	\$	Sn	50.12	X
76	2	RADIATOR MTG LOWER	\$	Sn	55.85	X
77	1	RADIATOR FAN COWLING	\$	SVC {	820.54	7X
78	1	RADIATOR FAN MOTOR LH	\$		967.36	7X
79	1	RADIATOR FAN MOTOR RH	\$		1,479.46	7X
80	1	RADIATOR TANK	\$	Sn	324.62	} X
81	1	RADIATOR HOSE UPPER	\$	Sn	240.56	
82	1	RADIATOR HOSE LOWER	\$	Sn	491.18	
83	1	RADIATOR TANK HOSE	\$	Sn	61.18	
84	1	LOWER ARM LH L70Y	\$	Sn	685.76	
85	1	KNUCKLE ARM LH L70Y	\$	Sn	846.98	
86	1	ABSORBER FRT LH L70Y	\$	Sn	360.54	
87	1	DRIVESHAFT LH	\$	M	1,747.45	
88	1	STABILIZER BAR FRT	\$	Sn	604.65	
89	1	DOOR PANEL FRT LH	\$	M	2,844.66	
90	1	DOOR MIRROR ASSY LH	\$	Sn	1,483.40	} X
91	1	DOOR HARNESS WIRE LH	\$	Sn	2,670.00	
92	1	DOOR PANEL FRT RH	\$	M	2,844.66	
93	1	DOOR MIRROR ASSY RH	\$	Sn	1,483.40	
94	1	DOOR HARNESS WIRE RH	\$	Sn	2,670.00	
95	1	AUTO COMPUTER	\$	Sn	5,032.17	
96	1	INJECTION COMPUTER	\$	Sn	4,706.30	
97	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	Sn	5,154.52	
98	1	STEERING PUMP ELECTRIC L70Y	\$	Sn	2,306.90	
99	1	STEERING PINION RACK L70Y	\$	Sn	4,413.11	
100	1	WINDSCREEN FRNT	\$	CM	1,364.06	✓
101	1	RAIN SENSOR	\$	Sn	509.48	X
102	1	WINDSCREEN SEALANT	\$	M	253.80	405A
103	1	SHELF ASSY (WINDSCREEN UNDER PANEL)	\$	M	443.76	X
104	1	WINDSCREEN LOW GRILLE COVER	\$	Sn	310.60	X
105	1	WINDSCREEN INNER GARNISH RH	\$	Sn	257.40	X

Trans-cab Auto Services Pte Ltd**AAD1907-150**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5557S

106	1	WINDSCREEN INNER GARNISH LH	\$	<i>Sn</i>	257.40	X
107	1	SEATBELT LH	\$	<i>Tn</i>	2,937.80	✓
108	1	SEATBELT RH	\$	<i>Tn</i>	2,937.80	✓
109	1	SEATBELT BUCKLE LH	\$			
110	1	SEATBELT BUCKLE RH	\$	<i>svc</i>	984.13	X
111	1	PASSENGER AIRBAG	\$	<i>Burh</i>	3,412.40	✓
112	1	STEERING AIRBAG	\$	<i>u</i>	2,525.75	✓
113	1	AIRBAG COMPUTER	\$	<i>na</i>	1,259.82	✓
114	1	AIRBAG SENSOR	\$	<i>na</i>	724.63	✓
115	1	DASHBOARD	\$	<i>Tn</i>	4,900.54	✓
116	1	FUSE BOX	\$	<i>Sn</i>	987.39	} X
117	1	ENGINE MOUNTING RH	\$	<i>Sn</i>	552.55	
118	2	ENGINE MOUNTING LOWER	\$	<i>Sn</i>	562.42	
119	1	ENGINE MOUNTING UPPER	\$	<i>Sn</i>	592.02	
120	1	OIL PAN ASSEMBLY	\$	<i>Sn</i>	2,283.91	
121	1	GLOVE BOX	\$	<i>Sn</i>	1,039.78	
122	1	GLOVE BOX FLAP	\$	<i>Sn</i>	1,278.96	
123	1	FACE CONSOLE	\$	<i>Sn</i>	949.60	
124	1	ENGINE HARNESS L70Y	\$	<i>Sn</i>	4,084.54	
TOTAL			\$		116,505.08	
10%			\$		11,650.51	
			\$		104,854.57	

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	<i>na</i>	52.00	—
2	1SET	BUMPER CLIP FRT	\$	<i>na</i>	66.00	—
3	1	BUMPER BRACKET CLIP FRT LH	\$	<i>na</i>	12.00	} X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	<i>na</i>	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	<i>na</i>	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	<i>na</i>	10.50	
7	1	TOW COVER FRT	\$	<i>na</i>	14.50	
8	1SET	RADIATOR GRILLE SCREW	\$	<i>na</i>	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	<i>na</i>	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i>	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	<i>na</i>	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	<i>na</i>	30.00	
13	1	Windscreen moulding	\$	<i>na</i>	120.00	✓

Trans-cab Auto Services Pte Ltd**AAD1907-150**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5557S

14	1	FRONT WINDSCREEN SEALANT	\$	<i>Repair</i> 253.80	X
15	1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00	X
16	1SET	Front licence plate with holder	\$	<i>mit</i> 80.00	<i>855a</i>
17	1SET	WHEELARCH CLIP FRT LH	\$	<i>nc</i> 30.50	—
18	1SET	WHEELARCH CLIP FRT RH	\$	<i>nn</i> 30.50	X
19	1	Front left tyre	\$	<i>pn</i> 330.00	} X
20	1	Front left tyre rim	\$	<i>sn</i> 380.00	
21	1	Front right tyre	\$	<i>pn</i> 330.00	
22	1	Front right tyre rim	\$	<i>sn</i> 380.00	
23	6	BONNET INSULATOR CLIP L70Y	\$	<i>nn</i> 7.30	
24	2	BONNET STRUT L70Y	\$	<i>nn</i> 88.61	
25	2	BONNET CABLE CLIP L70Y	\$	<i>nn</i> 6.31	
26	2	BONNET CABLE COVER SCREW L70Y	\$	<i>nn</i> 10.85	
27	1	FRONT LH DOOR STICKER 'Trans-Cab'	\$	<i>nn</i> 80.00	} <i>605a</i>
28	1	FRONT LH DOOR STICKER 'Classic'	\$	<i>nn</i> 80.00	
29	1	FRONT RH DOOR STICKER 'Trans-Cab'	\$	<i>nn</i> 80.00	
30	1	FRONT RH DOOR STICKER 'Classic'	\$	<i>nn</i> 80.00	
TOTAL			\$	2,850.38	<i>155a</i>

TOTAL PARTS \$ 107,704.95**LABOUR**

To rust-proofing of the affected areas.	\$	170.00	<i>901</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	7,500.00	<i>7001</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X

Trans-cab Auto Services Pte Ltd**AAD1907-150**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5557S

To remove and refit air bag system and reset vehicle warning indicators.	\$	480.00	2201
To check steering geometry and computer wheel alignment	\$	220.00	nn X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	nn X
Putty and spray painting of the affected portion.	\$	7,500.00	13201
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	380.00	nn X
To replace, refix and top up coolant for radiator	\$	170.00	501
To vacuum, replace, refix and recharge air condenser	\$	380.00	1001
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	501
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	350.00	nn X
To transfer of front windscreen fittings and conduct water seepage test	\$	200.00	1201
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	380.00	nn X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	nn X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	nn X

Trans-cab Auto Services Pte Ltd**AAD1907-150**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5557S

To check ABS and brake efficiency, final checking and testing.	\$	<i>nn</i>	380.00	<i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>nn</i>	450.00	<i>X</i>
To lift-up engine with gear box and refit.	\$	<i>nn</i>	440.00	<i>X</i>
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	<i>nn</i>	380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>2ol</i>
To replace and refill power steering fluid.	\$	<i>nn</i>	170.00	<i>X</i>
Towing Fees	\$		120.00	<i>5ol</i>
To dismantle and refit engine cross-member and engine mounting.	\$	<i>nn</i>	380.00	<i>X</i>
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i>	170.00	<i>X</i>
To conduct and perform a comprehensive engine diagnostic check.	\$	<i>nn</i>	380.00	<i>X</i>
TOTAL	\$		23,070.00	
Over All Total	\$		130,774.95	

Repair Days (LUMP SUM)**25 DAYS***8 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: