

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5753S**AAD1907-178***Not Authorised*

Vehicle No.:

Chassis No.:

22 JUL 2019

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5753S

VF1ABL15AUC281581

RENAULT

LATITUDE

19.7.19

AXA

3/7/2015

PART		LIST	
1	DOOR PANEL REAR RH	\$	2,844.66 ✓
1	DOOR GUIDE REAR RH	\$	176.82 X
1	DOOR HINGE UPPER RH	\$	274.50 ?
1	DOOR HINGE LOWER RH	\$	300.55 ?
1	DOOR CHECK REAR LH/RH L70Y	\$	203.06
1	DOOR LOCK REAR RH	\$	908.75
1	DOOR HANDLE OUTER REAR RH	\$	126.49
1	DOOR HANDLE CAP REAR RH	\$	35.52
1	DOOR HANDLE SEAL REAR RH	\$	7.89
1	DOOR HANDLE COVER REAR RH	\$	13.22
1	DOOR HANDLE MODULE REAR RH	\$	133.60
1	DOOR REGULATOR REAR RH	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	893.75
1	DOOR MOULDING REAR RH	\$	176.82
1	DOOR CASING REAR RH	\$	1,509.06
1	DOOR FINISHER REAR RH	\$	423.10
1	DOOR FINISHER INNER REAR RH	\$	323.44
1	DOOR WHEATHESTRIIP REAR RH	\$	410.66
1	DOOR SEAL REAR RH	\$	162.02
1	DOOR BLIND REAR RH	\$	741.80
1	DOOR GLASS RUNNER SEAL REAR RH	\$	229.31
1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69
TOTAL		\$	11,364.81
10%		\$	1,136.48
		\$	10,228.33

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$
1	DOOR CHECK BOLT	\$

80.00 605m
22.69 X

Trans-cab Auto Services Pte Ltd

AAD1907-178

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5753S

1	DOOR GUIDE SCREW	\$	na	10.85	} X
1	DOOR HINGE BOLT	\$	na	10.85	
1	DOOR HINGE NUT RH	\$	na	14.60	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR CHECK NUT	\$	na	3.75	
1	DOOR LOCK SCREW L70Y	\$	na	6.12	
1	DOOR CATCH SCREW L70Y	\$	na	10.06	
TOTAL		\$		181.63	
TOTAL PARTS		\$		10,409.96	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	2001
Putty and spray painting of the affected portion.	\$	4,500.00	2201
To rust-proofing of the affected areas.	\$	170.00	301
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	na X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of rear door fittings, attachment and perform water seepage test.	\$	380.00	601
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	na X
TOTAL	\$	10,480.00	

Over All Total \$ 20,889.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LUMP SUM (REPAIR DAY)~~15 DAYS~~

2 days